

PKS XCEL

MSIG

1


Date: 05/01/2018
GBC 8187C
06 Dec 2013

TO: GBC 8187C
Ryder Auto
Ikaki Bkt Ave 6 #01-56 Autobay

ISUZU NHR85AHE^{4AC} 2999
Blue
107389

Orson @ 90908277
After 2pm

JAANHR85ED7100091



Remarks: The van had commenced its repair at the time of inspection.

Type Size: 195/70R15 (Toyo)
165 R13 (BS)

Est. Repair: 24 HRS 'w/p'
Person Contacted: _____

u/s Ryder Auto 05-01-18 3pm
o/s Rear

Estimated repair range \$2,800 - \$3,500

[Signature]
26/3/2018

RECEIVED 27 MAR

MURPHY

Form with checkboxes for 'Print Report', 'Final Report', 'Days Of Repair', 'Resurvey No. of Trip', 'Add Fee', 'Site Fee', 'Name', 'Training', 'Fuel'.

Catherine Chong (LKK Auto)

From: Lionel Tan <lionel_tan@sg.msig-asia.com>
Sent: Thursday, 29 March, 2018 2:06 PM
To: 'Catherine Chong (LKK Auto)'
Cc: 'assignments'
Subject: FW: Our Ref: BK/18468.18, Yr Ref: 543810, Acc Inv: GBC 8187 C & YP 741 P ON 27 DECEMBER 2017

Hi Catherine,

Please attend to the re-inspection notice.

Kindly acknowledge. Thank you.

Regards

Lionel Tan
Executive, Claims Services (Motor)
D: +65 6643 1307 | F: +65 6225 7402 | lionel_tan@sg.msig-asia.com

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Thursday, 29 March, 2018 10:43 AM
To: Lionel Tan <lionel_tan@sg.msig-asia.com>; Claims <claims@sg.msig-asia.com>
Subject: Our Ref: BK/18468.18, Yr Ref: 543810, Acc Inv: GBC 8187 C & YP 741 P ON 27 DECEMBER 2017

Dear Lionel,

We refer to your letter dated 27 March 2018.

Kindly have your surveyor attend at No. 1 Kaki Bukit Avenue 6 #01-56 Singapore 417883 on 10 April 2018 at 11.00 a.m. for the re-survey of our client's vehicle.

Kindly ensure that your surveyor attends punctually.

Kindly let us know which surveyor you have appointed so that we may inform our client accordingly.

Please let us have your offer of settlement as soon as possible.

Regards,
June

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Reinspection

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jan 2018		05 Jan 2018 11:02 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	RADEEP SERVICES , Co. Reg. No.: 52871240C, Tel: +6591484079		
Main Claimant:	GORDON LOGISTICS (S) PTE LTD , Co. Reg. No.: 200917839R		
Vehicle Reg. No.:	GBC8187C	Date of Loss:	27/12/2017 15:00 - :59 [48 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 543810	Policy/Cover Note No.:	A28660427MKC (Comprehensive) Coverage: 21/12/2017 - 20/12/2018
Vehicle Reg. No. (Insured):	YP741P	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Ryder Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/04/2018]		
Driver/Custodian (Insured):	KANGAMUTHU RAJENDRAN (56 / Male), NRIC: S2762161I		
Adj Asg. Remarks:	Please contact Mr Orson / 9090 8277 or Mr Chan / 9792 4673 to arrange for survey .		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG_SG (29/03/2018): Report Send Back Alerts - GBC8187C (TP)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MSME17170574 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 29/12/2017 17:35
 SUBMITTED BY: Pei Ying

Ryder Auto Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/12/2017 17:35
Date Of Accident	27/12/2017 15:15
Exact Location Of Accident	TANNERY LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC8187C
Insured/Policyholder	
Name Of Registered Owner	GORDON LOGISTICS (S) PTE LTD
Co Reg No	200917839R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96854828
Alternative Phone No	OFFICE-63965285

Vehicle Particulars

Manufacturer	ISUZU
Model	NHR85AUE4AC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1569704
Cover Note Number	

Driver

Name of Driver	YU LINA
NRIC No	S7986370Z
Date Of Birth	04/05/1979
Occupation	INDOOR
Date Of Driving Pass	16/12/2014
Driving Experience	3 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96854828
Fax Number	
Contact Number	
Email Address	NOEMAIL

Ryder Auto Pte Ltd

Address BLK 376A HOUGANG ST 32 #10-12
 Postcode 531376
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY AT TANNERY LANE WHICH WAS A 2 WAY TRAFFIC WAITING FOR THE TRAFFIC TO BE CLEAR BEFORE MOVING OFF. SUDDENLY, VEHICLE B (YP741P) FROM OPPOSITE LANE TURN INTO A WAREHOUSE BUILDING AND VEHICLE B REAR PORTION SIDE SWIPE ONTO MY REAR RIGHT SIDE OF MY VEHICLE WHILE HE WAS TURNING IN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP741P
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage
No. Of Passenger (Including Driver)

Ryder Auto Pte Ltd


Sketch Plan Pg. 1

Ryder Auto Pte L

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material fact allow insurance companies to reassess policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Handwritten signature 'le'.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

28/12/17



A	GBC81B7C	B	YP741P	C		D		E		F	
---	----------	---	--------	---	--	---	--	---	--	---	--

Sketch Plan #2 Pg. 1

Circumstances of the Accident

I WAS STATIONARY AT Tannery LN WHICH WAS A TWO WAY TRAFFIC WAITING FOR THE TRAFFIC TO BE CLEAR BEFORE MOVING OFF. SUDDENLY VEHICLE B YP741P FROM THE OPPOSITE LANE TURN INTO A WAREHOUSE BUILDING AND VEHICLE B REAR PORTION SIDE-SWIPE ONTO MY REAR RIGHT SIDE OF MY VEHICLE WHILE HE WAS TURNING IN.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder / Driver / Date & Time
 28/12/17

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Insurance Co.	AXA		
Vehicle NO.	GBC8187C	Date Of Accident	27/12/2017
<input type="checkbox"/> Reporting Only	THIRD PARTY		
<input type="checkbox"/> Own Damage Claim			
<input type="checkbox"/> Third Party Claim			

RYDER AUTO PTE LTD

1 KAKI BUKIT AVENUE 6 #01-56 SINGAPORE 417883

HP: 9090 8277 (Mr. Orson) / 9792 4673 (Mr. Chan)

GORDON LOGISTICS (SINGAPORE) PTE. LTD.

NO. 629 ALJUNIED ROAD

#06-19 CITITECH INDUSTRIAL BUILDING

SINGAPORE 389838

DATE: 15/01/18

DEAR SIRs

ACCIDENT DATE: 27/12/17

FINAL REPAIR BILL TO GBC 8187 C

LUMP SUM REPAIRS RECOMMENDED

BY THE SURVEYOR-----\$ 13,000.00

DOLLARS: THIRTEEN THOUSAND ONLY

MIC SURVEY & ASSESSMENT SERVICE

BLK 355A, SEMBAWANG WAY #08-104, SINGAPORE 751355 TEL/FAX: 6299 9888 HP: 9674 5457
(LICENSED APPRAISERS & ADJUSTERS)

VEHICLE INSPECTION REPORT

TO: Gordon Logistics (S) Pte Ltd

REFERENCE

Requested by: Gordon Logistics (S) Pte Ltd
Date of Request: 29 December, 2017
Date of Inspection: 29 December, 2017

Our Ref:
Policy No.:
Claim No.:

DETAILS OF VEHICLE

Reg No: GBC 8187 C

Year: 2013

Make & Model: Isuzu NHR85 AUE4AC

Colour: Blue

Engine No: 4JJ1371384

Chassis No: JAANHR85ED710091

Speedo Reading: 106577

Carry Capacity: 2

Air-Conditioners: Yes

Radio/Cassette: Yes

Seat Belt: Yes

Others: Nil

PRE-ACCIDENT CONDITION (STATIC TESTS)

General: Good
Handbrake: Servicable
Footbrake: Servicable
Steering: Servicable


TYRES

60% ——— 60%
Ohtsu
60%60% ——— 60%60%

Rim: Standard

Size: 195 R 15
165 R 13

IMPACT: ARROW INDICATES
DIRECTION OF IMPACT.



GENERAL DESCRIPTION OF DAMAGE

The impact was confined to the rear o/s portion of the vehicle.

The above vehicle sustained damaged were rear o/s lower garnish - bent.

APPRAISEMENT

Original Quotation: \$ 15,980.00 Revised Quotation: \$ 15,380.00 Less Excess: Nil

SPECIAL REMARKS

The estimated period of repairs will take 10 days to complete. Pursuant to your instructions, we have not authorised M/s. Ryder Auto Pte Ltd to repair on your behalf. The survey was conducted strictly without prejudice basis.

.....
This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

MIC SURVEY & ASSESSMENT SERVICE

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

NAME OF REPAIRERS: Ryder Auto Pte Ltd

ADDRESS: 1 Kaki Bukit Ave. 6
#01-56 Autobay
Singapore 417883

Replaces of Parts	Conditions	Repairs Est.	Our Recommendation
<u>To Supply :- Nett Items</u>			
1 pc Rear o/s Tail-gate Bracket	Bent	\$ 380.00	\$ 380.00
1 pc Rear o/s Stainless Frame	Dented/Bent	2,400.00	2,400.00
1 pc O/S Refrigerator Board (Outer)	Cracked	4,800.00	4,800.00
1 pc O/S Refrigerator Insulator (Inner)	Necessary	3,200.00	3,200.00
1 pc O/S Advertisement	Necessary	400.00	400.00
		<u>\$11,180.00</u>	<u>\$11,180.00</u>
<u>Labour Charges & Miscellaneous :-</u>			
To dismantle rear o/s portion damaged parts, to replace rear stainless frame and o/s refrigerator board (Outer).		\$ 4,800.00	\$ 4,200.00
		<u>\$15,980.00</u>	<u>\$15,380.00</u>
<u>SPECIAL REMARKS</u>			
The repairers verbally agreed to repair the vehicle at a global sum of \$13,000.00 corresponding to labour charges & spray painting and replacement of parts. Your liability is \$13,000.00.			

MIC SURVEY & ASSESSMENT SERVICE

OHU

ONG HOCK LENG
Licensed Appraisers





...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jan 2018		05 Jan 2018 11:02 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	RADEEP SERVICES , Co. Reg. No.: 52871240C, Tel: +6591484079								
Main Claimant:	GORDON LOGISTICS (S) PTE LTD , Co. Reg. No.: 200917839R								
Vehicle Reg. No.:	GBC8187C	Date of Loss: 27/12/2017 15:00 - :59 [48 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 543810	Policy/Cover Note No.: A28660427MKC (Comprehensive) Coverage: 21/12/2017 - 20/12/2018							
Vehicle Reg. No. (Insured):	YP741P	Policy No. (Claimant): Excess: S\$1,500.00							
Repairer:	Ryder Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/04/2018]								
Driver/Custodian (Insured):	KANGAMUTHU RAJENDRAN (56 / Male), NRIC: S27621611								
Adj Asg. Remarks:	Please contact Mr Orson / 9090 8277 or Mr Chan / 9792 4673 to arrange for survey .								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (29/03/2018): Report Send Back Alerts - GBC8187C (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC8187C (543810)
[YP741P]
TP
GORDON LOGISTICS (S) PTE LTD
Dec 27 2017 3:00PM
[RADEEP SERVICES]
Ryder Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="checkbox"/>
Assessment Reports				1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/01/18 15:36	Accident Statement From:SC - Reg. No: YP741P, Claimant: RADEEP SERVICES	Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/03/18 18:34	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/03/18 18:34	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
10	26/03/18 18:34	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
11	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
12	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
13	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
14	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
15	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
16	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	31/05/18 12:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/01/18 15:36	TPD GBC8187C GIA REPORT	Load PDF	<input type="checkbox"/>
2	04/01/18 15:37	TPD GBC8187C - PRI	Load PDF	<input type="checkbox"/>
3	27/03/18 11:56	Survey report	Load PDF	<input type="checkbox"/>
4	27/03/18 11:56	Repairer's Bill	Load PDF	<input type="checkbox"/>
5	27/03/18 11:56	Survey photographs	Load PDF	<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 15:22	PRS Invoice	Load PDF	<input type="checkbox"/>
2	31/05/18 15:25	Photo	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG18000313/GRBE2-1**Date:** 31/05/2018REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28660427MKC
Claimant Vehicle No : GBC8187C	Insured Vehicle No :	YP741P
Date of Loss: 27/12/2017	Nature of Claim:	TP
		Claim No: 543810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC8187C	Engine No:	4JJ1371384
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Chassis No:	JAANHR85ED7100091
Reg. Date:	06/12/2013 (Man. Year: 2013)	Odometer:	116356 km
Colour:	Blue		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/70 R15	Rear Tyre Size:	165 R13
Front Left Side:	Toyo 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,180.00	2,680.00	8,500.00	76.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	1,200.00	3,600.00	75.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,980.00	3,880.00	12,100.00	75.72
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	15,980.00	3,100.00	12,880.00	80.60

INSPECTION

Date of Assignment:	05/01/2018	
Date Inspected:	10/04/2018 Inspected At:	Ryder Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-56 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 May 2018)	
Parts:	N/A	ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC8187C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S TAIL-GATE BRACKET	Replaced	380.00 FS	*80.00 FS
2	1		*REAR O/S STAINLESS FRAME	Replaced	2,400.00 FS	*700.00 FS
3	1		*O/S REFRIGERATOR BOARD (OUTER)	Replaced	4,800.00 FS	*850.00 FS
4	1		*O/S REFRIGERATOR INSULATOR (INNER)	Replaced	3,200.00 FS	*800.00 FS
5	1		*O/S ADVERTISEMENT	Replaced	400.00 FS	*250.00 FS
Total Parts (S\$)					11,180.00	2,680.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE REAR O/S PORTION DAMAGED PARTS, TO REPLACE REAR STAINLESS FRAME AND O/S REFRIGERATOR BOARD (OUTER)	New	4,800.00	1,200.00
			<hr/>	
			Gross Labour Cost (\$\$)	4,800.00
			<hr/>	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >