

RECEIVED 3 APR 2018

ASS. REF. BY	REF: C83/MSG7018833/Sr6-102	See Tail Note page
Surveyor	Sebastian	ASSIGNMENT (Office)
From Person	Irene Tan	of MSG
Estimated Cost		Date/Time 2/10/17 9:54am
OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS		
To Inspect Vehicle No	YP1847 L	Insured: GX4962M
at Workshop no	Zhang Cheng Enterprise	Tel: 9338 2859
or	Blk 6 Woodlands Rd, Yew Tee Ind Est 399J 1678008	
Policy No	P28748317 MKC	Claim No 530706
Sum Insured		Excess
Make of Veh		D.O.A 26/9/17
(Client's Record)		
CA / REV / REP. / REV 24 HRS	'wp'	H.O.D. Endorsement
Date/Time	2/10/17 12pm	Person Contacted MS-Sini
		Vehicle IN (OUT)
Date/Time	Action/Instruction	
	(✓) Estimate	Do Not Finalize
	YP1847 L - X	
	GX4962M - CS/MSG7018833/11/1/1/3 - D.O.A 7/8/2011	
According Sini, they didn't appoint SJE. They have independent survey		
Submit PRS report		

09/04/18 - To submit 2/5 2000/- with 4 days
of gap. (Red: \$1850, 48%.)

MV: \$77,000.00

LTA: \$31,211.00

NV: \$45,789.00

- PRS photos check. No gap.

- DDA and DOI are 2 months apart.

During this period, the tail gate is likely to be
useless.

- Photos by independent survey did not show any
dismantling.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17018833/Srb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-10-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GX 4962M	Veh. Inspected	YP 1847L
Policy No.	P28748317MKC	Coverage (\$)	0.00
Claim No.	530706	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	02/10/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/09/2017	Inspection Date	
Survey held at	ZHONG CHENG ENTERPRISE BLK 4 YEW TEE IND 393-H WOODLANDS ROAD SINGAPORE 677969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2017		02 Oct 2017 09:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]
Insured:	AV-SCIENCE MARKETING PTE LTD, Co. Reg. No.: A04611/1988D	
Main Claimant:	WELLMAX METAL WORKS, Co. Reg. No.: 52912307W	
Vehicle Reg. No.:	YP1847L	Date of Loss: 25/09/2017 09:00 - :59
Claim Type:	TP / 530706	Policy/Cover Note No.: P28748317MKC (TP, Fire & Theft) Coverage: 10/06/2017 - 09/06/2018
Vehicle Reg. No. (Insured):	GX4962M	Policy No. (Claimant):
		Excess:
Repairer:	Zhong Cheng Enterprise () Blk 6 Woodlands Road, Yew Tee Industrial Estate 3991, 678008 Woodlands - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/10/2017]	
Driver/Custodian (Insured):	HAN WIN THEIN (/ Male), NRIC: G5803493U, Tel: +6597628913	
Adj Asg. Remarks:	Contact Person : Ms Sini Handphone No : 9338 2889	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete																				
<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">Due Date</th> <th style="text-align: left;">Priority</th> <th style="text-align: left;">Type</th> <th style="text-align: left;">Task Group</th> <th style="text-align: left;">Subject</th> <th style="text-align: left;">Handler</th> <th style="text-align: left;">Assigned By</th> <th style="text-align: left;">Completed On</th> <th style="text-align: left;">Created On</th> <th style="text-align: left;">Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

ZHONG CHENG ENTERPRISE

Blk 4 Yew Tee Industrial Estate 393H

Woodlands Road

Singapore 677699

Tel: 9826 8959

Fax: 6893 9984

Bill No. ZC70770.17

8 March 2018

WELLMAX METAL WORKS

c/o Zhong Cheng Enterprise

393H Yew Tee Industrial Estate

Singapore 677902

Dear Sir

FINAL REPAIR BILL FOR YP 1847 L - Mitsubishi Canter 3.0

Repair Costs

S\$3,850.00

=====

SINGAPORE DOLLARS: THREE THOUSAND EIGHT HUNDRED AND FIFTY ONLY



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2017 16:56
Date Of Accident	25/09/2017 09:30
Exact Location Of Accident	HOUGANG AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP1847L
Insured/Policyholder	
Name Of Registered Owner	WELLMAX METAL WORKS
Co Reg No	52912307W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94562055
Alternative Phone No	OFFICE-62428842

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	TKG-FEB50
Exact Purpose for which vehicle was being used at time of accident	COMPANY'S USAGE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17002230
Cover Note Number	

Driver

Name of Driver	TAMIL VENDAN RAJIV
Passport No/FIN	G8115791Q
Date Of Birth	12/04/1987
Occupation	OUTDOOR
Date Of Driving Pass	03/01/2013
Driving Experience	4 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90162468
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

-

-

Insurance Company of Driver's Own Vehicle -

-

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 5

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

At the mention date and time of accident 25.09.2017, 0930, I was driving (YP1847L) along upper Serangoon Road towards in front of traffic junction and turning left into the filter lane to turn left toward Hougang Ave 8. When I reach the traffic junction filter lane, I slow down and stop for waiting clearance for on coming vehicle. I stationary stopped while waiting vehicle to be clear about 2 minutes time and suddenly vehicle B (GX4962M) collided my rear lorry portion impact quite heavy.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GX4962M

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver HAN WIN THEIN

NRIC/Passport Number G5803493U

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

维美铝窗锻铁工厂
WELLMAX METAL WORKS
144 TAGORE LANE
SINMO INDUSTRIAL ESTATE
SINGAPORE 787842

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

維美鋁窗鍛鐵工廠
WELLMAX METAL WORKS

144 TAGORE LANE
SINDO INDUSTRIAL ESTATE
SINGAPORE 787562
TEL: 6242 8842 FAX: 6242 2152
REG. NO: 52912307W

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Vehicle A 7K 18472

Vehicle B 6K 74621

Vehicle C 6K 74621

Vehicle D 6K 74621

Vehicle E 6K 74621

Vehicle F 6K 74621

Vehicle G 6K 74621

Vehicle H 6K 74621

Vehicle I 6K 74621

Vehicle J 6K 74621

Vehicle K 6K 74621

Vehicle L 6K 74621

Vehicle M 6K 74621

Vehicle N 6K 74621

Vehicle O 6K 74621

Vehicle P 6K 74621

Vehicle Q 6K 74621

Vehicle R 6K 74621

Vehicle S 6K 74621

Vehicle T 6K 74621

Vehicle U 6K 74621

Vehicle V 6K 74621




Vehicle W 6K 74621

Vehicle X 6K 74621

Vehicle Y 6K 74621

Vehicle Z 6K 74621

90162468



EQ Insurance Company Limited
 5 Maxwell Road #17 00 Tower Block MND Complex Singapore 069110
 tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
 reg no. 1978 00490 N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

COMMERCIAL VEHICLE PRIVATE (SCH I) Comprehensive

Certificate No.: DMCPhQ17-002230

Form: LCVPI

Excess:

Section 1

SGD750.00

YEID-AC

Additional SGD3,000.00

1. Index Mark and Registration Number of Vehicles
 YP1847L

2. Name of Policyholder
 WELLMAX METAL WORKS

3. Effective Date of the Commencement of Insurance for the purpose of the Act
 20/04/2017

4. Date of Expiry of Insurance
 19/04/2018

5. Person or Classes of Persons entitled to drive*
 Goods carrying - (MZ300) Authorised Driver. Any of the following :-
 1. The Policyholder
 2. Any person on the order or with the permission of the Policyholder

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitations as to use*
 1) Use in connection with the Insured's business. 2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business. 3) Use for social domestic and pleasure purposes.

THE POLICY DOES NOT COVER

1) Use for hire or reward or for racing pace-making reliability trial or speed testing. 2) Use whilst drawing a greater number of trailers in all than is permitted by law. 3) Use for the carriage of passengers for hire or reward. 4) Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in cylinders.

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Authorised Signatory
 EQ Insurance Company Limited

misjb/HO/A000317/PF Risk Management P



A Member of Citystate

ACCIDENT STATEMENT Pg. 1

Describe Circumstances of the Accident

At The mention Date & time of accident 25/09/2017, 09:30 am

I was driving along Upper Serangoon Road towards in front traffic

Junction and turning left into the filter lane to turn left

~~to~~ ~~the~~ towards Hougang Ave 8. when I reach the traffic

Junction filter lane I slow down and stop for waiting clearance

for oncoming vehicle. I stationary stopped while waiting

vehicle to be clear ~~about~~ about two minutes time and

suddenly vehicle B" GX 4962 M" collided my rear body

portion impact quite heavy.

Declaration

We declare the foregoing particulars are true in every respect.

维美铝窗锻铁工厂
WELLMAX METAL WORKS

144 TAGORE LANE
SINDO INDUSTRIAL ESTATE
SINGAPORE 797562
TEL: 6742 8842 FAX: 6742 2152
PROD. NO: 17912/07W

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo

As Of Aluminium, Wrought & General Renovation Work



Accident Photo



Accident Photo



Enquire PARF/COE Rebate for Registered Vehicle

D.O.A. 20/9/2017

Bal: 8 yrs 6 mths

\$77,000

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

2307W

Vehicle Details

Vehicle No.:

YP1847L

Vehicle to be Exported:

No

Intended De-registration Date:

19 Mar 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

CANTER 3.0 DIESEL AUTO

Primary Colour:

Silver

Manufacturing Year:

2015

Engine No.:

4P10B84404

Chassis No.:

FEB50542612

Maximum Power Output:

-

Open Market Value:

\$38,316.00

Original Registration Date:

20 Apr 2016

First Registration Date:

20 Apr 2016

Transfer Count:

0

Actual ARF Paid:

\$1,916.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

19 Apr 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$38,612.00

COE Rebate Amount:

\$31,211.00

Total Rebate Amount:

\$31,211.00

The information contained herein is correct as at 19 Mar 2018

OK

Your Perfect Companion for a Great Journey
Receive a Samsonite Orfeo Luggage
 Maybank Credit Cards and Creditable



Terms and Conditions apply.



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
 From \$/35 Onwards, Lowest
 3.68% P.A. BGV Cars Financing.
 GV Credit Pte Ltd - Star4d



Browse by Category





Sort by Date Posted

20 results/page

Advanced Search

10 vehicles

Mitsubishi Canter

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Canter		Any	Any	2016	Any	Any	Any	Available
	Mitsubishi	Fuso Canter FEB21	\$83,800	\$9,930 /yr	26-Aug-2016	2,998 cc	62,267 km	Truck	Available
Fuel Type: Diesel New Body Paintwork Done. Well Kept Condition For Interior. No Repairs Needed & Reasonable Mileage. Durable Plus Reliable 14FT Lorry. High Loan High Trade-In! Call Or Whatsapp For View Now! ABWIN Bus Pte Ltd Posted: 19-Mar-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$102,800	\$12,310 /yr	25-Jul-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel High Trade In For Your Old Vehicle. High Loan Is Possible. We Can Quote Your Insurance For You. Hurry While Stock Last. KSL Automotive Pte Ltd Posted: 17-Mar-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$89,800	\$11,130 /yr	12-Apr-2016	2,998 cc	11,900 km	Truck	Available
Fuel Type: Diesel Best Of The Best (Hweejan) Freezer Box -25 Degree! From Day 1 Seldom Drive Till Now With A Superb Low Mileage At 11,900km, Orig Paintwork Well Kept With A Smell Of Brand New Unit, Box Comes With Over... Victory Automotives Pte Ltd Posted: 16-Mar-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$102,988	\$11,780 /yr	15-Dec-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel Ready Stock! Warranty Given Under Agent! Low Interest Rate! 8 Days Handover. Door Step Appointment Service Available, Call Fast, And Check Location Before Drop By. ABWIN Bus Pte Ltd Posted: 16-Mar-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Mitsubishi Fuso Canter FEB21 \$84,000 \$9,820 /yr 07-Oct-2016 2,998 cc 43,000 km Truck Available

Fuel Type: Diesel
 Massive Savings From Brand New. 14 Feet Lorry With Box, Vehicle In Very Good Condition. Rarely Driven, Very Low Mileage. Cheapest In Town. Price
 Negotiable. Call Now To Arrange Viewing.

Posted: 15-Mar-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi



Mitsubishi Fuso Canter FEB21 \$74,800 \$9,340 /yr 21-Mar-2016 2,998 cc - Truck Available

Fuel Type: Diesel
 1 Owner Only! Low Mileage! Come With Full Canopy! Wooden Deck! Agent Maintenance! Under Agent Warranty! Almost New! High Loan High Trade-
 In! See To Believe! Call Us Now To Arrange Door Step View!

Net Link Partners Pte Ltd

Posted: 13-Mar-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi

Mitsubishi Fuso Canter FEB21 \$78,800 \$9,740 /yr 21-Apr-2016 2,998 cc 33,000 km Truck Available

Fuel Type: Diesel



Very Rare Auto 14 Foot Lorry With Retractable Canopy, Vehicle Like New Condition, In House Loan Available, Trade In Are Welcome, Door Step Viewing Can Be Arranged. Call Now Before It's Gone To Avoid D...

ABWIN (1994) Pte Ltd

Posted: 27-Feb-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi



Mitsubishi Fuso Canter FEB21 **\$72,000** **\$9,050 /yr** **01-Mar-2016** **2,998 cc** **41,040 km** **Truck** **Available**

Fuel Type: Diesel

Almost New Vehicle. Still Under Agent Warranty. Fully Serviced At Agent, Powerful Engine, No Need VPC, Class 3 License Can Drive, No Repairs Needed. Viewing Is Strictly By Appointment Only. Please Cal...

Posted: 18-Feb-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi



Mitsubishi Fuso Canter 3.0M **\$75,800** **\$9,300 /yr** **13-May-2016** **2,998 cc** **6,000 km** **Truck** **Available**

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 16-Feb-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi



Mitsubishi Fuso Canter FEB50 **\$72,800** **\$8,710 /yr** **27-Jul-2016** **2,998 cc** **8,100 km** **Truck** **Available**

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 06-Feb-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

20 results/page

For old advertisements, view Expired ads

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mitsubishi Canter, Mitsubishi Canter Singapore, used Mitsubishi Canter Singapore, used Mitsubishi Canter, used vehicles Singapore or even buy used Mitsubishi Canter Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

**Cheonghoh
Law Corporation**

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

12 MAR 2018 9:50am
Nso Lay Hing

In reply please quote our Reference Number
Our Ref: LCH.lg/W6ZC-70770.17


530706

17

9 March 2018

WITHOUT PREJUDICE

CERTIFICATE OF POSTING



BY HAND



MSIG Insurance (S) Pte Ltd-Motor Claims
16 Raffles Quay #24-01
Hong Leong Building
Singapore 048581

Ac - Science Marketing Pte Ltd
3 Upper Aljunied Link
#08-06 Joo Seng Warehouse
Singapore 367902

Han Win Thein
3 Upper Aljunied Link
#08-05 Joo Seng Warehouse
Singapore 367902

Attn: Motor Claims Dept.
(Vehicle No. GX 4962 M)

Dear Sirs

TRAFFIC ACCIDENT INVOLVING YOUR/YOUR INSURED'S VEHICLE GX 4962 M AND YP 1847 L ON 25 SEPTEMBER 2017 AT 9:30 AM ALONG/AT HOUGANG AVENUE 8

We act for the claimant **Wellmax Metal Works**, the owner of the above said motor vehicle no. **YP 1847 L**.

We are instructed to claim damages against you/your driver/your insured in connection with the above-captioned accident involving our client's vehicle registration number **YP 1847 L** and vehicle registration number **GX 4962 M** driven by you/your driver/your insured at the material time.

We are instructed that the accident was caused by you/your driver's/your insured's negligent driving and/or management of motor-vehicle **GX 4962 M**. As a result, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as stated in Part 1 of the Annexure.

A copy each of the supporting documents as stated in Part 2 of the Annexure is enclosed.

We have on 28 September 2017 notified your insurer (abovenamed addressee) of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurers appointed surveyor as your insurers rejected our proposed list of surveyors on 29 September 2017.

Please note that:

- (a) if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer;
- (b) you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days of your/your insurer receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer;
- (c) if you have a counterclaim against our client arising out of this accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

For the avoidance of doubt, unless otherwise indicated, this letter of claim is sent to the abovenamed addressees.

Yours faithfully

Lee Cheong Hoh
Cheonghoh Law Corporation

enc: supporting documents in paragraph 4 enclosed in covering letter to Insurers only
cc: client (via email /fax only) - YP 1847 L

EG,
1. Upload
2. MH 42
13/3/18

ANNEXURE

Part 1 - particulars of loss and expense

Cost of repairs	\$3,850.00
Loss of use @ 4 days	800.00
Survey Report	480.00
GIA Reports/LTA, RCB searches	39.00
Loss of Use for PRS (6days x \$200)	1,200.00
Incidentals	50.00
Costs Contribution	600.00
TOTAL	<u>\$7,019.00</u>

Part 2 - list of supporting documents enclosed in the letter of claim.

LTA search

GIA reports/Police reports & type-written transcripts

surveyor's report

the insurer has been notified of the accident and allowed to carry out a pre-repair inspection of claimant's vehicle

supporting documents for all other expenses claimed (if any)

correspondence with the potential defendant's insurer relating to pre-repair survey and/or post repair inspection of the claimant's vehicle

repairer's bill and evidence of payment (if any)

photocopies of photos of damages to client's vehicle

K A A S
kelvin automotive appraising services

6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/4883/1847/TP/09.17

Invoice No. : 4883

Date : 09 February 2018

To: Wellmax Metal Works
c/o Blk 6 No.399J Woodlands Road
Yew Tee Industrial Estate
Singapore 678008

INVOICE	
PARTICULARS	AMOUNT
Vehicle No. : YP 1847L Make/Model : Mitsubishi Canter 3.0 Diesel (A)	
<input checked="" type="checkbox"/> Inspection of Vehicle)
<input checked="" type="checkbox"/> Appraisal Report)
<input checked="" type="checkbox"/> 15 Colored Photographs) SGD 480.00
<input checked="" type="checkbox"/> Transport charges)
<input type="checkbox"/> Re-inspection fee)
<input type="checkbox"/> Disbursements)
<input type="checkbox"/> Others (Specify))
Total	SGD 480.00

Dollars: Four Hundred and Eighty Only

(Cheque should be crossed and make payable to "Kelvin Automotive Appraising Services")



Kelvin Automotive Appraising Services

Insured	: -
Policy No.	: -
Sum Insured	: -
Excess	: -
Our Reference	: KAAS/TA/4883/1847/TP/09.17
Date	: 09 February 2018

To: Wellmax Metal Works
c/o Blk 6 No.399J Woodlands Road
Yew Tee Industrial Estate
Singapore 678008

VEHICLE APPRAISAL REPORT

Name of Workshop	: Zhong Cheng Enterprise
Place of inspection	: Blk 6 No. 399J Woodlands Road, Yew Tee Industrial Estate, Singapore 678008
Date of Assignment	: 30 November 2017
Date of Accident	: 25 September 2017
Date of Inspection	: 30 November 2017

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: YP 1847L	Engine No.	: Hidden From View
Make/Model	: Mitsubishi Canter 3.0 Diesel (A)	Chassis Frame No.	: FEB50542612
Year of Manufacture/Reg	: 2016	Colour	: Silver
Class/Type	: Truck	Odometer Reading	: 76,304 KM

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)


General Condition	: Good	Undercarriage (Front)	: Serviceable
Paintwork	: Good	Undercarriage (Rear)	: Serviceable
Footbrakes	: Serviceable	Market Value	: -
Steering	: Serviceable	Scrap Value (PARF/OMV)	: -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front Left	HEADWAY 110 / 108R	8mm
Rear Left	HEADWAY 110 / 108R	8mm
Front Right	HEADWAY 110 / 108R	8mm
Rear Right	HEADWAY 110 / 108R	8mm


*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



: KAAS/TA/4883/1847/TP/09.17
: YP 1847L

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	Tailgate	Buckled	\$ 1,650.00	\$ 1,650.00
2	6 pcs	Tailgate hinges @S\$55.00	Buckled	\$ 330.00	\$ 330.00
3	2 pcs	Tailgate "L" hinge @S\$146.00	Buckled	\$ 292.00	\$ 292.00
4	1 pc	LH taillamp	Cracked	\$ 187.00	\$ 187.00
5	1 pc	Rear step panel	Buckled	\$ 480.00	\$ 480.00
6	1 pc	Rear floor panel	Buckled	\$ 4,620.00	Repair
		Less 25%		\$ 7,559.00	\$ 2,939.00 \$ 734.75
		SPECIAL NETT ITEMS:-		\$ 7,559.00	\$ 2,204.25
7	1 set	Advertisement sticker	Necessary	\$ 300.00	\$ 200/- 280.00
8	1 pc	Rear " 60 km/h " sticker	Necessary	\$ 30.00	\$ 25.00
9	1 pc	Rear " 7 pax " sticker	Necessary	\$ 30.00	\$ 25.00
				\$ 360.00	\$ 330.00
			Sub - Total	\$ 7,919.00	\$ 2,534.25



Our Reference : KAAS/TA/4883/1847/TP/09.17
 Vehicle Number : YP 1847L

6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 7,919.00	\$ 2,534.25
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,040.00	\$ 500/- 960.00
2		To check wiring and rewire		\$ 60.00	\$ 30/- 50.00
3		To anti-rust	1020/-	\$ 100.00	\$ 40/- 80.00
4		To putty and spray-paint of affected areas		\$ 960.00	\$ 500/- 880.00
				\$ 2,160.00	\$ 1,970.00
					2557.50
					1/52000/-
					4 days.
		Sub - Total		\$ 10,079.00	\$ 4,504.25

Our Reference
Vehicle Number

: KAAS/TA/4883/1847/TP/09 17
: YP 1847L

K A A S
Kelvin automotive appraising services


6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered

Squarely to the Rear

portion of the vehicle.



The general area of damages is at the

Rear portion

(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Zhong Cheng Enterprise** is \$ 10,079.00 .
We have adjusted the cost to \$ 4,504.25 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 3,850.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of 4 working days.

15 photographs were taken at the time of static inspection.

This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. 4883 for our services rendered and
we thank you for engaging our services.

Kelvin Automotive Appraising Services

KELVIN TEO



Licensed Automotive Appraiser


Nitec in Automotive Technology


Dip MS

MSAAA

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.







...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2017		02 Oct 2017 09:54 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	AV-SCIENCE MARKETING PTE LTD, Co. Reg. No.: A04611/1988D		
Main Claimant:	WELLMAX METAL WORKS, Co. Reg. No.: 52912307W		
Vehicle Reg. No.:	YP1847L	Date of Loss:	25/09/2017 09:00 - :59 [17 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 530706	Policy/Cover Note No.:	P28748317MKC (TP, Fire & Theft) Coverage: 10/06/2017 - 09/06/2018
Vehicle Reg. No. (Insured):	GX4962M	Policy No. (Claimant):	
		Excess:	
Repairer:	Zhong Cheng Enterprise () Blk 6 Woodlands Road, Yew Tee Industrial Estate 399J, 678008 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 11/04/2018]		
Driver/Custodian (Insured):	HAN WIN THEIN (/ Male), NRIC: G5803493U, Tel: +6597628913		
Adj Asg. Remarks:	Contact Person : Ms Sini Handphone No : 9338 2879		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

































- MSIG_SG (09/04/2018): Report Send Back Alerts - YP1847L (TP)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP1847L (530706)**
[GX4962M]
TP
WELLMAX METAL WORKS
Sep 25 2017 9:00AM
[AV-SCIENCE MARKETING PTE LTD]
Zhong Cheng Enterprise

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	02/10/17 13:07	Accident Statement <small>From: SC - Reg. No: GX4962M, Claimant: AV-SCIENCE MARKETING PTE LTD</small>	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	19/03/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	02/10/17 10:00	OI GIA REPORT - GX4962M	 Load PDF		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
2	02/10/17 10:00	TP GIA REPORT - YP1847L	1	Load PDF	
3	16/03/18 16:12	LOD - YP1847L	1	Load PDF	
4	16/03/18 16:12	KAAS TAX INVOICE - YP1847L	1	Load PDF	
5	16/03/18 16:12	KAAS APPRAISAL REPORT - YP1847L	1	Load PDF	
6	16/03/18 16:12	TP PHOTO -YP1847L	1	Load PDF	
7	16/03/18 16:12	REPAIR BILLING - YP1847L	1	Load PDF	
8	16/03/18 16:12	ENQUIRE VEHICLE -GX4962M	1	Load PDF	
9	16/03/18 16:12	GEN INS - YP1847L.	1	Load PDF	
10	16/03/18 17:47	instruction to LKK to upload final survey report	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/04/18 16:18	PHOTO	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>	^ v
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17018833/SRBE2-1

Date: 09/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: P28748317MKC

Claimant Vehicle No : YP1847L

Insured Vehicle No : GX4962M

Date of Loss: 25/09/2017

Nature of Claim: TP

Claim No: 530706

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP1847L

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M)

Engine No: 4P10B84404

Reg. Date: 20/04/2016 (Man. Year: 2015)

Chassis No: FEB50542612

Colour: Grey

Odometer: 76136 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/75 R16C

Rear Tyre Size: 205/75 R16C

Front Left Side: Headway 6 mm

Rear Left Side: Headway 6 mm

Front Right Side: Headway 6 mm

Rear Right Side: Headway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,919.00	1,487.50	6,431.50	81.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,070.00	1,090.00	50.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,079.00	2,557.50	7,521.50	74.63
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	10,079.00	2,000.00	8,079.00	80.16

INSPECTION

Date of Assignment: 02/10/2017

Date Inspected: 29/11/2017 Inspected At:

Zhong Cheng Enterprise
Blk 6 Woodlands Road, Yew Tee Industrial
Estate 399J
Singapore 678008

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$77,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$31,211.00=NETT VALUE: \$45,789.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Apr 2018)
Parts: N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for YP1847L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,650.00 F	*1,650.00 FL
2	6		*TAILGATE HINGES	Not Necessary	330.00 F	*- FL
3	2		*TAILGATE L HINGE	Not Necessary	292.00 F	*- FL
4	1		*LH TAILLAMP	Not Necessary	187.00 F	*- FL
5	1		*REAR STEP PANEL	Not Necessary	480.00 F	*- FL
6	1		*REAR FLOOR PANEL	Repair	4,620.00 F	*- FL
7	1		*SET ADVERTISEMENT STICKER	Necessary	300.00 FS	*200.00 FS
8	1		*REAR 60KM/H STICKER	Necessary	30.00 FS	*25.00 FS
9	1		*REAR 7 PAX STICKER	Necessary	30.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,919.00	1,900.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	412.50
Total Parts (S\$)	7,919.00	1,487.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,040.00	500.00
2	TO CHECK WIRING AND REWIRE	New	60.00	30.00
3	TO ANTI- RUST	New	100.00	40.00
4	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	960.00	500.00
Gross Labour Cost (S\$)			2,160.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >