

INS. CASE OWNER:

CC3 /AIG1800

LKK:

IDAC:

Surveyor:

KALUN

DOI:

ASSIGNMENT

6/4/18

Date / Time:

6/4/18

Registered in Merimen:

11/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFE 5778A

Name of Insured:

PAN UNY.

Insured Tel No.:

HP:

4227604

Excess Sec II :SS

D.O.A.:

5/4/18

Is driver the owner?

(YES/ NO)

Nature of Accident:

Claim No.:

96222445256

Policy No.:

700848440-01

Make / Model:

MERCEDES

Place of Accident:

BAT TIMAH / ONVEREN RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/ NO)

OI GIA REPORT: YES/ NO : TP GIA REPORT: YES/ NO

Insured Liability: %

Final ? Yes / No

SHE 3447P



INSRS:

WSP:

Tel:

Liability:

RMKS:

COBE W



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/4/18
TH

SHE 3447P-V

SFE 5778A-V

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> THIN 23/4 > 24/4/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

11/5/18

Confirm with:

Cecilia

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.: 15

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

3103.00

Loss of Rental (LOR):

S\$

442.13

(

4.5 days) x 98.25

Loss of Use (LOU):

S\$

225.00

(\$

50 x 4.5 days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

3777.62

Global Sum S\$:

3770.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3,770.00

Name 1:

Comfortdelgro Engineering Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
16/5/18

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee:

Base: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
Estimate Cost: _____
OD / TP / NS / TP RES / OD RES / EVA / INV / MV
To: Insp Vehicle No: _____
at: Work shop no: _____
if: _____
Insured: _____
Policy No: _____
Claims File: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Vch: _____

(Policy Condition)

Remark: The vch had commenced its repair at the time of inspection.

Balance Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 3 days Res: Yes or No

Lum Surv: 20 % 3 Vol: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Vch No: SHC3447P Yr Reg: 28 Feb 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/ / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe CC 199

Colour: Blue A/C: Ins Std / NI / NA

Sp. Reading: 333423 T/Radio: Ins Std / NI / NA

Eng/No: _____

C/N: KMHE741VMBAB05900

Gen. Cond: G / F / Poor / Burnt

Steering: G / Jammed / Leaked / Burnt or

Brake: G / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD / R/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / ONTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 5/4/8

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/4/18 Lat 45 \$2900 / 3 days

LIS - \$2900+ (Red: \$1489.88 / 34%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

Survey Fee:

Transportation:

\$ + PS, \$

TRIP



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18006497/K1ub3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 09-04-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKE 5778A	Veh. Inspected	SHC 3447P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/04/2018	Inspection Date	06/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eam: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NC305138795

COMFORT TRANSPORTATION PTE LTD	REGN NO	SHC3447P	MILEAGE
7010045	MAKE	HYUNDAI	FUEL
383 SIN MING DRIVE	MODEL	SONATA	E.....1/2.....F
Singapore SINGAPORE 575717	YR OF MANU	28.02.2011	DATE/TIME IN
65508755	CHASSIS CODE	KMHET41VMBA805900	05.04.2018 10:55
(R)			TARGET DATE
(P)			COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 05.04.2018
ATURE: 3P 05.04.2018

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

ICKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedge. Slip

Exit Pass

44

e No.:

SHC3447P

CHIANG @

Vehicle No.:

SHC3447P

of Service Advisor

Signature/Date _____

Name of Service Advisor

Date _____

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SH 3447P

DATE 5/4/2018 16:11

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door (LH) ✓			\$ 1,294.70	
	Rear Door Protector(LH) + repair			\$ 54.50	
	Front Door (LH) ✓			\$ 1,344.50	
	Front Door Protector (LH) X repair			\$ 74.90	
	Rear Fender (LH) X repair				
	SUB TOTAL			\$ 2,768.60	
	LESS 20%			\$ 553.72	
	DISCOUNTED TOTAL			\$ 2,214.88	
	Rear Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Rear Door Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Rear Door Tel No. Sticker (LH) ✓			\$ 10.00	Nett
	Front Door Coloured Comfort Logo (LH) ✓			\$ 75.00	Nett
	Front Door Advertisement Logo (LH) ✓			\$ 100.00	Nett
				\$ 385.00	
	Labour Charge				
	Panel Beating- Repair Fender			\$ 750.00 400	
	Spray Painting Charge			\$ 750.00 600	
	Tuff Kote			\$ 50.00 20	
	Transfer of Door		\$ 120.00	\$ 240.00 100	
	TOTAL LABOUR			\$ 1,790.00	
	ESTIMATE TOTAL			\$ 4,389.88	
	Kalam '10/10 N 6/4/18 1015 hrs. 3 Pys 4s After Repair photo				
	KK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
	Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Our Ref : T 0418 / SHC3447P /CL(st)
Your Ref:
Date : 16-Apr-18

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Buliding
78 Shenton Way
#07-16
Singapore 079120

Attn : Motor Claims Department WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC3447P YOUR INSURED SKE5778A
AND OTHER ON 05.04.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHC3447P** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SKE5778A** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 3,103.00
2	5 days Loss of Rental @ \$ 98.25 per day	\$ 491.25
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation	\$ -
Sub Total :		\$ 3,601.74

HIRER'S CLAIM

7	5 days Loss of Income @ \$ 80.00 per days	\$ 400.00
Total Claims :		\$ 4,001.74

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 8 pcs.
b) LTA search slip/s of : SKE5778A
c) GIA / Police report/s of : SHC3447P
d) Letter of authority from owner / hirer / operator
(X) Photograph/s of Accident Scene () Certificate of Insurance
() Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

CDGE Taxi Claims Dept
59 Loyang Drive 4th Floor
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506349V

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 750156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18006497/K1ub3

24 APRIL 2018

PAN LING

BLK 401 CHOA CHU KANG AVE
#05-205
SINGAPORE 680401

Dear Sir/Madam,

ACCIDENT INVOLVING SKE 5778A & SHC 3447P ON 05/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360

FAX: 6741 4108

Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****SONATA SHC3447P , SKE5778A
DUNEARN RD TWDS SERANGOON RD
(NEAR SIAN TUAN AVE)****ON 05-Apr-18 09:55**

I / We

TAN TONG SENG(Hirer) NRIC No.: **S0210728G**

and/or

(Relief) NRIC No.:

Taxi Number:

SHC3447P

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

05-Apr-2018

Name of Hirer

TAN TONG SENG

Hirer NRIC

S0210728G

Signature :



Address

**437 JURONG WEST AVENUE 1 #07-434
640437**

Contact No.

96619458

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **COMFORTDELGRO ENGINEERING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$ 3,110.00** (Global Sum) for vehicle no. **SHC 3447P** that was damaged pursuant to the accident which occurred on **05/04/2018** (date) along **DUNEARN RD TWDS SERANGOON RD (NEAR SIAN TUAN AVE)** (location) involving vehicle no/s **SKE 5778A**.

This is pursuant to the inspection conducted on **06/04/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **COMFORT TRANSPORTATION PTE LTD** ("the third party claimant") of vehicle no. **SHC 3447P** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SHC 3447P** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11th (day) of May (month) **20**18 (year)



Signed by appointed surveyor

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 579701

Signed by "the workshop" (with chop)

Please forward your cheque made payable to:-
COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

Our Ref: CT18040105

Date: 10 April 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	05/04/2018 @ 09:55 hrs
ALONG	DUNEARN RD TWDS SERANGOON RD(NEAR SIAN TUAN AVE)
INVOLVING	SKE5778A

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC3447P** (the "Taxi"). The Taxi was hired to **TAN TONG SENG IC NO S0210728G** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$98.25** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

DATE	NAME OF DRIVER	MILEAGE READING					MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER
								FROM	TO		
26-3-18	TTS	330	775				353	6:00pm	8:20pm		
27-3-18	TTS	331	094				319	6:00pm	8:30pm		
28-3-18	TTS	331	296				202	11:00am	6:30pm		
29-3-18	TTS	331	664				368	6:00am	8:30pm		
30-3-18	TTS	331	926				264	8:00am	6:45pm		
31-3-18	TTS	332	290				364	6:00am	8:50pm		
2-4-18	TTS	332	660				370	6:00am	8:20pm		
3-4-18	TTS	332	954				294	6:00am	9:10pm		
4-4-18	TTS	333	228				284	6:00pm			
05-04-18	7 Accident Report		SHC3447P					10:55			
09-04-18							307.5		11:20		

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKE5778A	05 Apr 2018 / 09:55:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Previous](#)[OK](#)

SHC3447P

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING
















Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Apr 2018 Edit Reg		06 Apr 2018 00:00 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	PAN LING , ID: S2666463B								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC3447P	Date of Loss:	05/04/2018 09:00 - :59 [85 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9623299352SG	Policy/Cover Note No.:	2100458540 (Comprehensive) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	SKE5778A	Policy No. (Claimant):	S-18088936MFSH						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 18/04/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC3447P (9623299352SG)
[SKE5778A]
TP
COMFORT TRANSPORTATION PTE LTD
Apr 5 2018 9:00AM
[PAN LING]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser			
Video											1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)							Thumbnail		Print			
1	10/04/18 15:41	Video - Accident <small>From: OO - Reg. No: SKE5778A, Claimant: PAN LING</small>								Load MP4				
Letters/Correspondences													1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown								Edit				
Assessment Reports													1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)							Thumbnail		Print			
1	10/04/18 14:34	Accident Statement <small>From: OO - Reg. No: SKE5778A, Claimant: PAN LING</small>								Load HTM				
Photos/Images													3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
2	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
3	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
4	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
5	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
6	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
7	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
8	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
9	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
10	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
11	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
12	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
13	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
14	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
15	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
16	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
17	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
18	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
19	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
20	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
21	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
22	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
23	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
24	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
25	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			
26	09/04/18 17:43	General View								Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
27	10/04/18 08:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	10/04/18 08:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	10/04/18 08:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	10/04/18 08:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	10/04/18 08:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	10/04/18 08:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	10/04/18 08:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 17:28	TP ESTIMATE- MARKED	 Load PDF	
2	09/04/18 17:28	TP GIA REPORT	 Load PDF	
3	23/05/18 09:15	WORKSHOP INVOICE	 Load PDF	
4	23/05/18 09:15	AUTHORISATION TO ACT FORM	 Load PDF	
5	23/05/18 09:15	Release Voucher	 Load PDF	
6	23/05/18 09:15	RENTAL RECEIPT	 Load PDF	
7	23/05/18 09:15	LTA SEARCH	 Load PDF	
8	23/05/18 09:15	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKE5778A (Insd veh)	Model:	HYUNDAI SONATA 2.0 (A)
	SHC3447P (TP veh)		
Date of Accident:	05/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No
Repair Estimate	:	\$	4,697.17
Final Repair Cost	:	\$	3,770.00
Loss of Use	:	\$	4.50 days at \$50.00 per day
Rental (if any)	:	\$	4.50 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,770.00

Is Third Party Workshop GIA Registered? ☒ [X] YES ☐ [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 3,770.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

23 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18006497/K1UB3Q2

Date: 23/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100458540

Claimant Vehicle No: SHC3447P Insured Vehicle No: SKE5778A

Date of Loss: 05/04/2018 Nature of Claim: TP Claim No: 9623299352SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC3447P**
 Make & Model: HYUNDAI SONATA, 2.0 (A) Engine No: D4EAB936527
 Reg. Date: 28/02/2011 (Man. Year: 2011) Chassis No: KMHET41VMBA805900
 Colour: Blue Odometer: 333423 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm
 Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,599.88	2,496.36	103.52	3.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,120.00	670.00	37.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,389.88	3,616.36	773.52	17.62
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	4,389.88	2,900.00	1,489.88	33.94
+ GST 7.00/7.00% (S\$)	307.29	203.00	104.29	33.94
Nett Amount (S\$)	4,697.17	3,103.00	1,594.17	33.94
+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
+ Car Rental (4.5 x S\$98.25/day) (S\$)		442.13		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,777.62		
Global Sum Settlement (S\$)		3,770.00		

INSPECTION

Date of Assignment: 06/04/2018

Date Inspected: 06/04/2018 Inspected At: ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (LH)	Dented	1,294.70 FL	*1,294.70 FL
2	1		*REAR DOOR PROTECTOR (LH)	Repair	54.50 FL	*- FL
3	1		*FRONT DOOR (LH)	Dented	1,344.50 FL	*1,344.50 FL
4	1		*FRONT DOOR PROTECTOR (LH)	Repair	74.90 FL	*- FL
5	1		*REAR FENDER (LH)(NPA)	Repair	0.00 FL	*- FL
6	1		*REAR FENDER ADVERTISEMENT LOGO(LH)	Necessary	100.00 FS	*100.00 FS
7	1		*REAR DOOR ADVERTISEMENT LOGO(LH)	Necessary	100.00 FS	*100.00 FS
8	1		*REAR DOOR TEL NO.STICKER (LH)	Necessary	10.00 FS	*10.00 FS
9	1		*FRONT DOOR COLOURED COMFORT LOGO(LH)	Necessary	75.00 FS	*75.00 FS
10	1		*FRONT DOOR ADVERTISEMENT LOGO(LH)	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,153.60	3,024.20
- List Item Discount on L Items 20.00/20.00% (S\$)	553.72	527.84
Total Parts (S\$)	2,599.88	2,496.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING -REPAIR FENDER	New	750.00	400.00
2	SPRAY PAINTING CHARGE	New	750.00	600.00
3	TUFF KOTE	New	50.00	20.00
4	TRANSFER OF DOOR	New	240.00	100.00
Gross Labour Cost (S\$)			1,790.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >