

Surveyor: Menmen
 From (Person): Irene Tay of CTI Date/Time: 9/4/18 @ 4:03pm

Estimated Cost: _____ Bill to: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SLW 4964D Insured: SGQ 5188L
 at Workshop w/ Hock Wah Motor Tel: 6785 3933
 of Bik 3011, Bedok Ind. Prk E #01-2008
 Policy No: DMHCSN1730401700 Claim No: SMM18D01806C02
 Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05/04/2018
 (Client's Record) _____
 CA / REV / REP. / REV 24 HRS ^{'imp'} Insp: Bik 900 B tempines # 01-204
 Date/Time: 4:03pm @ 9/4/18 Person Contacted: Mr. Han Vehicle-IN (OUT) (OUT)
12/04/2018 @ 10am-12pm

Date/Time	Action/Instruction (✓) Estimate
	<u>SLW 4964D - x</u>
	<u>SGQ 5188L - x</u>

Est. Repairs: 5 days Res: Yes or No _____
 Lum Sum: 20 % 3 Val: Yes or No _____
 CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT _____
 D.O.A. 5/4/18 D.O.T. 14/7/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27A 14641 Rep 8500
26/4/18 confirmed 1/5 @ 3200 with han.

RECEIVED 27 APR 2018

Date/Time: File Pass to? Preli. Report Final Report
 Days Of Repair: 5
 Resurvey No. of Trip: 2
 Survey Fee: _____
 Transportation: _____
 Add Fee: Site Insp \$ _____
 Interview \$ _____
 Tech Insp \$ _____
 Weekend \$ _____
 Report Format: TP
 Lump Sum / I.B.H: (\$) 3200

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO GIM REPORT


DECLARATION

I/We declare the foregoing particulars are true in every respect.


6/14/2018
12:05

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4500A
Vehicle Details	
Vehicle No.:	SLW4964D
Vehicle to be Exported:	No
Intended De-registration Date:	12 Apr 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	G4FCAU824277
Chassis No.:	KMHDU41BMAU988303
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$10,722.00
Original Registration Date:	25 Oct 2010
First Registration Date:	25 Oct 2010
Transfer Count:	1
Actual ARF Paid:	\$10,722.00 <i>5761</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Oct 2020
PARF Rebate Amount:	\$6,433.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$32,415.00
COE Rebate Amount:	\$8,208.00
Total Rebate Amount:	\$14,641.00

The information contained herein is correct as at 12 Apr 2018

OK

**Hyundai Avante 1.6A****\$27,800**

\$8,240 /yr

31-Dec-2010

1,591 cc

11

Engine In Tip Top Conditions, Test Drive To Believe, Accident Free, Low Down Payment, Hurry, Call Now To Arrange For Benefit Auto Enterprise Pte Ltd

Posted: 05-Apr-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

**Hyundai Avante 1.6A Sunroof****\$25,000**

\$8,760 /yr

15-Jun-2010

1,591 cc

85

Well Maintained. Very Low Mileage! 100% Accident Free. STA/Vicom Inspection Welcome. Included A Reverse Camera F Plate Number Of 3 Same Digits.

Posted: 04-Apr-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

**Hyundai Avante 1.6A S****\$22,800**

\$8,480 /yr

12-May-2010

1,591 cc

Down Payment \$2.7k Monthly \$839. Well Maintained By Fussy Owner, Accident Free And Serviced Regularly, No Repairs Quality Cars You Can Trust Only From Choon Bee.

Posted: 29-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

**Hyundai Avante 1.6A RS Sunroof****\$25,800**

\$9,570 /yr

13-May-2010

1,591 cc

10

Looks, Drive And Feels Like New. Perfectly Well Maintained, No Repairs Needed, \$1500 Guaranteed Body Purchase After Risk, Drive Till Scrap, 6 Months Warranty Provided, 24/...

Posted: 28-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

**Hyundai Avante 1.6A S****\$19,500**

\$7,970 /yr

02-Jan-2010

1,591 cc

12

Very Low Mileage 128,557km. Servicing Just Done. Vehicle Serviced And Maintained Regularly. Very Well Kept. Please C

Posted: 24-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

**Hyundai Avante 1.6A S****\$26,800**

\$9,240 /yr

23-Jul-2010

1,591 cc

92

Looks, Drive And Feels Like New. Perfectly Well Maintained, No Repairs Needed, \$1500 Guaranteed Body Purchase After Risk, Drive Till Scrap, 6 Months Warranty Provided, 24/...

Posted: 23-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

**That Special Number In Your Heart**

Want to remember the good times? Need to earn some brownie points? Got a lucky number or a special date you want to Find out if they are on sale and it could just be yours!

Find out more!

**Hyundai Avante 1.6A****\$19,800**

\$7,190 /yr

27-Mar-2010

1,591 cc

14

10% Down Payment. \$820 /Month. Good Condition. Flexible Loan Package. Instant Approval. Ex Bankrupt Welcome. Hig

Posted: 19-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

**Hyundai Avante 1.6A S Sunroof****\$30,000**

\$9,130 /yr

13-Dec-2010

1,591 cc

16

Well Maintained By Previous Owners! Smooth And Quiet Engine, Clean And Neat Interior, 2nd Owner, Car In Good Work Very Low Basic Maintenance, Great Family Car. View To Bel...

Carro

Posted: 13-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
 SINGAPORE 528840
 TEL :67853933 FAX:67883933
 R.O.C No. 200104141D GST Reg.No. 20-0104141-D

TO : S7324500A
 POH CHEE YONG
 BLK 523A TAMPINES CENTRAL 7
 07-75
 SINGAPORE 521523
 TEL : FAX :
 PH : 92236986
 ATTN :

ESTIMATE BILL

Number : EBK0000239
Date : 09/04/2018
Case No : ADK0000313
Vehicle No : SLW4964D
Chassis:
Year of Mfr
Policy No
Model : HYUNDAI AVANTE

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
	<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
SINGAPORE DOLLARS : SIX THOUSAND ONE HUNDRED FIVE AND CENTS EIGHTY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		5,706.40
			GST 7.00%		399.45
			TOTAL		6,105.85

Date of accident : 05/04/2018 10:50 AM. Place : PIE TOWARDS TUAS BEFORE KALLANG AVE EXIT

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

 CUSTOMER SIGNATURE

 AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Apr 2018		09 Apr 2018 16:03 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	1 PAGESUS , Co. Reg. No.: 53360970D								
Main Claimant:	POH CHEE YONG , ID: S7324500A								
Vehicle Reg. No.:	SLW4964D	Date of Loss:	05/04/2018 10:00 - :59 [89 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01806C02		Policy/Cover Note No.:	DMHCSN1730401700 (Comprehensive)					
Vehicle Reg. No. (Insured):	SGQ5188L	Policy No. (Claimant):	5098385431						
		Excess:	S\$0.00						
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/04/2018]								
Driver/Custodian (Insured):	ANDY XU JIAHAO (27 / Male), NRIC: S9043618Z, Tel: +6583636107								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW4964D (SNM18D01806C02)

[SGQ5188L]

TP

POH CHEE YONG

Apr 5 2018 10:00AM

[1 PAGESUS]

Hock Wah Motor Workshop Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/04/18 12:23	Accident Statement	Load HTML	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	06/04/18 12:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
2	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
3	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
4	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
5	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
6	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
7	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
8	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
9	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
10	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
11	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
13	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
14	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
15	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
16	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
17	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
18	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
19	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
20	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>
21	12/04/18 17:07	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
22	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/04/18 17:07	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/04/18 15:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
72	26/04/18 15:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	26/04/18 15:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/04/18 16:02	PRS	Load PDF	
2	09/04/18 16:03	OI GIA REPORT	Load PDF	
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/04/18 12:09	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 12:09	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/04/18 12:23	Accident Statement	Load HTM	
2	12/04/18 17:41	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
3	12/04/18 17:42	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	06/04/18 12:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/04/18 12:09	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 12:09	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	12/04/18 17:41	police report	Load JPG	<input checked="" type="checkbox"/>
4	12/04/18 17:41	police report	Load JPG	<input checked="" type="checkbox"/>
5	12/04/18 17:41	police report	Load JPG	<input checked="" type="checkbox"/>
6	12/04/18 17:41	police report	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006505/RD3Q2

Date: 04/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMHCSN1730401700	
Claimant Vehicle No: SLW4964D	Insured Vehicle No: SGQ5188L	
Date of Loss: 05/04/2018	Nature of Claim: TP	Claim No: SNM18D01806C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW4964D	Engine No: G4FCAU824277
Make & Model: HYUNDAI AVANTE, 1.6 (A)	Chassis No: KMHDU41BMAU988303
Reg. Date: 25/10/2010 (Man. Year: 2010)	Odometer: 88066 km
Colour: Black	
Engine Capacity: 1591 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185/65 R15	Rear Tyre Size: 185/65 R15
Front Left Side: Yokohama 6 mm	Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm	Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,506.40	2,317.60	1,188.80	33.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,710.00	490.00	22.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,706.40	4,027.60	1,678.80	29.42
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	5,706.40	3,200.00	2,506.40	43.92
+ GST 7.00/7.00% (S\$)	399.45	224.00	175.45	43.92
Nett Amount (S\$)	6,105.85	3,424.00	2,681.85	43.92

INSPECTION

Date of Assignment:	09/04/2018	
Date Inspected:	12/04/2018 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01- 2008/2010/2012 Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2018)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLW4964D)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Distorted	447.00 FL	*447.00 FL
2	2		*RR BUMPER SIDE RETAINER LH RH	Bent	68.00 FL	*68.00 FL
3	2		*RR BUMPER BRACKET LH RH	Not Necessary	60.00 FL	*- FL
4	10		*RR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
5	1		*RR BUMPER REINFORCEMENT	Cracked	250.00 FL	*250.00 FL
6	2		*RR BUMPER REINFORCEMENT BRACKET LH RH	Bent	170.00 FL	*170.00 FL
7	1		*RR BUMPER INNER SPONGE	Torn	130.00 FL	*130.00 FL
8	1		*RR BOOTLID	Bent / Buckled	830.00 FL	*830.00 FL
9	1		*RR BOOTLID LOGO S	Necessary	19.00 FL	*19.00 FL
10	1		*RR BOOTLID LOGO AVANTE	Necessary	28.00 FL	*28.00 FL
11	1		*RR BOOTLID INNER RUBBER	Twisted	150.00 FL	*150.00 FL
12	1		*RR BOOTLID LOCK TOP	Twisted	120.00 FL	*120.00 FL
13	1		*RR BOOTLID LOCK BOTTOM	Not Necessary	20.00 FL	*- FL
14	1		*RR END PANEL	Badly Dented	385.00 FL	*385.00 FL
15	1		*RR END PANEL TOP GARNISH	Not Necessary	48.00 FL	*- FL
16	8		*RR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
17	2		*RR BOOTLID HINGE LH RH	Repair	270.00 FL	*- FL
18	1		*RR BOOTLID NO PLATE LAMP LH	Not Necessary	68.00 FL	*- FL
19	1		*RR SPARE TYRE TOP TRIMBOARD	Not Necessary	230.00 FL	*- FL
20	1		*SET RR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
21	1		*RR BOOTLID PARKING CAMERA	Not Necessary	550.00 FS	*- FS
22	1		*RR SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS
23	2		*RR FENDER LH RH (NPA)	Repair	0.00 FS	*- FS
Sub Total (S\$)					4,183.00	2,847.00
- List Item Discount on L Items 20.00/20.00% (S\$)					676.60	529.40
Total Parts (S\$)					3,506.40	2,317.60

F=Franchise part. S=SpcNett. L=ListItemDisc

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	800.00
2	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	New	1,000.00	800.00
3	LABOUR TO INSTALL REVERSE SENSOR	New	120.00	50.00
4	ANTI RUST COATING	New	80.00	60.00
Gross Labour Cost (S\$)			2,200.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >