

ASS. REC. BY:

REF: CS/MSG18006509/K19d3/02

Special Instruction:

Surveyor: Kalvin ASSIGNMENT (Office)

From (Person): Meimen Monica chung of MSIG Date/Time: 9/11/08 @ 3:28pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC2193C Insured: FBB 3078 Y

at Workshop m/s: Comfort Delgro Tel: 62148300

of 59 Leyong Drive

Policy No: MSD/VMT/17-983506-WTT Claim No: MSC/V/18-000519

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05/04/2008
(Client's Record) 10/04/2008

CA / REV / REP. / REV 24 HRS (w/p) H.O.D. Endorsement: _____

Date/Time: 3:57pm @ 9/11/08 Person Contacted: Mr. Jim Vehicle: IN / OUT

Date/Time	Action/Instruction	Estimate
	SHC2193C - CCA / III 1800372 / M1ka3	D.O.A. 18/2/18
	FBB3078Y - X	
11/4/18 @ 4:28pm	revised to Monica chung via Meimen,	
		16/8

10/04/18

Ka/nh

REF: MS/G

ASSIGNMENT

From: Date: 10/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 2193C

at Workshop m/s Comfort Delgro
of SQ Loyang Drive

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (1/1)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHC 2193C Yr Regn: 3 Oct 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/ / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blk A/C: Insured / Std / NI / NA

Sp. Reading: 90213 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTOKB3F4603565138

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 5/4/18 D.O.I. 10/4/18

Survey held at CPHC (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/4/18 Conducted R/R at 6904.79 / 3 Rp.
(Cost @ 1176.03, 15%)

MKH
PIP

RECEIVED 1-9 APR 2018

Date/Time File Pass to?

: Preli. Report

11/19/4 typh

: Final Report

Date/Time File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Week-end (\$)

150

10

10

TOTAL

150
10
10
160

Report Format: MER-7p

Lump Sum / I.B.I. IS - 6904.79

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Ins Auth'ed	Status
Main	06 Apr 2018		09 Apr 2018 15:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHER KOK TECK , ID: S1537446B, Tel: +6596167396								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC2193C	Date of Loss:	05/04/2018 20:00 - :59 [6 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-983506-WTT (Third Party Only) Coverage: 08/06/2017 - 07/06/2018						
Vehicle Reg. No. (Insured):	FBB3078Y	Policy No. (Claimant):							
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/04/2018]								
Driver/Custodian (Insured):	CHER KOK TECK (55 / Male), NRIC: S1537446B, Tel: +6596167396								
Adj Asg. Remarks:	Please contact MR LIM TIEN SIONG @ 6214 8398 or 9635 8546 to arrange for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006509/K1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 09-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBB 3078Y	Veh. Inspected	SHC 2193C
Policy No.	MSD/VMT/17-983506-WTT	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/04/2018	Inspection Date	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 11 Apr 2018

Preliminary Advice

Insured Vehicle No	: FBB3078Y	Accident Date	: 05/04/2018
TP Vehicle No	: SHC2193C	Assignment Date	: 09/04/2018
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 3.00
Date of Inspection	: 10/04/2018		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	7,349.64
Revised Amount	:SS	6,271.89
Check Items (Estimated)	:SS	57.75
Total	:SS	6,329.64
Lump Sum Repair	:SS	

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2018 09:50
Date Of Accident	05/04/2018 20:10
Exact Location Of Accident	CROSS ST X JUNCTION OF ROBINSON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2193C
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	FONG TUCK HOY
NRIC No	S1536873Z
Date Of Birth	06/07/1962
Occupation	OUTDOOR
Date Of Driving Pass	01/03/1980
Driving Experience	38 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 247 KIM KEAT LINK 05-31
Postcode	310247
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TOA PAYOH N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO POLICE REPORT : T/20180405/2193

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBB3078Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	UNKNOWN
------	---------

Approximate Age

Injuries Sustain

NOT SURE

Injured person in which vehicle?

FBB3078Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

[Handwritten Signature]

6/4/18
Jackson Hong
CSO

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GWRM4C SketchPlanForm_V3




1

Sketch Plan Pg. 2

SKETCH PLAN

Robinson Rd



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer: Police Report attach T/20180405/2193

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

6/4/18
Jackson Heng Jackson
CSO

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180405/2193

1 of 3

Report No. T/20180405/2193

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/04/2018 22:58	Vide Report No.: A/20180405/0138	Station Diary No.: 211
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: FONG TUCK HOY		Address: APT BLK 247 KIM KEAT LINK #05-31 SINGAPORE 310247	
ID Type / ID No.: NRIC NO / S1536873Z		Contact No.: Home/Office: Mobile: 97536252	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 55	Date of Birth: 06/07/1962	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 2B,3,4	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 05/04/2018 20:10	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 CROSS STREET ROBINSON ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB3078Y	Motorcycle				Slightly Damaged	0
SHC2193C	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180405/2193

2 of 3

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20180405/2193

CONTINUATION OF REPORT

Driver			
Name	FONG TUCK HOY	ID No.	S1536873Z
Related Vehicle	NIL	Contact No.	97536252
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05/04/2018 at about 2010hrs, I was driving my taxi bearing registration number SHC2193C along Cross Street. As I was turning right at the junction of Cross Street and Robinson Road, I suddenly heard a loud thud and felt an impact on my right side. I then stopped my vehicle and alighted, where I then discovered motorcycle FBB3078Y had collided against the right front side of my vehicle. The motorcyclist was already lying on the floor. Police and ambulance arrived a few minutes later and the motorcyclist was conveyed to the hospital, condition conscious. I wish to state that while making the right turn, I did not notice the motorcycle coming from anywhere.

My taxi suffered dents and the right side mirror is damaged. The rim of the right front tyre is also damaged. I did not manage to take down the particulars of the motorcyclist. No government property involved. There is an in-car camera in my vehicle and I am lodging this report as requested by TP.



**SINGAPORE
POLICE FORCE**



T/20180405/2193

3 of 3

Report No. T/20180405/2193

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 SITI NADIA BINTE ROSLI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 05/04/2018 22:58
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216	Classification Of Case: SN 168
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE

REPAIR ESTIMATE

VEHICLE NO : SHC 2193C

MAKE :

MODEL : TOYOTA PRIUS

MSIG-CP(P)

6/4/2018

(Fri)

R, 9/14 @ 1540 hrs. LKK → Kalvin → Naz

TS
1530

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRONT BUMPER COVER - <i>dent</i>			\$ 490.50
FRONT BUMPER CLIPS - <i>all</i>			\$ 22.00
BRACKET, FRONT BUMPER SIDE, RH <i>X 2</i>			\$ 77.00
FENDER SUB-ASSY, FRONT RH <i>2 - dent</i>			\$ 933.10
FRONT FENDER SHIELD - <i>two</i>			\$ 198.50
FRONT FENDER SHIELD CLIP - <i>all</i>			\$ 14.90
FRONT FENDER HYBRID EMBLEM, RH - <i>all</i>			\$ 86.50
PANEL SUB-ASSY, FRONT DOOR, RH - <i>dent</i>			\$ 1,227.00
MIRROR ASSY, OUTER REAR VIEW, RH - <i>all</i>			\$ 1,374.00
FRONT PILLAR UPPER COVER, RH <i>X 2</i>			\$ 96.00
FRONT WHEEL RIM, RH - <i>dent</i>			\$ 1,570.55
Wheel Cap Frt RH - <i>2315</i>		\$ 175.80	
Panel Paint Finish (RH) - <i>int</i>		\$ 570.10	
Radiator grille Emblem - <i>all</i>			\$ 87.10
Wing Mirror Outer Cover RH - <i>all</i>		\$ 141.90	
FRONT DOOR COMFORT LOGO - <i>all</i>			\$ 75.00
REAR DOOR COMFORT & APPS STICKER - <i>all</i>			\$ 80.00
LABOUR CHARGE			
Panel Beating-Repair Rear RH Door			\$ 750.00
Spray Painting Charge			\$ 1,400.00
Wiring Charge			\$ 50.00
Tuff Kote			\$ 100.00
Transfer of Door			\$ 120.00
FRT Wheel Alignment			\$ 120.00
TOTAL LABOUR			\$ 2,540.00
ESTIMATE TOTAL			\$ 7,349.64
			7993.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL LABOUR Acknowledged by Repairer
Signature: _____
Date: _____

Kalvin (LKK)
10/4/18 1235 L.
3 Days
P/P Before Paint p/L

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305139164
 REGN NO : SHC2193C
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 03.10.2017
 DATE/TIME IN : 06.04.2018 08:50
 ACCIDENT DATE : 05.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2292-G	FRT BUMPER	1	490.50	25.00	367.87
0002	04-01-0302-2267-G	FRT BUMPER CLIPS	10	22.00	25.00	16.50
0003	04-01-0302-0573-G	FRT FENDER RH	1	933.10	25.00	699.82
0004	04-01-0302-2934-G	FRT FENDER SHIELD RH	1	198.50	25.00	148.87
0005	04-01-0302-2297-G	FRT FENDER (HYBRID) RH	1	86.50	25.00	64.87
0006	04-01-0302-0592-G	FRT DOOR RH	1	1,227.00	25.00	920.25
0007	04-01-0302-0594-G	WING MIRROR RH	1	1,374.00	25.00	1,030.50
0008	04-01-0302-0898-G	Wing Mirror Outer Cover RH *1	1	141.90	25.00	106.42
0009	04-01-0302-3911-G	FRT UPPER PILLAR COVER RH	1	96.00	25.00	72.00
0010	03-01-0302-2020-G	FRT WHEEL RIM RH	1	1,570.55	25.00	1,177.91
0011	03-01-0302-2057-G	FRT WHEEL CAP RH**	1	175.80	25.00	131.85
0012	28-01-0103-0003-A	Frt Door COMFORTDELGRO RH	1	75.00		75.00
0013	28-01-0103-2013-A	Rear Door APPS Sticker RH	1	80.00		80.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305139164
 REGN NO : SHC2193C
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(C
 DATE OF REGN : 03.10.2017
 DATE/TIME IN : 06.04.2018 08:50
 ACCIDENT DATE : 05.04.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 04-01-0302-0810-G Rocker Panel Garnish RH**	1		570.10	25.00	427.57
0015 04-01-0302-0988-G RADIATOR GRILLE EMBLEM**	1		87.10	25.00	65.32
SUB-TOTAL :					5,384.79

JOB NATURE

0000 L	PANEL BEATING		600.00		
0001 23-502	SPRAYPAINT ON AFFECTED AREA		800.00		
0002 17-01	CHECK ALL LIGHTING		20.00		
0003 20-00	TUFF COAT ON AFFECTED PARTS.		50.00		
0004 L	TRANSFER OF DOOR		50.00		
SUB-TOTAL :					1,520.00

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305139164
REGN NO : SHC2193C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 03.10.2017
DATE/TIME IN : 06.04.2018 08:50
ACCIDENT DATE : 05.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 6,904.**79**

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive, Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305139164
Date : 12/04/18

FINALIZATION FORM

To : LKK Fax : _____
Attn : KALVIN ANG
Vehicle Reg No. : SHC2193C Date of Accident : 05-Apr-18


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG --- FBB3078Y
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$5,384.79</u>
(b) Labour Charges	<u>\$1,520.00</u>
Total for Part-By-Part Repair Cost	<u>\$6,904.79</u>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	_____
Final Lumpsum Repair cost	_____

3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 12/4/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006509/K1QD3N2
Date: 20/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-983506-WTT	
Claimant Vehicle No :	SHC2193C	Insured Vehicle No :	FBB3078Y	
Date of Loss:	05/04/2018	Nature of Claim:	TP	Claim No: MSC/V/18-000519

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2193C	Engine No:	2ZRS066597
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU603566138
Reg. Date:	03/10/2017 (Man. Year: 2017)	Odometer:	90213 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,453.71	5,384.79	68.92	1.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,520.00	1,020.00	40.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,993.71	6,904.79	1,088.92	13.62
+ GST 7.00/7.00% (S\$)	559.56	483.34	76.22	13.62
Nett Amount (S\$)	8,553.27	7,388.13	1,165.14	13.62

INSPECTION

Date of Assignment:	09/04/2018	
Date Inspected:	10/04/2018	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2018)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC2193C)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	490.50 FL	*490.50 FL
2	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*BRACKET,FRONT BUMPER SIDE,RH	Serviceable	77.00 FL	*- FL
4	1		*FENDER SUB-ASSY,FRONT RH	Dented	933.10 FL	*933.10 FL
5	1		*FRONT FENDER SHIELD	Torn	198.50 FL	*198.50 FL
6	1		*FRONT FENDER SHIELD CLIP	Not Necessary	14.90 FL	*- FL
7	1		*FRONT FENDER HYBRID EMBLEM,RH	Necessary	86.50 FL	*86.50 FL
8	1		*PANEL SUB-ASSY,FRONT DOOR,RH	Dented	1,227.00 FL	*1,227.00 FL
9	1		*MIRROR ASSY,OUTER REAR VIEW,RH	Cracked	1,374.00 FL	*1,374.00 FL
10	1		*FRONT PILLAR UPPER COVER,RH	Cut	96.00 FL	*96.00 FL
11	1		*FRONT WHEEL RIM,RH	Bent	1,570.55 FL	*1,570.55 FL
12	1		*WHEEL CAP FRT RH	Missing	175.80 FL	*175.80 FL
13	1		*ROCKER PANEL GARNISH (RH)	Cracked	570.10 FL	*570.10 FL
14	1		*RADIATOR GRILLE EMBLEM	Necessary	87.10 FL	*87.10 FL
15	1		*WING MIRROR OUTER COVER RH	Cut	141.90 FL	*141.90 FL
16	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
17	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,219.95	7,128.05
- List Item Discount on L Items 25.00/25.00% (S\$)	1,766.24	1,743.26
Total Parts (S\$)	5,453.71	5,384.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING-REPAIR REAR RH DOOR	New	750.00	600.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	100.00	50.00
5	TRANSFER OF DOOR	New	120.00	50.00
6	FRT WHEEL ALIGNMENT	New	120.00	-
Gross Labour Cost (S\$)			2,540.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >