

ASS. FLOOR

REF.

CS3/11918006511/G24d302

Date/Time

Surveyor

Menmen

GQ

ASSIGNMENT (Office)

From (Person)

chin lee ying

at

AIG

Date/Time

9/1/18 @ 3.08pm

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKH 3127B

Insured

SGS 8825B

at Workshop n/a

Hiap Tek Automobile

Tel

9660 1347

of

160 Sin Ming Drive # 05-17

Policy No.

2100501589-01

Claim No.

9452287901SG

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A.

05/04/2018

CA / REV / REP. / REV 24 HRS

10/04/2018

Date/Time

3.13pm @ 9/1/18

Person Contacted

Mr. Ong

H.O.D. Endorsement

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKH 3127B - X


SGS 8825B - CF / AIG CEO: C119 / SIO

D.O.A. 16/1/2028

11/0/18

Disassembled

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGS8825B & SKH3127B ON 05 APRIL 2018

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc:
Sent: 9/4/2018 3:08:53 PM
Attachments:  9235.pdf

Re-send

From: Chin, Lee-Ying
Sent: Monday, April 09, 2018 12:18 PM
To: 'assignments'; Admin A
Cc: Fong, Andy-SY
Subject: AIGENCRYPT - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGS8825B & SKH3127B ON 05 APRIL 2018
Importance: High

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Crystal Tan [<mailto:crystal@legaloptions.biz>]
Sent: Friday, April 06, 2018 10:37 AM
To: Supramaniam, Darshene
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGS8825B & SKH3127B ON 05 APRIL 2018

Dear all,

Our client rejected your list of surveyor.

We provide you herewith our client's list of surveyor: -

	SURVEYOR:	CONTACT PERSON:	CONTACT:
1.	PAR AUTOMOTIVE CONSULTANCY	B J LOI	94882266
2.	UNITED APPRAISAL AND MANAGEMENT PTE LTD	MARC	91461186
3.	OH APPRAISAL SERVICES	OH HAN CHEONG	97982959
4.	SK AUTO CONSULTANTS	KUMA (S. KU,AMAN)	90040225
5.	LEE AUTOMOBILE APPRAISERS SERVICES	LEE K W	81882833
6.	CM AUTOMOTIVE CONSULTANCY	NG CHENG MENG	91459178
7.	ISP MANAGEMENT PTE LTD	ZALI SAIDI	96553574
8.	AUTO PERFORMANCE APPRAISAL	LEK BOON HWEE	94301592

Your said surveyor may contact

Mr Ong Han Wei at 9660 1347, M/s Hiap Lek Automobile Trading at

160 Sin Ming Drive #05-17, Sin Ming Autocity, Singapore 575722

*

If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Thanks n regards,

Crystal

Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2803 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LEGAL OPTIONS LLC

ADVOCATES & SOLICITORS
Mediators ~ Commissioners for Oaths ~ Notary Public

法商律师事务所

Motor Accident & Personal Injuries

Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust & Estate, Family

Tel: (65) 6438 8039 Fax: (65) 6734 8230

We do not accept service of Court Documents by fax

Your Ref : SGS 8825B
Our Ref : 18-A14-9235-VL.jp.ct

5th April 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07-16

AIG Building

Singapore 079120

(Attn: Motor Claims Department)

Dear Sirs,

CLAIMANT : TAN SWEE WEE

ACCIDENT INVOLVING VEHICLE NOS. SKH 3127B AND SGS 8825B ALONG ANG MO KIO AVE 6 (AFTER ANDERSON JUNIOR COLLEGE) ON 05/04/2018

We are instructed by **MR TAN SWEE WEE** to notify you of a road traffic accident on **5TH APRIL 2018** at about **07:40 HOURS ALONG ANG MO KIO AVE 6 (AFTER ANDERSON COLLEGE)** involving our client's vehicle registration number **SKH 3127B** and vehicle registration number **SGS 8825B** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



Cc: Client (SKH 3127B)

Directors

Joan Lim Pheok Hoon LL.B (Hons)

Victor Leong Wai Meng LL.B (Hons)

Teo Lip Hua Benedict LL.B (Hons) LL.M

Legal Executive's DID: 6513 2803

Direct Fax: 6438 8275

(Email: pinky@legaloptions.biz)

Mailing Address for Accident Claims

Documents Support:

23 Kaki Bukit Avenue 4 #01-01 South Wing,
Singapore 415933

IMMEDIATE ATTENTION

By Fax: 6415 3727/Post



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18006511/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 09-04-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGS 8825B	Veh. Inspected	SKH 3127B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/04/2018	Inspection Date	
Survey held at	160 SIN MING DRIVE #05-17		
Repairer	HIAP LEK AUTOMOBILE TRADING		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2018 12:31
Date Of Accident	05/04/2018 07:40
Exact Location Of Accident	AMK AVE 6 (AFTER ANDERSON JUNIOR COLLEGE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH3127B
Insured/Policyholder	
Name Of Registered Owner	TAN SWEE WEE
NRIC No	S6818784B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98567418
Alternative Phone No	OTHERS-98567418

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5062602050-04 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	TAN SWEE WEE
NRIC No	S6818784B
Date Of Birth	23/05/1968
Occupation	INDOOR
Date Of Driving Pass	19/01/2005
Driving Experience	13 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98567418
Fax Number	
Contact Number	OTHERS-98567418
Email Address	NOEMAIL

Address BLK 318B #03-140 YISHUN AVENUE 9
Postcode 762318
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : UNKNOWN
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGS8825B
Vehicle Make/Model/Colour SUBARU FORESTER
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver GOH TAT CHONG
NRIC/Passport Number S1655548G
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have Insured vehicle(s) involved in this accident (all insurer(s) who have Insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

06 APR 2010

Driver's Signature
(if driver is not the policyholder)
Date & Time:

05 APR 2010

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

APR 26 1953

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	8784B
Vehicle No.:	SKH3127B
Vehicle to be Exported:	No
Intended De-registration Date:	11 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	1ZR230135
Chassis No.:	MR053REE104149012
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$14,885.00
Original Registration Date:	26 Nov 2012
First Registration Date:	26 Nov 2012
Transfer Count:	0
Actual ARF Paid:	\$14,885.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2022
PARF Rebate Amount:	\$10,419.00
COE Expiry Date:	25 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$63,000.00
COE Rebate Amount:	\$29,120.00
Total Rebate Amount:	\$39,539.00

The information contained herein is correct as at 11 Apr 2018

OK

SKH 312+B

DET 10-4-18

1. Front fender N/S - scratched ✓
2. Washer tank — damaged —
3. Front fender inner shield N/S - torn ✓
4. set clips for front fender inner shield - nec ✓
5. Front fender Emblem N/S - nec —
6. Front headlight assembly N/S - damaged —
7. Front bumper — distorted ✓
8. N/S front wheel rim - repair ✓
9. set clips for front bumper ✓

Paintwork 2 panels

workmanship 3 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2018 Edit Reg		09 Apr 2018 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Goh Tat Chong , ID: S1655548G		
Main Claimant:	TAN SWEE WEE , ID: S6818784B		
Vehicle Reg. No.:	SKH3127B	Date of Loss:	05/04/2018 07:00 - :59 [64 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9452287901SG	Policy/Cover Note No.:	2100501589-01 (Comprehensive)
Vehicle Reg. No. (Insured):	SGS8825B	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/04/2018]		
Claimant's Solicitor:	LEGAL OPTIONS LLC - Tel: 64388039		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (12/04/2018): **TP GIA REPORT**
- AIG_SG (12/04/2018): **NO OI GIA REPORT**






ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKH3127B (9452287901SG)
[SGS8825B]
TP
TAN SWEE WEE
Apr 5 2018 7:45AM
[Goh Tat Chong]

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <div>View in Browser</div>		
Photos/Images											3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print
1	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
2	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
3	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
4	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
5	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
6	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
7	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
8	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
9	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
10	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
11	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
12	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
13	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
14	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
15	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
16	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
17	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
18	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
19	28/04/18 12:47	General View										Load JPG	<input checked="" type="checkbox"/>
20	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
21	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
22	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
23	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
24	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
25	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
26	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
27	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
28	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
29	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
30	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
31	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
32	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
33	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
34	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
35	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
36	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
37	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>
38	28/04/18 12:47	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
39	28/04/18 12:47	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	28/04/18 12:47	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	28/04/18 12:47	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	28/04/18 12:47	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/04/18 12:47	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div><div></div><div>^</div><div>v</div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18006511/GZ4D3E2

Date: 10/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100501589-01
 Claimant Vehicle No: SKH3127B Insured Vehicle No: SGS8825B
 Date of Loss: 05/04/2018 Nature of Claim: TP Claim No: 9452287901SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH3127B**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRX230135
 Reg. Date: 26/11/2012 (Man. Year: 2012) Chassis No: MR053REE104149012
 Colour: Black Odometer: 126014 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/04/2018
 Date Inspected: 10/04/2018 Inspected At: 160 SIN MING DRIVE #05-17
 Repairer: HIAP LEK AUTOMOBILE TRADING
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER N/S	Scratched	0.00 F	*- F
2	1		*WASHER TANK	Damaged	0.00 F	*- F
3	1		*FRONT FENDER INNER SHIELD N/S	Torn	0.00 F	*- F
4	1		*SET CLIPS FOR FRONT FENDER INNER SHIELD	Necessary	0.00 F	*- F
5	1		*FRONT FENDER EMBLEM N/S	Necessary	0.00 F	*- F
6	1		*FRONT HEADLIGHT ASSEMBLY N/S	Damaged	0.00 F	*- F
7	1		*FRONT BUMPER	Distorted	0.00 F	*- F
8	1		*N/S FRONT WHEEL RIM	Repair	0.00 F	*- F
9	1		*SET CLIPS FOR FRONT BUMPER	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >