

22/03/2008

ASS. REC. BY:

Surveyor

Kenneth

REF: CS/SM018006512/K9d3ⁿ²

Special Instruction:

ASSIGNMENT (Office)

Date/Time: 9/4/18 @ 3:16pm

From (Person): Grace Teo

of SMO

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SKU 546B

To Inspect Vehicle No:

SFM 3383K

Tel: 64528211

at Workshop m/s

Supreme Auto (Autoworx)

of NO. 176 Sin Ming Drive # 02-01

Policy No:

Claim No: CMTD1801531/AGC

Sum Insured:

Excess:

D.O.A. 06/04/2018

Make of Vch:

(Client's Record)

10/04/2018

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS 'wp'

Vehicle

Amanda

Vehicle IN/OUT

Date/Time: 3:21pm @ 9/4/18

Person Contacted:

Date/Time Action/Instruction (✓) Estimate

SFM 3383K - X

SKU 546B - X.

11/4/18 @ 5:46pm Informed Agnes Chan, we are pending estimate from repairer.

3.11 11/4/18 84400 Cash (Red @ 11498.10, 72%)

REF: SMO

ASSIGNMENT

From: Date: 10/04/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFM3383K

at Workshop m/s Supreme Auto (Autoworx)

of No. 176 Sing Ming Drive #02-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

863k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFM 3383K Yr Regn: 08 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 740Li c.c.

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

195155

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAKB 42000CY 82483

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

6/4/18

D.O.I.

10/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14 File pass to Catherine, GIA & EM not ready

RECEIVED 01 FEB 2019.

Date/Time: File Pass to?

☐

Preli. Report

1) 01/2 12/18

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + RC) SI

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

4400

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18006512/Kqd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 09-04-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKU 546B	Veh. Inspected	SFM 3383K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801531/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	09/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/04/2018	Inspection Date	
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1801531/AGC

Date: 07th September 2018

Our Ref: CS/SMO18006512/Kqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFM 3383K


We thank you for the instruction on 09/04/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/04/2018 at the premises of M/s SUPREME MOTOR (AUTOWORX) and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,898.10</u>
Revised Estimate Amount	: S\$ <u>3,627.95</u>
"Check" Items Amount	: S\$ <u>2,036.57</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have NOT authorize repair.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 9 April 2018 3:16 PM
To: admin@supreme.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Chan, Shu Hui Agnes; Henry, Irene James
Subject: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection
Attachments: SFM 3383 K Pre-repair inspection.pdf

Our Claim Reference: CMTD1801531/AGC
Your Reference: SFM3383K

Hi Amanda,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have no objection of appointing the motor surveyor **LKK AUTO CONSULTANTS** stated in your said list to conduct the joint pre-repair survey as a single joint expert.

Aside to LKK AUTO,

Please make arrangement to conduct the survey for SFM3383K.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: admin@supreme.sg [<mailto:admin@supreme.sg>]
Sent: Monday, April 09, 2018 2:43 PM
To: Claims - Motor Survey

Subject: RE: SFM 3383 K & SKU546B Involving accident at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Hi Grace,

We have fax over to Sompo this morning @ 10:29 am.

Thank you.

Best regards,
Amanda Bee
Supreme Auto Service Pte Ltd
No.176 Sin Ming Drive
#02-01 Singapore 575721
Tel: 64528211
Fax: 64517423

From: admin@supreme.sg <admin@supreme.sg>

Sent: Monday, 9 April 2018 2:37 PM

To: 'motorsurvey@sompo.com.sg' <motorsurvey@sompo.com.sg>

Subject: SFM 3383 K & SKU546B Involving accident at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Hi Grace,

Attached our Pre-repair inspection for your arrangement.
Remark: we have fax over by today 00:00:31.

Thank you.

Best regards,
Amanda Bee
Supreme Auto Service Pte Ltd
No.176 Sin Ming Drive
#02-01 Singapore 575721
Tel: 64528211
Fax: 64517423

AUTOWORX HOUSE

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721
• Tel: 6452 8211 • Fax: 6451 7420

Sampo Insurance Singapore P/L
Attn: Motor Claims Department

9/4/18

Dear Sir,

RE: Request for PRI for STm 3383K **in an accident involving** STU 546B
@ AYE towards CTE Near Alexandra Exit 6 on 6/4/18 @ 16:00hrs

We have been authorised by Lim Lian Huey, the registered owner of motor vehicle: STm 3383K at the material time of accident to make a claim against your insured.

Please give us the list of panel of your 10 survey firms for our selection to inspect the above said vehicle or you may assign our choice from either one of the 3 survey firms,

- 1) Premier Appraiser Services
- 2) LKK Auto Consultants Pte Ltd
- 3) AJAX Inspection Services Pte Ltd

We will direct settle the claims with you if the survey is conduct by either of one the firms mentioned.

Kindly contact us at 64528211 before coming to ensure the vehicle is in the workshop.

Thank you.

Yours Sincerely,



Autoworx House
Email: autoworxhouse@hotmail.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 7 September 2018 1:59 PM
To: Chan, Shu Hui Agnes; assignments
Cc: SUR
Subject: RE: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection
Attachments: CSSMO18006512Kqd3.pdf

Dear Agnes,

Enclosed herewith preliminary advice of SFM 3383K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 6 September 2018 12:18 PM
To: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Dear Agnes,

Please be informed that we are recently received the estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Sent: Wednesday, 18 July 2018 3:58 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Dear LKK

Please advise the survey/ PRI report of SFM3383K.

8504 9629
6296 4038

Thank you.

Best Regards

Agnes Chan

Claims Division

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Shiao Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]

Sent: Wednesday, 11 April, 2018 5:36 PM

To: Teo, Grace <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Cc: Henry, Irene James <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Dear Agnes,

Please be informed that we have inspected the vehicle SFM 3383K on 10/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiao Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Monday, 9 April 2018 3:25 PM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Monday, 9 April 2018 3:16 PM

To: admin@supreme.sg; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Our Claim Reference: CMTD1801531/AGC

Your Reference: SFM3383K

Hi Amanda,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have no objection of appointing the motor surveyor **LKK AUTO CONSULTANTS** stated in your said list to conduct the joint pre-repair survey as a single joint expert.

Aside to LKK AUTO,

Please make arrangement to conduct the survey for SFM3383K.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: admin@supreme.sg [<mailto:admin@supreme.sg>]

Sent: Monday, April 09, 2018 2:43 PM

To: Claims - Motor Survey

Subject: RE: SFM 3383 K & SKU546B Involving accident at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Hi Grace,

We have fax over to Sompo this morning @ 10:29 am.

Thank you.

Best regards,
Amanda Bee
Supreme Auto Service Pte Ltd
No.176 Sin Ming Drive
#02-01 Singapore 575721
Tel: 64528211
Fax: 64517423

From: admin@supreme.sg <admin@supreme.sg>

Sent: Monday, 9 April 2018 2:37 PM

To: 'motorsurvey@sompo.com.sg' <motorsurvey@sompo.com.sg>

Subject: SFM 3383 K & SKU546B Involving accident at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Hi Grace,

Attached our Pre-repair inspection for your arrangement.
Remark: we have fax over by today 00:00:31.

Thank you.

Best regards,
Amanda Bee
Supreme Auto Service Pte Ltd
No.176 Sin Ming Drive
#02-01 Singapore 575721
Tel: 64528211
Fax: 64517423

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 11 April 2018 5:36 PM
To: 'Teo, Grace'; assignments; 'Chan, Shu Hui Agnes'
Cc: 'Henry, Irene James'; SUR
Subject: RE: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Dear Agnes,

Please be informed that we have inspected the vehicle SFM 3383K on 10/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 9 April 2018 3:25 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Monday, 9 April 2018 3:16 PM
To: admin@supreme.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1801531/AGC - SKU546B & SFM3383K ACC ON 06.04.18 at AYE towards CTE near Alexandra Exit 6 - Pre-repair inspection

Our Claim Reference: CMTD1801531/AGC

Your Reference: SFM3383K

Hi Amanda,

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1619I
Vehicle Details	
Vehicle No.:	SFM3383K
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	740LI 3.0L A/T ABS D/AB 2WD 4DR HID SR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	05237115N54B30A
Chassis No.:	WBAKB42000CY82483
Maximum Power Output:	240.0 kW (321 bhp)
Open Market Value:	\$101,674.00
Original Registration Date:	05 Aug 2009
First Registration Date:	05 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$101,674.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Aug 2019
PARF Rebate Amount:	\$50,837.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,189.00
COE Rebate Amount:	\$1,652.00
Total Rebate Amount:	\$52,489.00

The information contained herein is correct as at 07 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2018 14:10
Date Of Accident	06/04/2018 16:50
Exact Location Of Accident	AYE TOWARDS CTE NEAR ALEXANDRA EXIT 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFM3383K
Insured/Policyholder	
Name Of Registered Owner	LIM LIAN HUAY
NRIC No	S1631619I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98588810
Alternative Phone No	OTHERS-98588810

Vehicle Particulars

Manufacturer	BMW
Model	740LI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1651681701
Cover Note Number	

Driver

Name of Driver	ANG PEI MENG
NRIC No	S8837374Z
Date Of Birth	03/10/1988
Occupation	INDOOR
Date Of Driving Pass	15/08/2007
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98588810
Fax Number	
Contact Number	
Email Address	DAVE8485ANG@GMAIL.COM

Address	BLK 158 YUNG LOH ROAD #14-54
Postcode	610158
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU546B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SONG WEN TAO
NRIC/Passport Number	S6860183E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ANG PEI MENG (HONG PEIMING)
Approximate Age	30

Injuries Sustain

BACK & NECK SORE

Injured person in which vehicle?

SFM3383K

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

BLK 158 YUNG LOH ROAD #14-54

Postcode

610158

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: - 9 APR 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time: - 9 APR 2018


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim
S6927273H

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along AYE towards CTE direction on the extreme right lane. Vehicles were travelling speed at about 70 km/h. Upon near the exit 6, vehicle in front of me stopped. I slowed down and stopped too. Vehicle B, SKU 546 B failed to stop in time, collided into the rear of my vehicle with a hard impact.

The next day I woke up from my sleep with a sore neck and upper back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

- 9 APR 2018

Driver's Signature

(If driver is not the policyholder)


Date & Time: - 9 APR 2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim
S6927273H



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 15 Aug 2007

NP 428A



Certificate of Insurance Pg. 1



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MX1ER SN
AN0083A
Cov. Type: C
AUTOSAFE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMPCSN1651681701	Engine No : 05237115N54B30A Chassis No: WBAKB42000CY82483
1. Index Mark and Registration Number of Vehicle	SFM3383K	
2. Name of Policy Holder	MDM LIM LIAN HUAY	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	5 AUGUST 2017	NAMED DRIVERS EX SECT. I\$81,500.00 ADDITIONAL EX OTHER THAN NAMED DRIVERS: EX SECT. I - AGE <= 25.....\$83,000.00 EX SECT. I - AGE >= 26.....\$8500.00 * AGE AS AT DATE OF ACCIDENT
4. Date of Expiry of Insurance	4 AUGUST 2018	EX ON WINDSCREEN\$8100.00
5. Persons or Classes of Persons entitled to drive *		
(A) THE POLICYHOLDER.		
(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.		
PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.		
6. Limitations as to use: *		
USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.		
EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED. ONE TIME WAIVER OF EXCESS FOR THE FIRST \$81,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.		
HIRE PURCHASE CO. : SINGAPORE FINANCE LTD AS HP OWNER * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse

KCB AGENCY

Co Reg No. 53118552C

200 Jalan Sultan

#02-38B Trade Centre

Singapore 190018

Tel: 6391 3813 Fax: 6391 3810

Authorised Officer

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Authorised Signatory

Countersigned By:

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along AYE towards CTE direction on the extreme right lane. Vehicles were travelling speed at about 70 km/h. Upon near the exit 6, vehicle in front of me stopped. I slowed down and stopped too. Vehicle B, SKU 546 B failed to stop in time, collided into the rear of my vehicle with a hard impact.

The next day I woke up from my sleep with a sore neck and upper back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x 
 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:


SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

x 

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AUTOWORX HOUSE

176 SIN MING DRIVE # 04-15 SINGAPORE 575721
TEL: 98123628 Fax: 67258033

REPAIR ESTIMATE

LIM LIAN HUAY
c/o 46 LENTOR PLAIN
SINGAPORE 786548

Date: 10/04/2018

*Not Authored
11pm @ 4400
Resurvey After Paint & clear*

QUANTITY	PARTICULARS	UNIT (\$)	AMOUNT (\$)
	RE: BMW 740Li / SFM 3383 K		
1 pc	rear boot lid		By 1,700.06 ✓
2 pcs	rear boot hinges	@ 474.55	R 949.10 ✓
1 pc	rear boot emblem logo		Mc 95.40 ✓
1 pc	rear boot emblem 740 Li		Mc 65.20 ✓
2 pcs	rear boot lamp	@ 548.00	Sn 1,096.00 ✓
1 pc	rear boot number plate garnish		Del 853.30 ✓
1 pc	rear boot lock		R 567.40 ✓
1 pc	rear boot lock catch		R 134.20 ✓
1 pc	rear boot lock sensor		Sn 224.00 ✓
1 pc	rear boot weather strip		Sn 226.50 ✓
1 pc	rear bumper lower pad		Sn 514.00 ✓
1 pc	rear bumper		By 1,711.60 ✓
1 pc	rear bumper reinforcement		By 529.30 ✓
1 pc	rear bumper inner pad		CM 289.80 ✓
2 pcs	rear bumper park sensor	@ 539.75	1,079.50 ✓
2 pcs	rear bumper reflector		Sn 274.50 ✓
1 pc	rear bumper tow cover		Sn 86.20 ✓
1 pc	rear bumper lower grille		Sn 468.75 ✓
2 pcs	rear bumper side retainer pad	@ 197.45	Sn 394.90 ✓
2 pcs	rear bumper exhaust heat shield	@ 267.40	R 534.80 ✓
1 pc	rear end panel		R 544.90 ✓
1 pc	rear end panel outer lower garnish		Sn 497.74 ✓
2 pcs	rear tail lamp assy	@ 663.70	Sn 1,327.40 ✓
		sub total	14,164.55
		less 10%	1,416.46
		sub total	12,748.10
1 pc	number plate	special nett	35.00 ✓
1 pc	number plate casing	special nett	35.00 ✓
		sub total	12,818.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	balance brought forwards	12,818.10	
	To supply specialist labours and equipments for repair to align chassis frame, panel and other parts to original positions.	1,000.00	500/
	To conduct wiring system check.	60.00	15/
	To supply spray paint, putty and other necessary materials to restore into original paint condition.	1,000.00	600/
	To supply waterproof sealant to apply onto affected areas.	nn 200.00	X
	To supply rust proofing materials to apply onto affected areas.	nn 200.00	X
	To install parking sensors.	150.00	60/
	To supply labour for remove carpet, trimming to the repair.	nn 120.00	X
	To supply specialised equipment reset ECU & reprogramming.	nn 350.00	X
	Total	15,898.10	




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18006512/Kqd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 08-02-2019		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 546B	Veh. Inspected	SFM 3383K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801531/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	09/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 740LI (A)	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WBAKB42000CY82483	Colour	METALLIC GREY	
Odometer	195155	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	CONTINENTAL	6 mm	
L/H Front Tyre	245/50 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	245/50 R18	CONTINENTAL	7 mm	
L/H Rear Tyre	245/50 R18	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/04/2018	Inspection Date	10/04/2018	
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFM 3383K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	BENT	1,700.06	1,700.06
2	REAR BOOT HINGES @\$474.55	TO REPAIR SEE LABOUR	949.10	-
1	REAR BOOT EMBLEM LOGO	NECESSARY	95.40	95.40
1	REAR BOOT EMBLEM 740LI	NECESSARY	65.20	65.20
2	REAR BOOT LAMP @\$548.00	SERVICEABLE	1,096.00	-
1	REAR BOOT NUMBER PLATE GARNISH	DENTED	853.30	580.62
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	567.40	-
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	134.20	-
1	REAR BOOT LOCK SENSOR	SERVICEABLE	224.00	-
1	REAR BOOT WEATHER STRIP	SERVICEABLE	226.50	-
1	REAR BUMPER LOWER PAD	SERVICEABLE	514.00	-
1	REAR BUMPER	BUCKLED	1,711.60	1,571.15
1	REAR BUMPER REINFORCEMENT	BENT	529.30	529.30
1	REAR BUMPER INNER PAD	CRACKED	289.80	289.80
2	REAR BUMPER PARK SENSOR @\$539.75	SHORTED (1 PC ONLY)	1,079.50	268.00
2	REAR BUMPER REFLECTOR	SERVICEABLE	274.50	-
1	REAR BUMPER TOW COVER	SERVICEABLE	86.20	-
1	REAR BUMPER LOWER GRILLE	SERVICEABLE	468.75	-
2	REAR BUMPER SIDE RETAINER PAD @\$197.45	SERVICEABLE	394.90	-
2	REAR BUMPER EXHAUST HEAT SHIELD @\$267.40	TO REPAIR SEE LABOUR	534.80	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	544.90	-
1	REAR END PANEL OUTER LOWER GARNISH	SERVICEABLE	497.74	-
2	REAR TAIL LAMP ASSY @\$663.70	SERVICEABLE	1,327.40	-
	LESS 10% DISCOUNT		-1,416.45	-509.95
			12,748.10	4,589.58
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE (SN)	SERVICEABLE	35.00	-
1	NUMBER PLATE CASING (SN)	SERVICEABLE	35.00	-
			70.00	-

Report Ref No. CS/SMO18006512/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO SUPPLY SPECIALIST LABOURS AND EQUIPMENTS FOR REPAIR TO ALIGN CHASSIS FRAME,PANEL AND OTHER PARTS TO ORIGINAL POSITIONS.INCLUSIVE OF THE REPAIR OF REAR BOOT HINGES,REAR BOOT LOCK,REAR BOOT LOCK CATCH,REAR BUMPER EXHAUST HEAT SHIELD AND REAR END PANEL.		1,000.00	500.00
	TO CONDUCT WIRING SYSTEM CHECK.		60.00	15.00
	TO SUPPLY SPRAY PAINT,PUTTY AND OTHER NECESSARY MATERIALS TO RESTORE INTO ORIGINAL PAINT CONDITION.		1,000.00	600.00
	TO SUPPLY WATERPROOF SEALANT TO APPLY ONTO AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO SUPPLY RUST PROOFING MATERIALS TO APPLY ONTO AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO INSTALL PARKING SENSORS.		150.00	60.00
	TO SUPPLY LABOUR FOR REMOVE CARPET,TRIMMING TO THE REPAIR.	NOT NECESSARY	120.00	-
	TO SUPPLY SPECIALISED EQUIPMENT RESET ECU & REPROGRAMMING.	NOT NECESSARY	350.00	-
			3,080.00	1,175.00
	GRAND TOTAL		15,898.10	5,764.58
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,400.00

Report Ref No. CS/SMO18006512/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.