



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 MERCEDES C180 (SKT600H)

Date of Loss

6 April 2018

Time of Loss

22.00

Loss Description

SKT600H (INSD) C/W FZ1400P (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$132,000.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/08/2018



Days of work completion *

128



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKT600H

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

08/07/2015



Mileage

44781

Age of Vehicle

2

Driver Details

CATEGORY Manufacturing Year

POLICY INFORMAT... 2015

CATEGORY Driver Name

ASSESSMENT INFO... 2015

FNOL INFORMATI... MEI HWEI STEPHANIE (LIN MEIHUI)

POST SURVEY INF...

CATEGORY	Make	
POLICY INFORMAT...	MERCEDES	
ASSESSMENT INFO...	MERCEDES BENZ	
CATEGORY	Model	
POLICY INFORMAT...	C180	
ASSESSMENT INFO...	C180 EXCLUSIVE (R17 LED)	
CATEGORY	Type	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Type of Paint	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Chassis No	
POLICY INFORMAT...	WDD2050402R077370	
CATEGORY	Date of Birth	
FNOL INFORMATI...	23 December 1971	
POST SURVEY INF...	dd/mm/yyyy	
CATEGORY	Age	
FNOL INFORMATI...	46	
POST SURVEY INF...		
CATEGORY	Occupation	
FNOL INFORMATI...	Unknown	
POST SURVEY INF...		
CATEGORY	Education Qualification	
FNOL INFORMATI...	Other	
POST SURVEY INF...		
CATEGORY	Driving Experience	

ASSESSMENT INFO... WDD2050402R077370

CATEGORY Engine No

POLICY INFORMAT... 27491030399914

ASSESSMENT INFO... 27491030399914

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1595

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 132000

FNOL INFORMATI... 8

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... 2 LINCOLN ROAD, #17-02 PARK INFINIA
AT WEE NAM, 308342, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Single

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7146644B

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

10/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

600

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/50R17

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

225/50R17

Front left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear left side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			RH/FRONT TYRE			Damaged	550				550	Review
☐		2	1			RH/FRONT FENDER			Bent	881.86				881.86	Review
☐		3	1			WHEEL HOUSE COVERING (FRONT PART)			Serviceable	0	0	0	0	0	Deny
☐		4	1			WHEEL HOUSE COVERING (BACK PART)			Deformed	118.22				118.22	Review
☐		5	1			RH/FRONT FENDER GAP COVER			Necessary	21.55				21.55	Review
☐		6	1			RIGHT FRONT DOOR			Bent	1691.06				1691.06	Review
☐		7	1			DOOR WEATHERSTRIP			Necessary	280.72				280.72	Review
☐		8	1			SELF-ADHESIVE TRIM			Necessary	16.05				16.05	Review
☐		9	1			RH/FRONT WINDOW GUIDE RAIL			Serviceable	0	0	0	0	0	Deny
☐		10	1			RH/FRONT DISK WHEEL			Cut	557.1				557.1	Review
☐		11	1			RH/FRONT STEERING KNUCKLE			Bent	1208.64				1208.64	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		12	1			RH/FRONT STRUT ROD			Bent	577.59				577.59	Review
☐		13	1			RH/FRONT SPRING LINK			Bent	592.02				592.02	Review
☐		14	1			RH/FRONT CONTROL ARM			Serviceable	0	0	0	0	0	Deny
☐		15	1			RH/FRONT SHOCK-ABSORBER STRUT			Bent	822.79				822.79	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RE
☐		1		USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	380	0	0	Reviewing		
☐		2		RESPRAY RH / FRONT FENDER, RH / FRONT DOOR	1200	0	0	Reviewing		
☐		3		DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	960	0	0	Reviewing		
☐		4		REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR	480	0	0	Reviewing		
☐		5		TO INSPECT & CONDUCT WHEEL ALIGNMENT	540	0	0	Reviewing		
☐		6		REMOVE CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE	1920	0	0	Reviewing		
☐		7		ACCIDENT TOWING FROM 870 DUNEARN RD TO PLSC USING KING DOLLEY AND MIDNIGHT CHARGE	0	0	0	Deny		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 5 DAYS	Reviewing			
☐		2	WHEEL BEARING	Reviewing	524.09	BENT (SUPPLEMENTARY)	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$12,721.69

Claim Amount

\$12,721.69

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$5,480.00	\$5,480.00
Miscellaneous	\$524.09	\$524.09
Excess	-\$600.00	-\$600.00
Spare Parts	\$7,317.60	\$7,317.60

Submit for Review