

ASS. REC. BY: REP: CS3/MSG18006527/Mzadz

Surveyor: Markus ASSIGNMENT (Office)

From (Person): Catherine Thia of MSG Date/Time: 09/04/18 @ 3:14pm

Estimated Cost: Bill to:

OD (TV) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDW 7717B Insured: SJV 5416S

at Workshop in/3: Y.S. Automobile Tel: 9662 7598

of: BIK 5 De fu lane 10 # 01-580

Policy No: 27637966DMA Claim No: 554849

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 9/4/2018

CA / REV / REP. / REV 24 HRS (up) 10/04/2018 H.O.D. Endorsement:

Date/Time: 5:30pm 09/4/18 Person Contacted: Peter Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SDW 7717B - X
	SJV 5416S - X
11/4/18	Disassembled

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ATP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDW 7717B

at Workshop m/s 1/5 Ashville

of £80

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 31

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SDW 7717B Yr Regn: 1209

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Honda civic c.c 1798

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 188605 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF026409:5200965

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-216

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 9/4/18 D.O.I. 10/4/18

Survey held at 11.06 am.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PRS LTA 18390 1yrs Invl. Dep 10k net 12610 6-7k.
19/4/18	Submit PRS Report
RECEIVED 20 APR 2018	

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: _____

1) _____

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: 120

Transportation: 50

S + RS, SI

Photos

Others: 10

TOTAL

180

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Apr 2018		09 Apr 2018 15:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	JULIANNA BINTE MOHAMED AMIN, ID: S7940695C		
Main Claimant:	SIM LYE HENG, ID: S6817540B		
Vehicle Reg. No.:	SDW7717B	Date of Loss:	09/04/2018 07:00 - :59 [99 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554849	Policy/Cover Note No.:	27637966DMA Coverage: 28/01/2018 - 27/01/2019
Vehicle Reg. No. (Insured):	SJV5416S	Policy No. (Claimant):	
		Excess:	
Repairer:	Y S Automobile Service (HQ) BLK 5 DEFU LANE 10, #01-580, 539186 Defu Lane - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/04/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18006527/Uz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 09-04-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJV 5416S	Veh. Inspected	SDW 7717B
Policy No.	27637966DMA	Coverage (\$)	0.00
Claim No.	554849	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/04/2018	Inspection Date	
Survey held at	Y S AUTOMOBILE SERVICE BLK 5 DEFU LANE 10 #01-580 DEFU LANE INDUSTRIAL PARK 3 SINGAPORE 539186		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2018 08:57
Date Of Accident	09/04/2018 07:20
Exact Location Of Accident	PIE(CHANGI) AFTER PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW7717B
Insured/Policyholder	
Name Of Registered Owner	SIM LYE HENG
NRIC No	S6817540B
Email Address	LHSIM@YAHOO.COM
Mobile Phone No	(LOCAL) +65-92291771
Alternative Phone No	OTHERS-92291771
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076002764-02
Cover Note Number	26/12/2017 - 25/12/2018
Driver	
Name of Driver	SIM LYE HENG
NRIC No	S6817540B
Date Of Birth	07/05/1968
Occupation	INDOOR
Date Of Driving Pass	14/04/1987
Driving Experience	30 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92291771
Fax Number	
CONTACT NUMBER	OTHERS-92291771
Email Address	LHSIM@YAHOO.COM

Address	139 PASIR RIS GROVE #07-12 D'NEST
Postcode	518134
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS TRAVELLING ON THE RIGHT LANE OF PIE(CHANGI AFTER PAYA LEBAR EXIT. VEHICLES INFRONT OF ME SUDDENLY STOPPED. I APPLIED MY BRAKES AND STOPPED IN TIME. SUDDENLY, I FELT A GREAT IMPACT ON MY VEHICLE REAR PORTION. VEHICLE B HAD HIT ONTO MY VEHICLE REAR PORTION. UPON ALIGHT, IT WAS A CHAIN COLLISION INVOLVING THREE VEHICLES. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV5416S
Vehicle Make/Model/Colour	VW
Details Of Properties	FRONT PORTION AND REAR BUMPER
Vehicle Category	PRIVATE CAR
Name of Driver	JULIANNA BINTE MOHAMED AMIN
NRIC/Passport Number	S7940695C
Contact Number	96999314
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

DETAILS OF OTHER VEHICLE PROPERTY 2

Address	139 PASIR RIS GROVE #07-42 D'NEST
Postcode	518134
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS TRAVELLING ON THE RIGHT LANE OF PIE(CHANGI AFTER PAYA LEBAR EXIT. VEHICLES INFRONT OF ME SUDDENLY STOPPED. I APPLIED MY BRAKES AND STOPPED IN TIME. SUDDENLY, I FELT A GREAT IMPACT ON MY VEHICLE REAR PORTION. VEHICLE B HAD HIT ONTO MY VEHICLE REAR PORTION. UPON ALIGHT, IT WAS A CHAIN COLLISION INVOLVING THREE VEHICLES. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV5416S
Vehicle Make/Model/Colour	VW
Details Of Properties	FRONT PORTION AND REAR BUMPER
Vehicle Category	PRIVATE CAR
Name of Driver	JULIANNA BINTE MOHAMED AMIN
NRIC/Passport Number	S7940695C
Contact Number	96999314
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKG375B
Vehicle Make/Model/Colour	PEUGEOT
Details Of Properties	FRONT BUMPER
Vehicle Category	PRIVATE CAR
Name of Driver	ONG OOI KEAT
NRIC/Passport Number	G5662299T
Contact Number	92399921
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No: M1

D.O.A:

9418

Vehicle No:

Make / Model:

SOW7717B

H/Civic

Report Date: 4/9/2018 Start Time: 9:06 AM

Reporting Type: TP

End Time:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.

4/9/2018 9:06

Policyholder's Signature
Date & Time:


4/9/2018 9:06

Driver's Signature (if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Chen Jun Liang
NRIC/Fin No: S990765

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS TRAVELLING ON THE RIGHT LANE OF PIE(CHANGI) AFTER PAYA LEBAR EXIT. VEHICLES IN FRONT OF ME SUDDENLY STOPPED. I APPLIED MY BRAKES AND STOPPED IN TIME. SUDDENLY, I FELT A GREAT IMPACT ON MY VEHICLE REAR PORTION. VEHICLE B HAD HIT ONTO MY VEHICLE REAR PORTION. UPON ALIGHT, IT WAS A CHAIN COLLISION INVOLVING THREE VEHICLES. NO ONE WAS INJURED.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 4/9/2018 9:06

 Driver's Signature (if driver is not the policyholder)
 Date & Time:

4/9/2018 9:06


 Reporting Centre Personnel's Signature
 Name: Chen JunLiang
 ID/CI Fin No: 5990765

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7540B
Vehicle Details	
Vehicle No.:	SDW7717B
Vehicle to be Exported:	No
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 2.0L 5AT
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	K20Z24500965
Chassis No.:	JHMF26409S200965
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$27,851.00
Original Registration Date:	26 Dec 2009
First Registration Date:	26 Dec 2009
Transfer Count:	0
Actual ARF Paid:	\$27,851.00 13925
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2019
PARF Rebate Amount:	\$15,318.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,267.00
COE Rebate Amount:	\$3,072.00
Total Rebate Amount:	\$18,390.00

The information contained herein is correct as at 10 Apr 2018

OK

CHEAPEST CAR INSURANCE RENEWAL



Choice of \$0 excess

Option of any workshop

GET


Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

5 Years Agent Warranty! Limited Units! Call Now!!



Special Promo! Last 3 Units Only.. Cheapest In Town.. High Trade In. No Gimmick
 Net Link Partners StarAd



Browse by Category ▾

Sort by

12 vehicles

HONDA CIVIC 2.0

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mil
Search Selection	HONDA CIVIC 2.0		Any	Any	2009	Any	
	Honda Civic 2.0A		\$31,000	\$9,730 /yr	26-Dec-2009	1,998 cc	12
2nd Owner. Selling Due To Upgrade. Posted: 07-Apr-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda							
	Honda Civic 2.0A		\$31,800	\$10,680 /yr	16-Dec-2009	1,998 cc	
Promo Bank Loan Interest Of 1.99%, 1 Owner, New Paint, New Leather Seats, All Points Checked By Workshop. Repairs Of Mind. Call For Viewing Appointment. Posted: 06-Apr-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda							
	Honda Civic 2.0A Si		\$35,188	\$12,050 /yr	14-Dec-2009	1,998 cc	
Must View! Cheapest In The Market! Most Popular, Reliable And Best Selling Jap Sedan! Excellent Condition! Price Negot Flexible Loan Packages! Fast And Easy Loan Approval, 10... Posted: 05-Apr-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda							
	Honda Civic Type R 2.0M 3DR		\$32,000	\$14,950 /yr	20-May-2009	1,998 cc	82
Fully Stock. Selling Due To Additional Member To Family. Call Or SMS For Viewing. Posted: 31-Mar-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda							

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



1a Civic Type R 2.0M (New r COE) **\$84,800** **\$8,470 /yr** **22-Jan-2009** **1,998 cc** **12**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Apr 2018		09 Apr 2018 15:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JULIANNA BINTE MOHAMED AMIN , ID: S7940695C								
Main Claimant:	SIM LYE HENG , ID: S6817540B								
Vehicle Reg. No.:	SDW7717B	Date of Loss:	09/04/2018 07:00 - :59 [99 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 554849	Policy/Cover Note No.:	27637966DMA Coverage: 28/01/2018 - 27/01/2019						
Vehicle Reg. No. (Insured):	SJV5416S	Policy No. (Claimant):							
		Excess:							
Repairer:	Y S Automobile Service (HQ) BLK 5 DEFU LANE 10, #01-580, 539186 Defu Lane - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 10/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDW7717B (554849)**
[SJV5416S]
TP
SIM LYE HENG
Apr 9 2018 7:00AM
[JULIANNA BINTE MOHAMED AMIN]
Y S Automobile Service

Upload Documents Upload Photos Compose New Letter		View View in Browser
Video		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)
1	17/04/18 08:54	TP Video - Accident
2	17/04/18 08:54	TP Video - Accident
Photos/Images		3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	18/04/18 14:21	General View
2	18/04/18 14:21	General View
3	18/04/18 14:21	General View
4	18/04/18 14:21	General View
5	18/04/18 14:21	General View
6	18/04/18 14:21	General View
7	18/04/18 14:21	General View
8	18/04/18 14:21	General View
9	18/04/18 14:21	General View
10	18/04/18 14:21	General View
11	18/04/18 14:21	General View
12	18/04/18 14:21	General View
13	18/04/18 14:21	General View
14	18/04/18 14:21	General View
15	18/04/18 14:21	General View
16	18/04/18 14:21	General View
17	18/04/18 14:21	General View
18	18/04/18 14:21	General View
19	18/04/18 14:21	General View
20	18/04/18 14:21	General View
21	18/04/18 14:21	General View
22	18/04/18 14:21	General View
23	18/04/18 14:21	General View
24	18/04/18 14:21	General View
25	18/04/18 14:21	General View
26	18/04/18 14:21	General View
27	18/04/18 14:21	General View
28	18/04/18 14:21	General View
29	18/04/18 14:21	General View
30	18/04/18 14:21	General View
31	18/04/18 14:21	General View
32	18/04/18 14:21	General View
33	18/04/18 14:21	General View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
59	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
60	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
61	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
62	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
63	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
64	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
65	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
66	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
67	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
68	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
69	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
70	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
71	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
72	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
73	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
74	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
75	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
76	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
77	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
78	18/04/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
79	18/04/18 14:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	18/04/18 14:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	18/04/18 14:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	18/04/18 14:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	18/04/18 14:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
85	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
86	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
87	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
88	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
89	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
90	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
91	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
92	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
93	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
94	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
95	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
96	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
97	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
98	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
99	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
100	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
101	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
102	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
103	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
104	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
105	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
106	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
107	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
108	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
109	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
110	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
111	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
112	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
113	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
114	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
115	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
116	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
117	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
118	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
119	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
120	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
121	18/04/18 14:23	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/04/18 15:10	TP PRI Request with GIA Report	Load PDF	
2	09/04/18 15:10	TP reject SJE - assign LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18006527/UZ4D3E2
Date: 20/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 27637966DMA	
Claimant Vehicle No : SDW7717B	Insured Vehicle No : SJV5416S	
Date of Loss: 09/04/2018	Nature of Claim: TP	Claim No: 554849

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDW7717B	Engine No: K20Z24500965
Make & Model: HONDA CIVIC, 2.0 L (A)	Chassis No: JHMFD26409S200965
Reg. Date: 26/12/2009 (Man. Year: 2009)	Odometer: 188605 km
Colour: White	
Engine Capacity: 1998 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	09/04/2018		
Date Inspected:	10/04/2018	Inspected At:	Y S Automobile Service (HQ) BLK 5 DEFU LANE 10, #01-580 Singapore 539186
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2018)
Parts: 143	HONDA CIVIC 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDW7717B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >