



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

2010 TPVD TOYOTA WISH-1.8 (A) (SGC2768G)

Date of Loss

4 April 2018

Time of Loss

19.00

Loss Description

SJT2936M (INSD) > SGC2768G (TP) > SLS5968H > SLP2666P

Comment

Workshop Details

Total Rebate Amount

16103

Nett Loss Amount

\$6,897.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

27/06/2018



Days of work completion *

82



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SGC2768G

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

12/01/2006



Mileage

145500

Age of Vehicle

12

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2015

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

KO SOON SHIN

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... BMW

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... 318 I

ASSESSMENT INFO... WISH 1.8 A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WBAPF72020A143266

CATEGORY Date of Birth

FNOL INFORMATI... 16 November 1987

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 30

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... ZNE100281161

CATEGORY Engine No

POLICY INFORMAT... A836I527N46B20BZ

ASSESSMENT INFO... 1ZZ2446293

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1794

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 23000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... BLK 126 GEYLANG EAST AVE 1, #09-79,
381126, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S8737616H



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

11/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/65R15

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

195/65R15

Front left side

LUXOTIK5mm

Front right side

LUXOTIK5mm

Rear left side

LUXOTIK5mm

Rear right side

LUXOTIK5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
		1	1			REAR WINDSCREEN MOULDING			Necessary	120		25		90	Review
		2	1			REAR GATE			Damaged	1275		25		956.25	Review
		3	1			REAR GATE LOGO			Necessary	55		25		41.25	Review
		4	1			REAR GATE INNER RUBBER			Damaged	398		25		298.5	Review
		5	1			REAR GATE LOCK			Twisted	443		25		332.25	Review
		6	1			REAR BUMPER			Damaged	500.3		25		375.23	Review
		7	2			REAR BUMPER RETAINER			Bent	60.8		25		91.2	Review
		8	10			REAR BUMPER CLIP			Necessary	5		25		37.5	Review
		9	2			REAR BUMPER BRACKET			Serviceable	0	0	0	0	0	Deny
		10	1			REAR BUMPER REFLECTOR N/S			Cracked	95		25		71.25	Review
		11	1			REAR BUMPER REFLECTOR O/S			Serviceable	0	0	0	0	0	Deny
		12	2			TAIL LAMP			Serviceable	0	0	0	0	0	Deny
		13	1			REAR END PANEL			Damaged	468		25		351	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
		14	1			REAR END PANEL TOP GARNISH			Serviceable	0	0	0	0	0	Deny
		15	1			REAR SPARE TYRE FLOOR PANEL			Repair	0	0	0	0	0	Deny
		16	1			FRT BONNET			Buckled	645		25		483.75	Review
		17	2			FRT BONNET HINGE			Repair	0	0	0	0	0	Deny
		18	1			FRT BONNET INSULATOR			Deformed	323		25		242.25	Review
		19	10			INSULATOR CLIP			Necessary	5		25		37.5	Review
		20	1			FRT BONNET LOCK			Twisted	86		25		64.5	Review
		21	1			FRT BONNET CHROME			Cracked	215		25		161.25	Review
		22	1			FRT GRILLE			Twisted	115		25		86.25	Review
		23	1			FRT GRILLE CLIP			Serviceable	0	0	0	0	0	Deny
		24	2			FRT GRILLE BUSH			Necessary	20		25		30	Review
		25	1			FRT BUMPER			Damaged	475		25		356.25	Review
		26	2			FRT BUMPER RETAINER			Bent	55		25		82.5	Review
		27	10			FRT BUMPER CLIP			Necessary	5		25		37.5	Review
		28	1			FRT BUMPER INNER SPONGE			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		29	1			FRT BUMPER REINFORCEMENT			Repair	0	0	0	0	0	Deny
		30	1			HEADLAMP N/S			Cracked	925		25		693.75	Review
		31	1			HEADLAMP O/S			Serviceable	0	0	0	0	0	Deny
		32	1			HEADLAMP SUPPORT PANEL			Buckled	890		25		667.5	Review
		33	1			BRACE PANEL			Twisted	90		25		67.5	Review
		34	1			AIRCON CONDENSER			Bent	1591.6		25		1193.7	Review
		35	1			RADIATOR			Serviceable	0	0	0	0	0	Deny
		36	1			RADIATOR MOTOR COWLING			Cracked	220		25		165	Review
		37	2			AIRCON SIDE DEFLECTOR			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		WIRE CHECKING	20	0	0	Reviewing		1
		2		REMOVE & REFIX AIRCON AND GAS	100	0	0	Reviewing		1
		3		REMOVE & REFIX REAR WINDSCREEN	120	0	0	Reviewing		1
		4		TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	60	0	0	Reviewing		1

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		5		REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	60	0	0	Reviewing		1
		6		CAVITY PROTECTION ON ALL AFFECTED AREA	80	0	0	Reviewing		1
		7		LABOUR CHARGE	1400	0	0	Reviewing		1
		8		SPRAY PAINTING	1500	0	0	Reviewing		1

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 8 DAYS	Reviewing			
		2	FRT NUMBER PLATE	Reviewing	40	BENT	
		3	REAR NUMBER PLATE	Reviewing	40	BENT	
		4	REAR WINDSCREEN GUM	Reviewing	40	NECESSARY	
		5	SET REVERSE SENSOR	Reviewing	200	SHORTED	
		6	RADIATOR COOLANT	Reviewing	25	NECESSARY	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$10,698.63

Claim Amount

\$10,698.63

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$3,340.00	\$3,340.00
Miscellaneous	\$345.00	\$345.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	FINAL LUMP SUM	Reviewing	6800		

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$6,800.00

Claim Amount\$6,800.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$6,800.00	\$6,800.00

Submit for Review