







Thatcham escribe

NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC18006535/Nvbe2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	23-04-2018		
				INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GZ 3691R	Veh. Ir	nspected	SHA 2258K	
	Policy No.	5092915159	Cover	age (\$)	0.00	
	Claim No.	MT/0990490-001	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	09/04/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI SONATA	c.c		1991	
	Engine No.	HIDDEN	Year o	f Reg.	2011	
	Chassis No.	KMHET41VMBA820447	Colou	r	BLUE	
	Odometer	750130	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	HANKC		5 mm	
	L/H Front Tyre	215/60 R16	HANKO	OOK	5 mm	
	R/H Rear Tyre	215/60 R16	HANKC	OOK	5 mm	
	L/H Rear Tyre	215/60 R16	HANKC		5 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/04/2018	Inspection Date 09/04/20			
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					