

22/03/2010

ASS. REC. BY:

REF: CS/FCI18006561 / R11d3<sup>n2</sup> Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time: 9/4/18 @ 5:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC3251S

Insured:

SHA 0872A

at Workshop m/s

SC Auto Industries

Tel:

6768 2222

of

51 Senoko Road

Policy No:

Claim No:

D18002770MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

03/03/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

9.14am @ 10/4/18

Person Contacted:

Mei Lin

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

PC3251S-X

SHA 0872A-NA/MSG13003153/v3

D.O.A: 10/2/13

12/04/18

@ 15:58 p.m revised to Sithara v.a email.

Part by Part 1640 (Red: 1180, 41%)

Surveyor *Farah*

REF:

6061K

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **PC32515** Yr Regn: **2014 / OK**  
 Type: M.Car / M.Cycle **(B)** / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: **ISUZU LT 434P** c.c **7790**  
 Colour: **MULTI** A/C: Insured / Std / NI / NA  
 Sp. Reading: **239310** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: **JALL7434PE 7000077**

Gen. Cond: Good / **(B)** / Fair / Poor / Burnt

Steering: **(B)** / Jammed / Leaked / Burnt or

Brake: **(B)** / Jammed / Leaked / Burnt or

Modi: **(B)** / Nil / S/Rim / STD A/Rim or

Tyre Size: F: **295/60R22.5**  
 R: **295/60R22.5**

**(B)** / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

| Front  |                 | Rear   |                 |
|--------|-----------------|--------|-----------------|
| R/Bal. | <b>8</b> mm     | R/Bal. | <b>8/8</b> mm   |
| L/Bal. | <b>8</b> mm     | L/Bal. | <b>8/8</b> mm   |
| D.O.A. | <b>07/03/18</b> | D.O.I. | <b>11/04/18</b> |

Survey held at **SC AUTO**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**N/S FR**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

1) **15/10 Typist.**

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

☐ \$ + RS. \$

☐ Photos

☐ Others

TOTAL

Report Format :

Lump Sum / **(B)** : (\$)

**TP**

**16401**

**110**

**50**

**50**

**22**

**232**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002770MFSH

Date: 12 April 2018

Our Ref: CS/FCI18006561/R1td3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. PC 3251S.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/04/2018 at the premises of M/s SC Auto Industries (S) Pte Ltd and have the following to report:-

|                          |                  |
|--------------------------|------------------|
| Workshop Estimate Amount | : S\$ 2,820.00 . |
| Revised Estimate Amount  | : S\$ 1,640.00 . |
| "Check" Items Amount     | : S\$ - .        |
| Market Value             | : S\$ - .        |
| LTA Reimbursement Value  | : S\$ - .        |
| Nett Value               | : S\$ - .        |

**Description of Damage:**

The vehicle sustained damages at the n/s front portion.



Repair days: 3 Days

**Comments/ Present Status:**

Damages Consistent.

Yours faithfully,  
Mohd. Rasul  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

|                    |                                           |                              |
|--------------------|-------------------------------------------|------------------------------|
| Date               | 09-04-2018                                | Our Ref No. D18002770MFSH    |
| Accident Date      | 03-03-2018                                | Claim Type. Third Party      |
| Insured Vehicle    | SHA0872A                                  | Third Party Vehicle. PC3251S |
| Survey Location    | 51 SENOKO ROAD                            |                              |
| Contact Person.    | AELYNE LEE MEI LIN                        |                              |
| Contact No.        | 67582222/ 0                               | Fax No. 62576931             |
| Survey Type        | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED: |                              |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD              |                              |
| Contact Person     | NA                                        | Fax No. 68416315             |
| Contact Number.    | NA                                        |                              |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                                   |                         |
|-------------------|-----------------------------------|-------------------------|
| Cc : Workshop     | SC AUTO INDUSTRIES<br>(S) PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                                | TP Solicitor Fax No. NA |
| Officer Incharge  | SITHARA                           |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 12 April 2018 3:58 PM  
**To:** cwsmotorclaims@msfirstcapital.com.sg; SITHARA@MSFIRSTCAPITAL.COM.SG; denisetay@lkkauto.com  
**Cc:** 'SUR'; assignments@lkkauto.com  
**Subject:** RE: SURVEY ASSESSMENT - D18002770MFSH/1, PC 3251S  
**Attachments:** PC 3251S - Preli Advise.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle PC 3251S  
Date of survey: 11/4/2018  
Number of days: 3 days

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 10 April 2018 9:19 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002770MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Monday, 9 April 2018 5:40 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); SITHARA@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18002770MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S KHIM SEAH ENTERPRISE PTE LTD  
NO 71 WOODLANDS IND PARK E9  
#06-08 WAVE 9  
SINGAPORE 757048  
Insured KHIM SEAH ENTERPRISE PTE LTD  
Policy VFX/P0902358/00225

## ESTIMATE Bill

GST Reg. No: 19-9800107D  
Date: 9/3/2018  
Our Case Ref. SC18/03/047/4KS-TP  
Accident Date 3/3/2018

Damaged Vehicle No: PC3251S

| S/no                         | Description                  | QTY  | Price      | Disc   | Amount                |
|------------------------------|------------------------------|------|------------|--------|-----------------------|
| <b><u>Replaced Parts</u></b> |                              |      |            |        |                       |
| 1                            | DOOR RUBBER                  | 1 PC | \$240.00   | SVC X  | \$240.00              |
| <b><u>Labour Charges</u></b> |                              |      |            |        |                       |
| 1                            | SPRAY PAINTING               | 1    | \$1,300.00 | - 1000 | <del>\$1,300.00</del> |
| 2                            | LABOUR FOR LHS FRONT PORTION | 1    | \$1,280.00 | - 640  | <del>\$1,280.00</del> |
| Sub Total                    |                              |      |            |        | \$ 2,820.00           |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Authorised Signature

Repair  
Hp 90010068  
3 days  
P/P  
11/04/18 @ 0950  
Revy after repair



# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

## Final Bill

GST Reg. No: 19-9800107D

Date: 3/6/2018

Our Case Ref: SC18/03/047/4KS-TP

Accident Date: 3/3/2018

M/S KHIM SEAH ENTERPRISE PTE LTD  
NO 71 WOODLANDS IND PARK E9  
#06-08 WAVE 9  
SINGAPORE 757048  
Insured KHIM SEAH ENTERPRISE PTE LTD  
Policy VFX/P0902358/00225

Damaged Vehicle No: PC3251S

| S/no                         | Description                  | QTY | Price      | Disc | Amount      |
|------------------------------|------------------------------|-----|------------|------|-------------|
| <b><u>Labour Charges</u></b> |                              |     |            |      |             |
| 1                            | SPRAY PAINTING               | 1   | \$1,000.00 | -    | \$1,000.00  |
| 2                            | LABOUR FOR LHS FRONT PORTION | 1   | \$640.00   | -    | \$640.00    |
| Sub Total                    |                              |     |            |      | \$ 1,640.00 |
| GST ( 7%)                    |                              |     |            |      | \$ 114.80   |
| Total Amount                 |                              |     |            |      | \$ 1,754.80 |

  
Authorised Signature





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                              |                              |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|------------------------------|------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                              | Ref : CS/FCI18006561/R1td3n2 |            |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                              | Date : 19-10-2018            |            |  |
|                                                                                                                                                                                        |                                                                              | Code : FCI2                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                              |                              |            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHA 872A                                                                     | Veh. Inspected               | PC 3251S   |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                              | Coverage (\$)                | 0.00       |                                                                                     |
| Claim No.                                                                                                                                                                              | D18002770MFSH                                                                | Excess (\$)                  | 0.00       |                                                                                     |
| Assign From                                                                                                                                                                            | SITHARA                                                                      | Assign Date                  | 09/04/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                              |                              |            |                                                                                     |
| Make & Model                                                                                                                                                                           | ISUZU LT434P                                                                 | c.c                          | 7790       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                       | Year of Reg.                 | 2014       |                                                                                     |
| Chassis No.                                                                                                                                                                            | JALLT434PE7000077                                                            | Colour                       | MULTI      |                                                                                     |
| Odometer                                                                                                                                                                               | 239310                                                                       | Steering                     | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                     | Modification                 | NIL        |                                                                                     |
| General                                                                                                                                                                                | FAIR                                                                         |                              |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                              |                              |            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                         | Make                         | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 295/80 R22.5                                                                 | BRIDGESTONE                  | 8 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 295/80 R22.5                                                                 | BRIDGESTONE                  | 8 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 295/80 R22.5 (D)                                                             | BRIDGESTONE                  | 8/8 mm     |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 295/80 R22.5 (D)                                                             | BRIDGESTONE                  | 8/8 mm     |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                              |                              |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                                                                        |                                                                              |                              |            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                              |                              |            |                                                                                     |
| Accident Date                                                                                                                                                                          | 03/03/2018                                                                   | Inspection Date              | 11/04/2018 |                                                                                     |
| Survey held at                                                                                                                                                                         | SC AUTO INDUSTRIES (S) PTE LTD<br>51, SENOKO ROAD #03-01<br>SINGAPORE 758133 |                              |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                              |                              |            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                              |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                              |                              |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                              | 3 Working Days               |            |                                                                                     |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3251S**

| Qty                                | Description of Parts          | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------|-------------|---------------------------|-------------------|
| 1                                  | <b>REPLACEMENT OF PARTS</b>   | SERVICEABLE |                           |                   |
|                                    | DOOR RUBBER (SN)              |             | 240.00                    | -                 |
|                                    |                               |             | 240.00                    | -                 |
|                                    | <b>LABOUR</b>                 |             |                           |                   |
|                                    | SPRAY PAINTING.               |             | 1,300.00                  | 1,000.00          |
|                                    | LABOUR FOR LHS FRONT PORTION. |             | 1,280.00                  | 640.00            |
|                                    |                               |             | 2,580.00                  | 1,640.00          |
| <b>GRAND TOTAL</b>                 |                               |             | <b>2,820.00</b>           | <b>1,640.00</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                               |             |                           | <b>1,640.00</b>   |

Report Ref No. CS/FCI18006561/R1td3n2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.