

ASS. REC. BY:

REF: CS/AGI18006562/Kvd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Albert Hong

of

AGI

Date/Time:

9/4/18 @ 5:52pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 969SE

Insured:

SL 6306Z

at Workshop m/s

Trans. Cab

Tel:

of

No. 2 AMK Street 63

Policy No:

Claim No:

C10001486

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/04/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

9:25am @ 10/4/18

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SHB 969SE - C3/TM 16010073/Kghn2

D.O.A. 27/5/16

REF: AGI

ASSIGNMENT

From: Date: 10/04/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHB 9695E

at Workshop m/s Trans-cab

of No. 2 AMK st-63

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1wp}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHB 9695E Yr Regn: 07 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1995

Colour: White / R A/C: Insured / Std / NI / NA

Sp. Reading: 645770 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VFI ABL 15AUC 273106

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

L/R: Long

BS / DUN / EXNOVA / G / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 5 mm

L/Bal. 9 mm

L/Bal. 5 mm

D.O.A. 5/4/18

D.O.I. 10/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/4 File pass to Catherine.

@ 635.12 (Red 22, 430.41, 977)

RECEIVED 12 APR 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

12/4- typist

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 ___ \$ + PS ___ \$

2 Photos

3 Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 635.12

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18006562/Kvd3

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 10-04-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 6306Z	Veh. Inspected	SHB 9695E
Policy No.		Coverage (\$)	0.00
Claim No.	C10001486	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	10/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/04/2018	Inspection Date	10/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Monday, 9 April 2018 5:52 PM
To: assignments
Cc: Julie Mangubat; SUR
Subject: Appoint LKK to conduct TP survey; Our Ref: C10001486
Attachments: img-409174550-0001.pdf

On behalf of Julie,

Hi Team,

Please accept assignment and liaise with TP workshop.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

-----Original Message-----

From: Candy Kong <candy.kong@transcab.com.sg>
Sent: Monday, 9 April, 2018 5:47 PM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: ARRANGE FOR SURVEY SHB9695E

Dear all ,

Please arrange for survey as below :

SLL6306Z - 05.04.2018 at 0658hrs - SHB9695E

Our lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs

Candy Kong

Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9695E
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000317
Chassis No.:	VF1ABL15AUC273106
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Jul 2013
First Registration Date:	18 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2021
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	17 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$21,239.00
Total Rebate Amount:	\$30,612.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2018 09:59
Date Of Accident	05/04/2018 06:55
Exact Location Of Accident	LOYANG VIEW SECONDARY SCHOOL CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB9695E
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	SHAMSURI BIN AHMAD
NRIC No	S6827494Z
Date Of Birth	27/07/1968
Occupation	OUTDOOR
Date Of Driving Pass	27/07/1968
Driving Experience	49 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91391577
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 161 SIMEI ROAD #04-300
Postcode	520161
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ADAM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHANGI N.P.C
Police Station Address	ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180406/2102

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	ADAM
Phone Number	98315421
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL6306Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	JANICE HAN CHIN WOON
NRIC/Passport Number	S7530305Z
Contact Number	90906097
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180406/2102

1 of 3

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

Report No. T/20180406/2102

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/04/2018 15:43		Vide Report No.: G/20180405/0058		Station Diary No.: 24	
Informant's Particulars					
Name of Informant: SHAMSURI BIN AHMAD			Address: APT BLK 161 SIMEI ROAD #04-300 SINGAPORE 520161		
ID Type / ID No.: NRIC NO / S6827494Z			Contact No.: Home/Office: Mobile: 91391577		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 27/07/1968	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/04/2018 07:00	Type of Location: SCHOOL CARPARK
Location: Along Road 1 PASIR RIS STREET 11 LOYANG VIEW SECONDARY SCHOOL, IN CARPARK COMPOUND				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

No. 9 Simei Street 2

Singapore 529914

Tel: 1800-5872999

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB9689Z SHB9695E	Car	RENAULT	LATITUDE	Red	Slightly Damaged	1
SLL6306Z	Car	HONDA	VEZEL	Red	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180406/2102

2 of 3

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

Report No. T/20180406/2102

CONTINUATION OF REPORT

Driver			
Name	SHAMSURI BIN AHMAD	ID No.	S6827494Z
Related Vehicle	SHB9689Z (Car)	Contact No.	91391577
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	JANICE HAN CHIN WOON	ID No.	S7530305Z
Related Vehicle	SLL6306Z (Car)	Contact No.	90906097
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date and time, I was sending a male student to the said school. My taxi was stationary and waiting for a car to reverse into a parking lot no. 10. Suddenly, this car was reversing and knocked onto my taxi's front right bumper portion. We came down of our vehicles and I tried to ask the driver about the accident but she just simply brushed me off, took some photos using her mobile phone, and walked away. I then called for Police assistance and both Police and Traffic Police came to scene. That was when the said driver came back down and we then managed to exchanged particulars. I also took some pictures of the scene using my mobile phone. I do have a witness (Adam, M/14, HP: 98315421) which is my passenger who was sitting at the front seat of my taxi, he is a student of the said school. The said driver could be the teacher from that school. I do not have any in-built car camera as that taxi was a temporary vehicle that I was using. I was advised by the officers to lodge a Police report thereafter.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999



T/20180406/2102

3 of 3

Report No. T/20180406/2102

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 LIONEL NEO SOON JIE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

06/04/2018 15:43

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Classification Of Case:

Authentication Stamp

NP168



**SINGAPORE
POLICE FORCE**

SIGNATURE

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9695E**AAD1804-067***Not Authorized
L1Bry @ 635.12*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9695E

VF1ABL15AUC273106

RENAULT

LATITUDE

5.4.2018

AUTO & GENERAL**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>N</i> 1,259.42 X
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41 X
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>CM</i> 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>N</i> 914.08
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61
14	1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>NA</i> 225.36
16	1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
17	1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79
19	1	HEADLAMP LH	\$	<i>SL</i> 1,184.43
20	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43
21	1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15
22	1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15
23	1	BONNET	\$	<i>N</i> 1,941.63
24	1	BONNET INSULATOR	\$	<i>SL</i> 405.73
25	1	BONNET STRUT LH	\$	<i>SL</i> 88.61
26	1	BONNET STRUT RH	\$	<i>SL</i> 88.61
27	1	BONNET HINGE LH	\$	<i>N</i> 348.31
28	1	BONNET HINGE RH	\$	<i>N</i> 348.31

Trans-cab Auto Services Pte Ltd

AAD1804-067

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9695E

29	1	BONNET CABLE COVER	\$	161.03 X
30	1	BONNET SEAL OUTER	\$	92.36 X
31	1	BONNET SEAL INNER	\$	157.28 X
32	1	FENDER PANEL FRT LH	\$	783.83 X
33	1	FENDER PANEL FRT RH	\$	783.83 X

TOTAL	\$	16,347.81
10%	\$	1,634.78
	\$	14,713.03

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00
2	1SET	BUMPER CLIP FRT	\$	66.00
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50
7	1	TOW COVER FRT	\$	14.50
8	1SET	RADIATOR GRILLE SCREW	\$	16.00
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
21	1	Windscreen moulding	\$	100.00
22	1SET	Front licence plate with holder	\$	80.00 15.00

TOTAL	\$	562.50
TOTAL PARTS	\$	15,275.53

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,450.00 15.00

To apply paint protection system (PPS) maintain and enhancement

\$ 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1804-067

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9695E

Putty and spray painting of the affected portion.	\$	2200.00
To rust-proofing of the affected areas.	\$	~ 170.00 X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	~ 170.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00 X
To replace, refix and top up coolant for radiator	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X

TOTAL \$ 7,790.00**Over All Total \$ 23,065.53****(LUMP SUM) Repair Days****7 DAYS****1 day**

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18006562/Kvd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 18-04-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 6306Z	Veh. Inspected	SHB 9695E
Policy No.		Coverage (\$)	0.00
Claim No.	C10001486	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273106	Colour	WHITE / RED
Odometer	645770	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	LING LONG	5 mm
L/H Rear Tyre	215/60 R16	LING LONG	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/04/2018	Inspection Date	10/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9695E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	CRACKED	266.80	266.80
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-

Report Ref No. CS/AGI18006562/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
	LESS 10% DISCOUNT		-1,634.78	-26.68
			14,713.02	240.12
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	DENTED	80.00	25.00
			562.50	25.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT,BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH,FENDER PANEL FRT LH AND FENDER PANEL FRT RH.		2,450.00	150.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	220.00

Report Ref No. CS/AGI18006562/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			7,790.00	370.00
GRAND TOTAL			23,065.52	635.12
RECOMMENDED COST OF REPAIRS				635.12

Report Ref No. CS/AGI18006562/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.