



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD TOYOTA WISH (SJT9576Y)

Date of Loss

December 28, 2017

Time of Loss

8.00

Loss Description

XD4940E (INSD) C/W SJT9576Y (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

06/26/2018



Days of work completion *

77



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJT9576Y

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

11/11/2009



Mileage

178958

Age of Vehicle

8

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2009

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

SJT9576Y LIM KIM HUN

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... WISH

ASSESSMENT INFO... WISH 2.0 AUTO

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... JTDGJ20W905001193

CATEGORY Date of Birth

FNOL INFORMATI... December 4, 1978

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI... 39

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... 3ZRA397441

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1987

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy



CATEGORY Address

FNOL INFORMATI... 62 TANAH MERAH KECHIL AVE, 465530,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7836609E

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

03/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/65R15

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

195/65R15

Front left side

CONTINENTAL7mm

Front right side

CONTINENTAL7mm

Rear left side

CONTINENTAL7mm

Rear right side

CONTINENTAL7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			O/S REAR BODY 1/4 PANEL			Buckled	752.21		25		564.16	Reviewing
		2	1			O/S REAR BODY 1/4 GLASS MOULDING			Necessary	73.25		25		54.94	Reviewing
		3	1			REAR BUMPER FASCIA			Damaged	1038.57		25		778.93	Reviewing
		4	1			REAR BUMPER O/S SIDE RETAINER			Broken	36		25		27	Reviewing
		5	1			O/S REAR DOOR			Buckled	1009.43		25		757.07	Reviewing
		6	1			O/S REAR DOOR OUTER HANDLE			Bent	63.7		25		47.78	Reviewing
		7	1			O/S REAR DOOR RUBBER			Damaged	143		25		107.25	Reviewing
		8	1			O/S REAR DOOR INNER LOCK ASSY			Damaged	415.3		25		311.48	Reviewing
		9	1			O/S REAR DOOR INNER LOCK CATCH			Bent	52.5		25		39.38	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		10	1			O/S REAR DOOR GLASS REGULATOR			Serviceable	0	0	25	0	0	Deny
		11	1			O/S REAR DOOR INNER TRIMBOARD			Serviceable	0	0	25	0	0	Deny
		12	1			SET O/S REAR DOOR WINDOW FRAME BLACK STICKERS			Necessary	158		25		118.5	Reviewing
		13	1			O/S REAR WHEEL HUB			Damaged	275.81		25		206.86	Reviewing
		14	1			O/S REAR SHOCK ABSORBER			Bent	267.65		25		200.74	Reviewing
		15	1			REAR AXLE BEAM ASSY			Serviceable	0	0	25	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
		1		REMOVE O/S REAR BODY 1/4 GLASS ASSY, TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME	60	0	0	Reviewing		
		2		REMOVE INTERIOR ROOF LINING ASSY, NECESSARY UPHOLSTERY'S AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT	100	0	0	Reviewing		
		3		REMOVE O/S REAR DOOR'S COMPLETE FITTINGS AND GLASS ASSY, CHECK, REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR AND REFIT	60	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
 	4		REMOVE LAMPS, NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK, REFIT SAME, TEST ELECTRICAL-CIRCUIT	30	0	0	Reviewing		
 	5		DISCONNECT REAR SUSPENSION ASSY, AND REAR AXLE BEAM ASSY, TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED PARTS AND REFIT SAME	200	0	0	Reviewing		
 	6		CHECK AND REALIGN WHEELS (COMPUTERISED)	60	0	0	Reviewing		
 	7		REMOVE DAMAGED PARTS, JACK AND CUT OUT DAMAGED BODY PANELS, JACK OUT, STRAIGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS,)	700	0	0	Reviewing		
 	8		WHICHEVER POSSIBLE AND NECESSARY, REPLACE AND WELD NECESSARY DAMAGED PARTS, REFIT AND ALIGN WHICHEVER PARTS NECESSARY (INCL ALIGNMENT OF BODY STRUCTURE)}	0	0	0	Reviewing		
 	9		PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE (CHEMICAL PEARL PAINT)	800	0	0	Reviewing		
 	10		RUSTPROOF REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS	70	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
		2	SET O/S REAR BODY 1/4 PANEL INNER TRIMCOVER CLIPS	Reviewing	42	NECESSARY	
		3	O/S REAR BODY 1/4 GLASS SEALANT	Reviewing	50	NECESSARY	
		4	SET REAR BUMPER CLIPS	Reviewing	35	NECESSARY	
		5	BODY PANEL JOINT SEALANT	Reviewing	40	NECESSARY	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		6	SET O/S REAR DOOR INNER TRIMBOARD CLIPS	Reviewing	42	NECESSARY	
☐		7	O/S REAR ALLOY WHEEL RIM	Reviewing	300	DENTED	
☐		8	O/S REAR TYRE	Reviewing		NOT NECESSARY	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$5,803.09

Claim Amount\$5,803.09

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,080.00	\$2,080.00
Miscellaneous	\$509.00	\$509.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	4600		

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$4,600.00

Claim Amount\$4,600.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$4,600.00	\$4,600.00

Submit for Review