

22/03/2012

ASS. REC. BY:

REF: CS/ICS18006627/Tlvdsb

Special Instruction:

Surveyor:  
MUMIN

ASSIGNMENT (Office)

From (Person): Junice Goh of ICS Date/Time: 10/4/18 @ 5:33pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 3655L Insured: SJG 5026M

at Workshop m/s: MORA Automotive Tel: 6272 3892

of 15 Fan Yong Road

Policy No: Claim No: \* DMPU1800042H

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 06/04/2018

CA / REV / REP. / REV 24 HRS (w/p) 1110418 H.O.D. Endorsement:

Date/Time: 5:49pm @ 10/4/18 Person Contacted: Nitha Vehicle:  IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	SKN 3655L - X
	SJG 5026M - X
5/6/18	@ 358pm Alan will email us finalised
7/6/18	Final fig. \$5535 confirmed by email (Reel 1215, 1892)

Biregular

Tanjong

REF: ECICS

ASSIGNMENT

From: \_\_\_\_\_ Date: 11/4/18

Estimated Cost: \_\_\_\_\_

OD  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 3655L

at Workshop m/s MOVA

of 15 Fan Yong Rd

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SKN 3655L Yr Regn: 2014 June

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_

Make: Toyota A11s C.C. 1598

Colour: 81/wh A/C: Insured / Std / NI / NA

Sp. Reading: 86821 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MROS3REH104509905

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Tyre Size: F: 25/55R15  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_

Front R/Bal. 6 mm  
L/Bal. 6 mm  
D.O.A. \_\_\_\_\_

Rear R/Bal. 6 mm  
L/Bal. 6 mm  
D.O.I. 12/4/18 or 17/5

Survey held at Mova Fan Yong

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Roof top or \_\_\_\_\_

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

*[Signature]*  
7/6/2018

RECEIVED 08 JUN 2018

Date/Time File Pass to?  : Preli. Report  
 : Final Report

1) \_\_\_\_\_

Date/Time File Return to? 8/6- typist

2) \_\_\_\_\_

Report Format: merimen

Lump Sum / I.B.I: (\$) 5535/-

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)

Survey Fee: 250

Transportation: \_\_\_\_\_ \$ + RS \_\_\_\_\_ \$

Photos: \_\_\_\_\_

Others: \_\_\_\_\_

TOTAL: 260



**Veron Chen (LKKAuto)**

---

**From:** motorsurvey <motorsurvey@ecics.com.sg>  
**Sent:** Friday, 13 April 2018 12:17 PM  
**To:** Veron Chen (LKKAuto); motorsurvey  
**Cc:** SUR  
**Subject:** RE: TP CLAIMS - SKN3655L AGAINST SJG5026M DOA 06.04.18 AT PIE TOWARDS TUAS

Dear Veron

Our ref DMPU1800042H.  
Thank you!

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY**, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Friday, 13 April, 2018 12:11 PM  
**To:** motorsurvey; Janice Goh Siew Geok (ECICS, Claims)  
**Cc:** SUR  
**Subject:** RE: TP CLAIMS - SKN3655L AGAINST SJG5026M DOA 06.04.18 AT PIE TOWARDS TUAS

Dear Janice,

Please provides us claim number.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 10 April 2018 5:49 PM  
**To:** 'motorsurvey' <motorsurvey@ecics.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: TP CLAIMS - SKN3655L AGAINST SJG5026M DOA 06.04.18 AT PIE TOWARDS TUAS

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** motorsurvey [<mailto:motorsurvey@ecics.com.sg>]

**Sent:** Tuesday, 10 April 2018 5:33 PM

**To:** nitha <[nitha@moval.com.sg](mailto:nitha@moval.com.sg)>; ASSIGNMENTS@LKKAUTO.COM; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** 'Enny' <[enny@moval.com.sg](mailto:enny@moval.com.sg)>; 'Alan Chng' <[tuckmeng@moval.com.sg](mailto:tuckmeng@moval.com.sg)>; ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>; motorsurvey <[motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)>

**Subject:** RE: TP CLAIMS - SKN3655L AGAINST SJG5026M DOA 06.04.18 AT PIE TOWARDS TUAS

Without Prejudice

Dear Nitha

Thank you for your email.  
We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,

Janice Goh

**Claims Division**

DID: +65 6303 0182

FAX: +65 6338 9267

**ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

**From:** nitha [<mailto:nitha@moval.com.sg>]

**Sent:** Tuesday, 10 April, 2018 5:37 PM

**To:** ECICS Claims; motorsurvey

**Cc:** 'Enny'; 'Alan Chng'

**Subject:** TP CLAIMS - SKN3655L AGAINST SJG5026M DOA 06.04.18 AT PIE TOWARDS TUAS

Dear Sir/Madam,

Good day

REF : SJG5026M


Kindly assist revert officer in charge and arrange survey for the above mention vehicle.

Vehicle already lying at our workshop (Fan Yoong).

Best Regards,

*Nitha*

Claims Officer  
Mova Automotive Pte Ltd  
Tel: 6272 3892 Fax: 6270 8314



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## Nivitha (LKK Auto)

---

**From:** motorsurvey <motorsurvey@ecics.com.sg>  
**Sent:** Tuesday, 10 April 2018 5:33 PM  
**To:** nitha; ASSIGNMENTS@LKKAUTO.COM; Admin A  
**Cc:** 'Enny'; 'Alan Chng'; ECICS Claims; motorsurvey  
**Subject:** RE: TP CLAIMS - SKN3655L AGAINST SJG5026M DOA 06.04.18 AT PIE TOWARDS TUAS  
**Attachments:** RPT.PDF; EST.PDF

Without Prejudice

Dear Nitha

Thank you for your email.  
We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

---

**From:** nitha [mailto:nitha@mova.com.sg]  
**Sent:** Tuesday, 10 April, 2018 5:37 PM  
**To:** ECICS Claims; motorsurvey  
**Cc:** 'Enny'; 'Alan Chng'  
**Subject:** TP CLAIMS - SKN3655L AGAINST SJG5026M DOA 06.04.18 AT PIE TOWARDS TUAS

Dear Sir/Madam,  
Good day

REF : SJG5026M  
Kindly assist revert officer in charge and arrange survey for the above mention vehicle.  
Vehicle already lying at our workshop (Fan Yoong).

Best Regards,  
Nitha

Claims Officer  
Mova Automotive Pte Ltd  
Tel: 6272 3892 Fax: 6270 8314



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## Alan Chng

---

**From:** Enny [enny@mova.com.sg]  
**Sent:** Saturday, 7 April 2018 2:56 PM  
**To:** 'Alan Chng'  
**Subject:** RE: TP ECICS - SKN3655L

Hi Alan,

The vehicle left passenger door (below) and front bonnet got damage, owner ask can do f.o.c or not. If not please kindly call him and give him a quote. Thanks

Thank you

Best Regards,

*Enny Lee*

Claims Executive  
Mova Automotive Pte Ltd  
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

---

**From:** Enny [mailto:enny@mova.com.sg]  
**Sent:** Saturday, 7 April 2018 2:35 PM  
**To:** 'Alan Chng'  
**Subject:** TP ECICS - SKN3655L

Dear Alan,

Please submit tp ecics. Thanks

Thank you

Best Regards,

*Enny Lee*

Claims Executive  
Mova Automotive Pte Ltd  
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
 Owner ID: 3069F

**Vehicle Details**

Vehicle No.: SKN3655L  
 Vehicle to be Exported: Yes  
 Intended De-registration Date: 09 Apr 2018  
 Vehicle Make: TOYOTA  
 Vehicle Model: TOYOTA COROLLA ALTIS 1.6L CVT  
 Primary Colour: Silver  
 Manufacturing Year: 2014  
 Engine No.: 1ZRY059605  
 Chassis No.: MR053REH104509905  
 Maximum Power Output: 90.0 kW (120 bhp)  
 Open Market Value: \$18,761.00  
 Original Registration Date: 05 Jun 2014  
 First Registration Date: 05 Jun 2014  
 Transfer Count: 0  
 Actual ARF Paid: \$13,761.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 04 Jun 2024  
 PARF Rebate Amount: \$10,320.00

**Intended COE Rebate Details**

COE Expiry Date: 04 Jun 2024  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Period(Years): 10  
 QP Paid: \$65,689.00  
 COE Rebate Amount: \$40,422.00  
**Total Rebate Amount: \$50,742.00**

The information contained herein is correct as at 09 Apr 2018

OK

TPFCIS

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	07/04/2018 13:27
Date Of Accident	06/04/2018 21:25
Exact Location Of Accident	ALONG PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SKN3655L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOH SOON DEE
NRIC No	S1103069F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90069043
Alternative Phone No	OTHERS-90069043

**Vehicle Particulars**

Manufacturer	TOYOTA
Model	TOYOTA COROLLA ALTIS 1.6L CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

**Insurance Company**

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA225089/1
Cover Note Number	

**Driver**

Name of Driver	GOH SOON DEE
NRIC No	S1103069F
Date Of Birth	25/05/1955
Occupation	INDOOR
Date Of Driving Pass	10/05/1975
Driving Experience	42 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90069043
Fax Number	
Contact Number	OTHERS-90069043
EMail Address	NOEMAIL

Address	BLK 219 JURONG EAST ST 21 #08-607
Postcode	600219
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHUA GUAT HWA GENDER: : FEMALE
Passenger 2	NAME: : CHERVELLE NG GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG5026M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHIAM SWEE PHUANG
NRIC/Passport Number	S2174943E
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SKN 3655 L	ACCIDENT DATE & TIME: 6/4/18
CONTACT NUMBER: 90069043	E-MAIL ADDRESS:
LOCATION: PIE TOWARDS THAS.	
<p>MY CAR WAS TRAVELLING ALONG PIE AND SUDDENLY THE CAR INFRONT BRAKE SO I ALSO BRAKE BEHIND THE OTHER CAR AND STOP ABOUT 2 METERS AWAY. AND AFTER ABOUT 6 SECONDS LATER MY CAR WAS BRAG BY SJG 5026M AND JERK FORWARDS. LUCKY I WAS ALERT AND ADLY BRAKE AND JUST STOP BEHIND THE OTHER CAR.</p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Automotive Pte Ltd

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

10/04/2018

ECICS LIMITED

7 Temasek Boulevard,  
#10-01 Suntec Tower One,  
Singapore 038987.

Attention :- ECICS

Page # :- 1

Veh # :- SKN3655L

Veh Model :- TOYOTA ALTIS

Estimate# :- CK417334

Claim # :-

ACC. Date :- 06/04/18

Terms :- C.O.D Days

Remarks :- Alan 96869276

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	REAR BUMPER	1 PC	550.00	550.00 <i>del</i>
2.	REAR BUMPER SIDE RETAINER	2 PC	120.00	240.00 <i>nel</i>
3.	REAR BUMPER REINFORCEMENT	1 PC	395.00	395.00 <i>bt</i>
4.	REAR BUMPER CLIPS	10 PC	5.50	55.00 <i>ren</i>
5.	BOOT LID	1 PC	760.00	760.00 <i>bl</i>
6.	BOOT LID LOCK <i>check price 260</i>	1 PC	400.00	400.00 <i>bt</i>
7.	BOOT LID REFLECTOR LAMP LH	1 PC	350.00	350.00 <i>one</i>
8.	BOOT LID LOGO	1 PC	70.00	70.00 <i>nel</i>
9.	BOOT LID (ALTIS) EMBLEM	1 PC	60.00	60.00 <i>nl</i>
10.	BOOTLID (COROLLA) EMBLEM	1 PC	60.00	60.00 <i>nl</i>
11.	TAILLAMP LH	1 PC	395.00	395.00 <i>av</i>
12.	TAILLAMP BOTTOM BRACKET LH	1 PC	90.00	90.00 <i>nel</i>
13.	TRUCK LID WETAHRESTRIP	1 PC	195.00	195.00 <i>fw</i>
14.	END PANEL GARNISH	1 PC	250.00	250.00 <i>bt</i>
15.	END PANEL ASSY	1 PC	590.00	590.00 <i>del</i>
16.	FLOOR PANEL BOARD	1 PC	250.00	250.00 <i>Rx</i>
17.	REAR PARKING SENSOR	1 PC	350.00	350.00 <i>non</i>
LIST TOTAL SS				5,060.00
25% DISCOUNT SS				-1,265.00
				<u>3,795.00</u>
<b>SPECIAL NET ITEMS :</b>				
1.	REAR NUMBER PLATE	1 PC	50.00	50.00 <i>45</i>
2.	ACCIDENT TOWING TO FAN YOONG	1 PC	55.00	55.00
SPECIAL NET TOTAL SS				<u>105.00</u>
<b>LABOUR :</b>				
TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST				20 40.00
TO REMOVE & INSTALL REAR COMPARTMENT GARNISH CARPET & ETC IN ORDER TO CUT OFF END PANEL				60 200.00
TO CUT OFF END PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS				700 900.00
TO APPL BODY JOINT SEALANT ON CUTTING AREAS				40 60.00
TO APPLY RUST PROOF ON AFFECTED AREAS				50 100.00
TO SPRAY PAINT ON REPLACED, REPAIRED AREAS				800 1,200.00
LABOUR TOTAL SS				<u>2,500.00</u>



Automotive Pte Ltd

Main Office:

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

Workshop Dept:

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

10/04/2018

ECICS LIMITED  
7 Temasek Boulevard,  
#10-01 Suntec Tower One,  
Singapore 038987.

Page # :- 1 131316  
Veh # :- SKN3655L  
Veh Model :- TOYOTA ALTIS  
Estimate# :- CK417334  
Claim # :-  
ACC. Date :- 06/04/18  
Terms :- C.O.D Days  
Remarks :-

Attention :- ECICS

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	6750
AMOUNT S\$	6,400.00
GST @ 7 %	448.00
AMOUNT DUE S\$	6,848.00

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanjoh 97495749  
up  
12/4/18 @ 1715  
Resurvey before paint  
7 days  
9 suv @ (kikanto.com)

30/5/18

6662.50

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 7 June 2018 9:53 AM  
**To:** Shu Pei (LKKAuto); Alan Chng; Taufikh (LKKAuto)  
**Cc:** Admin A; SUR  
**Subject:** RE: finalization for vhe no:SKN3655L

Dear Alan,

WITHOUT PREJUDICE

Confirmed finalize amount \$5535 before GST @ 7 working days.

**Final invoice and all supporting documents sent over to ECICS**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAuto)  
**Sent:** Wednesday, 6 June 2018 5:03 PM  
**To:** Alan Chng <tuckmeng@mova.com.sg>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** FW: finalization for vhe no:SKN3655L

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CS/ICS18006627/T1vd3	Taufikh /Veron

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Alan Chng [<mailto:tuckmeng@mova.com.sg>]

Sent: Wednesday, 6 June 2018 4:43 PM  
To: Taufikh (LKKAuto) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>  
Cc: Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
Subject: finalization for vhe no:SKN3655L

Dear Taufikh,

Please refer the attach estimate & all photos FYI.  
Repair cost P/P \$5535 & 7 working days.  
Please confirm and return by email ASAP.  
Thanks!

Best Regards  
Alan Chng  
Claims Estimator  
Mova Automotive Pte Ltd  
H/P 9686 9276  
Office No:6262 3377  
Fax No:6264 3151



# 5535  
7 days

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0068864-2

**Estimate**

10/04/2018

ECICS LIMITED

7 Temasek Boulevard,  
#10-01 Suntec Tower One,  
Singapore 038987.

Page # :- 1  
Veh # :- SKN3655L  
Veh Model :- TOYOTA ALTIS  
Estimate# :- CK417334  
Claim # :-  
ACC. Date :- 06/04/18  
Terms :- C.O.D Days  
Remarks :-

Attention :- ECICS

Alan 96869276

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :				
1.	REAR BUMPER	1	550.00	550.00 <i>de</i>
2.	REAR BUMPER SIDE RETAINER	2	120.00	240.00 <i>nel</i>
3.	REAR BUMPER REINFORCEMENT	1	395.00	395.00 <i>bt</i>
4.	REAR BUMPER CLIPS	10	5.50	55.00 <i>ner</i>
5.	BOOT LID	1	760.00	760.00 <i>bl</i>
6.	BOOT LID LOCK	1	<del>400.00</del> ?	<del>400.00</del> 260 <i>av</i>
7.	BOOT LID REFLECTOR LAMP LH	1	350.00	350.00 <i>av</i>
8.	BOOT LID LOGO	1	70.00	70.00 <i>nh</i>
9.	BOOT LID (ALTIS) EMBLEM	1	60.00	60.00 <i>nl</i>
10.	BOOTLID (COROLLA) EMBLEM	1	60.00	60.00 <i>nh</i>
11.	TAILLAMP LH	1	395.00	395.00 <i>av</i>
12.	TAILLAMP BOTTOM BRACKET LH	1	90.00	90.00 <i>ner</i>
13.	TRUCK LID WETAHRESTRIP	1	195.00	195.00 <i>ner</i>
14.	END PANEL GARNISH	1	250.00	250.00 <i>bt</i>
15.	END PANEL ASSY	1	590.00	590.00 <i>de</i>
16.	FLOOR PANEL BOARD	1	250.00	250.00 <i>R</i>
17.	REAR PARKING SENSOR	1	350.00	350.00 <i>ner</i>
	LIST TOTAL S\$			5,060.00
	25% DISCOUNT S\$			-1,265.00
				3,795.00

RH670

SPECIAL NET ITEMS :				
1.	REAR NUMBER PLATE	1	50.00	50.00 <i>nh</i>
2.	ACCIDENT TOWING TO FAN YOONG	1	55.00	55.00 ✓
	SPECIAL NET TOTAL S\$			105.00

SIN-100

LABOUR :				
	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST			20 40.00
	TO REMOVE & INSTALL REAR COMPARTMENT GARNISH CARPET & ETC IN ORDER TO CUT OFF END PANEL			80 200.00
	TO CUT OFF END PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS			700 900.00
	TO APPL BODY JOINT SEALANT ON CUTTING AREAS			40 60.00
	TO APPLY RUST PROOF ON AFFECTED AREAS			50 100.00
	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS			800 1,200.00
	LABOUR TOTAL S\$			2,500.00

Supplementary Parts.

1) Boot lid reflector lamp RH = \$350 (A) out ✓

LC-1670



Automotive Pte Ltd

Main Office: Mova Building, No. 22, Jalan Kilang, Singapore 159419. Tel: (65) 6476 3333, Fax: (65) 6271 5891, www.mova.com.sg

Workshop Dept: Block 1008, Bukit Merah Lane 3, #01-04/06/08/94, Singapore 159722

Tel: (65) 6272 3892, Fax: (65) 6270 8314

Co. Reg. 198904033G, GST Reg. M2-0088864-2

Estimate

10/04/2018

ECICS LIMITED, 7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987.

Attention :- ECICS

Page # :- 1 131316
Veh # :- SKN3655L
Veh Model :- TOYOTA ALTIS
Estimate# :- CK417334
Claim # :-
ACC. Date :- 06/04/18
Terms :- C.O.D Days
Remarks :-

No. Description Qty U.Price Amounts S\$

E. & O.E

Handwritten signature

NON-TAX AMOUNT S

AMOUNT S\$ 6,400.00

GST @ 7 % 448.00

AMOUNT DUE S\$ 6,848.00

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Handwritten list of items: P-4670, P-350 - Supply, P-5020 - 2SE, P-3765, SN-100, LC-1670, 5535

Handwritten notes: Tanjin 9749749, up, 12/4/18 R 1715, Recovery before paint, 7 days, q suv@kikanto.com

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jun 2018 17:27 <a href="#">Edit Reg</a>		10 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,535.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,535.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: <b>GOH SOON DEE</b> , ID: S1103069F									
Vehicle Reg. No.:	<b>SKN3655L</b>	Date of Loss:	06/04/2018 21:00 - :59 [46 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SJG5026M</b>	Policy No. (Claimant):							
		Excess:							
Repairer: <b>Mova Automotive Pte Ltd (FAN YOONG BRANCH)</b> 15 Fan Yoong Road, CNG Singapore Centre, 629792 Boon Lay - Tel:									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 24/04/2018]									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SKN3655L**  
**[SJG5026M]**  
**TP**  
**GOH SOON DEE**  
**Apr 6 2018 9:00PM**  
**[-]**  
**Mova Automotive Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View	View in Browser <input type="checkbox"/>
<b>Photos/Images</b>			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/06/18 17:17	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/18 17:17	General View	Load JPG	<input checked="" type="checkbox"/>
39	06/06/18 17:17	General View	Load JPG	<input checked="" type="checkbox"/>
40	06/06/18 17:17	General View	Load JPG	<input checked="" type="checkbox"/>
41	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	06/06/18 17:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18006627/T1VD3E2

Date: 13/06/2018

#### REFERENCE

Handling Insurer: ECICS Limited	Policy No:			
<b>Claimant Vehicle No :</b> SKN3655L	<b>Insured Vehicle No :</b>	SJG5026M		
Date of Loss: 06/04/2018	Nature of Claim:	TP	Claim No:	N/A

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKN3655L</b>		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Engine No:	1ZRY059605
Reg. Date:	05/06/2014 (Man. Year: 2014)	Chassis No:	MR053REH104509905
Colour:	Silver	Odometer:	86821 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,107.50	3,810.00	297.50	7.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,555.00	1,725.00	830.00	32.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,662.50</b>	<b>5,535.00</b>	<b>1,127.50</b>	<b>16.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>466.38</b>	<b>387.45</b>	<b>78.93</b>	<b>16.92</b>
<b>Nett Amount (S\$)</b>	<b>7,128.88</b>	<b>5,922.45</b>	<b>1,206.43</b>	<b>16.92</b>

#### INSPECTION

Date of Assignment:	10/04/2018	
Date Inspected:	12/04/2018 Inspected At:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre Singapore 629792
Estimated Period of Repair:	7.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2018)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKN3655L)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	550.00 FL	*550.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	240.00 FL	*240.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*395.00 FL
4	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
5	1		*BOOT LID	Bent	760.00 FL	*760.00 FL
6	1		*BOOT LID LOCK	Bent	400.00 FL	*260.00 FL
7	1		*BOOT LID REFLECTOR LAMP LH	Cracked	350.00 FL	*350.00 FL
8	1		*BOOT LID LOGO	Necessary	70.00 FL	*70.00 FL
9	1		*BOOT LID (ALTIS) EMBLEM	Necessary	60.00 FL	*60.00 FL
10	1		*BOOTLID (COROLLA) EMBLEM	Necessary	60.00 FL	*60.00 FL
11	1		*TAILLAMP LH	Cracked	395.00 FL	*395.00 FL
12	1		*TAILLAMP BOTTOM BRACKET LH	Necessary	90.00 FL	*90.00 FL
13	1		*TRUCK LID WEATHERSTRIP	Twisted	195.00 FL	*195.00 FL
14	1		*END PANEL GARNISH	Bent	250.00 FL	*250.00 FL
15	1		*END PANEL ASSY	Deformed	590.00 FL	*590.00 FL
16	1		*FLOOR PANEL BOARD	Repair	250.00 FL	*- FL
17	1		*REAR PARKING SENSOR	Not Working	350.00 FL	*350.00 FL
18	1		*REAR NUMBER PLATE	Missing	50.00 FS	*45.00 FS
19	1		*BOOTLID REFLECTOR LAMP RH	Cut	350.00 FL	*350.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,460.00</b>	<b>5,065.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,352.50	1,255.00
<b>Total Parts (S\$)</b>	<b>4,107.50</b>	<b>3,810.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ACCIDENT TOWING TO FAN YOUNG	New	55.00	55.00
2	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST	New	40.00	20.00
3	TO REMOVE & INSTALL REAR COMPARTMENT GARNISH CARPET & ETC IN ORDER TO CUT OFF END PANEL	New	200.00	60.00
4	TO CUT OFF END PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS	New	900.00	700.00
5	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00	40.00
6	TO APPLY RUST PROOF ON AFFECTED AREAS	New	100.00	50.00
7	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,200.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,555.00</b>	<b>1,725.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >