

INS. CASE OWNER:

Lynthia.

CC 4 RSM
AXA1800

6679, F Wb352

CKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

10/4/18

Date / Time:

11/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBE 4293U

Claim No.:

88M0006X / 31155

Name of Insured:

RASA RASA GROUP CATERING SERVICES

Policy No.:

GAR40751

Insured Tel No.:

HP:

Make / Model:

Tumpu

Excess Sec II :\$S

D.O.A:

04/04/18

Place of Accident:

MAMON RO

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

RAMNATHAN THIRUPATHI

OI GIA REPORT:

YES / NO

TP GIA REPORT:

YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SKD1319Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

Alan's



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
11/4/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OE:	13/10/18
	After call ltr to OE:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OE:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD:	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐
11/4/18	RECEIVED 05 DEC 2018	
13/4/18	Smartclaim.	
	the validity of the v/c. " " pls obtain evidence & liaise with O.I."	
	Receive video from TP	
13/4/18	called OAD'S Boss Mr Sebe. Confirm accident details. Inform TP claim, inform we receive CCTV from TP. agree to settle. letter send out	
20/4/18	File pass to typist type report	
16/11/18, 30/11/18	Sebe made via SMART	
3/12/18	Mandate approve via SMART	
PRELIMINARY ADVICE	Date/Time: 11/4/18	Sent By: [Signature]
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$S (days) Reduction:	%
FINAL SETTLEMENT	Date/Time: 4/12/18	Confirm with: [Signature]
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.:	15
Repair Cost:	\$S 13910.00	
Loss of Rental (LOR):	\$S (days)	
Loss of Use (LOU):	\$S 800.00 (\$80 x 10 days)	
Loss of Income (LOI):	\$S (S x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	\$S 2.00	
Medical:	\$S -	
Disbursement:	\$S -	(e.g. Tow/ Independent)
Legal Cost	\$S -	
Total:	\$S 14712.00	Global Sum \$S:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S 14712.00	Name 1: Alan's united Auto Pte Ltd
Payee 2: (Strike if N.A.)	\$S	Name 2:
Payee 3: (Strike if N.A.)	\$S	Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee:

ASS. REC. BY:

REF:

Add /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

102%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKD 13197

Yr Regn:

04, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mw E200

c.c.

1796

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

123547

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 212 04 82A 391788

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Mic

245/45 ER17

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

4

mm

L/Bal.

5

mm

L/Bal.

4

mm

D.O.A.

7/4/18

D.O.I.

10/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/4

File pass to Cethum

20/4/18

Confirm LIS \$13000.00 with 6 working days

(Ad \$ 3781.48

23.1)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18006679/Kwb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 11-04-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 4293U		Veh. Inspected	SKD 1319Z
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	11/04/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/04/2018		Inspection Date	10/04/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05761

Vehicle Insured : GBE4293U

Accident Date : 07-Apr-2018

Date : 10-Apr-2018

Our Ref : 218065 (AXA) / CHAN

PAGE : 1

TAN YEW HUAT

BLK 753 WOODLANDS CIRCLE

#07-552

Singapore 730753

*Not Authored
11 Sep @ 1300
Resurvey After Painting*

6 days

ESTIMATED COST OF REPAIR FOR M/BENZ E200 CGI SKD1319Z

=====

1 pc Bonnet		R 2,575.00	✓
1 pc Bonnet insulator		S 291.00	X
1 pc O/s bonnet inner lock		D 138.00	✓
2 pcs Bonnet hinge	@ S\$164.00	D 328.00	✓
2 pcs Bonnet emergency activator	@ S\$447.00	A 894.00	✓
1 pc Bonnet lock release handle		R 28.00	X
2 pcs Bonnet damper	@ S\$161.00	S 322.00	✓
2 pcs Bonnet spring stopper	@ S\$ 37.00	S 74.00	✓
2 pcs Headlamp asst	@ S\$1268.00	2,536.00	✓
2 pcs Headlamp clip	@ S\$ 18.00	36.00	✓
1 pc O/s headlamp top panel		R 282.00	✓
1 pc O/s headlamp lower panel		D 56.00	✓
1 pc Front o/s fender inner shield		D 215.00	✓
8 pcs Fender inner shield rivet	@ S\$ 3.80	M 30.40	✓
1 pc Front o/s fender		R 1,134.00	✓
1 pc Front bumper fascia		T 1,585.00	✓
1 pc Front bumper reinforcement		R 583.00	✓
1 pc O/s reinforcement bracket		R 342.00	✓
1 pc Front o/s bumper sponge		C 58.00	✓
1 pc Front bumper sponge (centre)		C 117.00	✓
1 pc Front o/s bumper side retainer		D 18.00	✓
1 pc Front o/s bumper foglamp		C 246.00	✓
1 pc Front bumper day running lamp		C 125.00	✓
2 pcs Front bumper foglamp chrome	@ S\$ 45.00	M 90.00	✓
1 pc Front o/s bumper foglamp grille		M 45.00	✓
1 pc Front bumper foglamp bracket		R 51.00	✓
1 pc Front bumper tow cover		M 86.00	✓
2 pcs Front bumper lower side chrome	@ S\$ 98.00	M 196.00	✓

*o/s CM
old m*

WISCR

*14335.20
10/19.68*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE4293U

Page : 2

1 pc	Front bumper lowe grille	56.00	*	✓
3 pcs	Front o/s bumper parking sense @ S\$279.00	837.00	*	✓
1 pc	Front parking sensor wire(set)	281.00	*	
1 pc	Front bumper cover	248.00	X	
2 pcs	Front bumper side inner parts @ S\$ 75.00	150.00	✓	
1 pc	Front bumper centre inner part	85.00	✓	
16 pcs	Front bumper inner part revit @ S\$ 3.80	60.80	✓	
1 pc	Radiator support panel	196.00	X	
1 pc	Support panel top cover	186.00	X	
1 pc	O/s horn	199.00	✓	
		14,780.20		
		Less 10% :	1,478.02	

13,302.18

To rewire damaged parts and refocus headlamp beam, daynositce headlamp

150.00 Sol

To remove air con condenser, pipes and drier, vacuum and to recharge

120.00 X

To apply undersealing

60.00 Sol

To putty and spray replaced parts

1,100.00 900

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

900.00 700

Total : S\$15,632.18

Singapore Dollars Fifteen Thousand Six Hundred and Thirty Two and Cents Eighteen Only

16781.48

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE4293U (AXA)

Accident Date : 07-04-2018

Date : 10-04-2018

Our Ref : 218065 / CHAN

TAN YEW HUAT

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR M/BENZ E200 CGI SKD1319Z

1 PC RADIATOR GRILLE ASSY

CM \$1,277.00 ✓
LESS 10% \$127.70
\$1,149.30

Singapore Dollars One Thousand One Hundred Forty Nine And Cents Thirty Only

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

<< Service Request Details

Claim

S8M00DGX

Reference

None 

Loss Date

April 7, 2018

Request Date

April 10, 2018

Due Date

April 17, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

11.04.2018 @ 1051am
Kenny veh in
Kenneth

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKD1319Z

Make

TPVD MERCEDES-BEN

Service Address

...

Primary Contact/Insured

RASA RASA GROUP CATERING SERVICES LLP
8A ADMIRALTY STREET, #04-08, 757437, Singapore
65113025
JOEY.LIM@ALPINECREDIT.COM.SG

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

4/10/18 11:38 AM

FROM

LOH Cynthia

SUBJECT

Please proceed DS

BODY

Please assist:- (1) check the validity of ID's D/L...





Re:RE: S8M00DGX-mandate approval

Type

🔔 Question

Message

MANDATE APPROVED

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBE 4293U (Insd veh)	Model:	MERCEDES BENZ
	SKD 1319Z (TP veh)		E 200CGI
Date of Accident:	07/04/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	17,956.18
Final Repair Cost	:	\$	13,910.00
Loss of Use	:	\$	800.00
			10 days at \$80.00 per day
Rental (if any)	:	\$	
			days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	14,712.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	ALAN'S UNITED AUTO PTE. LTD.	:	\$ 14,712.00

NUR SHAQILAH BTE ABDOL
WAHAB

12/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim

S8M000GX

Reference

CC4/ASM1800679/Kw3s2 

Request Date

April 7, 2018

Due Date

April 10, 2018

Vendor Name

April 11, 2019

Type of Loss

LKK AUTO CONSULTANTS PTE LTD (TP)

Services

Third Party Vehicle Damage

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

Document Type

Document SubType

Upload Documents

Vehicle Information

Incident Vehicle Registration #

SKD1319Z

Make

Service Address

TPVD MERCEDES-BEN

Model

E200

Primary Contact/Insured

RASA RASA GROUP CATERING SERVICES LLP

8A ADMIRALTY STREET, #04-08, 757437, Singapore

65113025

JOEY.LIM@ALPINECREDIT.COM.SG

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

NAME

TYPE

REPORTS & STATEMENT

OTHERS

DATE UPLOADED

MARKED ESTIMATE.pdf

Reports & Statement

Others

November 16, 2018

Messages

Invoices

History

Documents

Assessment

Melrics

Notes

<< Service Request Details

Claim

S8M00DGX

Reference

CC4IASM18006679Kwb3s2 

Loss Date

April 7, 2018

Request Date

April 10, 2018

Due Date

April 11, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

More

Auto

Vehicle Information

Incident Vehicle Registration #

SKD1318Z

Make

TPVD MERCEDES-BEN

Model

E200

Primary Contact/Insured

RASA RASA GROUP CATERING SERVICES LLP
8A ADMIRALTY STREET, #04-08, 757437, Singapore
65113025
JOEY.LIM@ALPINECREDIT.COM.SG

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

STATUS

SHARE

CLONE

CREATED USER

VERSION DATE

ESTIMATED AMOUNT

APPROVED AMOUNT

Open

Close

User Portal

5/28/18 8:59 AM

13000

13000

Open

Close

<< Assessment Details

General & Workshop Details	Vehicle & Driver Details	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Vehicle & Driver Details					
Vehicle Registration#	SKD1319Z	Purchase Date	mm/dd/yyyy		
Registration State	SINGAPORE	Registration Date *	04/25/2011		
Mileage	123547	Age of Vehicle	6		
Driver Details					
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FINL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year		2010	Driver Name	TAN GUAN YU	
Make	TPVD MERCEDES-BEN	MERCEDES BENZ	Date of Birth	December 18, 1995	mm/dd/yyyy
Model	E200	E 200CGI	Age	22	
Type			Occupation	Unknown	
Type of Paint			Education Qualification	Other	
Chassis No		WDD2120482A391798	Driving Experience	0	
Engine No		27186030192663	Driver License #		
Engine Capacity		1796 cc	License Type		

<< Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary	
Detailed Assessment													
Inspection Date *				04/10/2018				Condition of Vehicle at time of survey					
Total Loss				Yes		No		General condition		Good			
Towing Charges				0				Steering (Serviceable)		Yes		No	
Voluntary Excess				0				Footbrake (Serviceable)		Yes		No	
Compulsory Excess				0				Handbrake (Serviceable)		Yes		No	
Young/Inexperienced/Unlicensed Driver Excess				0				Engine Modification		Yes		No	
Other Excess								Pre-accident condition		Good			
Tyre Condition													
Age of Tyres								Spare wheel					
Front Tyre Size				245/45ZR17				Rear Tyre Size		245/45ZR17			
Front left side				MICHELIN 5mm				Rear left side		DUNLOP 4mm			
Front right side				MICHELIN 5mm				Rear right side		DUNLOP 4mm			

Assessment Details

General & Workshop Details				Vehicle Condition		Taxes & Rate		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	EST PRICE	DEPR/ BTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			BONNET			Bent	2575		10		2317.5	Reviewing	
	2	1			BONNET INSULATOR			Serviceable	0		10		0	Reviewing	
	3	1			O/S BONNET INNER LOCK			Damaged	138		10		124.2	Reviewing	
	4	2			BONNET HINGE			Damaged	164		10		295.2	Reviewing	
	5	2			BONNET EMERGENCY ACTIVATOR			Necessary	447		10		804.6	Reviewing	
	6	1			BONNET LOCK RELEASE HANDLE			Repair	0		10		0	Reviewing	
	7	2			BONNET DAMPER			Damaged	161		10		289.8	Reviewing	
	8	2			BONNET SPRING STOPPER			Serviceable	0		10		0	Reviewing	
	9	2			HEADLAMP ASST			Cracked	1268		10		2282.4	Reviewing	
	10	2			HEADLAMP CLIP			Necessary	18		10		32.4	Reviewing	
	11	1			O/S HEADLAMP TOP PANEL			Bent	262		10		253.8	Reviewing	
	12	1			O/S HEADLAMP LOWER PANEL			Damaged	56		10		50.4	Reviewing	
	13	1			FRONT O/S FENDER INNER SHIELD			Damaged	215		10		193.5	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC CUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		29	1			FRONT BUMPER LOWER GRILLE			Serviceable	0		10		0	Reviewing	
		30	3			FRONT O/S BUMPER PARKING SENSE			Shorted	279		10		753.3	Reviewing	
		31	1			SET FRONT PARKING SENSOR WIRE			Serviceable	0		10		0	Reviewing	
		32	1			FRONT BUMPER COVER			Serviceable	0		10		0	Reviewing	
		33	2			FRONT BUMPER SIDE INNER PARTS			Cracked	75		10		135	Reviewing	
		34	1			FRONT BUMPER CENTRE INNER PART			Cracked	85		10		76.5	Reviewing	
		35	16			FRONT BUMPER INNER PART REVIT			Necessary	3.8		10		54.72	Reviewing	
		36	1			RADIATOR SUPPORT PANEL			Repair	0		10		0	Reviewing	
		37	1			SUPPORT PANEL TOP COVER			Serviceable	0		10		0	Reviewing	
		38	1			O/S HORN			Damaged	199		10		179.1	Reviewing	
		39	1			RADIATOR GRILLE ASSY			Cracked	1277		10		1149.3	Reviewing	
Labour																
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)			PART NAME		LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE			
		1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM. DAYNOSITCE HEADLAMP.				80	0		0	Reviewing					
		2	TO REMOVE AIR CON CONDENSER, PIPES AND DRIER. VACUUM AND TO RECHARGE.				0	0		0	Reviewing					
		3	TO APPLY UNDERSEALING.				30	0		0	Reviewing					

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		6	

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$14,629.68

Claim Amount \$14,629.68

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$12,919.68	\$12,919.68
Labour	\$1,710.00	\$1,710.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Auto

Approve

Deny

Submit All

EDIT

SR NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE

1

Reviewing

13000

FINAL LUMP SUM