

CLASS. REC. BY:

REF: CS/SM018006685/ N rd3/2

Special instruction:

70114

ASSIGNMENT (Office)

From (Person): Grace TEO of SMD Date/Time: 10/4/2018 @ 3.58pm

Estimated Cost: _____ Bill to: _____

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBF 3104J Insured: SIK 2272S

at Workshop m/s SG 98 Motor Tel: 6452 4898

of BIK 4001 #01-21, Amk Ind. Park I

Policy No: _____ Claim No: CMTD1801551/7HE

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9/4/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{1wp}

H.O.D. Endorsement: _____

Date/Time: 4:51pm 3/10/4/18 Person Contacted: Rose Vehicle: IN/OUT

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBF 3104J-X SJK 22728-X.
	Naz confirmed with Rose L/S \$1600 @ 3 days (Red: \$2540.60, 61%.)

Rusul

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBF 3104 J Page: 3 MAY 2011

Type: M.Car (M.Cycle) Bus Van Lorry Taxi Prime Mover /

Truck / Trailer or

Make: YAMAHA X1-R No: 135Colour: Red A.O. Insured / Std / NI (NA)Sp. Reading: 65,270 Radio: Insured / Std / NI (NA)

Eng/No: _____

C.No: 483304507

Gen. Cond: Good / (Fair) Poor / Burnt

Steering: (Inorder) Jammed / Leaked / Burnt or

Brake: (Inorder) Jammed / Leaked / Burnt or

Modi: Nil / S/Rim (STD A/Rim or

Tyre Size: F: 80/90-17REAR R: 90/80-17

BS (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 9/4/18 D.O.I. 12/4/18Survey held at SG 98 MOTOR

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S, N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NAZ

pls see my remarks

SMD LB

[Signature]
20/9

RECEIVED 22 NOV 2018

Date/Time File Pass to:

☐ : Preli. ReportDays Of Repair: 3

by print

☒ : Final ReportResurvey No. of Trip: 1

Survey Fee

Date/Time File Return to:

Transportation

Add Fee: ☐ : Site Insp \$☐ : Inter. \$☐ : Tech. \$☐ : Other \$

Photo

Draw

Report Format: TPLump Sum: 1200 1600

250

250

DONE

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 10 April 2018 3:58 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Sg Motor; Sg Motor; Choo, Thelma
Subject: CMTD1801551/THE - SUV(LKK)/ SJK2272S & FBF3104J ACC ON 09.04.18
Attachments: FBF 3104J-Sompo(PRI).pdf

Our Reference: CMTD1801551/THE

Dear LKK AUTO,

Please make arrangement to conduct the survey for FBF3104J.

Please be informed that Thelma Choo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sg Motor [mailto:sgmotor2000@yahoo.com.sg]

Sent: Tuesday, April 10, 2018 3:03 PM

To: Teo, Grace

Cc: Sg Motor; Choo, Thelma

Subject: Re: CMTD1801551/THE - PRI/ SJK2272S & FBF3104J ACC ON 09.04.18

Dear Grace

Please arrange LKK Auto Consultants for the Pre Repair Inspection.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

On Tuesday, 10 April 2018, 2:35:32 PM GMT+8, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1801551/THE

Your Reference: FBF3104J

Without Prejudice

Date: 10th April 2018

Attention:

M/S SG 98 MOTOR PTE LTD

Dear Linda,

ACCIDENT INVOLVING SJK2272S & FBF3104J ON 09.04.2018

We refer to your Notice of Accident dated 10/04/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sg Motor [<mailto:sgmotor2000@yahoo.com.sg>]
Sent: Tuesday, April 10, 2018 1:08 PM
To: Claims - Motor Survey
Cc: Sg Motor
Subject: Please arrange PRI For bike FBF 3104J

Dear Sir/Madam

Please arrange PRI For bike FBF 3104J as per attached.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

SG 98 MOTOR PTE LTD

Blk 4001 Ang Mo Kio Industrial Park 1

#01-21 Singapore 569622

Office Tel: 6452 4898 / Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date : 10th APRIL 2018

Tenet Sompo Insurance Pte Ltd
50 Raffles Place
#05-01 Singapore Land Tower
Singapore 048623

Attn : Motor Claim Dept
Fax : 6221 3147

Dear Sir/Mdm,

PRE-REPAIR INSPECTION

Accident between FBF 3104J and SJK 2272S accident on 9/04/2018 - 1420 HRS
Location: Along Ang Mo Kio Industrial Park 2 (in front of ESSO Station)

- 1) We hereby give you NOTICE that we are claiming against your insured motor Vehicle No : SJK 2272S damages to our client's Motor Vehicle No: FBF 3104J
- 2) Kindly provide a list of surveyors and their respective company name.
- 3) Kindly let us know if you wish to conduct a pre-repair inspection only after 11.30am at Blk 4001 Ang Mo Kio Industrial Park 1 #01-21 Singapore 569622.
(Tel : 6452 4898, HP : 9171 1655
- 4) If we do not hear from you within the next two (2) working days, we shall advise our clients to proceed with their own inspection and repairs.

Hope you are able to assist us on the above matter soonest.

Yours faithfully



Rose
SG 98 Motor Pte Ltd
Tel : 6452 4898
SG 98 Motor Pte Ltd
Tel : 6452 4898

Amended

MSI116047689 / STA INSPECTION PTE LTD - Sin Ming
ENTRY DATE & TIME: 10/04/2018 14:21
SUBMITTED BY: Wong Up Yong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/04/2018 14:21
Date Of Accident	09/04/2018 14:20
Exact Location Of Accident	ANG MO KIO IND PARK 2 IN FRONT OF ESSO STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF3104J
Insured/Policyholder	
Name Of Registered Owner	CHUA ZHONG HENG (CAI ZHONGHENG)
NRIC No	S8123625I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91593260
Alternative Phone No.	OTHERS-91593260

Vehicle Particulars

Manufacturer	YAMAHA
Model	X-1R-134CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5092751619
Cover Note Number	

Driver

Name of Driver	CHUA ZHONG HENG (CAI ZHONGHENG)
NRIC No	S8123625I
Date Of Birth	11/08/1981
Occupation	INDOOR
Date Of Driving Pass	23/06/2003
Driving Experience	14 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91593260
Fax Number	
Contact Number	OTHERS-91593260

Address	BLK 290 BISHAN ST 24 #15-29 SINGAPORE
Postcode	570290
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK2272S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YOON FOO WAH
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHUA ZHONG HENG (CAI ZHONGHENG)
------	---------------------------------


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



On 09-04-2018 at about 2.20pm. I was riding my bike no: FBP 3104 J along Ang Mo Kio Ind Park heading out to Hongkong Ave 3 main Road. When I reach the Esso station on my left. Suddenly a vehicle no: SJK 2272 S (Silver Mercedes) abruptly make a right turn into the Esso station from the opposite direction without giving way to me. As a result as it was too sudden & closed, my bike (FBP 3104 J) hit the frontal of SJK 2272 S (Vehicle B). The impact caused me to fall off & sustained injuries to my right hand, elbow & knuckle to my right knee cap & right pain to my hip area. Passers by then called for ambulance & police to the scene. but I was not conveyed as I feel I'm ok. The ambulance then left the scene. Veh B driver Mr. Yoon For each then apologized and say sorry to me for causing the accident. We then exchange particulars & left the scene and I proceed to Nawaz Clinic at Bk 410 AMK Ave 10 for consultation & my hand & kneedwrts. The doctor then give me 2 days Medical leave to rest and advised me to go for a Xray to my knee injuries. If the pain persist I will go for further Checkup. I'm lodging this report to Claim for the damages to my bike (FBP 3104 J) and my personal injuries and medical fee.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Fax: 17/4/2018

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 17th April 2018

To : LKK

Attn : Mr Rasul

Tel :

By Fax: 62564315

VEHICLE NO : FBF 3104J

Yamaha X1R135

ACCIDENT DATE: 9th April 2018

Description	Qty	Quotation \$
1 Handle Bar	1	135.00 XSVL
2 Clutch Lever	1	75.00 / SCR
3 Mirror LH	1	68.00 / SCR
4 Meter Visor	1	75 175.00 / SCR
5 Meter Assembly	1	380.00 XSVL
6 Front Cowling	1	165.00 / CRA
7 Front Head Lamp	1	100 165.00 / SCR
8 Fork Tube	1 set	300 480.00 / SCR
9 Front Mudguard	1	50 180.00 / SCR
10 Front Rim	1	380.00 XSVL
11 Front RH Signal	1	68.00 / CRA
12 Front Side Panel	1	100 135.00 / CRA
13 Radiator Tank	1	150 450.00 / DD
14 Engine Lower side fairing RH	1	150 195.00 / CRA
15 Foot rest	1	68.00 / SCR
16 Foot Rest Rubber	1	45.00 / TORN
17 Foot Brake pedal	1	75.00 / BT
18 Exhaust Pipe	1	200 450.00 / SCR
19 Exhaust Guard	1	50 195.00 / SCR
		1,739
Sub-Total		3,884.00
Less 10%		388.40
Sub-Total		3,495.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

①

VEHICLE NO : FBF 3104J

Yamaha X1R135

Nett items

- 1 Towing fees
- 2 To remove & replace parts, alignment etc
- 3 Remove & replace front fork, front Rim & top up fork oil
- 4 Supply Body Sticker Decal
- 5 Front number plate

50.00 ⁴⁰
280.00 ¹⁵⁰

(to remove & replace front fork & top up fork oil)

180.00 ¹⁰⁰

120.00 ^{rec}

15.00 ^{rec}

Sub-Total

645.00 ⁴¹⁵

Nett Total

4,140.60 ^{1,584.08}

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

L/S TOTAL = \$1,600

NA2 LK11

L/S

3 DAYS

AFTER REPAIR PHOTO

[Signature]
20/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2

Fax: 17/4/2018

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 17th April 2018

To : LKK

Attn: Mr Rasul / Mr. Niaz

Tel :

By Fax: 62564315

VEHICLE NO : FBF 3104J

Yamaha X1R135

ACCIDENT DATE: 9th April 2018

Description	Qty	Quotation \$
1 Handle Bar	1	135.00 XSVL
2 Clutch Lever	1	75.00 / SCR
3 Mirror LH	1	68.00 / SCR
4 Meter Visor	1	75 175.00 / SCR
5 Meter Assembly	1	380.00 XSVL
6 Front Cowling	1	165.00 / CRA
7 Front Head Lamp	1	100 165.00 / SCR
8 Fork Tube	1 set	300 480.00 / SCR
9 Front Mudguard	1	50 180.00 / SCR
10 Front Rim	1	380.00 XSVL
11 Front RH Signal	1	68.00 / CRA
12 Front Side Panel	1	100 135.00 / CRA
13 Radiator Tank	1	150 450.00 / DD
14 Engine Lower side fairing RH	1	150 195.00 / CRA
15 Foot rest	1	68.00 / SCR
16 Foot Rest Rubber	1	45.00 / TORN
17 Foot Brake pedal	1	75.00 / BT
18 Exhaust Pipe	1	200 450.00 / SCR
19 Exhaust Guard	1	50 195.00 / SCR
		1,739
Sub-Total		3,884.00
Less 10%		388.40
Sub-Total		3,495.60

①

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO : FBF 3104J

Yamaha X1R135

Nett items

- 1 Towing fees
- 2 To remove & replace parts, alignment etc
- 3 Remove & replace front fork, front Rim & top up fork oil
- 4 Supply Body Sticker Decal
- 5 Front number plate

50.00 ⁴⁰
280.00 ¹⁵⁰

(to remove & replace front fork & top up fork oil)

180.00 ¹⁰⁰

120.00 ^{rec}

15.00 ^{rec}

Sub-Total

645.00 ⁴¹⁵

Nett Total

4,140.60 ^{1,584.08}

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

L/S TOTAL = \$1,600

NA2 LK11

L/S

3 DAYS

AFTER REPAIR PHOTO


20/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2

Janice Lee (LKKAUTO)

From: Naz (LKKAUTO)
Sent: Thursday, November 15, 2018 11:34 AM
To: Sg motor enterprise Giam
Cc: Janice Lee (LKKAUTO)
Subject: Re: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J
Attachments: FINALIZE 2.pdf

Dear Ms Rose

We will proceed to finalize if you are agreeable with the amended COR;

PARTS	- \$1,739
LESS 10%	- \$1,565.10
SPECIAL NETT	- \$40
LABOUR	- \$385
LESS 20% LUMP SUM	- \$1,584.08

TOTAL - \$1,600 / 3 REPAIR DAYS

Thank you.

Best Regards,
Naz | Technical Investigator
LKK Auto Consultants
Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAUTO)
Sent: Monday, 15 October 2018 11:31 AM
To: Naz (LKKAUTO); Sg motor enterprise Giam
Subject: RE: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Dear Rose,

Please ignore the previous email sent.

The revised calculation as below :

Parts :	\$1,289.00
10% :	\$1,160.10
Labour :	\$325.00
Total :	\$1,485.10
L/S :	\$1,150.00

Repair day : 3 days

Kindly confirm.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Naz (LKKAuto)

Sent: Monday, September 24, 2018 5:41 PM

To: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>

Cc: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Subject: Re: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Dear Ms Rose

We will proceed to finalize if you are agreeable with the amended COR;

PARTS	- \$1,724
LESS 10%	- \$1,551.60
LABOUR	- \$325
LESS 20% LUMP SUM	- \$1,501.28

TOTAL - \$1,500 / 3 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>

Sent: Monday, 24 September 2018 5:17 PM

To: Naz (LKKAuto)

Subject: Re: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Hi Mr Naz,

Pls give us the lump sum amount first for our review.

thank you

rose

On Monday, 24 September 2018, 5:06:19 PM GMT+8, Naz (LKKAUTO) <Naz@lkkauto.com> wrote:

Dear Ms Rose,

Photos received with thanks. However I am unable see the damage on the checked items from the photos. Attached herewith is the marked estimate together with the part prices in red. We will proceed to finalize the cost of repair if you are agreeable with the amended part prices.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>

Sent: Friday, 21 September 2018 10:52 AM

To: Naz (LKKAUTO)

Cc: Janice Lee (LKKAUTO)

Subject: Re: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Hi all,

attached damaged items, pls assist to finalise soonest.

thank you

rose

On Friday, 21 September 2018, 9:44:47 AM GMT+8, Naz (LKKAUTO) <Naz@lkkauto.com> wrote:

Dear Ms Rose,

After repair photos received. Do you have any dismantle photos? I need to check the damage on the checked items.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>
Sent: Thursday, 20 September 2018 10:44:24 AM
To: Naz (LKKAUTO)
Cc: Janice Lee (LKKAUTO)
Subject: Re: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Dear Janice lee,

Re : FBF 3104J,

As spoken attached after repaired photo, kindly assist to finalise soonest.

thank you
rose

On Wednesday, 19 September 2018, 6:29:39 PM GMT+8, Naz (LKKAUTO) <Naz@lkkauto.com> wrote:

Dear Ms Linda,

Do you have the dismantle and after repair photos? I will need them before I can finalize as there are a few checked items which is in the marked estimate I have attached. Kindly send me the photos.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, 19 September 2018 11:38 AM
To: Naz (LKKAUTO)
Subject: FW: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor [<mailto:sgmotor2000@yahoo.com.sg>]
Sent: Wednesday, September 19, 2018 10:53 AM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Subject: Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Attached pls find the Cost of Repairs & GIA for bike FBF 3104J

Thank You

Regards
Leena

SG 98 Motor Pte Ltd
Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO18006685/Nrd3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			<div style="text-align: right;">Date : 22-11-2018</div> <div style="text-align: right;">Code : SMO</div>	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJK 2272S	Veh. Inspected	FBF 3104J
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD1801551/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	10/04/2018
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA X-1R	c.c	135
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	4S3304507	Colour	RED
	Odometer	65270	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	80/90-17	PIRELLI	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	90/80-17	DUNLOP	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	09/04/2018	Inspection Date	12/04/2018
	Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 3104J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	SERVICEABLE	135.00	-
1	CLUTCH LEVER	SCRATCHED	75.00	75.00
1	MIRROR LH	SCRATCHED	68.00	68.00
1	METER VISOR	SCRATCHED	175.00	75.00
1	METER ASSEMBLY	SERVICEABLE	380.00	-
1	FRONT COWLING	CRACKED	165.00	165.00
1	FRONT HEAD LAMP	SCRATCHED	165.00	100.00
1	SET FORK TUBE	SCRATCHED	480.00	300.00
1	FRONT MUDGUARD	SCRATCHED	180.00	50.00
1	FRONT RIM	SERVICEABLE	380.00	-
1	FRONT RH SIGNAL	CRACKED	68.00	68.00
1	FRONT SIDE PANEL	CRACKED	135.00	100.00
1	RADIATOR TANK	DENTED	450.00	150.00
1	ENGINE LOWER SIDE FAIRING RH	SCRATCHED	195.00	150.00
1	FOOT REST	SCRATCHED	68.00	68.00
1	FOOT REST RUBBER	TORN	45.00	45.00
1	FOOT BRAKE PEDAL	BENT	75.00	75.00
1	EXHAUST PIPE	SCRATCHED	450.00	200.00
1	EXHAUST GUARD	SCRATCHED	195.00	50.00
	LESS 10% DISCOUNT		-388.40	-173.90
			3,495.60	1,565.10
	<u>SPECIAL NETT ITEMS</u>			
1	BODY STICKER DECAL (SN)	NECESSARY	120.00	120.00
1	FRONT NUMBER PLATE (SN)	NECESSARY	15.00	15.00
			135.00	135.00
	<u>LABOUR</u>			
	TOWING FEES.		50.00	40.00
	TO REMOVE & REPLACE PARTS, ALIGNMENT ETC.		280.00	150.00
	REMOVE & REPLACE FRONT FORK, FRONT RIM & TOP UP FORK OIL.		180.00	100.00
			510.00	290.00
	GRAND TOTAL		4,140.60	1,990.10

Report Ref No. CS/SMO18006685/Nrd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	----------

Report Ref No. CS/SMO18006685/Nrd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.