

INS. CASE OWNER

Simehan

CC4 / III 1800 6697, U Wb3

LKK:

IDAC:

Surveyor:

wrmms

DOI:

ASSIGNMENT

20/4/18

Date / Time:

11/4/18

Registered in Merimen:

11/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 77932

Name of Insured:

L7P2

Insured Tel No.:

HP:

Excess See II :S\$

D.O.A.:

7/4/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

TOH KOK KUNH9

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

MUTIS040NY

Policy No.:

M00M0015

Make / Model:

HUMMER

Place of Accident:

SENTOSA GATEWAY TUNNEL
SENTOSA OUTSIDE OF ST

OI GIA REPORT:

YES / NO : TP GIA REPORT: YES / NO TIMES

Insured Liability:

% Final ? Yes / No

SLM4990E



INSRS:

WSP:

Tel:

Liability:

RMKS:

pegnus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

12/4/18

wrmms

13/4/18

19/4/18

19/4/18

20/4/18

23/4/18

SLM4990E - 4

SHA 77932 - 4

RECEIVED 23 APR 2018

Seek liability unclear via merimen

Receive video from III

Get rejection from III

III approval rejection. Base on Q20 video, TP
Shared info Q20's lane.

Email to workshop reject TP claim.

Reject Case

By (name): Vmms

Approved by: Oliver

Date: 23/4/18

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

A250.00

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF: III

ASSIGNMENT

From: Date: 20042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLM 4990E

at Workshop m/s

Pegasus

of: 51 Debu Lane 10

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

CA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lump Sum: 1.81 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLM 4990E Yr Regn: 3 / 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: MCF 3 C.C. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 68/59 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BN22A8H0147227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A/Rim or

Tyre Size: F:

R: 205/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A. 7/4/18 D.O.I. 20/4/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/4/18 Confirmed final by \$600 with miller.

(200 - \$ 200.00
29%)

Date/Time, File Pass to?

☐: Prel. Report

Days Of Repair:

1)

☐: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Insp (\$☐: Weekend (\$

Survey Fee:

Transportation:

) \$ - RS - \$

) Photo:

) Other:

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

emailed on
10/04/18
@ 11:04h

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : TAN LIM MOTOR Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/04-1120	Quotation Date : 09/04/2018	Terms : 30 DAYS
Vehicle No : SLM4990E	Chassis No : JM6BN22A8H0147227	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: III, INSURED VEHICLE NO: SHA7793Z, DATE OF ACCIDENT: 07.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. REPAIR RH REAR FENDER AND REAR BUMPER	1	300.0000	200 300.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	550.0000	400 550.00

Not Authorised
24th
take photo after repair
20/4/18
P/P \$ 600
2dy.

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To survey damaged part(s) during resurvey
- Final prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer
Signature
Date

Sub Total	850.00
GST(7.00%)	59.50
Total (SGD)	909.50

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	7200G

Vehicle Details

Vehicle No.:	SLM4990E
Vehicle to be Exported:	No
Intended De-registration Date:	20 Apr 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520435732
Chassis No.:	JM6BN22A8H0147227
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,640.00
Original Registration Date:	31 Mar 2017
First Registration Date:	31 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$9,640.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2027
PARF Rebate Amount:	\$7,230.00

Intended COE Rebate Details

COE Expiry Date:	30 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$45,423.00
Total Rebate Amount:	\$52,653.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive of up to \$3,500 for owners of older, more pollutive motorcycles which were registered before 1 July 2003, to de-register their motorcycles on or before 5 April 2023.

The last registered owner of this motorcycle will receive \$2,000 if it is de-registered on or before 5 April 2023. If this motorcycle's COE is not renewed on or after 7 April 2018, the last registered owner will receive an additional \$1,500 upon its de-registration on or before 5 April 2023.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 11 April 2018 10:25 AM
To: Pegasus Engineering; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: Third party survey - SLM4990E Your insured: SHA7793Z DOA: 07.04.2018
Attachments: 10042018103745.pdf; GIA REPORT - SLM4990E.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLM4990E and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

10.50am @ 11/4/18
person @ Cayman
vehicle not in

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: 10 April, 2018 5:51 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: Third party survey - SLM4990E Your insured: SHA7793Z DOA: 07.04.2018

Dear Gabriel,

We will like to appoint LKK Auto Consultants Pte Ltd to survey our vehicle (SLM4990E).

Thanks & Regards,

Alvin Low

-CT

Pegasus Engineering & Trading Pte Ltd

51 Defu Lane 10

Singapore 539216

Tel : 6858 1846

Fax : 6487 6070

Email : claims@pegasusengrg.com.sg

On Tue, Apr 10, 2018 at 12:00 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: 10 April, 2018 11:13 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Lalitha Krishnan - III <lalitha@iii.com.sg>; Lawrence Sim <lawrencesim@pegasusengrg.com.sg>

Subject: Third party survey - SLM4990E Your insured: SHA7793Z DOA: 07.04.2018

Your Ref: SHA7793Z

Our Ref: SLM4990E

DOA: 07.04.2018

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a **list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

The vehicle is currently not in our premises.

Thanks & Regards,

Alvin Low

-CT

Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Monday, 23 April, 2018 10:34 AM
To: 'Pegasus Engineering'
Cc: Thin Thin (LKKAUTO)
Subject: Your Ref: SLM 4990E ,Our Ref: CC4/III18006697/Uwb3,Accident involving SLM 4990E & SHA 7793Z ON 07/04/2018
Attachments: SHA 7793Z.MP4; Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: SLM 4990E
Our Ref: CC4/III18006697/Uwb3

Dear Sir/Madam,

Accident involving SLM 4990E & SHA 7793Z ON 07/04/2018

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client swerved into our Insured's lane

We attached herewith our insured's accident report and our insured's video for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

As such, we will close the matter at our end.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Apr 2018 Edit Reg		20 Apr 2018 00:00 Edit Adj Rpt	S\$600.00 Edit Estimates	S\$600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLM4990E	Date of Loss:	07/04/2018 21:00 - :59 [12 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18040217	Policy/Cover Note No.:	MC0M0015
Vehicle Reg. No. (Insured):	SHA7793Z	Policy No. (Claimant):	A29069766MKF
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/04/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (20/04/2018): Alert - Adj Mandate Approved (S\$0.00) - SLM4990E - Claim Handler: Sundari Nagara...
- III_SG (19/04/2018): Alert - Adj Mandate Approved (S\$0.00) - SLM4990E - Claim Handler: Sundari Nagara...
- III_SG (13/04/2018): Alert - Adj Mandate Approved (S\$0.00) - SLM4990E - Claim Handler: Sundari Nagara...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM4990E (MCT18040217)
[SHA7793Z]
TP
GRAB RENTALS PTE LTD
Apr 7 2018 9:00PM
[COMFORT TRANSPORTATION PTE LTD]
Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail		Print	
1	19/04/18 12:09	Video - Accident						Load MP4		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
2	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
3	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
4	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
5	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
6	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
7	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
8	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
9	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
10	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
11	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
12	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
13	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
14	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
15	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
16	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
17	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
18	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
19	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
20	21/04/18 12:43	General View						Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	11/04/18 16:39	EMAIL FROM III DD 11042018						Load PDF		
2	11/04/18 16:39	TP ESTIMATE						Load PDF		
3	11/04/18 16:39	TP GIA REPORT						Load PDF		
4	23/04/18 10:36	Email to wkshop reject claim 23.4.18.						Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail		Print	
1	12/04/18 08:45	Singapore Accident Statement						Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18006697/UWB3Q2

Date: 24/04/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MC0M0015
 Claimant Vehicle No: SLM4990E Insured Vehicle No: SHA7793Z
 Date of Loss: 07/04/2018 Nature of Claim: TP Claim No: MCT18040217

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM4990E
 Make & Model: MAZDA 2, 1.5 SEDAN L SP.6EAT (A) Engine No: P520435732
 Reg. Date: 31/03/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0147227
 Colour: Blue Odometer: 68159 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	600.00	250.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	850.00	600.00	250.00	29.41
+ GST 7.00/7.00% (S\$)	59.50	42.00	17.50	29.41
Nett Amount (S\$)	909.50	642.00	267.50	29.41

INSPECTION

Date of Assignment: 20/04/2018
 Date Inspected: 20/04/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)
 51 DEFU LANE 10
 Singapore 539216
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2018)
Parts:	143	MAZDA 2 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM4990E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS .ADJUST AND REALIGN THE SAME ,REPAIR RH REAR FENDER AND REAR BUMPER	New	300.00	200.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	550.00	400.00
Gross Labour Cost (S\$)			850.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >