

Surveyor

REF: CS1 / 2CS 18006701 / Dabaz

Special Instruction:

US: \$ 25200.00

From (Person): Jania Goh of ICS Date/Time: 10042018 440pm
Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: LEE Automobile

Workshop: MJE Motor

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SKE 1952P Insured: SIX 5089C

at Workshop m/s MJE Motor

Tel:

of Blk 7 Sin Ming Ind Est #01-96

Policy No: Claim No: DMPIU1700268H

Sum Insured: Excess:

Make of Veh: D.O.A. 24042017

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 11 days)

Date/Time: Submit Final Fig days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	SKE 1952P - 203 18006701/5089C
	SIX 5089C - X
17/05/18	To submit L/S 183501 - with 9 days of gr. (Red \$ 6850, 27%) Part prices checked in VIEWS.
	RECEIVED 17 MAY 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add
Transport
Photos
Others
Total

150

150

1) Date/Time 17/5/18 File Pass to [Signature]

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

Catherine Chong (LKK Auto)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Tuesday, 10 April, 2018 4:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Subject: PAPER SURVEY FOR TP's VEHICLE SKE1952P ; Our ref DMPU1700268H
Attachments: img-410162320-0001.pdf; img-410162455-0001.pdf; SAS2211067.PDF; SKE1952P.PDF

Hi LKK

Please assist for paper survey of TP's vehicle SKE1952P.
Attach is our insured and TP's report with TP's survey report for your kind attention.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

TO: TAN ENG LEE

c/o BLK 7 SIN MING IND. EST. SECTOR C
#01-96
SINGAPORE 575642

OUR REF. LEE/TP/04/1774/17
DATE 03 JUNE 2017

AUTOMOBILE APPRAISAL REPORT

Vehicle Registration No. : SKE 1952 P
Make/Model : Volvo S60
Year Manufacture/Register : 2012
Colour : Silver
Engine No. : Obscure
Chassis No. : YV1FS485BC2120055
Odometer Reading : 139513km
Nature Of Inspection : Third Party
Date Of Accident : 24 April 2017
Date Of Inspection : 28 April 2017
Name of Workshop : MJE Motor
Place Of Inspection : Blk 7 Sin Ming Ind. Est. Sector C #01-96
: Singapore 575642

TYRE CONDITION ON VEHICLE

Location	Make	Size	Thread Balance
Nearside Front	Michelin	215/50ZR17	8mm
Offside Front	Michelin	215/50ZR17	8mm
Nearside Rear	Michelin	215/50ZR17	8mm
Offside Rear	Michelin	215/50ZR17	8mm

*(The above represent on estimated remaining life of the tyre thread in mm)

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The damages sustained on the vehicle were apparently confined at its front & rear portion.
(Details are describe in the attached schedule)

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items in this survey, kindly notify the company within (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

LEE**LEE AUTOMOBILE APPRAISERS SERVICES**

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809

FAX: (65) 6763 3827, HANDPHONE: 8188 2833

BUSINESS REG. NO.: 52891429D

APPRAISEMENT SCHEDULE

Vehicle Registration No: SKE 1952 P

Our Ref: LEE/TP/04/1774/17

S/NO.	Qty	Description	Comments/ Conditions	Repairer's Estimate	Assessed Amount	
		LIST ITEMS				
1	1	Rear bumper	bent/cut/deformed	\$ 1,560.00	\$ 1,560.00	✓
2	1	Rear bumper reinforcement	bent/oblique	\$ 950.00	\$ 950.00	✓
3	1	Rear bumper lower cover	bent/cut/deformed	\$ 240.00	\$ 240.00	✓
4	1	Rear bumper side bracket-LH	essential	\$ 88.00	\$ 88.00	SVL
5	1	Rear boot cover	buckled	\$ 2,450.00	\$ 2,450.00	✓
6	1	Rear boot cover inner lock	bent/cut	\$ 199.00	\$ 199.00	✓
7	1	Rear boot cover lamp -LH	bent	\$ 210.00	\$ 210.00	✓
8	1	Rear boot cover "S60" emblem plate	essential	\$ 88.00	\$ 88.00	✓
9	1	Rear boot cover "T4" emblem	essential	\$ 84.00	\$ 84.00	✓
10	1	Rear boot cover "Volvo" emblem	essential	\$ 92.00	\$ 92.00	✓
11	1	Rear boot cover hinge-LH	bent/stiffened	\$ 245.00	\$ 245.00	✓
12	1	Rear boot cover rubber	essential	\$ 268.00	\$ 268.00	✓
13	1	Rear fender-LH	distorted	\$ 1,750.00	\$ 1,750.00	✓
14	1	Taillamp-LH	bent	\$ 310.00	\$ 310.00	✓
15	1	Rear end panel	distorted	\$ 680.00	\$ 680.00	✓
16	1	Rear end panel garnish	serviceable	\$ 195.00	reuse	SVL
17	1	Rear exhaust silencer	bent/cut	\$ 970.00	\$ 970.00	✓
18	1	Rear windscreen moulding	essential	\$ 239.00	\$ 239.00	✓
19	1	Front bumper	bent/cracked/deformed	\$ 1,650.00	\$ 1,650.00	✓
20	1	Front bumper reinforcement	bent/oblique	\$ 930.00	\$ 930.00	✓
21	2	Front bumper centre bracket @\$90.00	bent/oblique	\$ 180.00	\$ 180.00	✓
22	2	Front bumper side retainer @\$80.00	essential	\$ 160.00	\$ 160.00	SVL
23	2	Front bumper lamp @\$252.00	a/s cracked, n/s bent	\$ 504.00	\$ 504.00	✓
24	1	Front bumper inner plastic garnish	deformed	\$ 346.00	\$ 346.00	✓
25	1	Front radiator grille c/w "Volvo" emblem & chrome moulding	cracked/bent	\$ 565.00	\$ 565.00	✓
26	2	Front headlamp @\$950.00	bent/cut/holder snapped	\$ 1,900.00	\$ 1,900.00	✓
27	1	Front bumper lower centre grille	essential	\$ 113.00	\$ 113.00	SVL
28	1	Front bumper fog lamp cover -RH	intact	\$ 98.00	reuse	SVL
29	1	Front engine intercooler	bent	\$ 1,050.00	\$ 1,050.00	✓
30	1	Front radiator	bent/puncture	\$ 930.00	\$ 930.00	✓
31	1	Front aircon condenser	bent/puncture	\$ 1,130.00	\$ 1,130.00	✓
32	1	Front fan motor c/w cowling	motor shorted	\$ 959.00	\$ 959.00	✓
33	1	Front support panel	bent/distorted	\$ 1,707.00	\$ 1,707.00	✓
34	1	Front bonnet cover	distorted/bent	\$ 2,648.00	\$ 2,648.00	✓
35	1	Front bonnet cover lock	bent	\$ 166.00	\$ 166.00	✓
36	1	Front bonnet heat insulator	essential	\$ 533.00	\$ 533.00	SVL
37	1	Front fender -LH	distorted/bent	\$ 1,040.00	\$ 1,040.00	✓
38	1	Front tow cover	missing	\$ 74.00	\$ 74.00	✓
		Less 5%		\$ 27,301.00	\$ 27,008.00	
		Sub total parts		-	\$ (1,350.40)	
		SPECIAL NETT ITEMS		\$ 27,301.00	\$ 25,657.60	
1	2	Rear reverse sensor @\$250.00	cut/shorted	\$ 500.00	\$ 500.00	220/-
2	1 tube	Rear windscreen sealant	essential	\$ 90.00	\$ 80.00	✓
		Total parts		\$ 27,891.00	\$ 26,237.60	
		SUB TOTAL		\$ 27,891.00	\$ 26,237.60	

20466.00

19442.70

220/-



CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

Vehicle Registration No. SKE 1952 P

Our Ref. LEE/TP/04/1774/17

S/NO.	Qty	Description	Comments	Repairer's Estimate	Assessed Amount
			b/f	\$ 27,891.00	\$ 26,237.60
		To remove & refix rear windscreen glass.		\$ 220.00	\$ 200.00
		To check wiring and function including to refocus headlamp including to remove & refix rear reverse sensor.		\$ 190.00	\$ 150.00
		Labour charges as recommended for repaired, cut/weld panels & replaced damaged parts.))	\$ 2,250.00	\$ 2,000.00
		To mount vehicle onto chassis alignment bench to facilitate repair.		\$ 800.00	\$ 600.00
		To putty and spraypainting including touch up all affected areas.		\$ 1,780.00	\$ 1,500.00
		To apply rustproof treatment to the replaced/repared panels.		\$ 280.00	\$ 200.00
		To remove & refill aircon condenser, etc including to refill gas.		\$ 220.00	\$ 200.00
		To supply radiator coolant.		\$ 40.00	\$ 30.00
		To reset engine management system using diagnosis equipment.	3290/-	\$ 600.00	\$ 400.00
		GRAND TOTAL		\$ 34,271.00	\$ 31,517.60

22952.70

2183501-

9 days.

LEE**LEE AUTOMOBILE APPRAISERS SERVICES**

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

Vehicle Number: - SKE 1952 P

Our Ref: LEE/TP/04/1774/17

ASSESSMENT SUMMARY

The damages sustained on the vehicle were thoroughly inspected and every item that was mentioned in the repair estimate against the actual damages found on the vehicle. Before we arrived at our recommendation as to whether the parts needed to be replaced or repair.

We have listed the breakdown of our finding and our recommendation as per schedule attached.

Our assessment to reinstate the vehicle is **\$31517.60** revised amount of the repairer's estimate of **\$34271.00**. The aforesaid recommendation, in our opinion, is fair and reasonable for the restoration of the vehicle to its pre-accident condition.

However, after taken into consideration the age and condition of the vehicle and the availability of the recondition components and to economize the repair, we therefore recommend a contract **Lump Sum at \$25200.00** corresponding to supply of parts, labour and spray painting charges.


119 photographs were taken at the times of static inspection.

Under normal circumstances, the repairs should be completed within a reasonable period 11 full working days

This inspection was conducted entirely on a 'Without Prejudice' basis and we have not given authorization and instruction to the repairer to proceed with the repair.

We are reverting the matter to you for your discretion.

Very truly yours,



.....
K. W. LEE Dip.Auto. Engrg
MIAME, AMIMI, CAE, ENG. TECH, MSAE, AMIRTE, AMSOE
AUTOMOTIVE ENGINEER ASSESSOR

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/04/2017 17:15
Date Of Accident 24/04/2017 18:00
Exact Location Of Accident BKE TOWARDS SLE NEAR MANDAI FLYOVER
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKE1952P
Insured/Policyholder
Name Of Registered Owner TAN ENG LEE
NRIC No S7718217I
Email Address ENGLEE07@YAHOO.COM
Mobile Phone No (LOCAL) +65-92274588
Alternative Phone No OFFICE-92274588

Vehicle Particulars

Manufacturer VOLVO
Model S60-1.6 T4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMPCSN3007491700
Cover Note Number

Driver

Name of Driver TAN ENG LEE
NRIC No S7718217I
Date Of Birth 30/06/1977
Occupation INDOOR
Date Of Driving Pass 16/10/2003
Driving Experience 13 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-92274588
Fax Number
Contact Number OFFICE-92274588
EMail Address ENGLEE07@YAHOO.COM

Address	BLK 31 BISHAN STREET 11 #08-06
Postcode	579819
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (TP HIT INSURED)
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX5089C
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Name of Driver	YAP PENG KEONG, DARREN
NRIC/Passport Number	S8822663A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKW3876T
Vehicle Make/Model/Colour	NISSAN TEANA

Details Of Properties

Name of Driver	WONG PAK FOONG
NRIC/Passport Number	S1344507I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name	TAN WEE HOW JAYSTON
Approximate Age	
Injuries Sustain	COMPLAINED HEADACHE
Injured person in which vehicle?	SKE1952P
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	TAN WEE KIAT RYAN
Approximate Age	
Injuries Sustain	COMPLAINED HEADACHE
Injured person in which vehicle?	SKE1952P
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Tan 15/4/17
@ 2.10pm

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan


<div style="text-align: center;">  </div> <div style="text-align: center; margin-top: 20px;"> <p>BKE towards SLE</p> </div>	<p>A: SKE 1952P</p> <p>B: SGX 5089L</p> <p>C: SKW 3876T</p>
--	---

Describe Circumstances of the Accident

On 24th April 2017, at about 1800 hrs, I was driving along BRE towards SLE after mandai exit. The traffic was heavy and vehicles were moving slowly towards SLE. I followed behind the queue moving slowly. After a few seconds, I felt an impact on the rear of my vehicle. Vehicle B, SKX 5089C, collided into the rear of my vehicle. Due to the impact my vehicle surged forward and collided into Vehicle C, SKW 3876T, in front of me. My son seated behind felt pain in his head.

Declaration

We declare the foregoing particulars are true in every respect.

 24/4/17
@ 2.10pm.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/05/2017 17:35
Date Of Accident	24/04/2017 18:00
Exact Location Of Accident	ALONG BKE TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX5089C
Insured/Policyholder	
Name Of Registered Owner	LTC LIMO
Co Reg No	53341066E
Email Address	TOWCHONG.LIM@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-93850897

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.5 4AT
Exact Purpose for which vehicle was being used at time of accident	UBER/GRABCAR
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPU17A00086900
Cover Note Number	

Driver

Name of Driver	YAP PENG KEONG DARREN
NRIC No	S8822663A
Date Of Birth	29/06/1988
Occupation	OUTDOOR
Date Of Driving Pass	26/10/2007
Driving Experience	9 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97620204
Fax Number	
Contact Number	
EMail Address	DARRENPINKY88@GMAIL.COM

Address BLK 679 CHOA CHU KANG CRESCENT #04-600
Postcode 680679
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION- CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name CHOA CHU KANG NPC
Police Station Address ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 ,
COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Refer to police report no: JI/20170502/2180.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKE1952P
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver TAN ENG LEE
NRIC/Passport Number S77182171
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name KYLE NATHANIEL
Phone Number 97250110

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKW3876T
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver WONG PAK FOONG
NRIC/Passport Number S1344507I
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


 19/5/17

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan




Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident


As per Police Report


Lined area for describing the circumstances of the accident.



Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

 19/5/17
Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



J/20170502/2180

1 of 2

POLICE REPORT (NP299)

Report No. J/20170502/2180

Police Station Of Origin
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Date/Time Report Made 02/05/2017 19:47		Vide Report No.		Station Diary No. 82	
Name Of Informant YAP PENG KEONG, DARREN		Address APT BLK 679 CHOA CHU KANG CRESCENT #04-600 SINGAPORE 680679			
ID Type / ID No. NRIC NO / S8822663A		Contact No. Home/Office Mobile 97620204			
Nationality SINGAPORE CITIZEN		Email Address			
Occupation Singapore Armed Forces personnel		Sex Male	Age 28	Date of Birth 29/06/1988	Race Chinese
Institution/School Name		Language			
Date/Time Of Incident 24/04/2017 18:00 - 24/04/2017 18:30		Location Of Incident BUKIT TIMAH EXPRESSWAY SINGAPORE			

Brief details.

On 24/04/2017 at around 1800hrs, I was traveling along BKE towards SLE on my rented vehicle (SGX5089C, rented from LTC Limo Pte Ltd) as a relief driver. As I was traveling, after passing Mandai Flyover, the vehicle(SKE1952P) in front of me suddenly jammed brake causing me to collide in to the vehicle. The traffic was heavy on that day, road was dry and vision was clear. I alighted the vehicle and noticed that there was another vehicle (SKW3876T) in front. I spoke to both of the driver, and they insisted that its my fault. My insurance company informed me that they are currently trying to claim for them and have required me to make a report. I have a witness with me who saw what happen. I am

Signature Of Officer Recording The Report: J / HONG KEN NAM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/05/2017 19:47
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Sgt KISHO ABDUL KHALIQ Contact No.: 67910000	Classification Of Case:

Authentication Stamp



Signature :

Singapore Police Force



**SINGAPORE
POLICE FORCE**



J/20170502/2180

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT





Report No. J/20170502/2180

lodging this report for my insurance company to take action.

Contact detail for SKE1952P: Tan Eng Lee(Chen Rong Li) , S77182171

Contact detail for SKW3876T: Wong Pak Foong,S13445071

Contact detail for my witness: Kyle Nathaniel, S9729455J , Hp: 97250110.

Signature Of Officer Recording The Report: J / HONG KEN NAM 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 02/05/2017 19:47
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Sgt KISHO ABDUL KHALIQ Contact No.: 67910000	Classification Of Case:
Authentication Stamp  Signature: 	
Singapore Police Force	

Your Ref: DMPU1700268H

Date: 17th May 2018

Our Ref: CS1/ICS18006701/Dqbe2

M/s ECICS Ltd

7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SKE 1952P
INSURED VEHICLE: SGX 5089C
ACCIDENT DATE: 24/04/2017**

We thank you for your instruction on 10/04/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKE 1952P from M/s Lee Automobile Appraisers Services.
- b) Singapore Accident Statement of Vehicles SKE 1952P and SGX 5089C.
- c) Colour damaged vehicle photographs of SKE 1952P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKE 1952P
Make & Model	: Volvo S60
Year of Registration	: 2012
Chassis Number	: YV1FS485BC2120055

2. We recommend that the repairs of the entire damage require about 9 (nine) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 1952P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BENT / CUT / DEFORMED	1,560.00	1,560.00
1	REAR BUMPER REINFORCEMENT	BENT / OBLIQUE	950.00	950.00
1	REAR BUMPER LOWER COVER	BENT / CUT / DEFORMED	240.00	240.00
1	REAR BUMPER SIDE BRACKET - LH	SERVICEABLE	88.00	-
1	REAR BOOT COVER	BUCKLED	2,450.00	2,450.00
1	REAR BOOT COVER INNER LOCK	NOT NECESSARY	199.00	-
1	REAR BOOT COVER LAMP - LH	BENT	210.00	210.00
1	REAR BOOT COVER "S60" EMBLEM PLATE	ESSENTIAL	88.00	88.00
1	REAR BOOT COVER "T4" EMBLEM	ESSENTIAL	84.00	84.00
1	REAR BOOT COVER "VOLVO" EMBLEM	ESSENTIAL	92.00	92.00
1	REAR BOOT COVER HINGE - LH	NOT NECESSARY	245.00	-
1	REAR BOOT COVER RUBBER	ESSENTIAL	268.00	268.00
1	REAR FENDER - LH	TO REPAIR SEE LABOUR	1,750.00	-
1	TAILLAMP - LH	BENT	310.00	310.00
1	REAR END PANEL	DISTORTED	680.00	680.00
1	REAR END PANEL GARNISH	SERVICEABLE	195.00	-
1	REAR EXHAUST SILENCER	BENT / CUT	970.00	970.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	239.00	-
1	FRONT BUMPER	BENT / CRACKED / DEFORMED	1,650.00	1,650.00
1	FRONT BUMPER REINFORCEMENT	BENT / OBLIQUE	930.00	930.00
2	FRONT BUMPER CENTRE BRACKET @\$90.00	BENT / OBLIQUE	180.00	180.00
2	FRONT BUMPER SIDE RETAINER @\$80.00	SERVICEABLE	160.00	-
2	FRONT BUMPER LAMP @\$252.00	O/S CRACKED / N/S BENT	504.00	504.00
1	FRONT BUMPER INNER PLASTIC GARNISH	DEFORMED	346.00	346.00
1	FRONT RADIATOR GRILLE C/W "VOLVO" EMBLEM & CHROME MOULDING	CRACKED / BENT	565.00	565.00
2	FRONT HEADLAMP @\$950.00	BENT / CUT / HOLDER SNAPPED	1,900.00	1,900.00

Report Ref No. CS1/ICS18006701/Dqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER CENTRE GRILLE	SERVICEABLE	113.00	-
1	FRONT BUMPER FOG LAMP COVER - RH	SERVICEABLE	98.00	-
1	FRONT ENGINE INTERCOOLER	NOT NECESSARY	1,050.00	-
1	FRONT RADIATOR	BENT /PUNCTURE	930.00	930.00
1	FRONT AIRCON CONDENSER	BENT / PUNCTURE	1,130.00	1,130.00
1	FRONT FAN MOTOR C/W COWLING	NOT NECESSARY	959.00	-
1	FRONT SUPPORT PANEL	BENT / DISTORTED	1,707.00	1,707.00
1	FRONT BONNET COVER	BENT / DISTORTED	2,648.00	2,648.00
1	FRONT BONNET COVER LOCK	NOT NECESSARY	166.00	-
1	FRONT BONNET HEAT INSULATOR	SERVICEABLE	533.00	-
1	FRONT FENDER - LH	TO REPAIR SEE LABOUR	1,040.00	-
1	FRONT TOW COVER	MISSING	74.00	74.00
	LESS 5% DISCOUNT		-	-1,023.30
			27,301.00	19,442.70
	<u>SPECIAL NETT ITEMS</u>			
2	REAR REVERSE SENSOR @\$250.00 (SN)	CUT / SHORTED	500.00	220.00
1	TUBE REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	90.00	-
			590.00	220.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	220.00	-
	TO CHECK WIRING AND FUNCTION INCLUDING TO REFOCUS HEADLAMP INCLUDING TO REMOVE & REFIX REAR REVERSE SENSOR.		190.00	60.00
	LABOUR CHARGES AS RECOMMENDED FOR REPAIRED, CUT / WELD PANELS & REPLACED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER - LH AND FRONT FENDER - LH.		2,250.00	1,600.00
	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH TO FACILITATE REPAIR.	NOT NECESSARY	800.00	-
	TO PUTTY AND SPRAY PAINTING INCLUDING TOUCH UP ALL AFFECTED AREAS.		1,780.00	1,400.00
	TO APPLY RUSTPROOFING TREATMENT TO THE REPLACED / REPAIRED PANELS.		280.00	80.00
	TO REMOVE & REFILL AIRCON CONDENSER, ETC INCLUDING TO REFILL GAS.		220.00	120.00

Report Ref No. CS1/ICS18006701/Dqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY RADIATOR COOLANT.	NOT NECESSARY	40.00	30.00
	TO RESET ENGINE MANAGEMENT SYSTEM USING DIAGNOSIS EQUIPMENT.		600.00	-
			6,380.00	3,290.00
GRAND TOTAL			34,271.00	22,952.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				18,350.00

Report Ref No. CS1/ICS18006701/Dqbe2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.