



Your Ref: DMPU1700268H

Date: 17<sup>th</sup> May 2018

Our Ref: CS1/ICS18006701/Dqbe2

**M/s ECICS Ltd**

7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SKE 1952P**

**INSURED VEHICLE: SGX 5089C**

**ACCIDENT DATE: 24/04/2017**

We thank you for your instruction on 10/04/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKE 1952P from M/s Lee Automobile Appraisers Services.
- b) Singapore Accident Statement of Vehicles SKE 1952P and SGX 5089C.
- c) Colour damaged vehicle photographs of SKE 1952P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKE 1952P
Make & Model	: Volvo S60
Year of Registration	: 2012
Chassis Number	: YV1FS485BC2120055

2. We recommend that the repairs of the entire damage require about 9 (nine) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.