

15/5/2010

INS. CASE OWNER:

CC 3 /AIG1800 6708 /F2hbb

LKK:

IDAC:

Surveyor:

Kalin

DOI:

ASSIGNMENT

10/4/18

Date / Time :

10/4/18

Registered in Merimen:

11/4/18

Pre-assign / CCU / FTE



Insured Vehicle No. :

SLM 57864

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S\$

D.O.A :

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability :

%

Final ? Yes / No

SL 90002



INSRS:

WSP:

Tel :

Liability :

RMKS:

LME
M.

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
SL 90002 - X	Non-Reporting ltr (1st):	
SLM 57864 - X	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA :	☐ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☐ ☐
	LOD	☐ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: S\$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost: S\$		
Loss of Rental (LOR): S\$	(days)	
Loss of Use (LOU): S\$	(\$ x days)	
Loss of Income (LOI): S\$	(\$ x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]	
GIA/LTA Search	S\$	
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S\$	3) Survey fee:
Total: S\$	Global Sum S\$:	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: S\$	Name 1:	
Payee 2: (Strike if N.A.) S\$	Name 2:	
Payee 3: (Strike if N.A.) S\$	Name 3:	

(06/11/13)

Name: Mr: Kevin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work shop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 9000 ZYr Regn: 20 Dec 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HyundaiC.C. 1685Colour: BlueA/C: Insured / Std / NI / NASp. Reading: 42429T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1CM HLD 414AH 4099777

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/60 R 16R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Haruh

Front

Rear

R/Bal. 7

mm

R/Bal. 7

mm

L/Bal. 7

mm

L/Bal. 7

mm

D.O.A. 6/4/8D.O.I. 10/4/8Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S wing mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>11/4/8</u>	<u>Labour P/P \$100 / 1 Pp.</u>

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508989 24 Senoko Loop Singapore 758151
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 721
45 Pandan Road Singapore 609286 6 Defu Avenue 1 Singapore 539531
324 Ubi Road 3 Singapore 508649

Date/Time: 10.04.2018 10:47

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305140433

CUSTOMER	REGN NO.: SH 9000Z	MILEAGE
MR/MS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
CUSTOMER NO. 7010045	MODEL I-40	E.....1/2.....
ADDRESS 383 SIN MING DRIVE	DATE/TIME IN 10.04.2018 09:35	
Singapore SINGAPORE 575717	YR OF MANU. 20.12.2017	TARGET DATE
TEL. (R) 65508755 (O)	CHASSIS CODE KMHLB41UMHU099377	COMPLETION DATE/T
(P)		
DISCOUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 06.04.2018

NATURE: 3P 06.04.18/C

AIG

S/NO

LABOR CODE

DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Name:

I/C No.:

Vehicle No.:

SH 9000Z

FZ AIG

Exit Pass

Vehicle No.:

SH 9000Z

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date