REF: CS/FCI18006713/ Krd3 (Secial Instruction: ASS. REC. BY: Kenneh ASSIGNMENT (Office) From (Person): Lyrene Jaw FCI Date/Time: 11418 04.01 pm Estimated Cost: Bill to: OD (TP) WS/TP RES / OD RES / EVA / INV / MY 7 CS SLS 6764 Y To Inspect Vehicle No: Insured: SHC 0740 L at Workshop m/s Tel: 6483 1244 of 176 Sin Ming Drive # 05-12 Policy No: Sum Insured: Excess: Make of Veh: D.O.A. 06/04/2018 (Client's Record) 16/04/18 @ 10.3 (am; Insp: CAMK) CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement: Date/Time: 4-09pm 311 4118 Zila Vehicle IN (OUT) Person Contacted: Date/Time Action/Instruction Estimate Pending ID's VF to defermine liability SHC740 L-CS3/PCT17001153/R176m2 Owner claim - Zila said

1 - 1		4581	GNNIENI			
From:	Date: 16	041018	Veh No.	15676	4 Y _{Yr Regni} /	1 08
Estimated Cost:			Type: W.Car / M.Cy	cle / Bus / Van / I	orry / Taxi / Prime Mo	ver/
OD (TP) WS / TP RES /	OD RES / EVA / INV / MV		Truck / Trail	er or A	,	- 1
To Inspect Vehicle No:	SLS 6761	17	Make /	Audi	A6 00	1984
at Workshop m/s	Ah Lim Mu	tu	Colour Man	y Black	She/C: Insured /	Std / NI / NA
of Blk	10 AMK IND PU	rk 2A #01-09	Sp.Reading	182221	T/Radio Insured I	Std/NI/NA
Insured			Eng/No: L	ı	-17	
Policy No.			C/No.	AUZ	274F18N	17877
Claims No.			Gen. Cond: Good /	Fair / Poor / Burn	nt	
Sum Insured:	Excess:		Steering: Inorder /	Jammed / Leaked	d/Burnt or	
(Client's Record)			Brake: Inoder /	Jammed / Leake	d/Burnt or	
Make of Veh:			Modi: Nil / S/Ri	STD A/Rim	or	
	10. 20		Tyre Size: F:	Pus		
(Policy Condition)	10-30am		R:	7070	24513	5 ZR18
Remark: The veh had co	mmenced its	N/S O/S	BS / DUN / EXNOV	/A / GY / FS / LIZ/	A / MIC / OHTSU / PIR /	SUMI/
repair at the tin	ne of inspection.		TOYO / YOKO or	r		
Bal. or Market Value:	28/c	O	Front	,	Rear	
IDAC Accident Rport:	Consistent?: Yes	s or No	R/Bal.	mm	R/Bal.	9 mm
GIA / PR Seen:	Consistent? : Yes	s or No	L/Bal.	6 mm	L/Bal.	✓ mm
Est. Repairs: 0	3 days Res.: Yes	s or No	D.O.A. 61	14/18	D.O.I. /	6/4/18
Lum Sum:	% 3 Val.: Yes	or No	Survey held at			
CA / REV / REP. /	24 HRS				S / N/S / U/C / Rooft	op or
Date: Pe	erson Contacted:	Vehicle: IN / OUT	N/S	Real	dy Structure affected	due to collision
	/ Instruction		The U/C / Cha	assis frame 7 bo	dy Structure anecieu	aue to compon.
Date / Time Action	parsto Carh	inu				
	//					
		RECEIV	ED 2 3 NOV	2018		
	-	****				
Date/Time, File Pass to?	: Preli. Report		Days Of Repair:	-		
typint	: Final Report		Resurvey No. of	Trip: 3	Survey Fee	140
Date/Time, File Return to?					Transportation	50
27 -		Add Fee	: Site Insp	(\$) S+RS SI	
			Interview	(\$	I Photos	14
Report Format:	TP		Tech Inv	s (\$) ortigin	
Lump Sum / I.B.I: (3	-		Weekend	(\$		THE STATE OF THE S
					noral,	204




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

IF	RST CAPITAL INSU	Affiliated to Federation Internation	Ref : CS/FCI18006713/				
	.01 0/11 11/12 11100	TO TO LID	Nei . CS/FC116006/13/	Krd3			
	ROBINSON ROAD 3-01 CITY HOUSES	SINGAPORE 068877	Date: 11-04-2018 Code: FCI2				
۱.	CANAL TO THE	Policy Particulars	:- THIRD PARTY CLAIM	THE WEST			
	Insured Veh.	SHC 740L	Veh. Inspected	SLS 6764Y			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	D18002772MFSH	Excess (\$)	0.00			
	Assign From	CWS (LURENE JAW)	Assign Date	11/04/2018			
2.		Vehicle Partie	culars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	-0	Steering				
	Brakes		Modification				
	General						
3.		Conditi	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre			mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre			mm			
		Description	on of Damages				
	Brumersto, 1276	General	Information				
	Accident Date	06/04/2018	Inspection Date				
	Survey held at	AH LIM MOTOR CO					
		NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047					
a.			marks	ALTERNATION			
	A)THE INSPECTIO	ON WAS CONDUCTED ON A"WITH CE TO YOUR INSTRUCTIONS, WE	HOUT PREJUDICE" BASIS.				



MS First Capital Insurance Limited co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580

Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

09-04-2018

Our Ref No. D18002772MFSH

Accident Date

06-04-2018

Claim Type. Third Party

Insured Vehicle

SHC0740L

Third Party Vehicle. SLS6764Y

Survey Location

176 SIN MING DRIVE #05-12 SIN MING AUTOCARE

Contact Person.

ZILA

Contact No.

64831244/0

Fax No. 64836170

Survey Type

WITHOUT PREJUDICE: PENDING ID'S VF TO DETERMINE LIABILITY

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

AH LIM MOTOR

COMPANY

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

	1 .						
	Job Sheet (/	/ClaimWS/Surveyor/JobSheet	:/236763) P	RI Documents 🚇 Close 🗶			
ř				PRI Header Details			
	Claim No	D18002772MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & AH LIM I	
	Workshop Name	AH LIM MOTOR COMPANY (Contact Person : ZILA)	Survey Location & Contact Details	176 SIN MING DRIVE #05- Mobile: 0 , Phone: 64831 EmailId: ZILA@AHLIMMOT	244 , Fax: 64	AUTOCARE 836170	
1 3	Our Gurveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: PEN	DING ID'S VF	TO DETERMIN	
	nsured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0740L	TP Vehicle No	SLS6764Y	
R	PRI Recieved Pate	11-04-2018 03:23:44 PM	Surveyor Appointed Date	11-04-2018 04:00:42 PM	Surveyor Accept Date	11-04-2018 (
	,			Survey Report Upload			
I	urveyor nspection ate *:		Surveyor Report Date	11-04-2018	Upload Survey Report *:	Choose File	
	1			Vehicle Particulars			
М	ake	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year •	
CI	hasis No		Engine No		Mileage		
Co	olor		Cubic Capacity				
N	Aultiple Do	cuments Upload					
	File Name	<u> </u>	Upload Multiple I	Documents	Action		
s	urveyor Jo	b Remarks	9				
R	emarks				Save		
						I	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5675E

Vehicle Details

Vehicle No.: SLS6764Y

Vehicle to be Exported: Yes

Intended De-registration Date: 10 Apr 2018

Vehicle Make: AUDI

Vehicle Model: A6 2.0T FSI MU CVT ABS D/AIRBAG

GAS/D

Primary Colour: Blue

Manufacturing Year: 2008

Engine No.: BPJ114305

Chassis No.: WAUZZZ4F18N178771

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$44,199.00 Original Registration Date: 10 Nov 2008

First Registration Date: 10 Nov 2008

Transfer Count: 2

Actual ARF Paid: \$44,199.00

Intended PARF Rebate Details

Yes PARF Eligibility:

PARF Eligibility Expiry Date: 09 Nov 2018

PARF Rebate Amount: \$22,099.00

Intended COE Rebate Details

COE Expiry Date: 09 Nov 2018

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$12,001.00


COE Rebate Amount: \$441.00

Total Rebate Amount: \$22,540.00

The information contained herein is correct as at 10 Apr 2018

OK

My- 529/C



Your Policy Details

Here's a quick summary of your policy:

Your Motor Car insurance policy begins 06/10/2017 and runs until 05/10/20

Policy Number: MT/00421520

Policyholder/ Car Owner : Keng Chong Chia

Declared Main Driver : Keng Chong Chia

Vehicle Registration No. : SLS6764Y

Coverage/ Driver Plan : Third-Party Fire and Theft/ Value Plan

Policy Period : 06/10/2017 to 05/10/2018

Vehicle Usage : Private and Business Use

No Claim Discount : 0 %

Offence Free Discount : No


Based on the information provided and coverage selected, you are covered following driver plan:

Value Plan: only the Main Driver and any Named Driver(s) on the policy are

Your 'My Account' Login Details

We have created an account for you which gives you details of your own pen allowing you to manage your own insurance needs 24/7.

Your identification (ID) is your FIN/NRIC Your password is: ebNfwYdz







Contact us at

Hotline: (65) 6532 2888

E-mail: CustomerService@DirectAsia.com

YOUR POLICY SCHEDULE

This document forms part of your contract with us and should be read together with your Certificate of Insurance and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Cai	- T	n	CI	1	ra	n	-	0
Cal			Э.	ч	ıa		•	_

Policy number MT/00421520

Period of cover Policy begins 06/10/2017 15:23 and runs until 05/10/2018 23:59

Premium S\$ 1,262.86 (inclusive of GST)

Own Damage Excess S\$ 900.00 (before any applicable GST)

Windscreen Excess Not Applicable (before any applicable GST)

Vehicle Details

Vehicle Registration SLS6764Y Chassis number : WAUZZZ4F18N178771

Audi A6 2.0 TFSI MU Make and model Car usage : Private and Business Use

(A)

Year of registration 2008

No. of Finance company / Hire accidents/claims in : NA

purchase the last 36months

Is your car modified?

No (Modifications are according to LTA guidelines)

Policyholder

Policyholder : Chia, Keng Chong

127 LORONG L TELOK KURAU, #04-04 BLU CORAL, Singapore 425562 **Mailing Address**

F-mail Address sam4000@hotmail.s Mobile Number : 91054000

q

No Claims Discount : 0% Your NCD is 0% : you were not insured in the last (NCD)

because 12 months but you have been

insured before

Main Driver Details

Named Driver Details

licence

Main Driver : Chia, Keng Chong Date of Birth

: 15/07/1973 **Marital Status** : Married Gender

: Male Occupation : Business owner/self employed : 0 Certificate of Merit Number of accidents or : No

months

claims in the last 36 Years of valid driving

licence : > 5

Named Driver (1) Chia, Kheng Wei (Non-YIED)

Date of Birth : 30/03/1977 **Marital Status**

: Male Gender Occupation : Business owner/self employed

Certificate of Merit Number of accidents or : 1: Not at fault : No claims in the last 36 Years of valid driving months

: > 5 Important Note: This policy is on a named driver basis. Any unnamed drivers will not be covered.

Young and/ or Inexperienced Driver (YIED): refers to any driver who is below the age of 30 or holds a driving licence for less than 2 years.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	09/04/2018 17:49
Date Of Accident	06/04/2018 07:30
Exact Location Of Accident	SLIP RD NEAR BCA ACADEMY
Country/State of Loss	SINGAPORE

	DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SLS6764Y		
Insured/Policyholder			
Name Of Registered Owner	KENG CHONG CHIA		

NRIC No S7325675E Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-94733233
Alternative Phone No OTHERS-94733233

Vehicle Particulars

Manufacturer AUDI

Model A6-2.0 TFSI (A)

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy NO

Policy Number MT/00421520

Cover Note Number

Driver

Name of Driver CHIA KHENG WEI (XIE QINGWEI)

 NRIC No
 S7708261A

 Date Of Birth
 30/03/1977

 Occupation
 INDOOR

 Date Of Driving Pass
 02/04/1997

Driving Experience 21 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-94733233

Fax Number

Contact Number OFFICE-94733233

EMail Address ANSONCHIA@GMAIL.COM

Address

BLK 467A FERNVALE LINK

#26-513

Postcode

791467

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

SIBLING

Vehicle Registration Number of Driver's Own

Vehicle

A STATE OF THE STA

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC740L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ALL	III.	- 10	STA	- 11

Date Of Report

09/04/2018 17:49

Date Of Accident

06/04/2018 07:30

Exact Location Of Accident

SLIP RD NEAR BCA ACADEMY

Country/State of Loss

SINGAPORE

DETAILS OF	OWN	VEHICLE

Vehicle Registration Number

SLA6764Y

Insured/Policyholder

Name Of Registered Owner

KENG CHONG CHIA

NRIC No

S7325675E

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-94733233

Alternative Phone No

OTHERS-94733233

Vehicle Particulars

Manufacturer

AUDI

Model

A6-2.0 TFSI (A)

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

NO

Policy Number

MT/00421520

Cover Note Number

Driver

Name of Driver

CHIA KHENG WEI (XIE QINGWEI)

NRIC No
Date Of Birth
Occupation

S7708261A 30/03/1977

Date Of Driving Pass

INDOOR 02/04/1997

Driving Experience

21 YEARS AND 0 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-94733233

Fax Number

Contact Number

OFFICE-94733233

EMail Address

ANSONCHIA@GMAIL.COM

Address

BLK 467A FERNVALE LINK

#26-513

Postcode

791467

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SIBLING

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC740L

Vehicle Make/Model/Colour

Details Of Properties

Of Froperties

TAXI

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centile Personnel's Signature

Name:

NRIC/FIN No .:

Sketch Plan Pg. 2

Date of accident: 060	104/18 Time: 9:40	Location:	Slip od New BCA Arademy
	7644 Vehicle B:	PHC7401	Vehicle C:
KETCH PLAN	W 11		4
		· ·	8
	A.	. 1 :	Collection
		× 1 =	8 rac
2	3		
ESCRIBE CIRCUMSTANCES	OF THE ACCIDENT		
0 /	towards CTE	, p+ +	he clip road. I was
+ (itesina	left when I number plate		umped from behind by
I did was		particular	incident and all
report this	issue -		
Remarks : Please forward	im Motor		rkshop Reporting Only
My workshop : Email address : (in 9 & myself : Email address :	sonchia Ogmail · con	n Hp:	94733233
Note: Please take note th you own policy. Kindly ch	at your insurer have 14 days ti eck with your own insurer for	meframe for you more informatio	to submit own damage claim under n.
CLARATION Ve declare the foregoing parti	culars are true in every respect.		
licyholder's Signature	Driver's Signature		3

AH LIM MOTOR COMPANY



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COP

M/S:

KENG CHONG CHIA

BLK 467A FERNVALE LINK

#26-513

SINGAPORE 791467

Estimate No:

MC0912998

Date:

11 Apr 2018

Policy No:

MT/00421520

Veh Reg No:

SLS6764Y

Make/Model:

AUDI A6 2.0T FSI MU

Your Ref No:

ATTN:

SLS6764Y

Claim Type:

Third Party

Accident Date:

06/04/2018

TP Veh Reg No:

SHC740L

(Foot cap) Not Nothorised

LIEm 87

Resorry After Paint

3da

Estimate Repair Cost to Vehicle No :SLS6764V

	Description	Quantity	List Price	Amount
	Description	Quantity	S\$	Amount S\$
	SPARE PARTS		33	23
1	REAR BUMPER	1 PC	N 1,808.70 ⊀	
2	REAR BUMPER SIDE RETAINERS LH & RH	2 PC	5 76.70 x	
3	REAR BUMPER CLIPS	12 PC	1 30.00 X	
4	REAR BUMPER LOWER SPOILER	1 PC	149.50 L	
5	REAR BUMPER REVERSE SENSOR SIDE	2 PC	\$5 491.30 X	
6	REAR BUMPER REVERSE SENSOR CTR	2 PC	√n 491.30 X	
7	REAR WHEEL BEARING WITH HUB LH	1 PC	477.70 ?	
8	REAR ABSORBER LH	1 PC	360.20 7	
			3,885.40	
		Less 10%	388.54	3,496.86
	Special Nett			
9	SPORT RIM LHR - CHECK PRICE	1 PC	Pel 0.00 -	
			0.00	0.00
	LABOUR			
10	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
11	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	25
12	TO RESET REAR BUMPER REVERSE SENSOR CTR, SIDE	1 PC	250.00 X	
13	TO REMOVE & REINSTALL/REPLACE UNDERCARRIAGE REAR WHEEL BEARING LH, WHEEL BEARING HUB, ABSORBER LH	1 PC	280.00	
14	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	ルル 120.00 X	
5	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR BUMPER REINFORCEMENT, REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00 2	al
16	TO SPRAY REAR BUMPER, REAR FENDER LH, REAR BUMPER REINFORCEMENT.	1 PC	600.00	od





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S: KENG CHONG CHIA

BLK 467A FERNVALE LINK

#26-513

SINGAPORE 791467

ATTN:

Your Ref No: SLS6764Y

Claim Type:

Third Party

Accident Date:

SURVEYOR COPY

Estimate No:

MC0912998

Date:

11 Apr 2018

Policy No:

MT/00421520

Veh Reg No: Make/Model: **SLS6764Y**

AUDI A6 2.0T FSI MU CVT

06/04/2018

TP Veh Reg No:

SHC740L

Estimate Repair Cost to Vehicle No :SLS6764Y

Description	Quantity List Pri	ce Amount
	<u>SS</u>	S\$
	Total	S\$ 5,466.86
	Add GST @ 7%	382.68
	Total Amount Payable	S\$ 5,849.54

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND EIGHT HUNDRED FORTY NINE AND CENTS FIFTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify

- the Repairer of the following: · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(:) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Carrier Land	Affiliated to Federation Interna	ationale Des Experts En Autom	nobile		
MS	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI180067	13/Krd3e2		
	ROBINSON ROAD -01 CITY HOUSES	INGAPORE 068877	Date: 28-11-2018 Code: FCI2			
1.		Policy Particula	rs :- THIRD PARTY CLAI	M		
	Insured Veh.	SHC 740L	Veh. Inspected	SLS 6764Y		
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00		
	Claim No.	D18002772MFSH	Excess (\$)	0.00		
	Assign From	LURENE JAW	Assign Date	11/04/2018		
2.		Vehicle Pa	rticulars & Condition			
	Make & Model	AUDI A6 (A)	c.c	1984		
	Engine No.	HIDDEN	Year of Reg.	2008		
	Chassis No.	WAUZZZ4F18N178771	Colour	MATALLIC DARK BLUE		
	Odometer	182221	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Cond	ditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	245/35Z R19	DUNLOP	6 mm		
	L/H Front Tyre	245/35Z R19	DUNLOP	6 mm		
	R/H Rear Tyre	245/35Z R19	TOYO	4 mm		
	L/H Rear Tyre	245/35Z R19	TOYO	4 mm		
4.		Descri	ption of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE	N/S REAR PORTION.			
	DAMAGES SEE D	ETAILS.				
5.		Gene	eral Information	ADJUNE NEW YORK		
	Accident Date	06/04/2018	Inspection Date	16/04/2018		
	Survey held at	AH LIM MOTOR CO				
		NO 10 ANG MO KIO IND PK #01-09 AMK AUTOPOINT SINGAPORE 568047	2A			
5a.			Remarks			
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estima	te Days of Repair			
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	rs .		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 6764Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,808.70	-
2	REAR BUMPER SIDE RETAINERS LH & RH	SERVICEABLE	76.70	-
12	REAR BUMPER CLIPS	NOT NECESSARY	30.00	-
1	REAR BUMPER LOWER SPOILER	MISSING	149.50	149.50
2	REAR BUMPER REVERSE SENSOR SIDE	SERVICEABLE	491.30	-
2	REAR BUMPER REVERSE SENSOR CTR	SERVICEABLE	491.30	-
1	REAR WHEEL BEARING WITH HUB LH	* CHECK	477.70	-
1	REAR ABSORBER LH	* CHECK	360.20	-
	LESS 10% DISCOUNT		-388.54	-14.95
			3,496.86	134.55
	SPECIAL NETT ITEMS			
1	SPORT RIM LHR (SN)(NPA)	DENTED		_
i i	S. S. C.		-	-
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNIT, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	15.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		, 80.00	60.00
	TO RESET REAR BUMPER REVERSE SENSOR CTR,SIDE.	NOT NECESSARY	250.00	-
	TO REMOVE & REINSTALL/REPLACE UNDERCARRIAGE REAR WHEEL BEARING LH, WHEEL BEARING HUB, ABSORBER LH.	* CHECK	280.00	-
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	NOT NECESSARY	120.00	-
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR BUMPER REINFORCEMENT.REAR FENDER LH INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	200.00
	TO SPRAY REAR BUMPER, REAR FENDER LH, REAR BUMPER REINFORCEMENT.		600.00	400.00
			1,970.00	675.00

Report Ref No. CS/FCI18006713/Krd3e2



Page No.:2 of 2

GRAND TOTAL	5,466.86	809.55
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$1,034.11 NETT)		809.55

Report Ref No. CS/FCI18006713/Krd3e2

KONG SENG CHEONG

Licensed Appraiser