

ASS. REC. BY:

REF: CS/SMO18006716/ K-1d3<sup>02</sup> Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time 11/04/2018 @ 3:21pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 6331R Insured: XE 3778J

at Workshop m/s: Lim Motor Tel: 9271 2214

of Blk 160 Sin Ming Drive # 05-20

Policy No: Claim No: CMTD1801577/GPL

Sum Insured: Excess:

Make of Veh: / D.O.A. 09/04/2018  
(Client's Record)CA / REV / REP. & REV 24 HRS 'wp' 12/04/2018  
H.O.D. Endorsement:

Date/Time: 3:27pm @ 11/4/18 Person Contacted: chris Vehicle-IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJW 6331R - NA / INC / 7012 331 / h4 DOA: 26/06/17
	XE 3778J - X
BLU-	Revert advise via email
	lump sum \$5600 - (Red: 7365.80 ; 56%)

ASS. REC. BY:

REF:

Sum/

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SYW 6331R

Yr Regn: 04, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S Sympy

c.c. 14.98

Colour:

M. Maron

A/C: Insured / Std / NI / NA

Sp. Reading

169844

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN13AA G11 70110930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F. Giti

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

9/4/18

D.O.I.

12/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/4

File passed to Carhume

RECEIVED 27 APR 2004

Date/Time, File Pass to?



: Prell. Report

1) 26/4 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

350

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Tp

Lump Sum / I.B.I. (\$

5600f

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Wednesday, 11 April 2018 3:21 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** chan pick yuen; Gnoh, Pau Loong  
**Subject:** CMTD1801577/GPL - SUV(LKK)/ XE3778J & SJW6331R ACC ON 09.04.18  
**Attachments:** GIA REPORT-SJW6331R.PDF

Our Reference: CMTD1801551/THE

Dear LKK AUTO,

Please make arrangement to conduct the survey for SJW6331R.

Please be informed that Thelma Choo the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** chan pick yuen [mailto:chris\_chanbebe@hotmail.com]  
**Sent:** Wednesday, April 11, 2018 3:14 PM  
**To:** Teo, Grace  
**Subject:** Re: CMTD1801577/GPL - PRI/ XE3778J & SJW6331R ACC 09.04.18

Dear Sir / Mdm ,

LKK AUTO CONSULTANT PTE LTD .

Please let us have your reply soon . Thanks

Regards,  
Chris Chan Pick Yuen



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1801577/GPL

Date: 13/4/2018

Our Ref: CS/SMO18006716/Ktd3

The Motor Claims Department  
SOMPO INSURANCE SINGAPORE PL

**Without Prejudice**

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SJW 6331R.**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/04/2018 at the premises of M/s Lim Motor and have the following to report: -

Workshop Estimate Amount	: S\$ 12,965.80
Revised Estimate Amount	: S\$ 1,795.40
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

**Description of Damage:**

The vehicle sustained damages at the o/s body portion.



Repair days: 7

**Comments/ Present Status:**

Damages Consistent.

Yours faithfully  
Kenneth  
Licensed Appraiser

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Wednesday, April 11, 2018 2:36 PM  
**To:** chan pick yuen  
**Cc:** Gnoh, Pau Loong  
**Subject:** CMTD1801577/GPL - PRI/ XE3778J & SJW6331R ACC 09.04.18

Our Reference: CMTD1801577/GPL  
Your Reference: SJW6331R

**Without Prejudice**

Date: 11<sup>th</sup> April 2018

**Attention:**  
**M/S LIM MOTOR PTE LTD**

Dear Chris,

**ACCIDENT INVOLVING XE3778J & SJW6331R ON 09.04.2018**

We refer to your Notice of Accident dated 11/04/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Sompo Insurance Singapore Pte Ltd

[www.sompo.com.sg](http://www.sompo.com.sg)

Sompo Insurance Singapore Pte Ltd

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** chan pick yuen [[mailto:chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)]

**Sent:** Wednesday, April 11, 2018 11:19 AM

**To:** Claims - Motor Survey

**Subject:** SJW6331R DOA 4/9/18

Dear Sir / Mdm ,

Enclosed is our GIA report . We got video to prove that your insured lorry cut in & caused accident.  
Please let us have your 10 name list of surveyor to survey our clients car : SJW6331R .

Best Regards

Chris Chan

Lim Motor Pte Ltd

Hp:92712214

Block 160 Sin Ming Drive

,Sin Ming Autocity #05-20

Get [Outlook for iOS](#)

From: Peter Lim <[admin@lscauto.com](mailto:admin@lscauto.com)>  
Sent: Wednesday, April 11, 2018 10:35:04 AM  
To: [chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)  
Subject: Fwd: GIA REPORT-SJW6331R

----- Forwarded message -----

From: Gareth Deng <[garethdgh@gmail.com](mailto:garethdgh@gmail.com)>  
Date: Tue, 10 Apr 2018 at 11:25 PM  
Subject: Fwd: GIA REPORT-SJW6331R  
To: <[admin@lscauto.com](mailto:admin@lscauto.com)>

Hi Peter

Forward you my report for the accident ( Nissan Sylphy Maroon SJW6331R)

Regards

Gareth Deng

----- Forwarded message -----

From: Susan <[susan@ajaxmars.com](mailto:susan@ajaxmars.com)>  
Date: Tue, Apr 10, 2018 at 7:15 PM  
Subject: GIA REPORT-SJW6331R  
To: [garethdgh@gmail.com](mailto:garethdgh@gmail.com)  
Cc: [group@ajaxmars.com](mailto:group@ajaxmars.com)

Dear Sir,  
Please find attached a copy of GIA Report for your perusal.  
Thank you.  
Best regards,

Mayury

Email: [susan@ajaxmars.com](mailto:susan@ajaxmars.com)

**AJAX MARS Pte Ltd**

120 Lower Delta Road

#08-08 Cendex Centre

Singapore 169208

Tel: (65) 6333 2222 Fax: (65) 6849 9155

<http://www.ajaxadjusters.com>

\*CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Virus-free. [www.avast.com](http://www.avast.com)





## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 13 April 2018 2:49 PM  
**To:** 'Teo, Grace'  
**Cc:** 'Gnoh, Pau Loong'; Admin-D (LKKAuto); assignments  
**Subject:** FW: CMTD1801577/GPL - SUV(LKK)/ XE3778J & SJW6331R ACC ON 09.04.18  
**Attachments:** PRELI ADVISED SJW 6331R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJW 6331R**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Wednesday, 11 April, 2018 3:30 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** 'chan pick yuen' <[chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)>; 'Gnoh, Pau Loong' <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>  
**Subject:** RE: CMTD1801577/GPL - SUV(LKK)/ XE3778J & SJW6331R ACC ON 09.04.18

Dear Grace,

Noted, with thanks.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Wednesday, 11 April 2018 3:27 PM  
**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** chan pick yuen ([chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)) <[chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)>; Gnoh, Pau Loong  
<[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>  
**Subject:** CMTD1801577/GPL - SUV(LKK)/ XE3778J & SJW6331R ACC ON 09.04.18

Dear All,

Please be formed that the claim reference is CMTD1801577/GPL and the handler, Gnoh Pau Loong.

We apologize for the typo error.

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 9124J

**Vehicle Details**

Vehicle No.: SJW6331R  
Vehicle to be Exported: Yes  
Intended De-registration Date: 11 Apr 2018  
Vehicle Make: NISSAN  
Vehicle Model: SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR  
Primary Colour: Red  
Manufacturing Year: 2010  
Engine No.: HR15344716B  
Chassis No.: JN1BAAG11Z0110750  
Maximum Power Output: 80.0 kW (107 bhp)  
Open Market Value: \$18,262.00  
Original Registration Date: 06 Apr 2010  
First Registration Date: 06 Apr 2010  
Transfer Count: 1  
Actual ARF Paid: \$18,262.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 05 Apr 2020  
PARF Rebate Amount: \$10,044.00

**Intended COE Rebate Details**

COE Expiry Date: 05 Apr 2020  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$20,340.00  
COE Rebate Amount: \$4,036.00  
**Total Rebate Amount: \$14,080.00**

The information contained herein is correct as at 11 Apr 2018

OK

\$18,262.00  
- 14,080.00  
-----  
\$4,182.00

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/04/2018 19:03
Date Of Accident	09/04/2018 17:55
Exact Location Of Accident	ALONG JURONG PIER ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW6331R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DENG QINGHENG GARETH
NRIC No	S8929124J
Email Address	GARETHDQH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91119146
Alternative Phone No	OFFICE-91119146
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10777701
Cover Note Number	
<b>Driver</b>	
Name of Driver	DENG QINGHENG GARETH
NRIC No	S8929124J
Date Of Birth	25/08/1989
Occupation	INDOOR
Date Of Driving Pass	14/12/2009
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91119146
Fax Number	
Contact Number	OFFICE-91119146
Email Address	GARETHDQH@GMAIL.COM

Address	738 TAMPINES STREET 72 #05-42
Postcode	520738
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident


ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD ON THE EXTREME LEFT LANE, WHEN VEHICLE B COMING FROM MY RIGHT REAR CAME SO CLOSED TO MY VEHICLE AND GRAZED THE RIGHT PORTION OF MY VEHICLE WHILST MOVING. VEHICLE B THEN SEEN MOVING OFF WITHOUT STOPPING AND I HAD TO GIVE CHASE FOR ABOUT 200METERS TO STOP VEHICLE B. I THEN INFORMED THE DRIVER OF VEHICLE B THAT HIS VEHICLE HAD GRAZED AGAINST MY VEHICLE. THIS INCIDENT WAS CAPTURED IN MY IN CAR VIDEO WHICH I WILL BE FORWARDING TO MARS HQ FOR RECORD AND CLAIMS PURPOSES. NO BODY WAS INJURED BUT I DID WENT TO SEE A DOCTOR AND WAS GIVEN 2 DAYS OF MEDICAL LEAVE. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL FORWARD TO INSURANCE ONCE INSURED SEND
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3778J
Vehicle Make/Model/Colour	VOLVO / FM420 42T RSS SC WB3500 / WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEW AH CHYE
NRIC/Passport Number	S1581381D
Contact Number	81277673
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report objectively the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may affect insurance cover and/or result in policy cancellation.
4. The issue and acceptance of this form by you and/or your partner is not an admission of policy liability on the part of insurance companies.
5. Any case reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Masters of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon request by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available thereafter.
8. Consent under the Personal Data Protection Act (PDPA):
  - (a) I understand, acknowledge, agree and consent that:
    - (i) My insurer, my reinsurer and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data (personal information set out in this Form) and any other personal information provided by me or possessed by my insurer/reinsurer for the purposes of:
      - (i) processing and/or handling such Personal Information; and
      - (ii) disclosing and/or transferring such Personal Information to all insurer(s) who have insured my vehicle(s) involved in the accident (all insurers who have insured vehicle(s) involved in the accident shall be collectively referred to as the Insurers); the Insurers' reinsurer(s); the Monetary Authority of Singapore and any relevant government agency/authority (such as the Police), for the purposes of:
        - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
        - (ii) investigating the accident and/or my claims;
        - (iii) carrying out and/or dealing with my obligations in responding to any enquiries by me;
        - (iv) administering my claims (including the issuing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the sums as well as on the external cover of envelopes/mail packages); and/or
        - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
    - (b) collectively the "Purposes".
    - (c) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' reinsurer(s) may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - (d) any Personal Information may be disclosed to any of the Insurers and/or GIA to their third party service providers or agents including their insurers/reinsurers which may be based outside of Singapore for one or more of the above Purposes.


*[Signature]*  
Policyholder's Signature / Date & Time

Driver's Signature of driver at the policyholder / Date & Time

VERIFIED BY AMK MARK  
REPORTING OFFICER  
Hashim Kamari

Witnessed by Reporting Centre  
Personnel  
100418

### Sketch Plan



ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD ON THE EXTREME LEFT LANE, WHEN VEHICLE B COMING FROM MY RIGHT REAR CAME SO CLOSED TO MY VEHICLE AND GRAZED THE RIGHT PORTION OF MY VEHICLE WHILST MOVING. VEHICLE B THAN SEEN MOVING OFF WITHOUT STOPPING AND I HAD TO GIVE CHASE FOR ABOUT 200METERS TO STOP VEHICLE B. I THAN INFORMED THE DRIVER OF VEHICLE B THAT HIS VEHICLE HAD GRAZED AGAINST MY VEHICLE. THIS INCIDENT WAS CAPTURED IN MY IN CAR VIDEO WHICH I WILL BE FORWARDING TO MARS HQ FOR RECORD AND CLAIMS PURPOSES. NO BODY WAS INJURED BUT I DID WENT TO SEE A DOCTOR AND WAS GIVEN 2 DAYS OF MEDICAL LEAVE.

STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

10 April 2018 at 1:16 PM

Date/Time:

10 April 2018 at 1:17 PM



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8929124J



Name  
DENG QINGHENG, GARETH

邓 庆 恒

Race  
CHINESE

Date of birth 25-08-1989 Sex M

Country of birth  
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S8929124J

Name  
DENG QINGHENG, GARETH

Birth Date 25 Aug 1989

Issue Date 14 Dec 2009



001812478C



K+

# LIM MOTOR PTE LTD

BLOCK 160 Sin Ming Drive, Sin Ming Autocity # 05-20 Singapore 575722  
Tel : (65) 65527761 HP: 82658330

Not withorn  
U/Rp 8560ch  
Purway After Rain  
7days

DENG QINGHENG GARETH  
BIK 160 SIN MING DRIVE  
# 05-20 SIN MING AUTOCITY  
Singapore 575722

11<sup>th</sup> April 2018

Accident date: 9<sup>th</sup> APRIL 2018

Estimated repair cost for vehicle no: SJW6331R NISSAN SYLPHY 1.5 '10

S/n	Qty	Items	U/price	Amount	
1	1	Rear Bumper Side Bracket			
2	1	Rear Bumper		Rn \$22.10	X
3	1	Rear fender -RH		Rn \$784.40	X
4	1	Front R/H door		Rn \$957.90	✓
5	1	front R/H door inner lock		Rn \$1,050.30	✓
6	1	Rear R/H door		Rn \$350.20	X
7	1	Rear R/H door inner lock		Rn \$1,050.30	✓
				Rn \$350.20	X

305

Subtotal :- \$4,565.40

S/n	Qty	Items/Nett	U/price	Amount	
1	1	front R/H door inner trim board		Rn \$591.70	X
2	1	front R/H door inner rubber		Rn \$131.70	✓ 50%
3	1	front R/H door side mirror		Total \$480.20	2
4	1	Front R/H door gear		Rn \$385.10	2
5	1	Rear Fender inner Trim Board-RH		Rn \$250.20	X
6	1	Rear R/H door inner trim board		Rn \$591.70	X
7	1	Rear R/H door inner rubber		Rn \$131.70	50% Rn
8	1	Rear R/H door lower hinge		Rn \$60.10	X
9	1	Rear R/H door gear		Rn \$378.20	X
10	1	rear Tyre-RH		Rn \$450.00	X
11	1	Rear R/H Rim		Rn \$500.00	X
12	1	rear RH Shock absorber		Rn \$325.00	X

105

Sheet1

13	1	Rear R/H Lower Arm	Pr	\$354.70	X
14	1	Rear R/H Knuckle Arm	NIP	\$314.30	X
15	1	rear R/H Knuckle Arm Bearing	M	\$235.80	X
16		1pc Rear Axle Beam	B	\$1885.00	✓
Subtotal :-				\$5,180.40	

Labour charges

To Remove & refix cushion	\$120.00	1001
To Remove & refix rear RH undercarriage	\$280.00	249
To check wheel alignment computer	\$120.00	601
Tuff kote	\$120.00	901
To Check Wiring System	\$80.00	201
Towing charges	\$100.00	801
Panel beating	\$1,200.00	8001
Spray painting	\$1,200.00	7201
	\$3,220.00	
Total:-	\$12,965.80	
	14850.80	

## Sheet 1

**BLOCK 160 Sin Ming Drive, Sin Ming Autocity # 05-20 Singapore 575722**  
Tel : ( 65 ) 65527761 HP: 82658330

Not within  
V Lp 87  
Bureau After Rain  
Fday

DENG QINGHENG GARETH  
Blk 160 SIN MING DRIVE  
# 05-20 SIN MING AUTOCITY  
Singapore 575722

11<sup>th</sup> April 2018

Accident date: 9<sup>th</sup> APRIL 2018

Estimated repair cost for vehicle no: SJW6331R NISSAN SYLPHY 1.5 '10

S/n	Qty	Items	U/price	Amount	
1	1	Rear Bumper Side Bracket		\$22.10	X
2	1	Rear Bumper		\$784.40	X
3	1	Rear fender -RH		\$957.90	✓
4	1	Front R/H door		\$1,050.30	✓
5	1	front R/H door inner lock		\$350.20	X
6	1	Rear R/H door		\$1,050.30	✓
7	1	Rear R/H door inner lock		\$350.20	X
Subtotal :-				\$4,565.40	

S/n	Qty	Items/Nett	U/price	Amount
1	1	front R/H door inner trim board	R	\$591.70 X
2	1	front R/H door inner rubber	R	\$131.70 ✓ 50/R
3	1	front R/H door side mirror		\$480.20 ?
4	1	Front R/H door gear		\$385.10 ?
5	1	Rear Fender Inner Trim Board-RH	R	\$250.20 X
6	1	Rear R/H door inner trim board	R	\$591.70 X
7	1	Rear R/H door inner rubber	R	\$131.70 50/R
8	1	Rear R/H door lower hinge	R	\$60.10 X
9	1	Rear R/H door gear	R	\$378.20 X
10	1	rear Tyre-RH	R	\$450.00 X
11	1	Rear R/H Rim	R	\$500.00 X
12	1	rear RH Shock absorber	R	\$325.00 X

**LKK Auto Co**      **the Repairer**

- To resolve the dispute
- To identify the parties to the survey
- Parties has a right to object to information
- **68d part 1, 2, 3 and 4 without prejudice basis**
- No legal liability is imposed on the surveyor
- **Supplemental to the 68d survey and is subject to the 68d Insurance Company**

#### Acknowledged by Reporter

Signature:

Date:

# Lim Motor Pte Ltd

160 Sin Ming Drive #05-20

Sin Ming Auto City

Singapore 575722

Phone Number: 6552 7761

Fax Number: Mobile No. 9766 7543

Date: 4/13/2018 7:49 PM

VIN

Technician:

Order NO:

Customer: SJW6331R  
Company: 169844km  
License NO:  
Odometer:

## VEHICLE ALIGNMENT REPORT

NISSAN, SYLPHY K6G11 (2WD), 06-10 (Customized)

### Primary Angles

		Initial	Specifications Min Max	Final
Front	Caster	Left Right	4°00' 5°30'	4°00' 5°30'
	Camber	Left	-0°55'	-1°42'
		Right	-0°55'	-1°24'
	Toe	Left	0.0mm	4.8mm
		Right	0.0mm	3.8mm
	Total	8.6mm	1.1mm	8.6mm
Rear	Camber	Left Right	-2°01' -2°01'	-1°42' -2°48'
	Toe	Left	0.9mm	1.0mm
		Right	0.3mm	-4.8mm
	Total	2.3mm	5.0mm	-3.8mm
	Max Thrust Angle	0°02'		-0°28'

### Secondary Angles

	Initial	Specifications Min Max	Final
SAI	Left Right	9°55' 9°55'	9°55' 9°55'
Included Angle	Left		

OK





You Call, We Tow - Fast, Secured, Reliable

Blk 27 Marine Crescent Ville #10-01 Singapore 440027 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: <http://www.gaoexpress towing.sg>

## CASH SALE/WORK ORDER

實號

Messrs: \_\_\_\_\_

車號

Vehicle No: SW6331R

車型

Model No: Nissan Sylphy

時間(日/夜)

Time (day/night): 6:05 pm

Contact No: 97667543

由

Location: Tiong Pagar Road

到

To: Sin Ming Auto City

其他

Others: \_\_\_\_\_

Cash \$: 80.00

經手人

Authorised By: Jim

Tow Truck

Driver Name: Jim

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。  
Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

No. 141600  
Date: 9/4/18

- |   |   |  |   |  |                                     |   |                                       |   |   |  |                               |  |
|---|---|--|---|--|-------------------------------------|---|---------------------------------------|---|---|--|-------------------------------|--|
| <input type="checkbox"/> Jump Start/Changing of battery | <input type="checkbox"/> Tyre Replacement | <input checked="" type="checkbox"/> Accident/Breakdown | <input type="checkbox"/> Multi/Basement | <input type="checkbox"/> With Load/Cargo Box | <input type="checkbox"/> King Dolly | <input type="checkbox"/> Transport Charge | <input type="checkbox"/> Low Body Kit | <input type="checkbox"/> Door Opening Service | <input type="checkbox"/> Crane Up/Winch Out | <input type="checkbox"/> Collect Doc/Key | <input type="checkbox"/> Repo | <input type="checkbox"/> Woodlands and Tuas Checkpoint |
|---|---|--|---|--|-------------------------------------|---|---------------------------------------|---|---|--|-------------------------------|--|

To Remove & refix rear BL

# 高

# GAO

Express Towing Services

You Call, We Tow - Fast, Secured, Reliable



Blk 27 Marine Crescent Ville #10-01 Singapore 440027 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: <http://www.gaoexpress towing.sg>

## CASH SALE/WORK ORDER

實號

Messrs: \_\_\_\_\_

車號

Vehicle No: SJW6331R

車型

Model No: Nissan Sylphy

時間(日/夜)

Time (day/night): 6:05pm

Contact No: 97667543

由

Location: Tiong Pagar Road

到

To: Sin Ming Auto City

Cash \$: 80.00

其他

Others: \_\_\_\_\_

經手人

Authorised By: Am

Tow Truck

Driver Name: Jim

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

No. 141600

Date: 9/4/18

☐ Jump Start/Changing of battery

☐ Tyre Replacement

☒ Accident/Breakdown

☐ Multi/Baseament

☐ With Load/Cargo Box

☐ King Dolly

☐ Transport Charge

☐ Low Body Kit

☐ Door Opening Service

☐ Crane Up/Winch Out

☐ Collect Doc/Key

☐ Repo

☐ Woodlands and Tuas Checkpoint





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18006716/Ktd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-04-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 3778J	Veh. Inspected	SJW 6331R
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801577/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	11/04/2018

## 2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JN1BAAG11Z0110950	Colour	METALLIC MAROON
Odometer	169844	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI	8 mm
L/H Front Tyre	195/65 R15	GITI	8 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	09/04/2018	Inspection Date	12/04/2018
Survey held at	LIM MOTOR PTE LTD 160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 6331R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	22.10	-
1	REAR BUMPER	SERVICEABLE	784.40	-
1	REAR FENDER-RH	BENT	957.90	957.90
1	FRONT R/H DOOR	BENT	1,050.30	1,050.30
1	FRONT R/H DOOR INNER LOCK	TO REPAIR SEE LABOUR	350.20	-
1	REAR R/H DOOR	BENT	1,050.30	1,050.30
1	REAR R/H DOOR INNER LOCK	TO REPAIR SEE LABOUR	350.20	-
	LESS 30% DISCOUNT		-	-917.55
			4,565.40	2,140.95
<b><u>NETT ITEMS</u></b>				
1	FRONT R/H DOOR INNER TRIM BOARD (N)	SERVICEABLE	591.70	-
1	FRONT R/H DOOR SIDE MIRROR (N)	JAMMED	480.20	480.20
1	FRONT R/H DOOR GEAR (N)	DISTORTED	385.10	385.10
1	REAR FENDER INNER TRIM BOARD-RH (N)	SERVICEABLE	250.20	-
1	REAR R/H DOOR INNER TRIM BOARD (N)	SERVICEABLE	591.70	-
1	REAR R/H DOOR LOWER HINGE (N)	TO REPAIR SEE LABOUR	60.10	-
1	REAR R/H DOOR GEAR (N)	SERVICEABLE	378.20	-
1	REAR TYRE-RH (N)	SERVICEABLE	450.00	-
1	REAR R/H RIM (N)	TO REPAIR SEE LABOUR	500.00	-
1	REAR RH SHOCK ABSORBER (N)	SERVICEABLE	325.00	-
1	REAR R/H LOWER ARM (N)	SERVICEABLE	354.70	-
1	REAR R/H KNUCKLE ARM (N)	NO SUCH PARTS	314.30	-
1	REAR R/H KNUCKLE ARM BEARING (N)	NECESSARY	235.80	235.80
1	REAR AXLE BEAM (N)	BENT	1,885.00	1,885.00
	LESS 10% DISCOUNT		-	-298.61
			6,802.00	2,687.49
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT R/H DOOR INNER RUBBER (50%)(SN)	NECESSARY	131.70	65.85
1	REAR R/H DOOR INNER RUBBER (50%)(SN)	NECESSARY	131.70	65.85
			263.40	131.70

Report Ref No. CS/SMO18006716/Ktd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE & REFIX CUSHION.		120.00	100.00
	TO REMOVE & REFIX REAR RH UNDERCARRIAGE.		280.00	240.00
	TO CHECK WHEEL ALIGNMENT COMPUTER.		120.00	60.00
	TUFF KOTE.		120.00	90.00
	TO CHECK WIRING SYSTEM.		80.00	20.00
	TOWING CHARGES.		100.00	80.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT R/H DOOR INNER LOCK,REAR R/H DOOR INNER LOCK,REAR R/H DOOR LOWER HINGE AND REAR R/H RIM.		1,200.00	800.00
	SPRAY PAINTING.		1,200.00	720.00
			3,220.00	2,110.00
	<b>GRAND TOTAL</b>		<b>14,850.80</b>	<b>7,070.14</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,600.00</b>

Report Ref No. CS/SMO18006716/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.