

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: GBC 4163Y
 Policy No. 29075386mKC
 Claims No. 555349
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKT7863U Yr Regn: 2015 June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mazda 3 C.C. 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 59665 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: Jm6BM42A860308077
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/60R16
 R: 205/60R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 11/04/18
 Survey held at NHT
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSLG
SKT 7863U - X
GBC 4163Y - X
06/6/18 @ 2.42pm referred to Katherine Wong via Maximon.
LY \$ 2600, 4 days (red \$ 5047.60, 66%)

RECEIVED 07 JUN 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 41) 07/6/18 TP☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S+RS \$ _____

Photos

Others

TOTAL

Report Format: MED-TPLump Sum / I.B.I. (\$) 2600

150

10

160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/MSG18006736/Aqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 11-04-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 4163Y	Veh. Inspected	SKT 7863U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date		Inspection Date	11/04/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 06 Jun 2018

Preliminary Advice

Insured Vehicle No	: GBC4163Y	Accident Date	: 03/04/2018
TP Vehicle No	: SKT7863U	Assignment Date	: 13/04/2018
Make	: MAZDA 3	Est. Duration of Repair	: 4.00
Date of Inspection	: 11/04/2018		
Inspection At	: NEW HOCK TECK MOTOR WORKSHOP (HQ) BLK 1, KAKI BUKIT AVENUE 6 #01-43, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,647.60
Revised Amount	:S\$	3,232.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,232.80
Lump Sum Repair	:S\$	2,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 12 April 2018 4:30 PM
To: 'Katherine Wong'; 'Nabilah Rasol'
Cc: Christopher Chionh; KKLau; SUR; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - , NEW HOCK TECK MOTOR WORKSHOP, DOA: 03/04/2018 , SKT 7863U (TP VEHICLE), GBC 4163Y (OI VEHICLE)
Attachments: SKT7863U PR.pdf; SKT7863U GIA.pdf

Dear Katherine and Nabilah,

Please be informed that we had inspected the vehicle SKT 7863U at M/s: NEW HOCK TECK MOTOR WORKSHOP, BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA and police report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3838Z

Vehicle Details

Vehicle No.: SKT7863U
Vehicle to be Exported: Yes
Intended De-registration Date: 04 Apr 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour: Grey
Manufacturing Year: 2015
Engine No.: P520274403
Chassis No.: JM6BM42A8G0308077
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$14,098.00
Original Registration Date: 23 Jun 2015
First Registration Date: 23 Jun 2015
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Jun 2025
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 22 Jun 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$61,000.00
COE Rebate Amount: \$44,021.00
Total Rebate Amount: \$47,771.00

The information contained herein is correct as at 04 Apr 2018

OK

MSME18044895 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 04/04/2018 13:57
 SUBMITTED BY: Farida Wen Ya Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2018 13:57
Date Of Accident	03/04/2018 11:50
Exact Location Of Accident	OPEN CARPARK OF BLK 213 SERANGOON AVE 4.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT7863U
Insured/Policyholder	
Name Of Registered Owner	GOH KIM HONG
NRIC No	S1473838Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98639460
Alternative Phone No	OFFICE-98639460
Vehicle Particulars	
Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA216005/1
Cover Note Number	
Driver	
Name of Driver	CHEN JUNJIE LEONARD
NRIC No	S8809487E
Date Of Birth	21/03/1988
Occupation	INDOOR
Date Of Driving Pass	10/02/2009
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94897080
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 68 SIMON LANE #05-25
 Postcode 546057
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name HOUGANG NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4890999 - FAX NO: 63128989
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO POLICE REPORT NO.T/20180404/2016.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC4163Y
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Carpark of Bk 213
Serangoon Ave 4
A: SKT78634
B: ABC41634


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report no. 1/2018 0404/2016.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180404/2016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/04/2018 10:03	Vide Report No.:	Station Diary No.: 22
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHEN JUNJIE, LEONARD			Address: 6B SIMON LANE #05-25 SINGAPORE 546057		
ID Type / ID No.: NRIC NO / S8809487E			Contact No.: Home/Office: Mobile: 94897080		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 30	Date of Birth: 21/03/1988	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: FINANCIAL SPECIALIST			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 03/04/2018 11:50	Type of Location: Open cark park
Location: Along Road 1 SERANGOON AVENUE 4				
Open carpark at block 213, serangoon ave 4 open carpark.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC4163Y	Van					0
SKT7863U	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL		



Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Driver			
Name	CHEN JUNJIE, LEONARD	ID No.	S8809487E
Related Vehicle	NIL	Contact No.	94897080
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 03/04/18 at 0900hrs, I parked my vehicle no:SKT7863U at the blk 213 open carpark and everything was intact when I last checked.

On 03/04/18 at 1630hrs,I realized that my vehicle no: SKT7863U was hit as there was dent and scratches on my vehicle front right tires and there was scratches that extended till the headlight too. I went to check my in car camera footages and I saw a van no:GBC4163Y who collided into my vehicle as they were reversing.



**SINGAPORE
POLICE FORCE**



T/20180404/2016

3 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180404/2016

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 KOH PEI QI

Signature Of Interpreter:
Not applicable

Signature Of Informant:

Date/Time:
04/04/2018 10:03

Officer In Charge Of Case:
TP / HRT /
SI ABDUL KAREEM BIN ABDUL HAGUE
Contact No.: 65476079

Classification Of Case:

SN 085

Authentication Stamp
NP168



Signature: 

Singapore Police Force



MS16- Advian Lkk
新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

GOH KIM HONG

09/04/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP MS16.

Xiao Chen

Jm6BM42 4860308077

Accident date: 03/04/2018

Estimated repair cost for vehicle no: SKT7863U MAZDA 3 1.5A '15

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Head Lamp <i>lt</i>		\$873.30 ✓
2	1	Front R/H Head Lamp Lower Bracket <i>NP N</i>		\$25.20 +
3	1	Front Bumper <i>Deformed</i>		\$925.10 ✓
4	1	Front R/H Bumper Side Retainer <i>NEC</i>		\$28.70 ✓
5	10	Front Bumper Clips <i>NEC</i>	\$6.50	\$65.00 * 30
6	1	Front R/H Fender <i>Deformed</i>		\$333.90 ✓
7	1	Front R/H Fender Cowling <i>3mm</i>		\$128.00 +
8	8	Front R/H Fender Cowling Clips	\$6.50	\$52.00 +
9	1	Front R/H Rim <i>lt</i>		\$1,023.00 * 750 (sw)
10	1	Front R/H Lower Arm <i>2</i>		\$484.70 +
11	1	Front R/H Knuckle Arm <i>NP</i>		\$383.40 +
12	1	Front R/H Knuckle Arm Bearing <i>NEC</i>		\$541.70 +
13	1	Front R/H Shock Absorber		\$343.60 +

2191

1752.80

Subtotal :-

\$5,207.60

S.N. 750

Labour charges

To remove & refit front R/H undercarriage	\$380.00	+
To check wheel alignment	\$150.00	+
To check wiring	\$60.00	30
Tuff kote	\$150.00	+
Panel beating	\$850.00	300
Spray painting	\$850.00	400

Subtotal :- \$2,440.00

Total:- \$7,647.60

L/s Adrian Ling
14/04/18.

0.4 days

total 3232.80

L/s 2.6K
0.4 days

2.6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18006736/AQBN2

Date: 07/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29075386MKC
Claimant Vehicle No :	SKT7863U	Insured Vehicle No :	GBC4163Y
Date of Loss:	03/04/2018	Nature of Claim:	TP
		Claim No:	555349

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT7863U	Engine No:	P520274403
Make & Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	JM6BM42A8G0308077
Reg. Date:	23/06/2015 (Man. Year: 2015)	Odometer:	59665 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,207.60	2,502.80	2,704.80	51.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	730.00	1,710.00	70.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,647.60	3,232.80	4,414.80	57.73
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	7,647.60	2,600.00	5,047.60	66.00
+ GST 7.00/7.00% (S\$)	535.33	182.00	353.33	66.00
Nett Amount (S\$)	8,182.93	2,782.00	5,400.93	66.00

INSPECTION

Date of Assignment: 13/04/2018

Date Inspected: 11/04/2018 Inspected At:

New Hock Teck Motor Workshop (HQ)
Blk 1, Kaki Bukit Avenue 6 #01-43,
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2018)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT7863U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H HEAD LAMP	Cut	873.30 F	*873.30 FL
2	1		*FRONT R/H HEAD LAMP LOWER BRACKET	Not Necessary	25.20 F	*- FL
3	1		*FRONT BUMPER	Deformed	925.10 F	*925.10 FL
4	1		*FRONT R/H BUMPER SIDE RETAINER	Necessary	28.70 F	*28.70 FL
5	10		*FRONT BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
6	1		*FRONT R/H FENDER	Dented	333.90 F	*333.90 FL
7	1		*FRONT R/H FENDER COWLING	Not Necessary	128.00 F	*- FL
8	8		*FRONT R/H FENDER COWLING CLIPS	Not Necessary	52.00 F	*- FL
9	1		*FRONT R/H LOWER ARM	Not Necessary	484.70 F	*- FL
10	1		*FRONT R/H KNUCKLE ARM	Not Necessary	383.40 F	*- FL
11	1		*FRONT R/H KNUCKLE ARM BEARING	Not Necessary	541.70 F	*- FL
12	1		*FRONT R/H SHOCK ABSORBER	Not Necessary	343.60 F	*- FL
13	1		*FRONT R/H RIM	Cut	1,023.00 FS	*750.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	5,207.60 2,941.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 438.20
					Total Parts (\$\$)	5,207.60 2,502.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT R/H UNDERCARRIAGE	New	380.00	-
2	TO CHECK WHEEL ALIGNMENT	New	150.00	-
3	TO CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	150.00	-
5	PANEL BEATING	New	850.00	300.00
6	SPRAY PAINTING	New	850.00	400.00
Gross Labour Cost (\$\$)			2,440.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >