



Customer Code: 3000066

SMRT BUSES LTD

Block Unit STREET 62 6 ANG MO KIO SINGAPORE 569140



SMRT Automotive Services Pte Ltd 251 North Bridge Road Singapore 179102 Tel: 65 63311000 Fax: 65 63340247

## Tax Invoice

Vehicle No.

GST Reg No. : MR-8500001-7 CRN : 199004280Z Invoice No. : IV180400592 Date : 26.04.2018

Your Ref No. : BUS/04/18/5012

: SMB3519L

Our Ref No. : 24095518
Terms : 30 Days

Description	Qty	Unit	Add /	(Discount)	Amount
		Cost	ક	Amount	
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00				\$ 2,800.00
			GRAND	TOTAL	\$ 2,800.00

#### Remark:

Make/Model : ENVIRO 500 Accident Date : 09.04.2018

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'. No receipt will be issued unless requested.

Authorised Signature

for SMRT Automotive Services Pte Ltd

#### SINGAPORE ACCIDENT STATEMENT

#### - IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

					Ξ										

 Date Of Report
 10/04/2018 11:27

 Date Of Accident
 09/04/2018 18:00

Exact Location Of Accident BT BATOK WEST AVE 6 BEFORE BS: 43371 (BLK 109)

Country/State of Loss SINGAPORE

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SMB3519L

Insured/Policyholder

Name Of Registered Owner SMRT BUSES LTD

Co Reg No 198202292D Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-NOPHONE

Vehicle Particulars

Manufacturer ALEXANDER DENNIS
Model ENVIRO500-8.8 D (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

## Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage THIRD PARTY

Fleet Policy YES

Policy Number D-18090224MFBP

Cover Note Number

Driver

Name of Driver R MAGAINDARAN A/L S R RAMALINGAM

Passport No/FIN F1721766Q
Date Of Birth 10/01/1970
Occupation OUTDOOR
Date Of Driving Pass 23/03/2007

Driving Experience 11 YEARS AND 0 MONTHS

Gender MALE

Mobile Number
Fax Number
Contact Number

EMail Address NOEMAIL

**NOADDRESS** Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

**COLLISION - HEAD TO REAR** Type Of Accident

Weather Conditions **CLEAR** DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

YES

NO

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

30

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING STRAIGHT ON THE LEFT MOST LANE HEADING TOWARDS BUS STOP NO. 43371 (BLK 109) OF BUKIT BATOK WEST AVENUE 6. AS MY BUS HAD ALMOST ENTERED HALFWAY THROUGH THE YELLOW BOX. SUDDENLY A VAN FROM THE OPPOSITE ROAD TURNED RIGHT ABRUPTLY AND CUT THROUGH THE YELLOW BOX COLLIDING ONTO THE RIGHT FRONT PORTION OF MY BUS. NO INURY REPORTED.

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

Remarks/ Reasons:

PENDING DOWNLOAD

Was there any audio recorded?

NO

## DETAILS OF OTHER VEHICLE PROPERTY 1

GX9001D Vehicle Registration Number

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category COMMERCIAL VEHICLE

Name of Driver LEE CHOW HUAT

NRIC/Passport Number S1217508F Contact Number 98260948

Address

Postcode

Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

2

FRONT PORTION Nature Of Damage

No. Of Passenger (Including Driver)

### **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Refer to report		
		 _
	atan par aganaganan mag	
		1
8		
		2

# DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

# **Enquire Transaction History**

Transaction History Details

Log Date/Time:

10 Apr 2018 / 11:24:42

Asset Type:

Vehicle

Transaction Amount:

\$7.49

Asset ID:

GX9001D

Transaction Type:

18.32 Insurance Enquiry (GIRO Payment) Channel: ESASBAHO - BALQISH BINTE ABDUL

External Agency

User ID:

HALIL

Business Transaction Reference No.:

20180410112442370216

Search Date / Time:

09 Apr 2018 18:00:00

Insurance Company:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Information displayed is correct as at the log date and time.

**Enquire Related Logs** 

Back to List

















