

22/03/2002

ASS. REC. BY:

REF: CS / MS618006756 / R17 bn2 Special Instruction:

Survivor

Rusul

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSH

Date/Time: 11042018 4:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 8820L

Insured:

GU 6241M

at Workshop m/s

Motorviva

Tel:

8816 2758

of

10 Tuus Ave 18

Policy No:

2716 7371TMV

Claim No:

555088

Sum Insured:

Excess:

Make of Veh:

D.O.A. 07042018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

16.04.2018 @ Blk K Perdan Loop #01-12.

H.O.D. Endorsement:

Date/Time:

12042018 9:08am

Person Contacted:

Andy

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBG 8820L - X
	GU 6241M - X
	Lump Sum \$2250, 5 days CRed: 5229.52 (697.)

(08/11/13)

REF:

02029

Surveyor: P. J. Smith

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 666 8820L Yr Regn: 2017 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FIAT DOBLO CARGO SX 1.3M.c 1248Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 5446 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2FA 263000064 26369Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 07/04/18 D.O.I. 16/04/18Survey held at WOLFE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 MAY 2018

Date/Time, File Pass to?

1) 21/5 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 5Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150
10

160

Report Format :

Lump Sum / I.B.I: (\$ 2250)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006756/R1tb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 12-04-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GU 6241M	Veh. Inspected	GBG 8820L	
Policy No.	27169371TMV	Coverage (\$)	0.00	
Claim No.	555088	Excess (\$)	0.00	
Assign From	MERIMEN (LIONEL TAN)	Assign Date	11/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/04/2018	Inspection Date	16/04/2018	
Survey held at	BLK K PANDAN LOOP #01-12			
Repairer	MOTORVIVA PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018		11 Apr 2018 16:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Megastone Holdings Pte Ltd, Co. Reg. No.: 199504015N								
Main Claimant:	SINGAPORE POOLS (PRIVATE LIMITED), Co. Reg. No.: 196800202G								
Vehicle Reg. No.:	GBG8820L	Date of Loss:	07/04/2018 00:00 - :59 [4 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 555088	Policy/Cover Note No.:	27169371TMV (Third Party Only) Coverage: 23/10/2017 - 22/10/2018						
Vehicle Reg. No. (Insured):	GU6241M	Policy No. (Claimant):							
		Excess:							
Repairer:	Motorviva Minerva Pte Ltd (TUAS) 10 TUAS AVE 18, 638894 Tuas - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/04/2018]								
Adj Asg. Remarks:	Workshop Address: Block K Pandan Loop Ind. Est #01-12 Singapore 128230								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

12/04/2018 @ 9:08am
Andy veh not in

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/04/2018 11:17
Date Of Accident	07/04/2018 16:50
Exact Location Of Accident	THOMSON RD TO FLYOVER JLN TOAPAYOH ZEBRA CROSSING
Country/State Of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBG8820L
Insured/Policyholder	
Name Of Registered Owner	SINGAPORE POOLS (PRIVATE) LIMITED
Co Reg No	196800202G
Email Address	WONGTECKFONG@SGPOOLZ.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-98298641
Vehicle Particulars	
Manufacturer	FIAT
Model	DOBLO CARGO SX 1.3 MJT 5MT GLAZE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P2038760
Cover Note Number	
Driver	
Name of Driver	WONG TECK FONG
NRIC No	S1482853B
Date Of Birth	22/06/1961
Occupation	OUTDOOR
Date Of Driving Pass	10/03/1999
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98298641
Fax Number	
Contact Number	
Email Address	WONGTECKFONG@SGPOOLZ.COM.SG

Address BLK 808 TAMPINES AVE 4 #10-139 SINGAPORE
 Postcode 520808
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

KINDLY REFER TO ATTACHED SKETCH PLAN -1

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GU6241M
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver ARUMUGAM LOGANATHAN
 NRIC/Passport Number O 34022291
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBA3099S
 Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ANG KOK SOON

NRIC/Passport Number

S7113645J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 10:30a.m.
9/4/2018


Driver's Signature
(If driver is not the policyholder)
Date & Time: 10:30a.m.
9/4/2018


Reporting Centre Personnel's Signature
Name: OO, UEE WEOM
NRIC/FIN No.: 578821457

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 7/4/2018 at about 1650 P.M as I was travelling along Thomson Road toward Highway Jalan Pagar Payu Hwy 1, my vehicle was knocked by behind vehicle BU 6241M when I stop in front of station vehicle CQA 3099S. The knocked was too heavy and my vehicle A36 88202 pushed forward and hit front vehicle CQA 3099S.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 10:20am
7/4/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 10:50 a.m
7/4/2018

Reporting Centre Personnel's Signature
Name: BOI LEE KHEONG
NRIC/FIN No.: 51881451



redefining / Insurance

Date: 09/04/18

To: Owner of Vehicle Number: 6BQ 8820 L

The following has been advised to you via your workshop, GOLDRELL ENGINEERING through their staff, ANDY LOI.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ (✓) You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
 - ☒ (✓) You had been advised by the workshop on the liability and merits of the case accordingly.
 - ☒ (✓) You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
 - ☒ (✓) There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
 - ☒ (✓) There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
 - ☒ (✓) The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
 - ☒ (✓) You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
 - ☒ (✓) For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☒ (✓) You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
 - ☒ (✓) For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
 - ☒ (✓) Others _____

Signed and acknowledge by:

Wong Teck Fong

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

ANDY LOI



NRIC & DRIVING LICENCE -DRIVER Pg. 1

0218056



NRIC No: S1482853B



Blood Group: O+ Date of Birth: 08-01-1992

APT BLK 808 TAMPINES AVENUE 4 #10-139
SINGAPORE 520808

NRIC No: S1482853B Date: 21-05-2004 (R) No: 4963368

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: 10 Mar 1999

NP 428A



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1482853B



Name: WONG TECK FONG



Race: CHINESE
Date of Birth: 22-06-1961 Sex: M
Country of Birth: SINGAPORE

1387
S1482853B

REPUBLIC OF SINGAPORE DRIVING LICENCE

S1482853B



WONG TECK FONG

Birth Date: 22 Jun 1961
Issue Date: 24 Feb 2003



0002211628

CERTIFICATE OF INSURANCE Pg. 1

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel: (65)63387288 Fax: (65)63382522
Website: www.axa.com.sg
GST Registration Number: 199903512M
Customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

<p>■ Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)</p>	
CERTIFICATE NO.	VCA/P2038760
Account No.	15525
Coverage	Comprehensive
Sum Insured	Market value At The Time Of Loss
Name of Policy Holder	SINGAPORE POOLS (PRIVATE) LIMITED
Vehicle Registration No.	GBG8820L
Period of Insurance	From 29/11/2017 To 28/11/2018 (Both Dates Inclusive)
<p>PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*</p> <p>Any person who is driving on the Policyholder's order or with their permission.</p> <p>Provided that the person driving is permitted in accordance with the licensing or other law or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>LIMITATIONS AS TO USE*</p> <p>(a) Use in connection with the Policyholder's business (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business (c) Use for social, domestic and pleasure purposes</p> <p>This Policy does not cover</p> <p>(a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.</p> <p style="text-align: right;">(01)</p>	
<p>EXCESS</p> <p>Own Damage Excess : SGD 600.00 Windscreen Excess : SGD NIL (Please refer to your policy for Additional Excess)</p> <p>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>	

I/We hereby certify that the policy to which this Certification relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SCOSTPR on 13/12/2017

IMPORTANT:

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with the obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act, (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, cover note and endorsement etc.

DATE : 9/4/2018

TO : MSIG INSURANCE

ATTN : MOTOR CLAIM DEPARTMENT

OFFICE / MOBILE :

EMAIL ADDRESS :

FROM : GOLDBELL PANDAN

ATTN : ANDY OOI

OFFICE / MOBILE : 67730073

FAX NO. : 67730928

VEHICLE NO. : GBG8820L

MODEL NO. : FIAT DOBLO CARGO SX 1.3

CHASSIS NO. : ZFA26300006H26369

ENGINE NO. : 263A20006524962

REG. DATE : 29/11/2017

REF. NO. : GBE/SVC/SALES

D.O.A. : 7/4/2018

POLICY NO. : VCA/P2038760

CLAIM TYPE : TP CLAIM - MSIG INSURANCE

WORKSHOP : BLK K PANDAN LOOP IND EST
#01-12 SINGAPORE 128230

S/N	PART NO.	DESCRIPTION	QUANTITY	LIST PRICE
1		REAR BUMPER	1	\$ PE 601.02
2		REAR BUMPER REINFORCEMENT	1	\$ PH 320.92
3		REAR BUMPER BRACKET LH	1	\$ XH 23.10
4		REAR BUMPER BRACKET RH	1	\$ XH 23.10
5		REAR END PANEL	1	\$ R 332.94
6		REAR END PANEL TOP GARNISH	1	\$ XH 112.70
7		FRONT BUMPER	1	\$ R 475.90
8		FRONT NUMBER PLATE BASE GARNISH	1	\$ SVCX 44.69
9		RADIATOR GRILLE	1	\$ SVCX 255.62
10		RADIATOR GRILLE LOGO	1	\$ SVCX 69.27
11		REAR DOOR LH	1	\$ R 2,415.62
12		"PROFESSIONAL" CHROME EMBLEM	1	\$ AN 110.57
13		MULTIJET"2 CHROME EMBLEM	1	\$ AN 119.09
14		"DOBLO" CHROME EMBLEM	1	\$ AN 76.13
15		"90" CHROME EMBLEM	1	\$ AN 96.57

SUB-TOTAL	\$ 5,077.24
PART DISCOUNT 10%	\$ 507.72
BALANCE	\$ 4,569.52

SPECIAL-NETT ITEMS

1	REAR BUMPER REVERSE SENSOR
2	70 K/M H STICKER
3	6 PAX STICKER
4	FRONT NUMBER PLATE WITH GARNISH

1	\$ 280.00 ^{7 X NW} 200
1	\$ 20.00 20.00
1	\$ 20.00 20.00
1	\$ 60.00 35
	\$ 380.00

PARTS TOTAL :

\$ 4,949.52

LABOUR CHARGES

1	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.
2	TO CHECK FOR & RECTIFY WIRING FAULT, ETC
3	TO REMOVE & REFIT REAR SPARE TYRE BOARD TO ASSIST
4	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC
5	RUST PROOFING
6	SUNDRIES

1	\$ 1,000.00 ⁶⁰⁰ 500
1	\$ 80.00 80.00
1	\$ 120.00 60 120.00
1	\$ 1,200.00 ⁹⁵⁰ 950
1	\$ 80.00 40 80.00
1	\$ 50.00 ²⁰ 20 50.00 nec

LABOUR TOTAL :

\$ 2,530.00

GRAND TOTAL :

\$ 7,479.52

PREPARED BY : ANDY OOI

DATE / TIME : 16/04/18 @ 0900

SURVEYOR : RASUL

MOBILE NO. : 90010068

OFFICE FAX NO. :

EMAIL ADDRESS : rasul@lkkauto.com

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / CUMPSUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 5 to days

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006756/R1TBN2

Date: 23/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27169371TMV
Claimant Vehicle No :	GBG8820L	Insured Vehicle No :	GU6241M
Date of Loss:	07/04/2018	Nature of Claim:	TP
		Claim No:	555088

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG8820L	Engine No:	263A20006524962
Make & Model:	FIAT DOBLO, 1.3 D SX Cargo (M)	Chassis No:	ZFA26300006H26369
Reg. Date:	29/11/2017 (Man. Year: 2017)	Odometer:	5446 km
Colour:	White		
Engine Capacity:	1248 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,999.52	1,367.36	3,632.16	72.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,690.00	790.00	31.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,479.52	3,057.36	4,422.16	59.12
Approved Total (Overridden) (S\$)		2,250.00		
Nett Amount (S\$)	7,479.52	2,250.00	5,229.52	69.92

INSPECTION

Date of Assignment:	11/04/2018	
Date Inspected:	16/04/2018 Inspected At:	Blk K Pandan Loop #01-12 Repairer: Motorviva Minerva Pte Ltd (TUAS) 10 Tuas Avenue 18 Singapore 638894

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 May 2018)	
Parts:	N/A	FIAT DOBLO 1.3 D SX Cargo (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8820L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	601.02 FL	*601.02 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	320.92 FL	*320.92 FL
3	1		*REAR BUMPER BRACKET LH	Serviceable	23.10 FL	*- FL
4	1		*REAR BUMPER BRACKET RH	Serviceable	23.10 FL	*- FL
5	1		*REAR END PANEL	Repair	332.94 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Serviceable	112.70 FL	*- FL
7	1		*FRONT BUMPER	Repair	475.90 FL	*- FL
8	1		*FRONT NUMBER PLATE BASE GARNISH	Serviceable	44.69 FL	*- FL
9	1		*RADIATOR GRILLE	Serviceable	255.62 FL	*- FL
10	1		*RADIATOR GRILLE LOGO	Serviceable	69.27 FL	*- FL
11	1		*REAR DOOR LH	Repair	2,415.62 FL	*- FL
12	1		*PROFESSIONAL CHROME EMBLEM	Not Necessary	110.57 FL	*- FL
13	1		*MULTIJET 2 CHROME EMBLEM	Necessary	119.09 FL	*119.09 FL
14	1		*DOBLO CHROME EMBLEM	Necessary	76.13 FL	*76.13 FL
15	1		*90 CHROME EMBLEM	Necessary	96.57 FL	*96.57 FL
16	1		*REAR BUMPER REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
17	1		*70K/M H STICKER	Necessary	20.00 FS	*20.00 FS
18	1		*6 PAX STICKER	Not Necessary	20.00 FS	*- FS
19	1		*FRONT NUMBER PLATE WITH GARNISH	Bent	60.00 FS	*35.00 FS
20	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,507.24	1,488.73
- List Item Discount on L Items 10.00/10.00% (\$\$)	507.72	121.37
Total Parts (\$\$)	4,999.52	1,367.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC	New	1,000.00	600.00
2	TO CHECK FOR & RECTIFY WIRING FAULT,ETC	New	80.00	40.00
3	TO REMOVE & REFIT REAR SPARE TYRE BOARD TO ASSIST	New	120.00	60.00
4	TO PUTTY,CLEAN SPRAY PAINT & POLISH,ETC	New	1,200.00	950.00
5	RUST PROOFING	New	80.00	40.00
Gross Labour Cost (\$\$)			2,480.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >