

English (default) * LKK AUTO CONSULTANTS PTE LTD (OO) *				PART NAME	LABOUR HSR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 SERVICE REQUESTS	 MESSAGES			CLAIMS						
		2		TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	2400	0	0	Reviewing		
		2		TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CONDUCT MUT TEST, TO CARRY OUT DIAGNOSTICS CHECK.	200	0	0	Reviewing		
		3		TO REMOVE & REFIX AIRCOND SYSTEMS AND RADIATOR. TO TOP UP GAS. TO CHECK FUNCTION.	300	0	0	Reviewing		
		4		TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.	2100	0	0	Reviewing		

🔍	SERVICE REQUESTS			MESSAGES	CLAIMS	FRONT BUMPER WICK	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC QUANTY	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐		13	1				"FIAT" LOGO (DISC 10%)			Necessary	125.23		0		125.23	Reviewing	
☐		14	1				FRONT BUMPER REINFORCEMENT (DISC 10%)			Bent	365.22		0		365.22	Reviewing	
☐		15	1				FRONT SUPPORT PANEL (DISC 10%)			Bent	300.42		0		300.42	Reviewing	
☐		16	1				FRONT SUPPORT PANEL LHS			Serviceable	0		0		0	Reviewing	
☐		17	1				FRONT SUPPORT PANEL RHS			Serviceable	0		0		0	Reviewing	
☐		18	1				HEADLAMP LHS (DISC 10%)			Cracked	467.6		0		467.6	Reviewing	
☐		19	1				HEADLAMP RHS (DISC 10%)			Cracked	467.68		0		467.68	Reviewing	
☐		20	1				AIRCOND CONDENSER (DISC 10%)			Bent	1076.1		0		1076.1	Reviewing	
☐		21	1				AIRCOND CONDENSER BRACKET TOP			Serviceable	0		0		0	Reviewing	
☐		22	1				AIRCOND CONDENSER BRACKET BOTTOM			Serviceable	0		0		0	Reviewing	
☐		23	1				AIRCOND CONDENSER HOSE			Serviceable	0		0		0	Reviewing	
☐		24	1				AIRCOND CONDENSER HOSE			Serviceable	0		0		0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS

ASSESSMENT INFORMATION

53000

FNOL INFORMATION

POST SURVEY INFORMATION

CATEGORY

License Issue Date

January 1, 2000

mm/dd/yy

License Expiration Date

mm/dd/yy

Address

BLK 687B CHOIA CHU KANG DRIVE, #06-386, 682687, Singapore

Address type

Personal Correspondence

Gender

Male

Marital status

Unknown

Identification #

S8102795A

TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 26, 2019
Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 16, 2019
Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 16, 2019
Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	April 16, 2019
Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 18, 2018
Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	April 17, 2018
Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 17, 2018
Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	TEO Kitty	April 12, 2018
Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	TEO Kitty	April 12, 2018
Reports & Statement	GIA Report	TEO Kitty	April 12, 2018
Other	Other	SHAH Kunal	April 11, 2018
Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	April 10, 2018
Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	April 10, 2018

📎 AXA Immediate Advice - GBD8333S.pdf

📎 GBD8333S Inspection photo.pdf

📎 GBD8333S SUPPLEMENTARY.pdf

📎 gbd8333s_info.pdf

📎 GBD 8333S.pdf

📎 PREL ADVISED GBD 8333S.pdf

📎 CI.pdf

📎 POLICY SCHEDULE.pdf

📎 GVS663E - GIA RPT (1st Veh).PDF

📎 EMAIL WITH ESTIMATE AND GIA REPORT.msg

📎 GIA YP6136Y TP.PDF

📎 GIA GBD8333S INSD.PDF