

SATISFACTION VOUCHER

To: **Motorviva Pte Ltd.**
10 Tuas Avenue 18
Singapore 638894

Date: **7/6/2018**
Reference: **586211**

We hereby confirm the receipt of the our vehicle in good and working condition from the repairer;
M/s Goldbell Engineering Pte Ltd. , and that all necessary repairs resulting from the
belowmentioned accident had been completed to our satisfactory.

Vehicle Number : **GBD8333S**

Make & Model : **FIAT DOBLO CARGO SX JTD**

Chassis Number : **ZFA26300006177444**

Engine Number : **198A30007168582**

Accident Date : **7/4/2018**

Claim Reference : **GBE/SVC/SALES-4612/180410**

Remarks : **OD CLAIM REPAIR - AXA**

On behalf of M/s **THE MAGIC EMPIRE**



Company's Stamp :

Signature :

Name : **Tang Way Ming Sherman**

Date : **7th June 2018**