

Service Order Confirmation

SERVICE ORDER NO: 18IP1110

CUSTOMER NO.: CV008857

CUSTOMER NAME: TANG HUI SIAN

TELEPHONE NO.:

ADDRESS: 85 WEST COAST DRIVE #06-12
Singapore

VEH No.: SLN3383J

Order Date: 25/04/18

Reg Date: 30/06/17 KM: 16,972

VIN NO.: WVWZZZAUZH511078 ENGINE NO:

SA: Kong Charmaine

MODEL: SPORTSVAN 1.4 TSI HL MODEL NO.: AM14HZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
2	B&P ALEX LABOUR R&R RIM & BALANCE	1	UNIT	50		50
3	B&P ALEX LABOUR LABOUR	3	UNIT	840		2,520
4	B&P WHEEL ALIGNMENT B&P WHEEL ALIGNMENT -NETT	1		360		360
5	B&P ALEX PAINT SPRAY PAINT	3	UNIT	800		2,400
6	B&P ALEX LABOUR TRANSFER DOOR MECHANISM PARTS	0.5	UNIT	840		420
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
9	510833055N DOOR	1	PCS	1,851.64		1,851.64
10	510839699D DOOR SEAL	1	PCS	86.48		86.48
11	D 378500A2 DOOR INSULATOR	1	PCS	46.22		46.22
12	5G0601025G 88Z 18" 'DURBAN' RIM ONLY	1	PCS	1,526.17		1,526.17
13	311601361 RUBBER VALVE	1	PCS	1.72		1.72 <i>ch rec</i>

Remarks : FIRST CAPITAL DIRECT SETTLEMENT

DOA 09.04.2018

SURVEYOR LKK

TP VEHICLE SHA7946A