

**NATIONAL Assessment Centre Services** [wef: 10/2005]

Date In: 13/04/2018 11:28	Job description: SAS e-filing	Date & Time Completed:	Done by:
Ref No: NA/INC18006817/K4	E-mail (within 8hrs. AIC 2hrs):		
Veh No: GBH 2130D	i-Motor Claim Form: MT/0990238-001	13/4/18	13:20
D.O.A: 12/4/2018 15:00	i-Motor W/O (Within: OD 2hrs. TP 4hrs):		
OD TP: Reporting Only	i-Photo Uploaded:		
TP Insurer:	Assessment/Survey Report:		
	Ass't Report by Fax / Hand to Owner/Wksp:		

Preferred Wksp / INC Assign Wksp / QW: ( ) Tel: ( ) Fax: ( )

TP Particulars: Veh No: Hilton Tree INC ( ) / Non-INC ( )

Owner / Driver: ( ) Tel: ( )

Policy No: ( ) Period: ( ) Cover Type: ( )

Confirmed by: ( ) Date: ( ) Time: ( )

Insured/Driver Liability: ( ) % [Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]

Year of Registration: ( ) Warranty: YES ( ) / NO ( )

Excess: (\$ ) Loading: \$1,000 ( ) / \$2,000 ( )

**General Remarks:-**

( ) Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

( ) Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In ( ) / Towed-In ( ); Invoice: YES ( ) / NO ( ); Towing Co: ( )

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance ( ) / Courtesy Car ( )		
2) QC Check / Post Repair Inspection ( )		
3) Upload Resurvey Photo [Repair Cost > \$3000] ( )		

**Injury:**

Date/Time	Actions

Claimant's Particulars :-	Invoice Preparation Checklist	
	Ant (\$) 1st Bill	Ant (\$) Add Bill
Driver/Owner:	1) AR: Accident Reporting (\$30);	
Contact No:	2) DA: Damage Assessment (\$100); INC (\$80)	
Damaged Portion:	3) TP: Towing Fee \$40/\$45	
QC Checked by (Engr-In-Charge):	4) FT: Follow-Through Survey \$120	
Auditors' Comments :-	5) FT: Follow-Through Survey (Resurvey) \$30	
Cat. 1:	For claiming against INC Only (wef 10 Jan 2005)	
Cat. 2/3:	6) TR: Re-inspection \$75	
	7) NI: Idac DA + SMRT Survey \$160	
	8) NTUC Additional Services:-	
	OD*	
	*N5: Courtesy Car / Tpt Allowance	\$5
	*N6: Repair Co-ordination	\$10
	*N7: Post Repair Inspection	\$25
	*N8: DV / Collect Excess Coordination	\$5
	TP (N11): TP (Non INC) against INC	\$20
	9) N12: Idac Mobile	\$0
	Invoice dated	Fee Charged
	Invoice dated	Fee Charged

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/04/2018 11:28
Date Of Accident	12/04/2018 15:00
Exact Location Of Accident	TUAS VIEW CIRCUIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH2130D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LBE CONSTRUCTION PTE LTD
Co Reg No	200808719K
Email Address	LBE_ENGRG@LBE.COM.SG
Mobile Phone No	(LOCAL) +65-98103053
Alternative Phone No	OFFICE-68622103

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 3.0 MANUAL
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099005781
Cover Note Number	

### Driver

Name of Driver	ALAM BADRUL
Passport No/FIN	G8266583N
Date Of Birth	02/06/1984
Occupation	OUTDOOR
Date Of Driving Pass	07/12/2017
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98103053
Fax Number	
Contact Number	OTHERS-98103053
EMail Address	LBE_ENGRG@LBE.COM.SG

Address LBE ENGINEERING PTE LTD  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Vehicle -  
 Insurance Company of Driver's Own Vehicle -  
 -

**General Information of the Accident**

Type Of Accident COLLIDED INTO PROPERTY  
 Weather Conditions RAINING  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? NO  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO THE ATTACHED STATEMENT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF INJURED PERSON 1**

Name ALAM BADRUL  
 Approximate Age  
 Injuries Sustain RIGHT ARM & LEFT /RIGHT LEGS  
 Injured person in which vehicle? GBH2130D  
 Were seat belts worn? YES  
 Was this injured conveyed to hospital by ambulance?  
 Address  
 Postcode

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A after turn right hit the tree B at tuas view circuit. vehicle A was damage very & badly at the front area

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

*Daryl*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

*13/4/2018*  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Ap. to Idac Paya Ubi (National Assessment Centre  
Service)

51 Ubi Avenue 1 # 01-25

Paya Ubi Industrial Park

Singapore 408933

tel: 6841 0055

① Company chop

② IC / Passport / WP

③ Driving License

④ Police Report

Please mention preferred workshop

Optima Werkz Pte Ltd.

email to us katherin@the.com.sg



TRAFFIC INVESTIGATION BRANCH  
TRAFFIC POLICE  
10 UBI AVENUE 3  
SINGAPORE 408865  
Fax: 65474749

CASE CARD

REPORT NO.: 3/20100412/0045  
Traffic Accident along Tuas View Circuit, CP 15  
involving vehicles: Large and size  
on 12/04/15 at about \_\_\_\_\_ am/pm

With reference to the above, you are advised to lodge an accident report online via the SPF Electronic Police Centre website (<http://www.police.gov.sg/epc>) within 24 hours.

You are required to be present at Traffic Police on \_\_\_\_\_  
at about \_\_\_\_\_ am/pm to see the Investigation Officer to assist in the  
investigation to the traffic accident.

2. Please bring along your :-

- a) Identity card/Passport/Work Permit
- b) Driving Licence/Vocational Licence
- c) Vehicle Insurance/Medical Certificate
- d) Any video footage
- e) Any other relevant documents/Witnesses (if any)

3. If you are unable to keep to the appointment, kindly contact the Investigation Officer:

Name: \_\_\_\_\_  
Contact: 65476433



## LBE ENGINEERING PTE LTD

No. 19 Tuas View Circuit  
Singapore 637571  
Tel : 6862 2103 (5 Lines)  
Fax: 6862 2106  
Email: [lbe\\_engr@lbe.com.sg](mailto:lbe_engr@lbe.com.sg)  
Web: [www.lbe.com.sg](http://www.lbe.com.sg)

**Katherine Ngan**  
Email: [katherine@lbe.com.sg](mailto:katherine@lbe.com.sg)



## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	GBH2130D
Vehicle Type:	B31 - Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Attachment 1:	With Hood
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 MANUAL
Chassis No.:	KDY2318027691
Propellant:	Diesel
Engine No.:	1KD2673020
Engine Capacity:	2982 cc
Maximum Power Output:	-
Maximum Laden Weight:	3425 kg
Unladen Weight:	1780 kg
Year Of Manufacture:	2016
Original Registration Date:	15 Mar 2018
Lifespan Expiry Date:	14 Mar 2038
COE Category:	C - Goods Vehicle & Bus
Quota Premium:	\$36,003.00
COE Expiry Date:	14 Mar 2028
Road Tax Expiry Date:	14 Sep 2018
Inspection Due Date:	14 Mar 2019
Intended Transfer Date:	13 Apr 2018
CO2 Emission:	203.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print



Reported on 13/4/2018 @ 11:03AM

# ACCIDENT STATEMENT

ACCIDENT DATE: 12/4/2018 (DD/MM/YYYY), TIME: 15:00 (HH:MM)

LOCATION: Tuas View circuit

## 1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: GBH2130 D
- b) INSURANCE COMPANY: \_\_\_\_\_
- c) POLICY NUMBER: \_\_\_\_\_
- d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
- e) MAKE & MODEL: \_\_\_\_\_
- f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
- g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
- h) PURPOSE OF USING AT ACCIDENT TIME: \_\_\_\_\_
- i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO) (OD)  
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

## 2. INSURED / POLICY HOLDER

- a) NAME: \_\_\_\_\_ (MALE / FEMALE)
- b) NRIC/FIN/PASSPORT: \_\_\_\_\_ CONTACT: \_\_\_\_\_
- c) ADDRESS: \_\_\_\_\_

\* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

## DRIVER

- a) NAME: \_\_\_\_\_ (MALE / FEMALE)
- b) NRIC/FIN/PASSPORT: \_\_\_\_\_ CONTACT: 98103053
- c) ADDRESS: \_\_\_\_\_

\* d) DATE OF BIRTH: (\_\_\_\_/\_\_\_\_/\_\_\_\_) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: \_\_\_\_\_

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO) (NO)

IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: \_\_\_\_\_

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS) \_\_\_\_\_

b) ROAD SURFACE: (DRY / WET / OTHERS) \_\_\_\_\_

6. WAS ANYBODY INJURED (YES / NO) Slight injury

7. a) REPORTED TO POLICE (YES / NO) \_\_\_\_\_

IF YES, PLEASE STATE WHICH POLICE STATION: \_\_\_\_\_

## 8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: Tree MODEL: \_\_\_\_\_
- b) DRIVER'S NAME: \_\_\_\_\_ CONTACT: \_\_\_\_\_
- c) NRIC/FIN/PASSPORT: \_\_\_\_\_

## 9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: \_\_\_\_\_ MODEL: \_\_\_\_\_
- e) DRIVER'S NAME: \_\_\_\_\_ CONTACT: \_\_\_\_\_
- f) NRIC/FIN/PASSPORT: \_\_\_\_\_

\* No of passenger (including driver) (1)

\* No of passenger (including driver) ( )

\* No of passenger (including driver) ( )

\* Tow in on 12/4/2018  
\* key in side  
\* cannot take out

Email =  
Fax =

Waiting for vehicle photos? OK

**WORK PERMIT**  
 Employment of Foreign Manpower Act (Chapter 91A)  
 Republic of Singapore

Employer  
**LRF ENGINEERING PTE. LTD.**



Name  
**ALAM BADRUL**

Work Permit No.  
**0 62652373**

Sector:  
**CONSTRUCTION**





**K0034033**

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number  
**G8266583N**

Name  
**ALAM BADRUL**

Birth Date: **02 Jun 1984**

Issue Date: **07 Dec 2017**

Valid Till **06/12/2022**




**002751323B**

**VISIT PASS** 31-10-2017  
 Immigration Regulations

Name  
**ALAM BADRUL**

Download SGWorkPass App to check status



#IN  
**G8266583N**

Date of Birth: **02-06-1984** Sex: **M**

Nationality  
**BANGLADESHI**

**MULTIPLE JOURNEY VISA ISSUED**

**YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.**




**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

**EFFECTIVE DATE**

**Class 3** Motor cars with unladen weight  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of driver; and other motor vehicles with unladen weight  $\leq$  2500kg **07 Dec 2017**

NP 428A



Licence No:G8266583N

3. pm

12/4/18

8, Tuan Ukuw Sironi  
Sharon



### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5099005781

Cover : Comprehensive

- 1. Index mark and Registration Number of Vehicle : **GBH2130D**  
Chassis Number : **KDY2318027691**
- 2. Name of Policyholder : **LBE CONSTRUCTION PTE LTD**
- 3. Effective Date of Insurance : **15 Mar 2018**
- 4. Expiry Date of Insurance : **14 Mar 2019**
- 5. Persons or Classes of Persons entitled to drive#
  - (a) The Policyholder.
  - (b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to Use#
  - (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.
  - (b) Use for the carriage of passengers or goods in connection with the Policyholder's business.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: SHUN HENG CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : PATRONUS PTE. LTD. (00000572664)  
Date of Issue : 15 Mar 2018 16:14 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

profer work shop  
is optima works

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)

[My Desktop](#)  
[Notice of Loss](#)

### Policy Query

Policy No.  Date of Accident   
Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5099005781	LBE CONSTRUCTION PTE LTD	200808719K	GCV	Comprehensive	GBH2130D	GBH2130D	15/03/2018	14/03/2019

▼ **Policy Information**

Policy No.	5099005781	Policyholder Name	LBE CONSTRUCTION PTE LTD	Policyholder NRIC	200808719K
Address	19 TUAS VIEW CIRCUIT SINGAPORE 637571				
Product Name	COMMERCIAL VEHICLE INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	15/03/2018	Effective Date	15/03/2018 00:00	Expiry Date	14/03/2019 23:59
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess		OS Premium	0		
Outside Singapore OD Excess		Outside Singapore TP Excess			
Agent	PATRONUS PTE. LTD.	Agent Tel.	63441918	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

▼ **Policyholder Mailing Address**

Address 1	19 TUAS VIEW CIRCUIT	Address 2	SINGAPORE 637571	Address 3	
Address 4		Address Type	Singapore address	Post Code	637571
Unit No.		Related Policy Number	5098755700		

▶ **Insured Object: GBH2130D**

▼ **Endorsements**

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
1	15/03/2018 00:00	Basic Information Endorsement	Endorsement Take Effective	Thank you for giving us the opportunity to serve you. We confirm that from 15 Mar 2018, the following policy details are amended as follows: HIRE PURCHASE COMPANY: SHUN HENG CREDIT PTE LTD CHASSIS NUMBER: KDY2318027691 ENGINE NUMBER: 1KD2673020 VEHICLE REGISTRATION NUMBER: GBH2130D ORIGINAL REGISTRATION DATE: 15 Mar 2018

Continue

Cancel

## Claim Handling

Accident MT/0990238

Policy No.	5099005781	Vehicle No.	GBH2130D	GST Registration No.	
Policyholder Name	LBE CONSTRUCTION PTE LTD			Policyholder NRIC	2001
Product Code	COMMERCIAL VEHICLE INSURAN	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	98103053	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	<input type="radio"/> No <input type="radio"/> Yes	TCA	<input checked="" type="radio"/> No <input type="radio"/> Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

## ▼ Accident Details

Report Date	13/04/2018 13:16	Accident Report Within 24 hrs	Yes	Accident Type	Coll
Date of Accident	12/04/2018	Time of Accident hh:mm	15:00	Country of Accident	Sing
Reporting Centre		Orange Force		ICM No.	
Accident Location	TUAS VIEW CIRCUIT				

## ▼ Benefits

## ▼ Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

## ▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	No
Modification History			

## ▼ Policyholder Mailing Address

Address 1	19 TUAS VIEW CIRCUIT	Address 2	SINGAPORE 637571	Address 3	
Address 4		Address Type	Singapore address	Post Code	6371
Unit No.		Related Policy Number	5098755700		

## ▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	ALAM BADRUL	Driver NRIC	G8266583N	Driver DOB	02/0
Register Date of Driver License	07/12/2017	Driver Age	33	Driving Experience	0
Contact No.(Mobile)	98103053	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	LBE ENGINEERING PTE LTD	Address 2		Address 3	
Address 4		Address Type	Singapore address	Post Code	
Unit No.					
Does he own a Singapore Registered car?	Yes <input type="radio"/> No <input type="radio"/>	Driver Vehicle No.		Driver Insurer Company	

## Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No
-------------------------------------	------	-------------	---

## Modification History

Claim 001 OD-MD

New

Claim Type *	OD-MD	Insured Name	LBE CONSTRUCTION PTE LTD	Insured NRIC	2001
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	6861
Email Address		OI Vehicle Number	GBH2130D	TP Vehicle Number	TRE1
Claim Description	GBH2130D / TREE ON 12 Apr 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability *	Partially at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Rec
Date Registered	13/04/2018 13:23	Claim Close Date		Date Received	13/0
Report Taken By	KRISHNASAMY	Workshop Repairer		Total Loss but Repaired	

 Print AK letter

Save Submit

## Attachment

▼

Accident No.  
Last Doc. Received

MT/0990238  
\* Yes  No

Claim No.  
Upload Date

001  
13/04/2018 13:20

Path \*

- Choose File No file chosen
- Message Read

Category *		Confidential	Urgency *
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:23	NRIC/ Driving License	Normal	NRIC/ Driving Lice
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:22	SAS	Normal	SAS 2011
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:22	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:22	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:22	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:22	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:21	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:21	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:21	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:21	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:21	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:20	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:20	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:20	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:20	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:20	Photos	Normal	Photos 20:
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) on 13 Apr 2018 13:20	Photos	Normal	Photos 20:

Video List

Uploaded By/Date	Folder Date	File Name	Source
<div style="display: flex; justify-content: space-around;"> <span>Display in New Window</span> <span>Scan and uploading</span> </div>			

## Claim Handling

LOS SAL SUB

## Accident MT/0990238

Policy No.	5099005781	Vehicle No.	GBH2130D	GST Registration No.	200808719K
Policyholder Name	LBE CONSTRUCTION PTE LTD			Policyholder NRIC	200808719K
Product Code	COMMERCIAL VEHICLE INSURAT	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	98103053	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	<input type="checkbox"/> No <input type="checkbox"/> Yes	TCA	<input type="checkbox"/> No <input type="checkbox"/> Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

## Accident Details

Report Date	13/04/2018 13:16	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	12/04/2018	Time of Accident hh:mm	15:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	TUAS VIEW CIRCUIT				

## Benefits

## Excess

Own damage Excess	600.00	Additional Excess	Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess		
Third Party Excess	0.00	Outside Singapore TP Excess		

## GST Registered Information

GST Registered	Yes	GST Registration Date	01/06/2008
GST Registration No.	200808719K	GST Status Verified	Yes
Modification History	16/04/2018 09:57:17 Nur Shahira Hassan changed GST Registered from No to Yes 16/04/2018 09:57:17 Nur Shahira Hassan changed GST Registration No. from null to 200808719K 16/04/2018 09:57:17 Nur Shahira Hassan changed GST Registration Date from null to 01/06/2008		

## Policyholder Mailing Address

Address 1	19 TUAS VIEW CIRCUIT	Address 2	SINGAPORE 637571	Address 3	
Address 4		Address Type	Singapore address	Post Code	637571
Unit No.		Related Policy Number	5098755700		

## OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	02/06/1984
Unnamed driver Name	ALAM BADRUL	Driver NRIC	G8266583N	Driving Experience	0
Register Date of Driver License	07/12/2017	Driver Age	33	Contact No.(Home)	0
Contact No.(Mobile)	98103053	Contact No.(Office)	0	Address 3	
Address 1	LBE ENGINEERING PTE LTD	Address 2		Post Code	
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	<input type="checkbox"/> Yes <input type="checkbox"/> No	Driver Vehicle No.		Driver Insurer Company	

## Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Modification History			

## Investigation

## Claim 001 OD-MD

## Claim Case Officer Ng Hak Joo

Claim Type	OD-MD	Insured Name	LBE CONSTRUCTION PTE LTD	Insured NRIC	200808719K
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	68622103
Email Address		OI Vehicle Number	GBH2130D	TP Vehicle Number	TREE
Claim Description	GBH2130D / TREE ON 12 Apr 2018			Name of Preferred Workshop	OPTIMA WERKZ PTE L
Preferred Workshop Contact No.	64849919	Insured Liability	Partially at Fault	GIA report	Received
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Nama unknown	Date Received	13/04/2018 13:20
Date Registered	13/04/2018 13:25	Claim Close Date		Total Loss but Repaired	
Report Taken By	KRISHNASAMY	Workshop Repairer			
<input checked="" type="checkbox"/> Print AK letter					
Modification History	13/04/2018 16:20 s991212 Modify Name of Preferred Workshop(-->OPTIMA WERKZ PTE LTD) 13/04/2018 16:20 s991212 Modify Preferred Workshop Contact No(-->64849919)				

## Special Claim Creation Approval

ASSIGNMENT (IDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle:
  - a) Motorcar ( )
  - b) Motorcycle ( )
  - c) Bicycle ( )
- 2) Vehicle hit ??
  - a) Pedestrian ( )
  - b) Animal ( )
- 3) Vehicle hit Road Side Objects:
  - a) Govt. Property ( )  
(Ex: signboard, barrier, tree etc)
  - b) Road Work Object ( )
  - c) Private Property ( )
- 4) Vehicle drop into drain ( )
- 5) Damage due to Act of God:
  - a) Fallen Object ( )
  - b) Flood ( )
  - c) Other, \_\_\_\_\_
- 6) Parked & Found Damaged:
  - a) Vandalism ( )
  - b) Hit by Moving Object ( )
- 7) Theft Case
  - a) Stolen ( )
  - b) Damage found ( )  
when recovered.
- 8) Fire
  - a) Whilst driving ( )
  - b) Parked ( )
- 9) Accident date more than 24hrs ( )

Remarks for internal information

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ( )
- 2) SRS Light on ( )
- 3) ABS Light on ( )

By Assessor- 1) Vehicle Information

Veh No: G BH 2130D Yr Regn: 15/3/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / ~~MPV~~  
/ Truck / Trailer or \_\_\_\_\_

Make & Model: Toyota Dyng cc 3000 2982

Colour: White Transmission Type: Auto / Manual

Eng/No: \_\_\_\_\_ Sp.Reading: \_\_\_\_\_

C/Nr: KDY231502769

Gen. Cond: Good / Fair / Poor / Burnt or \_\_\_\_\_

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or Unknown

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 175/75R15  
R: 145R/13L18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Bridgestone

Front		Rear	
R/Bal.	<u>7</u> mm	R/Bal.	<u>7</u> mm
L/Bal.	<u>7</u> mm	L/Bal.	<u>7</u> mm

Parallel Import: Yes / No

Repair Type: LS / I.B.I

No of Repair Days: 28

D.O.I. 16/4/18

Towed-In: Yes / No

Towing Required: Yes / No

Vehicle in Idac: Yes / No

Time: 1000

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
  - a. Vehicle ( ) b. Motorcycle ( ) c. Bicycle ( ) d. Pedestrian ( )
  - e. Animal ( ) f. Govt Object ( ) g. Road Work Object ( )
  - h. Private Property ( ) i. Drain ( ) j. Road Kerb/Grass Verge ( )
- 3) Vehicle does not seem damaged as a result of:
  - a. Fallen Object ( ) b. Flood ( ) c. Vandalism ( ) d. Fire ( )
  - e. Moving Object ( ) f. Stolen ( ) g. Stolen & Recovered ( )

Time Started:	Time completed:
1) CSO _____	_____
2) ASS _____	_____
3) Entire Operation Completed Time: _____	

**VIR / LORRY (FV)**

**Front Porion**

NAC	INC	Item	CON	AC	Qty	✓
1001	991886	Frt Number Plate	MS	✓	1	✓
1002	991887	Frt Number Plate Base	MS	✓	1	✓
1004	991300	Frt Bumper	MS	✓	1	✓
2001	991477	Frt Bumper Upper				
2002	991387	Frt Bumper Lower				
2003	991449	Frt Bumper Side Cover				
2004	991443	Frt Bumper Side				
1006	991325	Frt Bumper Bracket	MS	✓	2	✓
1008	991433	Frt Bumper Reinforcement	BT	✓	1	✓
2005	991466	Frt Bumper Signal Lamp				
1017	995100	Frt LH Bumper Fog Lamp Cover				
1018	991355	Frt RH Bumper Fog Lamp Cover	MS	✓	1	✓
1019	995079	Frt LH Bumper Fog Lamp				
1020	995080	Frt RH Bumper Fog Lamp				
1021	991793	Frt Grille	MS	✓	1	✓
1022	991328	Frt Grille Emblem	NEC	✓	1	✓
2006	990247	Frt Grille Sticker				
1023	991799	Frt Grille Chrome Moulding				
2007	991891	Frt Panel	BT	✓	1	✓
2008	991874	Frt Lower Panel				
2009	991328	Frt Panel Emblem	NEC	✓		✓
2010	990247	Frt Panel Sticker				
2011	991893	Frt Panel Garnish	BT	✓	1	✓
1024	991222	Frt Apron Panel				
2012	991527	Frt Corner Panel LH BT RH MS		✓	2	✓
2013	991532	Frt Corner Panel Signal Lamp				
2014	995245	Frt Signal Lamp LH				
2015	995246	Frt Signal Lamp RH				
1029	995153	Frt LH Headlamp Assy				
1030	991821	Frt RH Headlamp Assy	CRK	✓	1	✓
1031	995088	Frt LH Side Lamp				
1032	995089	Frt RH Side Lamp				
2016	992149	Frt Wiper Panel	BT	✓	1	✓
2017	995043	Frt Wiper Nozzle				
1120	992140	Frt Wiper Arm	DMG	✓	2	✓
1121	992142	Frt Wiper Blade	BT	✓	2	✓
2018	992145	Frt Wiper Link				
2019	992148	Frt Wiper Motor				
1122	995045	Wiper Panel Garnish				
1114	992093	Frt Windscreen	CRK	✓	1	✓
1115	992097	Frt Windscreen Rubber	NEC	✓		✓
1117	992098	Frt Windscreen Sealant	NEC	✓		✓
2020	992114	Frt Windscreen Outer Pillar				
2021	992113	Frt Windscreen Inner Pillar				
1118	991019	ERP Bracket	NEC	✓		✓
1119	991020	ERP Unit				
2022	991958	Frt Side Mirror (Big)				
2023	991959	Frt Side Mirror (Small)				
2024	991962	Frt Side Mirror (Round)				
2025	995015	Frt Wing Mirror Stay				
1025	992013	Frt Support Panel				
1053	990248	Bonnet				
1055	990287	Bonnet Lock				
1057	990273	Bonnet Hinge				
1059	990305	Bonnet Rubber				
1060	990119	Air Con Condenser				
1063	990122	Air Con Fan Assy				
1068	990149	Air Con Liquid Pipe				
1069	995066	Air Con Receiver Drier				
1052	995074	Radiator				
1053	992738	Radiator Cowling				
1054	992742	Radiator Fan Assy				
1056	992758	Radiator Hose Top				
1058	992741	Radiator Expansion Tank				
2026	992596	Oil Cooler				
1070	994431	Power Steering Cooler Pipe				
1059	990151	Air Duct				
1060	990070	Air Cleaner Assy				
1067	990219	Battery				
1069	990223	Battery Bracket				

NAC	INC	Item	CON	AC	Qty	✓	
1065	991011	Engine Under Cover					
1086	990945	Engine Mounting			7	✓	
2027	991500	Frt Cabin Assy	Defor	✓	1	✓	
2028	991501	Frt Cabin Mounting			?	✓	
2029	991502	Frt Cabin Rear Panel					
1092	991520	Frt LH Chassis Member			R	✓	
1093	991520	Frt RH Chassis Member	BT	✓		✓	
1094	990728	Frt Vertical Cross Member			?	✓	
1095	991863	Frt Lower Cross Member					
2030	990143	Air Con Evaporator Assy					
2031	990106	Air Con Blower			?	✓	
1087	990427	Brake Master Pump Assy			?	✓	
1088	990403	Brake Booster Pump Assy			?	✓	
2032	990431	Brake Pedal			?	✓	
2033	990021	Accelerator Pedal			?	✓	
2034	990627	Clutch Pedal			?	✓	
1127	994483	Steering Wheel Airbag	Act. unit	✓	1	✓	
1128	994485	Steering Wheel Airbag Sensor	NEC	✓		✓	
1131	990029	Airbag Control Unit	NEC	✓		✓	
1055	991922	Frt RH Seat Belt Assy	DM	✓	1	✓	
1055	995182	Frt LH Seat Belt Assy					
1074	990753	Dashboard Assy	Defor	✓	1	✓	
1085	992282	Glove Box Cover	Defor	✓	1	✓	
1026	992281	Glove Box Compartment	Defor	✓	1	✓	
1056	995070	Frt LH Fender DashBoard Speaker			?	2	✓
1097	995072	Frt LH Fender Inner Panel					
1100	991740	Frt LH Fender Inner Shield					
1101	995179	Frt LH Mudflap					
2035	994966	Frt LH Wheel Guard					
1029	995170	Frt LH Wheel Rim					
1034	995065	Frt LH Tyre					
1035	995071	Frt RH Fender					
1036	991739	Frt RH Fender Inner Panel					
1037	991740	Frt RH Fender Inner Shield					
1038	991884	Frt RH Mudflap			?	✓	
2036	994966	Frt RH Wheel Guard					
1039	992087	Frt RH Wheel Rim	DT	✓		✓	
1039	995065	Frt RH Tyre					
1038	995326	Frt LH Door					
1038	995140	Frt LH Door Protector					
1037	995104	Frt LH Door Hinge					
1038	995142	Frt LH Door Wing Mirror					
1038	995103	Frt LH Door Glass					
1037	991595	Frt LH Door Glass Regulator					
1037	991596	Frt LH Door Glass Regulator Motor					
1035	991662	Frt LH Door Rubber					
1035	991636	Frt LH Door Outer Handle					
1034	991617	Frt LH Door Inner Trim Board					
1037	995327	Frt RH Door	Defor	✓	1	✓	
1037	991654	Frt RH Door Protector	NEC	✓	1	✓	
1038	991601	Frt RH Door Hinge	BT	✓	2	✓	
1037	991685	Frt RH Door Wing Mirror	CRK	✓	1	✓	
1034	991584	Frt RH Door Glass Wing Mirror	Garnish	MS	✓	1	✓
1034	991595	Frt RH Door Glass Regulator	DMG	✓	1	✓	
1035	991596	Frt RH Door Glass Regulator Motor	DMG	✓	1	✓	
1036	991662	Frt RH Door Rubber	NEC	✓		✓	
1037	991636	Frt RH Door Outer Handle	DMG	✓		✓	
1033	991617	Frt RH Door Inner Trim Board	Defor	✓		✓	
2037	991644	Frt Door Frt Pillar					
2038	991657	Frt Door Rear Pillar	Frt RH Door	Lock	DMG	✓	
2039	992072	Frt Wheel Arch Panel	Frt RH Door	Glass	CRK	✓	
2040	992069	Frt Wheel Arch Panel Garnish					
2041	991996	Frt Step Panel	MS	✓		✓	
2042	994498	Frt Step Panel Top Garnish					
2043	994495	Frt Step Panel Inner Garnish					
1075	995053	Wiper Washer Tank					
1136	990247	Sticker					
		Partition Panel Frame	DT	✓	1	✓	
		RH Frt Upper Arm	BT	✓	1	✓	
		RH Frt Lower Arm	BT	✓	1	✓	

No of Items:             
 Frt Cabin Lining Defor ✓ 1 ✓  
 Frt Cabin Lining Ety NEC ✓ ✓

RH Frt Absorber BT ✓ ✓  
 Steering Rack & Axion DMG ✓ ✓  
 RH Frt Drive Shaft DMG ✓ ✓  
 RH Frt Hub & Bearing ? ✓

Approval Reason

Remarks

damage assessment Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	DYNA 3.0	Engine Capacity	1.67
Date of Registration	15/03/2018	Classis No.	KDY2318027691		
Towing Required *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Vehicle in IDAC *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Parallel Import *	<input type="radio"/> Yes <input checked="" type="radio"/> No
Type of Tender *	Own Damage	Assessor Name *	SEBASTIAN	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #D1-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	<input type="radio"/> Yes <input checked="" type="radio"/> No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

Remark

NO OF REPAIR DAYS 28 /2X FRT BUMPER BRACKET REPLACE/1X FRT WINDSCREEN REPLACE/1X FRT WINDSCREEN RUBBER REPLACE/1X AIR CON LIQUID PIPE UNCONFIRM /1X A UNCONFIRM/1X FRT CABIN LINING DEFORM REPLACE/1X FRT CABIN LINING CLIP NEC REPLACE/1X ENGINE MOUNTING UNCONFIRM /1X FRT VERTICAL CROSS MEMBER UNCONF PEDAL UNCONFIRM/1X STEERING WHEEL AIRBAG REPLACE/1X DASHBOARD ASSY REPLACE/2X DASHBOARD SPEAKER UNCONFIRM/1X FRT RH WHEEL RIM REPLACE/2X FRT RH C REPLACE/1X FRT RH DOOR WING MIRROR REPLACE/1X FRT RH DOOR WING MIRROR GARNISH REPLACE/1X FRT RH DOOR OUTER HANDLE REPLACE/1X FRT RH DOOR INNER TRT REPLACE/1X FRT DOOR REAR PILLAR REPLACE/1X FRT RH DOOR GLASS REPLACE/1X FRT STEP PANEL REPLACE/1X PARTITION PANEL FRAME REPLACE/2X RH UPPER AND RH LOW 1X RH FRT ABSORBER REPLACE /1X RH FRT HUB & BEARING UNCONFIRM/

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *
root	1	32200101	NUMBER PLATE (FRONT)	1	Replace
Not Applicable					
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace
ABSORBER	3	16000101	BUMPER (FRONT)	1	Replace
ACCELERATOR					
ACTUATOR	4	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace
ADVERTISEMENT STICKER	5	27100101	GRILLE (FRONT)	1	Replace
	6	33000101	PANEL (FRONT)	1	Replace
	7	33000301	PANEL EMBLEM (FRONT)	1	Replace
	8	38500202	SIGNAL LAMP (FRONT RIGHT)	1	Unconfirm
	9	27700101	HEAD LAMP (LEFT)	1	Unconfirm
	10	27700102	HEAD LAMP (RIGHT)	1	Replace
	11	45400501	WIPER LINK (FRONT)	1	Unconfirm
	12	451020	WINDSCREEN SEALANT	1	Replace
	13	112085	AIR CON RECEIVER DRYER	1	Unconfirm
	14	344005	RADIATOR COWLING	1	Unconfirm
	15	344008	RADIATOR FAN	1	Unconfirm
	16	344007	RADIATOR EXPANSION TANK	1	Unconfirm
	17	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace
	18	27100801	GRILLE EMBLEM (FRONT)	1	Replace
	19	33000401	PANEL GARNISH (FRONT)	1	Replace
	20	21300101	CORNER PANEL (FRONT LEFT)	1	Replace
	21	21300102	CORNER PANEL (FRONT RIGHT)	1	Replace
	22	454008	WIPER PANEL	1	Replace
	23	45400101	WIPER ARM (FRONT LEFT)	1	Replace
	24	45400102	WIPER ARM (FRONT RIGHT)	1	Replace
	25	45400301	WIPER BLADE (FRONT LEFT)	1	Replace
	26	45400302	WIPER BLADE (FRONT RIGHT)	1	Replace
	27	45400601	WIPER MOTOR (FRONT)	1	Unconfirm
	28	245001	ERP BRACKET	1	Replace
	29	245002	ERP UNIT	1	Unconfirm
	30	112023	AIR CON CONDENSER	1	Unconfirm
	31	112060	AIR CON FAN	1	Unconfirm
	32	344001	RADIATOR	1	Unconfirm
	33	34402802	RADIATOR HOSE (TOP)	1	Unconfirm
	34	338007	POWER STEERING COOLER PIPE	1	Unconfirm
	35	19600501	CHASSIS MEMBER (FRONT LEFT)	1	Repair
	36	112003	AIR CON BLOWER	1	Unconfirm
	37	161001	CABIN	1	Replace

38	161010	CABIN MOUNTING	<input type="text" value="1"/>	Unconfirm
39	19600502	CHASSIS MEMBER (FRONT RIGHT)	<input type="text" value="1"/>	Replace
40	15701601	BRAKE MASTER PUMP (FRONT LEFT)	<input type="text" value="1"/>	Unconfirm
41	103002	ACCELERATOR PEDAL	<input type="text" value="1"/>	Unconfirm
42	15700501	BRAKE BOOSTER PUMP (FRONT)	<input type="text" value="1"/>	Unconfirm
43	200017	CLUTCH PEDAL	<input type="text" value="1"/>	Unconfirm
44	401005	STEERING AIR BAG SENSOR	<input type="text" value="1"/>	Replace
45	106007	AIR BAG CONTROL UNIT	<input type="text" value="1"/>	Replace
46	36300102	SEAT BELT (FRONT RIGHT)	<input type="text" value="1"/>	Replace
47	270002	GLOVE BOX COVER	<input type="text" value="1"/>	Replace
48	31900102	MUDFLAP (FRONT RIGHT)	<input type="text" value="1"/>	Unconfirm
49	23305302	DOOR PROTECTOR (FRONT RIGHT)	<input type="text" value="1"/>	Replace
50	401028	STEERING RACK & PINION	<input type="text" value="1"/>	Replace
51	23600102	DRIVE SHAFT (FRONT RIGHT)	<input type="text" value="1"/>	Replace
52	23300202	DOOR (FRONT RIGHT)	<input type="text" value="1"/>	Replace
53	23302402	DOOR GLASS REGULATOR (FRONT RIGHT)	<input type="text" value="1"/>	Replace
54	23302502	DOOR GLASS REGULATOR MOTOR (FRONT RIGHT)	<input type="text" value="1"/>	Replace
55	23306102	DOOR RUBBER (FRONT RIGHT)	<input type="text" value="1"/>	Replace
56	454012	WIPER WASHER TANK	<input type="text" value="1"/>	Unconfirm

## Claim Handling

## Accident MT/0990238

Policy No.	5099005781	Vehicle No.	GBH2130D	GST Registration No.	200808719K
Policyholder Name	LBE CONSTRUCTION PTE LTD			Policyholder NRIC	200808719K
Product Code	COMMERCIAL VEHICLE INSURAT	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	98103053	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	No Yes	TCA	No Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

## Accident Details

Report Date	13/04/2018 13:16	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	12/04/2018	Time of Accident hh:mm	15:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	TUAS VIEW CIRCUIT				

## Benefits

## Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

## GST Registered Information

GST Registered	Yes	GST Registration Date	01/06/2008
GST Registration No.	200808719K	GST Status Verified	Yes
Modification History	16/04/2018 09:57:17 Nur Shahira Hassan changed GST Registered from No to Yes 16/04/2018 09:57:17 Nur Shahira Hassan changed GST Registration No. from null to 200808719K 16/04/2018 09:57:17 Nur Shahira Hassan changed GST Registration Date from null to 01/06/2008		

## Policyholder Mailing Address

Address 1	19 TUAS VIEW CIRCUIT	Address 2	SINGAPORE 637571	Address 3	
Address 4		Address Type	Singapore address	Post Code	637571
Unit No.		Related Policy Number	5098755700		

## OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	02/06/1984
Unnamed driver Name	ALAM BADRUL	Driver NRIC	GB266583N	Driving Experience	0
Register Date of Driver License	07/12/2017	Driver Age	33	Contact No.(Home)	0
Contact No.(Mobile)	98103053	Contact No.(Office)	0	Address 3	
Address 1	LBE ENGINEERING PTE LTD	Address 2		Post Code	
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	Yes No	Driver Vehicle No.		Driver Insurer Company	

## Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes No
-------------------------------------	------	-------------	--------

## Modification History

## Investigation

## Claim 001 OD-MD

## Claim Case Officer Ng Hak Joo

Claim Type	OD-MD	Insured Name	LBE CONSTRUCTION PTE LTD	Insured NRIC	200808719K
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	68622103
Email Address		OI Vehicle Number	GBH2130D	TP Vehicle Number	TREE
Claim Description	GBH2130D / TREE ON 12 Apr 2018			Name of Preferred Workshop	OPTIMA WERKZ
Preferred Workshop Contact No.	64849919	Insured Liability	Partially at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Date Registered	13/04/2018 13:25	Claim Close Date		Date Received	16/04/2018
Report Taken By	KRISHNASAMY	Workshop Repairer		Total Loss but Repaired	

## Print AK letter

Modification History	13/04/2018 16:20 s991212 Modify Name of Preferred Workshop(-->OPTIMA WERKZ PTE LTD) 13/04/2018 16:20 s991212 Modify Preferred Workshop Contact No(-->64849919)
----------------------	---

## Special Claim Creation Approval

Approval Reason

Remarks

**damage assessment** Attachment

Accident No. MT/0990238 Claim No. 001  
 Last Doc. Received \* Yes  No  Upload Date 16/04/2018 17:09

Path \*

- Choose File No file chosen
- Message Read

Clear	Category +	Confidential	Urgency *
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:09	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:09	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:09	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:09	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:09	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:09	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:09	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:08	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:08	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:08	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:08	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:08	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:07	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:07	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:07	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:07	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:07	Photos	Normal	Photos 2018-4-16
	NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:07	Photos	Normal	Photos 2018-4-16





NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:00	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:00	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:00	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 17:00	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:59	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:59	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:59	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:59	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:59	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:59	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:58	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:58	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:58	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:58	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:58	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16
NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 16 Apr 2018 16:57	Photos	Normal	Photos 2018-4-16





NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:23

NRIC/ Driving License

Normal

NRIC/ Driving License 2018

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:22

SAS

Normal

SAS 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:22

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:22

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:22

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:22

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:21

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:21

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:21

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:21

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:21

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:21

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:20

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:20

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:20

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:20

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:20

Photos

Normal

Photos 2018-4-13

NAC\_PAYA\_UBI\_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o n 13 Apr 2018 13:20

Photos

Normal

Photos 2018-4-13

Video List

Uploaded By/Date

Folder Date

File Name



Source

Display in New Window

Scan and uploading

## LKK Paya Ubi

---

**From:** Tan Siew Choo <siewchoo.tan@income.com.sg>  
**Sent:** Friday, 4 May 2018 5:28 PM  
**To:** NAC ; Hock Wah Motor Pte Ltd  
**Subject:** GBH2130D, OD claim no : MT/0990238

**Importance:** High

Dear IDAC and Hock Wah,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

**Dear Mr Legolas of Hock Wah,**

OD excess of \$1600/- (std : \$600/-, further excess : \$1K) is applicable, pls assist to liaise with contact person Ms Katherine at tel : 93365073.

Survey required and you have to arrange personally at [mtsurvey@income.com.sg](mailto:mtsurvey@income.com.sg)

Pls assist to expediate on repair works as owner needs her veh urgently for work.

**FOR PAYMENT:** Please forward the Invoice & Discharge Voucher within 14 days after the repair has been done to my email, cc a copy to Yap Chee Ling at [cheeling.yap@income.com.sg](mailto:cheeling.yap@income.com.sg)

Regards.

Without Prejudice

**Tan Siew Choo**  
Senior Claims Executive  
Motor Insurance  
T +65 6430 7882  
[www.income.com.sg](http://www.income.com.sg)



Our Ref: MT/CA/OD/051/0990238-001/TSC  
04 May 2018  
HOCK WAH MOTOR WORKSHOP PTE LTD  
BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12  
BEDOK INDUSTRIAL PARK E  
SINGAPORE 489977

Dear Sir

**CLAIM NUMBER: MT/0990238-001**

**REPAIR OF VEHICLE NUMBER: GBH2130D**

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 04 May 2018

Make: TOYOTA

Model: DYNA 3.0

Estimated Repair Days: 35

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at [motor@income.com.sg](mailto:motor@income.com.sg).

Yours sincerely

Low Choo Mee

Senior Manager

Motor Insurance

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



**Vehicle Movement Form**

**Vehicle Check-In**

Vehicle No: GBH21300 Date In: \_\_\_\_\_ Time In: \_\_\_\_\_ with Keys: Yes / No

*For Office use*

Attended by: \_\_\_\_\_

**Workshop Collection of Vehicle**

Workshop: Hock Wah.

Collection Date: 05.05.2018 Time: 1148 with Keys: Yes / No

Tow Truck No: YP7951D Tow Man: Fabian Tan NRIC: S8106925/E.

Signature: [Signature] 9822 8222.

*For office use*

Attended by: ROSALINDA

Approved by: \_\_\_\_\_

**Workshop Return of Vehicle**

Workshop: \_\_\_\_\_

Returned Date: \_\_\_\_\_ Time: \_\_\_\_\_ with Key: Yes / No

\* Tow In / Drive In  
Tow Man / Workshop Representative: \_\_\_\_\_ NRIC: \_\_\_\_\_

Signature: \_\_\_\_\_

*For office use*

Attended by: \_\_\_\_\_

**Owner Collection of Vehicle**

Collection Date: \_\_\_\_\_ Time: \_\_\_\_\_ with Key: Yes / No

Owner: \_\_\_\_\_ NRIC: \_\_\_\_\_

Signature: \_\_\_\_\_

*For office use*

Attended by: \_\_\_\_\_

Approved by: \_\_\_\_\_

## LKK Paya Ubi

---

**From:** Tan Siew Choo <siewchoo.tan@income.com.sg>  
**Sent:** Friday, 4 May 2018 5:28 PM  
**To:** NAC ; Hock Wah Motor Pte Ltd  
**Subject:** GBH2130D, OD claim no : MT/0990238

**Importance:** High

Dear IDAC and Hock Wah,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

**Dear Mr Legolas of Hock Wah,**

OD excess of \$1600/- (std : \$600/-, further excess : \$1K) is applicable, pls assist to liaise with contact person Ms Katherine at tel : 93365073.

Survey required and you have to arrange personally at [mtsurvey@income.com.sg](mailto:mtsurvey@income.com.sg)

Pls assist to expediate on repair works as owner needs her veh urgently for work.

**FOR PAYMENT:** Please forward the Invoice & Discharge Voucher within 14 days after the repair has been done to my email, cc a copy to Yap Chee Ling at [cheeling.yap@income.com.sg](mailto:cheeling.yap@income.com.sg)

Regards.

Without Prejudice

**Tan Siew Choo**  
Senior Claims Executive  
Motor Insurance  
T +65 6430 7882  
[www.income.com.sg](http://www.income.com.sg)



Our Ref: MT/CA/OD/051/0990238-001/TSC  
04 May 2018  
HOCK WAH MOTOR WORKSHOP PTE LTD  
BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12  
BEDOK INDUSTRIAL PARK E  
SINGAPORE 489977

Dear Sir

**CLAIM NUMBER: MT/0990238-001**  
**REPAIR OF VEHICLE NUMBER: GBH2130D**

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 04 May 2018

Make: TOYOTA

Model: DYNA 3.0

Estimated Repair Days: 35

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at [motor@income.com.sg](mailto:motor@income.com.sg).

Yours sincerely

Low Choo Mee

Senior Manager

Motor Insurance

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.