

Surveyor: P. Rame

REF: NS/INC 18006824 / R1/vbn2

22920

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: SJM 5462EPolicy No. 5096936154 29.12.17 - 01/01/19Claims No. MT/0986118-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMB 148T Yr Regn: 2011 / MSK

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ C140 C.C. 6374Colour MULTI A/C: Insured / Std / NI / NASp. Reading 648548 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WEB 62808323120703Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NA / S/Rim / STD A/Rim orTyre Size: F: 275 / 70R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIAT

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mmD.O.A. 12/03/18D.O.I. 11/04/18Survey held at SMARTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SMB 148T - 013/MSG13016146/K1/vbn2</u>
	<u>SJM 5462E - X</u>
<u>27/4/18</u>	<u>LS \$1500 confirmed by email (Ref 811, 359)</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 2

1)

☐ : Final ReportResurvey No. of Trip: -

Date/Time, File Return to?

2) 30/4 - typistAdd Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format: TPLump Sum / I.B.I: (\$ 1500/2)

TOTAL

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006824/R1vb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 13-04-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 5462E	Veh. Inspected	SMB 148T	
Policy No.	5096936154	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/04/2018	Inspection Date	11/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0992340-001	Comfort Transportation	SHA 5617M	EM 3928B	26/4/2018
2	MT/0992344-001	Comfort Transportation	SH 6997S	SJL 3515E	26/4/2018
3	MT/0986118-002	SMRT BUSES LTD	SMB 148T	SJM 5462E	12/3/2018
4	MT/0991797-002	CityCab	SHC 7718G	XD 8343C	24/4/2018
5	MT/0986118-002	SMRT BUSES LTD	SMB 148T	SJM 5462E	12/3/2018
6	MT/0992112-002	Comfort Transportation	SH8003Y	FBK 528M	26/4/2018
7	MT/0992351-001	Comfort Transportation	SH 6751J	GY 4005X	23/4/2018

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	S096936154	HUANG ZHANGLUN	S8233480G	GPC	drive CLASSIC	SJM5462E	SJM5462E	29/12/2017	07/01/2019

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 April 2018 4:58 PM
To: 'Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)'; Rasul (LKKAUTO)
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); AutoSvs-ARC (Bus); SUR
Subject: RE: Finalisation - SMB148T (BUS/03/18/1024) - IDAC

Dear Catherine,

Finalised amount LS \$1,500/- @ 2 working days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [mailto:catherineleesc@smrt.com.sg]
Sent: Friday, 27 April 2018 4:27 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; AutoSvs-ARC (Bus) <AutoSvs-ARCBUS@smrt.com.sg>
Subject: Finalisation - SMB148T (BUS/03/18/1024) - IDAC

Hi Rasul,

Attached herewith our copy and your marked copy of the bus repair estimate for the case.
Our finalised amount is \$1,500/- @ 2 working days under lump sum repair.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



Moving People, Enhancing Lives

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/03/2018 15:11
Date Of Accident	12/03/2018 19:35
Exact Location Of Accident	SERANGOON ROAD (BS: 60181 - AFT MOONSTONE LANE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB148T
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	CITARO O530-6.4 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087563MFBP
Cover Note Number	
Driver	
Name of Driver	GOH YING SIANG
NRIC No	G2851782W
Date Of Birth	11/11/1983
Occupation	OUTDOOR
Date Of Driving Pass	01/09/2016
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 15

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

AT THE STATED DATE AND TIME, I WAS TRAVELLING ALONG SERANGOON ROAD BEFORE BS 60181, ON THE LEFT MOST LANE WHEN THE RIGHT CENTRE PORTION OF MY BUS WAS GRAZED BY THE LEFT FRONT PORTION OF A PRIVATE CAR.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJM5462E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver HUANG ZHANG LUN

NRIC/Passport Number S8233480G

Contact Number 98771422

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver) 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. The report must be **completed by the Policyholder and/or the Licensed Driver**.
3. Information provided must be **as truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may result in the insurance company being **debarred** from providing insurance cover to you.
4. All insurance companies to **repudiate policy liability**.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
6. Any **claims** reporting may be referred to the Police for investigation.
7. The report will be forwarded by the insurers of the GAA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for free be made available upon application by interested parties.
8. By the engagement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as foretold.
9. Consent under the Personal Data Protection Act (PDPA)
10. I understand, acknowledge, agree and consent that:
- (a) My insurer, the Insurer, and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or provided by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law/insure law firm, the Ministry Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquires by me;
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of enveloped/mail packages); and/or
- (v) carrying out any applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) All Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law/insure law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law/insure law firm), which may be used outside of SIU purposes, for one or more of the above Purposes.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Personnel Witnessed by Dispensing Centre

(R) 201515145T

RECEIVED

Sketch Plan

CEYLANHODD ROAD (BEFORE BS 60181) - AFT MOONSTONE LANE

Describe Circumstances of the Accident

REFER TO SKETCH

Sketch Plan Pg. 2

Declaration

lyth declare the foregoing particulars are true in every respect.



Policyholder Signature / Date &
Time

1 MAR 2013



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Recruiting Centre
Personnel

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SMB148T
Vehicle Type:	H20 - Public Transport Bus/Coach/Minibus
Vehicle Attachment 1:	Air-Conditioned
Vehicle Scheme:	OmniBus (SMRT - ARF-exempted)
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CITARO O530
Chassis No.:	WEB62808323120703
Propellant:	Diesel
Engine No.:	90292600849071
Engine Capacity:	6374 cc
Maximum Power Output:	-
Maximum Laden Weight:	17900 kg
Unladen Weight:	11120 kg
Year Of Manufacture:	2010
Original Registration Date:	06 May 2011
Lifespan Expiry Date:	05 May 2028
Road Tax Expiry Date:	05 May 2018
Inspection Due Date:	05 May 2019
Intended Transfer Date:	16 Apr 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 05 May 2018. You may renew the road tax from 06 Feb 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 05 May 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 06 May 2018 to 05 Nov 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	850.00	-	850.00
Total Amount Payable:			875.00

Amount Payable (From 06 May 2018 to 05 May 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	1,700.00	-	1,700.00
Total Amount Payable:			1,725.00

You may print this page for reference.


OK

Print

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB148T
 Ref. No : BUS/03/18/1024
 Reg. Date : 14/03/2018
 Vehicle Type : BUS -12M
 Make : MB CITARO MERCEDES
 Model : MB CITARO O530
 Name of Driver : Goh Ying Siang
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 12/03/2018 07:33:00 PM
 Accident Reported Date / Time : 14/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : IDAC
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SMB148T - RIGHT CENTRE PORTION
 SJM5462E (TP) - INSURED WITH NTUC
 Prepared Date : 14/03/2018 03:21:54 PM



Chassis No :

Work Shop :

Summary of Repair Estimates

Total Labour Charges :
Total Spray Painting Charges :
Total Material Charges :
Other Charges :
TOTAL :
Lum Sum Total :
No. of Repair Days :
Prepared / Adjusted By :
Arc / Surveyor Sing Off Date :

Mileage : 0

Repair Completed Date / Time :

Adjusted by Surveyor, if applicable

Quotation from ARC :
1,325.00
786.00
0.00
0.00
2,111.00
2,100.00
3.00

000 2 days - Lump sum

01/01/1900 12:00:00 AM

11/04/2018 01:59:44 PM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/04/2018 01:59:37 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :
Quotation Date :
Invoice Amount :
Invoice No :
Invoice Date :
Prepared Date :

LIK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11/04/18 P1415

f

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	0.00 1060
Total Labour	1,325.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	786.00	0.00 600
Total Spray Painting & Panel Beating	786.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMO	4005299	SMRT STICKER(B)	1	200.00	0.00	200.00	Replace	Replace <i>AB</i>	No
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)										
								200.00	200.00	
								0.00	0.00	


Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB148T
Ref. No : BUS/03/18/1024
Reg. Date : 06/05/2011
Vehicle Type : BUS -12M
Make : MB CITARO MERCEDES
Model : MB CITARO O530
Name of Driver : Goh Ying Siang
Type of Accident : SIDE SWIPE
Date / Time of Accident : 12/03/2018 07:33:00 PM
Accident Reported Date / Time : 14/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095504
Special Instruction to ARC,if any :
SMB148T - RIGHT CENTRE PORTION
SJM5462E (TP) - INSURED WITH NTUC
Prepared Date : 14/03/2018 03:21:54 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WEB62808323120703

Mileage

0

Work Shop :

Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,325.00	1,060.00
Total Spray Painting Charges	: 786.00	600.00
Total Material Charges	: 160.00	160.00
Other Charges	: 0.00	-300.00
TOTAL	: 2,271.00 2311	1,520.00
Lum Sum Total	: 2,250.00	1,500.00
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	:	RASUL-LKK 90010068
Arc / Surveyor Sign Off Date	: 11/04/2018 01:59:44 PM	27/04/2018 08:53:30 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/04/2018 01:59:37 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	1,060.00
Total Labour	1,325.00	1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	786.00	600.00
Total Spray Painting & Panel Beating	786.00	600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	0.00	-300.00
Total Other Costs	0.00	-300.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMO N	4005299	SMRT STICKER(B)	1	200.00	0.00	200.00	Replace	Replace	No
TOTAL MATERIALS							200.00	200.00		
TOTAL MATERIALS(Discounted)							160.00	160.00		

nel

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006824/R1vbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 09-05-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 5462E	Veh. Inspected	SMB 148T	
Policy No.	5096936154	Coverage (\$)	0.00	
Claim No.	MT/0986118-002	Excess (\$)	0.00	
Assign From		Assign Date	11/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CITARO	c.c	6374	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WEB62808323120703	Colour	MULTI	
Odometer	648548	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2018	Inspection Date	11/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 148T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	NECESSARY		
	SMRT STICKER (B)(SN)		200.00	200.00
			200.00	200.00
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		1,325.00	1,060.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		786.00	600.00
			2,111.00	1,660.00
GRAND TOTAL			2,311.00	1,860.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,500.00

Report Ref No. NS/INC18006824/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.