

SS. REC. BY:

REF:

CS/CTU8006831 / Agb 9/1

Special Instruction:

Survivor

Action

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTU

Date/Time: 13042018 9:17am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 963B

Insured:

CB 6436R

at Workshop n/s

Hiap Hong Motor

Tel:

6745 9635

of

3 Kaki Bukit Ave 2 #02-13

Policy No:

DMB1SN181551800

Claim No:

9NM18 D01887C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 04042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

13042018 11:00am

Person Contacted:

An Chua

Vehicle: ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

SKQ 963B x

CB 6436R - CB/TNC18000331 / 1/16/18

DCA: 301115

Final Ptg 64401.52 (Ptd @ 2154.48, 33%)

no. lump sum.

Vok/4.

REF: 07

MURMUR

SIGNATURE

From: Date: 13042018

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.:

at Workshop no.:

of:

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKQ 963B -

Veh Regn:

31/10/14

Type: M/Cat / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 6

Colour:

White

Sp. Reading:

65950

Eng No:

Chassis:

JM64J1071E0

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

225/55R17

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

06

mm

Rear

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

13/04/18

Survey held at:

Hiap Hong

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front N/S

The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

TP Chinn

RECEIVED 27 APR 2018

Title/Time: File Pass to:



Preli. Report

Days Of Repair:

4

Title/Time: File Return to:



Final Report

Resurvey No. of Trip:

1

Survey Fee:

Suspension:

1.2500

Fuel:

1.0000

1.0000

TOTAL:

Report Format:

MER-TP

Lump Sum / L.B. / S:

4401.52

Add Fee:



Site Insp. 15



Inter-ops 15



Fgtn / LBS 15



Access 15

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CT118006831/Aqb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 13-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 6436R	Veh. Inspected	SKQ 963B	
Policy No.	DMB1SN1811551800	Coverage (\$)	0.00	
Claim No.	SNM18D01887C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	13/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/04/2018	Inspection Date	13/04/2018	
Survey held at	HIAP HONG MOTOR REPAIR 2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Apr 2018		13 Apr 2018 09:17 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by insurer]	
Insured:		GAN CHONG NERN, ID: S7533385D							
Main Claimant:		ONG SIONG HEE JAMES, ID: S1712369F							
Vehicle Reg. No.:		SKQ963B		Date of Loss:		04/04/2018 07:00 - :59			
Claim Type:		TP / SNM18D01887C02		Policy/Cover Note No.:		DMB1SN1811551800 (Third Party Only)			
Vehicle Reg. No. (Insured):		CB6436R		Policy No. (Claimant):		M0001879			
				Excess:		S\$0.00			
Repairer:		Hlap Hong Motor Repair () 2 Kaki Bukit Avenue 2, #02-13, 417921 Kaki Bukit - Tel:							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Claimant's Insurer:		Etika Insurance Pte Ltd (HQ) - Tel: 63360477							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/04/2018]							
Driver/Custodian (Insured):		TAN TIAN HING (66 / Male), NRIC: S0098597Z, Tel: +6582659875							
Adj. Asg. Remarks:		NO EST, ASSIGN MARCUS CHUA AS STE.							
ASSOCIATED MAIL RECEIVED								View All	
There are no mail for this case.								Compose Case Mail	
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/04/2018 13:03
Date Of Accident 04/04/2018 07:00
Exact Location Of Accident EAST SPRING PRIMARY SCHOOL CAR PARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKQ963B
Insured/Policyholder
Name Of Registered Owner ONG SIONG HEE JAMES
NRIC No S1712369F
Email Address JAMESONG.SH@GMAIL.COM
Mobile Phone No (LOCAL) +65-96967890
Alternative Phone No Office-96967890

Vehicle Particulars

Manufacturer MAZDA
Model 6
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company ETIQA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number M0001879
Cover Note Number

Driver

Name of Driver ONG SIONG HEE JAMES
NRIC No S1712369F
Date Of Birth 19/10/1965
Occupation INDOOR
Date Of Driving Pass 03/09/1984
Driving Experience 33 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96967890

Fax Number	
Contact Number	OFFICE-96967890
EMail Address	JAMESONG.SH@GMAIL.COM
Address	BLK 208 PASIR RIS ST 21 #08-346
Postcode	1851
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB6436R
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	BUS
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
	NA
Address	NA
	NA
Postcode	NA

Insurance Company Name

China Taiping Insurance (Singapore) Pte. Ltd.

Nature Of Damage

NA

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

11-4-2018
12.50PM

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see attached.

Insurance Co.	
Vehicle No.	Date of Accident
☐ Reporting Only	
☐ Own Damage Claim	
☒ Third Party Claim	@ Hiap Hoy Motor.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

11-4-2018
12.50 PM

Reporting Centre Personnel's Signature
Name
NRIC/Fin No:



**MOTOR ACCIDENT WITHIN EAST SPRING PRIMARY SCHOOL IN TAMPINES
ON 04.04.2018 BETWEEN CD6436R AND SKQ963B**

On 04.04.2018, I had parked my car (SKQ963B) in a proper car park lot in East Spring Primary School early in the morning. When I got to my car to leave the school, I noticed that the front left portion of my vehicle had been damaged. An investigation through the school's CCTV showed that a school bus, vehicle number CD6436R, had hit my car at 7.01am. He returned to the school to pick the students at about 1pm. When approached, he responded by saying that he will privately pay for the repair to the damage of my car. Hence we did not make the accident report immediately.

When we presented our workshop's repair estimate, he realised that he could not afford to settle privately and told us to claim against his vehicle's insurance.

I am making this report to claim against his insurer, Chiao Tai Ping Insurance Co. Pte Ltd.



JAMES ONG SIONG HEE
I/C: S1712365F

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1712369F



ONG SIONG HEE
王祥旭
Race
CHINESE
Date of Birth
19-10-1966
Sex
M
Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Personal Number S1712369F
Name
ONG SIONG HEE
Date of Birth 19 Oct 1966
Issue Date 29 Oct 2005




51712369F



2004 51712369F

Blood Group Date of issue
AB+ 30-04-1993

Address
APT BLK 206 PASIR RIS STREET 21
#08-346
SINGAPORE 1851

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CATEGORIES

PAGE 0071

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 03 Sep 1964

NP 428A

License No: S1712369F



CERTIFICATE OF INSURANCE

• MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) • MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 • ROAD TRANSPORT ACT, 1987 (MALAYSIA) • MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE No.	M0001879		
1. Index Mark and Registration Number of Vehicle	SKQ9638		
2. Name of Policyholder	Ong Siong Hee James		
3. Effective Date of Commencement of Insurance for the purposes of the Act	01/11/2017	Excess: Named Drivers	S\$900
		Excess: Unnamed Drivers	S\$1,800
4. Date of Expiry of Insurance	31/10/2018		
5. Persons or Classes of Persons entitled to drive	(A) THE POLICYHOLDER. THE POLICYHOLDER MAY ALSO DRIVE A MOTOR CAR NOT BELONGING TO HIM OR HIRED (UNDER A HIRE PURCHASE AGREEMENT OR OTHERWISE) TO HIM OR HIS EMPLOYER OR HIS PARTNER. (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION. Ong Siong Hee James Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle.		
6. Limitations as to Use	USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER: (i) USE FOR HIRE OR REWARD. (ii) USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING. (iii) USE FOR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS. (iv) USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.		

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these bindings.

Policy Owner's Protection Scheme

This policy is protected under the Policy Owner's Protection Scheme which is administered by the Singapore Deposit Insurance Corporation (SDIC). Coverage for your policy is automatic and no further action is required from you. For more information on the types of benefits that are covered under the scheme as well as the limits of coverage, where applicable, please contact your insurer or visit the GIA / UA or SDIC websites (www.gia.org.sg or www.ua.org.sg or www.sdic.org.sg).

I/WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of Etiqa Insurance Pte. Ltd.
Approved Insurer


Authorised Signatory

GOP25848 04/10/2017 15:04:49



Hiep Hong

SKQ 963B

TP China
Xiao Chen

Mazda 6

JM6BJ1071E0139264

Front Bumper Deformed

1096.40 ✓

Front Bumper Clips. New

30 ✓

Front Bumper Side Holder LH. New

62.20 ✓

Front Bumper Sensor Not New

280(SW) X

Front Bumper Fog Lamp LH

337.40 X

Front Bumper Fog Lamp Cover LH. Not New

47.50 X

Headlamp LH. Cracked

2577.60 ✓

Front LH Fender Buckled

385.70 ✓

Front LH Fender Inner Shield Not New

145.20 X

Front LH Fender Inner Shield Clips. Not New

30 X

Panel Beating

~~600~~ 400

Spray Painting

~~800~~ 600

Wiring

50.30

To remove front bumper sensor

100 50

list 4/5/80

Labour: 1080

len 20%: 3321.52

total 4401.52 (Part by Part.)

04 Days.

LKK Auto Consultants hence notify

the Repairer of the following:

- To ensure before/after state, painting
- To display before/after state, survey
- Parts must be "original"
- Third party must be notified if damaged
- No illegal modifications of parts
- Supplementary document must be submitted
- It is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date:

6/5/86

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Apr 2018		13 Apr 2018 09:17 Edit Adj Rpt	S\$4,401.52 Edit Estimates	S\$4,401.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GAN CHONG NERN , ID: S7533385D								
Main Claimant:	ONG SIONG HEE JAMES , ID: S1712369F								
Vehicle Reg. No.:	SKQ963B	Date of Loss:	04/04/2018 07:00 - :59 [41 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01887C02	Policy/Cover Note No.:	DMB1SN1811551800 (Third Party Only)						
Vehicle Reg. No. (Insured):	CB6436R	Policy No. (Claimant):	M0001879						
		Excess:	S\$0.00						
Repairer:	Hiap Hong Motor Repair () 2 Kaki Bykit Avenue 2, #02-13, 417921 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	Etika Insurance Pte Ltd (HQ) - Tel: 63360477								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/04/2018]								
Driver/Custodian (Insured):	TAN TIAN HING (66 / Male), NRIC: S0098597Z, Tel: +6582659875								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKQ963B (SNM18D01887C02)**
[CB6436R]

TP

ONG SIONG HEE JAMES

Apr 4 2018 7:00AM

[GAN CHONG NERN]

Hiap Hong Motor Repair

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)						Thumbnail	Print	
1	11/04/18 13:16	Accident Statement						Load HTM		
Photos/Images							3 per page		☒	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)						Thumbnail	Print	
1	11/04/18 13:10	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
2	11/04/18 13:10	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
3	11/04/18 13:10	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
4	11/04/18 13:10	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
5	11/04/18 13:10	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
6	11/04/18 13:10	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	24/04/18 15:56	General View						Load JPG	☒	
2	24/04/18 15:56	General View						Load JPG	☒	
3	24/04/18 15:56	General View						Load JPG	☒	
4	24/04/18 15:56	General View						Load JPG	☒	
5	24/04/18 15:56	General View						Load JPG	☒	
6	24/04/18 15:56	General View						Load JPG	☒	
7	24/04/18 15:56	General View						Load JPG	☒	
8	24/04/18 15:56	General View						Load JPG	☒	
9	24/04/18 15:56	General View						Load JPG	☒	
10	24/04/18 15:56	General View						Load JPG	☒	
11	24/04/18 15:56	General View						Load JPG	☒	
12	24/04/18 15:56	General View						Load JPG	☒	
13	24/04/18 15:56	General View						Load JPG	☒	
14	24/04/18 15:56	Reinspection Photo						Load JPG	☒	
15	24/04/18 15:56	Reinspection Photo						Load JPG	☒	
16	24/04/18 15:56	Reinspection Photo						Load JPG	☒	
17	24/04/18 15:56	Reinspection Photo						Load JPG	☒	
18	24/04/18 15:56	Reinspection Photo						Load JPG	☒	
19	24/04/18 15:56	Reinspection Photo						Load JPG	☒	
Documentation							1 per page		☒	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)						Thumbnail	Print	
1	11/04/18 13:15	Accident Sketch Plan [Linked Accident Report Documents]						Load JPG	☒	
2	11/04/18 13:15	Common Statement [Linked Accident Report Documents]						Load JPG	☒	
3	11/04/18 13:15	Individual Statement						Load TIF		

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
		[Linked Accident Report Documents]		
4	11/04/18 13:15	IC & DL [Linked Accident Report Documents]		Load TIF
5	11/04/18 13:15	CI [Linked Accident Report Documents]		Load TIF
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/04/18 09:15	PRS		Load PDF
2	13/04/18 09:17	OI GIA REPORT		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	11/04/18 13:16	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	11/04/18 13:10	Accident Photo		Load JPG ☒
2	11/04/18 13:10	Accident Photo		Load JPG ☒
3	11/04/18 13:10	Accident Photo		Load JPG ☒
4	11/04/18 13:10	Accident Photo		Load JPG ☒
5	11/04/18 13:10	Accident Photo		Load JPG ☒
6	11/04/18 13:10	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	11/04/18 13:15	Accident Sketch Plan		Load JPG ☒
2	11/04/18 13:15	Common Statement		Load JPG ☒
3	11/04/18 13:15	Individual Statement		Load TIF
4	11/04/18 13:15	IC & DL		Load TIF
5	11/04/18 13:15	CI		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006831/AQBQ2

Date: 04/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1811551800

Claimant Vehicle No: SKQ963B Insured Vehicle No: CB6436R

Date of Loss: 04/04/2018 Nature of Claim: TP Claim No: SNM18D01887C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ963B

Make & Model: MAZDA 6, 2.0 SP (A) Engine No: PE20517677

Reg. Date: 31/10/2014 (Man. Year: 2014) Chassis No: JM6GJ1071E0139264

Colour: White Odometer: 65950 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,006.00	3,321.52	1,684.48	33.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,080.00	470.00	30.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,556.00	4,401.52	2,154.48	32.86

INSPECTION

Date of Assignment: 13/04/2018

Date Inspected: 13/04/2018 Inspected At: Hiap Hong Motor Repair
2 Kaki Bykit Avenue 2, #02-13
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2018)
Parts: 143	MAZDA 6 2.0 SP (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKQ963B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,096.40 F	*1,096.40 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER LH	Necessary	62.20 F	*62.20 FL
4	1		*FRONT BUMPER SENSOR	Not Necessary	280.00 FS	*- FS
5	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	351.40 F	*- FL
6	1		*FRONT BUMPER FOG LAMP COVER LH	Not Necessary	47.50 F	*- FL
7	1		*HEADLAMP LH	Cracked	2,577.60 F	*2,577.60 FL
8	1		*FRONT LH FENDER	Buckled	385.70 F	*385.70 FL
9	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	145.20 F	*- FL
10	1		*FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,006.00	4,151.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	830.38

Total Parts (\$\$)	5,006.00	3,321.52
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	400.00
2	SPRAY PAINTING CHARGE	New	800.00	600.00
3	WIRING	New	50.00	30.00
4	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			1,550.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >