

ASS. REC. BY:

REF:

193 / MSC 18006833 / NZ416<sup>52</sup> Special Instruction:

Surveyor:

Naz

ASSIGNMENT (Office)

From (Person):

of

MSLH

Date/Time:

12042018

Estimated Cost:

Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 538A

Insured:

GBF 1154C

at Workshop m/s

Hiep Lek

Tel:

9660 1347

of

160 Sin Ming Drx # 05-17

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09042018

CA / REV / REP. / REV 24 HRS 'WPI'

H.O.D. Endorsement:

Date/Time:

13042018 952am

Person Contacted:

Han Wei

Vehicle B / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLN 538A - X
	GBF 1154C - X

NAZ

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLN 538A Page: 01 2017  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: TOYOTA HARRIER Yr: 1986  
 Colour: BLACK A.C. Insured / Std / NI / NA  
 Sp. Reading: 23435 Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_  
 C.No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 235/55 R18  
 R: 235/55 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front	Rear
R.Bal. <u>5</u> mm	R.Bal. <u>5</u> mm
L.Bal. <u>5</u> mm	L.Bal. <u>5</u> mm
D.O.A. <u>09/04/18</u>	D.O.I. <u>13/4/18</u>

Survey held at: HARLEX

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimate repair range \$3,000 - \$7,000 / 3 DAYS Sampo

25/4/18 Submit PRS Report

RECEIVED 26 APR 2018

Date/Time File Pass to:

☐

: Preli. Report

Days Of Repair:

Date/Time File Return to:

☐

: Final Report

Resurvey No. of Trip:

Survey Fee

Transportation

Report Format:

Lump Sum / I.B.I. / S

Add Fee:

☐

Site Insp: \$

☐

Inter. Insp: \$

☐

Tech. Insp: \$

☐

Witness: \$

13-15-18

Photos

12-13-18

Total




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18006833/Nz4b		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 13-04-2018		
		Code : MSG		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GBF 1154C	Veh. Inspected	SLN 538A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	09/04/2018	Inspection Date	13/04/2018	
Survey held at	160 SIN MING DRIVE #05-17			
Repairer	HIAP LEK AUTOMOBILE TRADING			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

# PCV Accident Report

(For Reporting only)



ComfortDelGro Engineering

No of PAX 3

2 male  
1 female

☐ Braddell ☐ Sin Ming ☐ Sg. Kadut ☐ Pandan ☐ Loyang ☐ Ubi

## Section A - To Be Completed By Driver Who Is Involved In The Accident

Date & Time of Accident	Date: 04/04/18	Time: 6.25 PM
Date & Time of Reporting	Date:	Time:
Place of Accident	Depot Rd	
Vehicle Reg. No.:	SLN 538 A	Make / Model: Toyota Harrier
Purpose of Use at Time of Accident: Goods transportation / private usage / others:		
Name:	Yeo Siew Teng	NRIC / FIN No. 573 816022
Address:	Blk 77A Red Hill Road #10-16	
Postcode:	151077	Date Of Birth: 26/03/1977
Home:		Handphone: 91066879
Email:	cyeo262@gmail.com	Gender: Male / Female
Occupation:	Management / Sales / Retiree / Housewife / Technical / Education / Others:	
Type of Claims:	Third Party / Own Damage / Reporting Only	Licence Pass Date:
Driver Status:	Owner / Non-owner	Years of Driving Experience:
		25 Feb 2002

If you are not the owner, the owner's name & tel: \_\_\_\_\_

Owner's Address: \_\_\_\_\_

Relationship with Owner: \_\_\_\_\_

Owner's NRIC / Company Reg. No: \_\_\_\_\_

Vehicle Towed In?	Yes / <input checked="" type="radio"/> No	My Insurance Company:	Sompo insurance Singapore
Police Reported?	Yes / <input checked="" type="radio"/> No	Police Report Reference No.:	
Company's Vehicle?	Yes / <input checked="" type="radio"/> No	Insurance Policy No:	
Do you have witness?	Yes / <input checked="" type="radio"/> No	Type of Policy: Comprehensive / Third Party Fire & Theft / Third Party Only	

(If Yes, Witness Name & Contact No: \_\_\_\_\_)

Weather Condition:	<input checked="" type="radio"/> Clear / Cloudy / Light Rains / Heavy Rains	Was anyone injured in the accident?	Yes / <input checked="" type="radio"/> No
Road Condition:	<input checked="" type="radio"/> Dry / Wet	Was Notice of Intended Prosecution given?	Yes / <input checked="" type="radio"/> No
Other vehicle or property damage?	<input checked="" type="radio"/> Yes / No		

Describe How Accident Happened: Please use **SKETCH PLAN** for accident description & sketch of accident scene

### Third Party's Details (Use Annex 2 for Chain Collision as attachment)

Vehicle Make / Model:	Nissan Cabstar	Vehicle Reg. No.:	GBF 1154 C
Name of Driver:	Tan Siew Huey	NRIC No.:	50961271H
Insurance Company:		Handphone:	9732 96637 927

**Driver's Declaration:** I declare that the information given in this report are true and correct and I undertake to assume full responsibilities for all consequences should any part given above be untrue.

Signature:

Date:

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN

① SLN 538 A  
② GBF 11542  
DEPOT RD




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/04/18 @ 6:25pm, I am travelling along depot Rd. I am travelling along lane ① going straight within my own lane. At the traffic junction, the traffic light turn red, the cars ahead of me slow down and stopped. I too stopped with safe keeping distance. My vehicle is still stationary, when suddenly, I saw that the front vehicle start to reverse, I start to horn at the driver, but still the vehicle still continue to reverse and hit onto my vehicle stationary front portion.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLN538A		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	With Sun Roof		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	HARRIER PREMIUM 2.0 A		
Chassis No. :	ZSU600077718		
Propellant :	Petrol		
Engine No. :	3ZRB779200		
Engine Capacity :	1986 cc		
Maximum Power Output :	111.0 kW ( 148 bhp)		
Maximum Laden Weight :	1885 kg		
Unladen Weight :	1610 kg		
Year Of Manufacture :	2016		
Original Registration Date :	20 Apr 2017		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$54,556.00		
COE Expiry Date :	19 Apr 2027		
Road Tax Expiry Date :	19 Oct 2018		
PARF Eligibility Expiry Date :	19 Apr 2027		
Inspection Due Date :	19 Apr 2020		
Intended Transfer Date :	25 Apr 2018		
CO2 Emission :	133.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$5,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	10 Apr 2018		18 Apr 2018 11:45 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NEO GUAN HIN POULTRYFARM, Co. Reg. No.: 0		
Main Claimant:	YEO SIEW TENG, ID: S7781602Z		
Vehicle Reg. No.:	SLN538A	Date of Loss:	09/04/2018 18:00 - :59 [11 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555462	Policy/Cover Note No.:	B28973895MKC (Comprehensive) Coverage: 29/06/2017 - 28/06/2018
Vehicle Reg. No. (Insured):	GBF1154C	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 19/04/2018]		
Driver/Custodian (Insured):	TAN SIEW HUAY (), NRIC: S0961271H, Tel: +6596637927		
Adj. Asg. Remarks:	ON WR		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















## Claim Documents

**\*SLN538A (555462)**  
**[GBF1154C]**  
**TP**  
**YEO SIEW TENG**  
**Apr 9 2018 6:00PM**  
**[NEO GUAN HIN POULTRYFARM]**  
**Hiap Lek Automobile Trading**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/18 15:23	<b>Accident Statement</b> From: SC - Reg. No: GBF1154C, Claimant: NEO GUAN HIN POULTRYFARM	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
2	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
3	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
4	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
5	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
6	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
7	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
8	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
9	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
10	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
11	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
12	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
13	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
14	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
15	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
16	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
17	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
18	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
19	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
20	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
21	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
22	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
23	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
24	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
25	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
26	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
27	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
28	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
29	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
30	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>
31	18/04/18 12:12	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/18 12:12	General View	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18006833/NZ4BS2  
 Date: 27/04/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28973895MKC  
 Claimant Vehicle No: SLN538A Insured Vehicle No: GBF1154C  
 Date of Loss: 09/04/2018 Nature of Claim: TP Claim No: 555462

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLN538A Engine No: 3ZRB779200  
 Make & Model: TOYOTA HARRIER, 2.0 (A) Chassis No: ZSU600077718  
 Reg. Date: 20/04/2017 (Man. Year: 2016) Odometer: 23435 km  
 Colour: Black  
 Engine Capacity: 1986 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 235/55R18 Rear Tyre Size: 235/55R18  
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 18/04/2018  
 Date Inspected: 13/04/2018 Inspected At: 160 SIN MING DRIVE #05-17  
 Estimated Period of Repair: 0.0 days Repairer: Hiap Lek Automobile Trading  
 Blk 14 #01-19 Sector B, Sin Ming Industrial Est  
 Singapore 575658

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/27/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$7,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2018)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN538A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >