

ASS. REC. BY:

REF: CS/MSG18006341/TI/bcz

Special Instruction:

Survivor

Tanjung

ASSIGNMENT (Office)

Merimen

From (Person):

Gene Tan

of

MSG1

Date/Time:

13042018 1038am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 1949M

Insured:

YP 992Y

at Workshop m/s

Tan Chong Motor

Tel:

6466 7411

of

911 Bukit Timah Road

Policy No:

A09045895MKC

Claim No:

554016

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

16-04-2018

Date/Time:

13042018 2.18pm

Person Contacted:

Ms. Nura

Nashida

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLX 1949M - X

YP 992Y - X

14/4/18

Send preli revised by merimen

14/6/18

Final fig \$9984.77 confirmed by email (Ref 3172.59, 24/5)

Merimen

Tan

REF: MSLH

ASSIGNMENT

From: Date: 16042018

Estimated Cost: ☐ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLX 1949M
at Workshop no: Tan Ching Motor
of 911 Tan Ching Motor

Insured

Policy No

Claims No

Sum Insured


Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repair:

days

Res

Yes or No

Lump Sum

%

Val

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Louise

SLX 1949M. 298 mach.

Type: ☒ Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Nissan Qashqai

1997

Colour

Blue

A/C: Insured / Std / Nil / NA

Sp. Reading

345.

T/Radio: Insured / Std / Nil / NA

Eng/No

C/No

8 JNFBA 3/14247626

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size:

F:

225/45x19

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A

D.O.I

Survey held at

7C Bht Timah

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

ER 785 Insured 762K

RECEIVED 19 JUN 2018

Clear Time, File Pass in



: Preli. Report

is



: Final Report

Clear Time, File Return in

19/6 - typist

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee

Transport

1.000

1.000

1.000

1.000

1.000

Report Format

Merimen

Lump Sum / LB 113

9984.77

Add Fee:



Site Insp 15



Interview 15



Tech Insp 15



Photograph 15

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006841/T1vb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 9992Y	Veh. Inspected	SLX 1949M
Policy No.	A29045895MKC	Coverage (\$)	0.00
Claim No.	554016	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/03/2018	Inspection Date	16/04/2018
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018		13 Apr 2018 10:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	WATERTECH PLUMBING & CONSTRUCTION PTE LTD, Co. Reg. No.: 200101846M, Tel: +6593699992																							
Main Claimant:	CHANG CHEE MENG STANLEY, ID: S7407492H																							
Vehicle Reg. No.:	SLX1949M	Date of Loss:	27/03/2018 17:00 - :59 [7 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / S54016	Policy/Cover Note No.:	A29045895MKC (Comprehensive) Coverage: 16/11/2017 - 15/11/2018																					
Vehicle Reg. No. (Insured):	YP9992Y	Policy No. (Claimant):																						
		Excess:	\$600.00																					
Repairer:	Tan Chong Motor Sales Pte Ltd (HQ) 911 BUKIT TIMAH ROAD, 589623 Bukit Timah - Tel:																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/04/2018]																							
Driver/Custodian (Insured):	KANDHASAMY SATHIYARAJ (J), NRIC: G2738092T, Tel: +6590030466																							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
There are no mail for this case.																								
☐ ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	Date: 17 Apr 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: YP9992Y		
TP Vehicle No	: SLX1949M	Accident Date	: 27/03/2018
Make	: NISSAN QASHQAI	Assignment Date	: 13/04/2018
Date of Inspection	: 16/04/2018	Est. Duration of Repair	: 7.00
Inspection At	: TAN CHONG MOTOR SALES PTE LTD (HQ) 911 BUKIT TIMAH ROAD SINGAPORE 589623		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,761.76
Revised Amount	:S\$	10,047.16
Check Items (Estimated)	:S\$	1,769.60
Total	:S\$	11,816.76
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is economical/not economical for repair.

☒ The above survey was conducted on a 'without prejudice' basis.



COVER NOTE

NISSAN AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : Chang Chee Meng Stanley
Period of Insurance : 20 Mar 2018 to 19 Mar 2019
Engine No. : MR20519608W
Chassis No. : SJNFBAJ11U2217626

Vehicle No. : SLX 1949M
Cover Note No. : 1800024129
Endorsement No. :
Issued Date : 17 Mar 2018

ABOUT THE COVER

Make/Model : NISSAN QASHQAI 2.0 PREMIUM
Engine Capacity/Tonnage : 1,997.00 CC
Sum Insured : Market Value
First Year of Registration : 2018
Driver Restriction : NA
Off Peak Car : No
Insuring with COE/PAFF : Yes
Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc :

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 115 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
Chang Chee Meng Stanley - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC AutoClinic Add: No. 1, South Lok Yang Road Singapore 628099 62622212
 2. Autotouch Industrial Add: 19 Ubi Road 4 Singapore 408623 64609606
 3. TC AutoClinic Add: 25 Leng Kee Road Singapore 150057 67038511 67038512 67038513
 4. Tan Chong Motor Sales Add: 613 Bukit Timah Road Singapore 589623 64694091 64694092 64694093
 5. Tan Chong Motor Sales Add: 17 Lorong 8 Toa Payoh Singapore 310254 63570753 63570754
- For other Approved Reporting Centres/Autotouch Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6300. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1955 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0500610532
 TAN CHONG CREDIT PTE LTD - JEG
 911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE
 SINGAPORE 589622 ANSP-MOTOR
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE: Goh Chai Sylene Lim

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7407492H



Name

CHANG CHEE MENG STANLEY

Race

CHINESE

Date of birth:
18-03-1974

Sex

M

Country of birth
SINGAPORE

S7407492H

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7407492H

Name:

CHANG CHEE MENG STANLEY

Birth Date: 18 Mar 1974

Issue Date: 07 Feb 2018



002771537B

3499281



NRIC No. S7407492H



Date of issue

29-03-2004

Address

APT BLK 636 JURONG WEST STREET 65
#11-358
SINGAPORE 640636

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 07 Feb 2018

NP 428A



Licence No: S7407492H

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-055139

Date of Request: 12/04/2018

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd
911, Bukit Timah Road
Singapore 589622

Dear Sir/Madam,

Enquiry Date 12/04/2018
Enquiry By Eric Koh Yong Lang
TP Vehicle No. YP9992Y
Accident Date 27/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YP9992Y	MSIG Insurance (Singapore) Pte. Ltd.	16/11/2017-15/11/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-055139
Date of Request: 12/04/2018

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd
911, Bukit Timah Road
Singapore 589622

Dear Sir/Madam,

Enquiry Date 12/04/2018
Enquiry By Eric Koh Yong Lang
TP Vehicle No. YP9992Y
Accident Date 27/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/03/2018 09:57
Date Of Accident	27/03/2018 19:40
Exact Location Of Accident	LORINE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX1949M
Insured/Policyholder	
Name Of Registered Owner	CHANG CHEE MENG STANLEY
NRIC No	S7407492H
Email Address	STANLEY.CHANGCM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83233618
Alternative Phone No	OTHERS-83233618

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-2.0 J10 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	1800024129

Driver

Name of Driver	CHANG CHEE MENG STANLEY
NRIC No	S7407492H
Date Of Birth	18/03/1974
Occupation	INDOOR
Date Of Driving Pass	07/02/2018
Driving Experience	0 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83233618
Fax Number	
Contact Number	OTHERS-83233618
EMail Address	STANLEY.CHANGCM@GMAIL.COM

Address	BLK 636 JURONG WEST ST 65 #11-358
Postcode	640636
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8729999 - FAX NO: 67748639
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP9992Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	G2738092T
Contact Number	93699992
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name	CHANG CHEE MENG STANLEY
Approximate Age	44
Injuries Sustain	HEAD
Injured person in which vehicle?	SLX1949M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see the police report attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:



**SINGAPORE
POLICE FORCE**



T/20180328/2143

1 of 3

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20180328/2143

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2018 16:38		Vide Report No.:		Station Diary No.: 154	
Informant's Particulars					
Name of Informant: CHANG CHEE MENG STANLEY			Address: APT BLK 636 JURONG WEST STREET 65 #11-358 SINGAPORE 640636		
ID Type / ID No.: NRIC NO / S7407492H			Contact No.: Home/Office: Mobile: 83233618		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 44	Date of Birth: 18/03/1974	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Senior Engineer			Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 27/03/2018 19:40	Type of Location: Straight Road
Location: Along Road 1 LORNIE ROAD				
Along Lornie Road towards PIE (12km mark)				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLX1949M	Car	NISSAN	QASHQAI 2.0 CVT	Blue	Slightly Damaged	0
YP9992Y	Lorry				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLX1949M	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800024129	20/03/2018	19/03/2019



**SINGAPORE
POLICE FORCE**



T/20180328/2143

2 of 3

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No: T/20180328/2143

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHANG CHEE MENG STANLEY	ID No	S7407492H
Related Vehicle	SLX1949M (Car)	Contact No.	83233618
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	27/03/2018	Date Discharge	28/03/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	KANDHASAMY SATHIYARAJ	ID No	G2738092T
Related Vehicle	NIL	Contact No.	93699992
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/03/2018 at about 1940hrs, I was travelling in my vehicle (SLX1949M) along Lorrie Road. When I was reaching the 12km mark, the traffic light turned amber and I start to slow down the vehicle. I was at a stop at the stop line when all of a sudden there was an impact to the rear of my vehicle. My head hit onto the headrest and I was in a daze. When I finally got my composure, I alighted the car and check what happened.

A lorry (YP9992Y) collided into the rear of my vehicle and caused me to surge forward. At that point of time, there was no visible injuries and we exchanged particulars before I call for tow truck to remove my vehicle as I don't feel comfortable to drive. My vehicle suffered dents in the rear of the vehicle, and his lorry suffered dents in the front. After going home, my family advice me to go to the doctors and I want to Ng Teng Fong Hospital to consult doctor and I was given 3 days MC from 28/03/2018 to 30/03/2018.

There is in vehicle camera in my car and this is the first time that such incident has happened.



**SINGAPORE
POLICE FORCE**



T/20180328/2143

3 of 3

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20180328/2143

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 BRENBAN LIM WEI JIE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

28/03/2018 16:38

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 85476430

Classification Of Case:

Authentication Stamp

SINGAPORE
POLICE FORCE

SN 37

SIGNATURE

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0139/2018
DATE : 12-APR-2018

MEIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 68277660
FAX : 62257402
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : MR CHANG CHEE MENG STANLEY
ADDRESS : BLK 636 JURONG WEST ST 65
#11-358
S(840636)
TELEPHONE NO : 83233618

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-YP9992Y
VEHICLE NO : SLE1949M
MODEL CODE : FDRAGMJ11ESAA----
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2017
ENGINE NO : MR26519608W
CHASSIS NO : SJHFDJ11U2217626
MILEAGE : 1 KM
DATE IN : 12/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 27/03/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjin 97495749
-WP-

16/4/18 @ 1450

* Resurvey before paint

sur @ lkkauto.com

7 days

30/5/18

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/S/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX1949H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	✓ ✓
2 RPT	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	240. ✓
3 SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100. ✓
4 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	✓ ✓
5 UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	✓ ✓
6 11/001	REPAIR BOTH REAR FENDER AND RENEW END PANEL, REAR BUMPER AND TAILGATE	1200.00	250- 875 ✓
7 11/002	S/PAINT REAR PORTION AND BUMPER (2 TONE)	1400.00	200- 1100. ✓
8 11/003	CHECK LIGHTING	48.00	✓ ✓
9 11/004	SUPPLY AND RENEW REAR NO. PLATE(SMART PLATE WITH CASING) LONG		
10 11/005	M/I REAR DVH TO ASSIST REPAIR	120.00	✓ ✓
11 11/006	TRANSFER TAILGATE MECHICAL PARTS	80.00	✓ ✓
	TOTAL LABOUR CHARGES	4018.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGD NO SLR1949H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 ANTENNA-SMART KEYLESS	285E5-JK60A	53.50	? X NM		
2 ANTENNA ASSY-DO	285E7-JK60A			64.40	? X NM
3 EMBLEM	90892-4EA0A	87.00	rec		✓
4 EMBLEM-REAR	90890-4EA0A	59.70	rec		✓
5 FINISHER BACK DOOR LOWER	90901-4EA0A	316.50	? X NM		
6 STRIKER-TAIL GA	90570-4EA0A	31.70	bt		✓
7 A LOCK LIFT	90502-4EA1B	116.70	bt		✓
8 WEATHER STRIP	90830-4EA0B	158.70	fm		✓
9 DOOR BACK	K0100-HV00A	2936.80	bt		✓
10 A FIN BACK TAILGATE NO PLATE FINISHED	90810-4EU0H	336.00	ad		✓
11 GLASS-TAIL GATE	90300-HV00A	930.00	ty rec		✓
12 RETAINER-BUMPER RH	79184-4EA0A	23.80	rec		✓
13 RETAINER-BUMPER LH	79185-4EA0A	23.80	rec		✓
14 GROMMET BUMPER \$2.20 EA X 02	01281-00111		rec	4.40	✓
15 GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00	rec		✓
16 BRACKET-BUMPER RH	85220-4EA0A	35.90	re		✓
17 BRACKET-BUMPER LH	85221-4EA0A	35.90	re		✓
18 STAY ASSY-REAR RH	H5210-4EAMA	126.00	? de		✓
19 STAY ASSY-REAR LH	H5211-4EAMA	126.00	? X NM		
20 REINF-BUMPER RH	H5030-4EAMA	619.20	bt		✓
21 ENERGY ABSORBER	85090-HV00A	126.40	de		✓
22 CANGE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00	re		✓
23 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20	re		✓
24 FINISHER-REAR BUMPER TOW	85071-HV00A	16.80	de		✓
25 FASCIA RR BMR	85022-HV30A	1574.70	de		✓

TAN CHONG MOTOR SALES PTE. LTD.
BOXIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR1949H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	SPACER LH FLOOR	84979-4EA0A	84.00	? X NY	
27	CLIP END PANEL/FINISHER \$1.20 EA X 04	01553-05323	4.80	NE	✓
28	CLIP-FINISHER \$1.20 EA X 04	01554-00181	4.80	NA	✓
29	PLATE-LOGGAGE	84992-4EA0A	63.50	de	✓
30	PANEL-REAR UPPE	G9110-HV0KA	482.60	bt	✓
31	GROMMET FENDER PROTECTOR	01281-00831	1.50	na	✓
32	CLIP PROTECTOR \$1.20 EA X 05	01553-05131	6.00	na	✓
33	PROTECTOR-REAR RH FENDER	76748-4EA2A	186.40	? X NY	
34	PROTECTOR-REAR LH FENDER	76749-4EA0A	186.40	? X NY	
35	CLIP ARC/BOMPER \$1.20 EA X 04	01533-05933	4.80	na ?	✓ nee
36	FENDER ARC RE REAR	93828-4EA0A	483.00	? X	} nh
37	CLIP C/LAMP \$4.80 EA X 02	26398-ED000	9.60	? X	
38	GROMMET C/LAMP \$1.90 EA X 02	76848-35F00	3.80	? X	
39	WASHER SEALING C/LAMP \$25.70 EA X 04	76848-83P00	102.80	? X	
40	LAMP COMB RR,RH TAILGATE	26550-HV55A	215.90	GA	✓
41	LAMP COMB RR,LH TAILGATE	26555-HV55A	215.90	GA	✓
42	LAMP COMB RR,RH	26550-HV00A	323.70	GA	✓
43	LAMP COMB RH,LH	26555-HV00A	323.70	? X NY	
44	RUBBER-DUM	G2716-89900	60.20	nee	✓
45	REAR W/SCREEN SEALANT	SEALANT - 4			80.00 nee ✓
46	HUNDRIES	NPN			100.00 ? ✓
47	REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP				60.00 bt ✓
SUB TOTAL			10543.70	0.00	308.80
LESS DISCOUNT (NETT-20.00%, LIST-10.00%, S/NETT-.00%)			2108.74	0.00	0.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGH NO SLR1949H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
	GRAND TOTAL		9434.96	0.00	308.80
	OVERALL TOTAL		8743.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLX1949H

TOTAL LABOUR CHARGES 4618.00

TOTAL SPARE PARTS CHARGES 8743.76

GRAND TOTAL 12761.76 *

13,157.36

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

13/10/24

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0139/2018
DATE : 12-APR-2018

MEIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 68277660
FAX : 62257402
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : MR CHANG CHEE MENG STANLEY
ADDRESS : BLK 636 JURONG WEST ST 45
#11-358
S(640636)
TELEPHONE NO : 83233618

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-YF99952Y
VEHICLE NO : SLX1949H
MODEL CODE : FDRARGHJ11ESAA----
MODEL/YEAR : NISSAN QASHQAI 2.0 HY2017
ENGINE NO : HR20S1960HW
CHASSIS NO : SJMFBAJ11U2217626
MILEAGE : 345 KM
DATE IN : 12/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 27/03/2018

CLK

Tan K

DIS

* SKETCHED

2nd

car only

7 day

TAN CHONG MOTOR SALES PTE. LTD.
 SUKIT TIRAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REG NO SL1949H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	120.00
2 RPI	PERFORM MUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	240.00
3 RS	SUPPLY & INSTALL REVERSE SENSOR - SUPPLEMENTARY	110.00	110.00 (A)
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESKAL NECESSARY AREA \$100/PANEL X 03	300.00	300.00
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	150.00
6 UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	240.00
7 EE/001	REPAIR BOTH REAR FENDER AND RENEW END PANEL, REAR BUMPER AND TAILGATE	1200.00	875.00
8 EE/002	S/PAINT REAR PORTION AND BUMPER (2 TONE)	1400.00	1100.00
9 EE/003	CHECK LIGHTING	48.00	48.00
10 EE/004	SUPPLY AND RENEW REAR NO. PLATE(SMART PLATE WITH CASING) LONG		
11 EE/005	R/I REAR DVR TO ASSIST REPAIR	120.00	120.00
12 EE/006	TRANSFER TAILGATE MECHANICAL PARTS	80.00	80.00
13 EE/007	VEHICLE TOW IN BY A.A W/O T145341 ON 27.03.2018 @ 2140HRS		
TOTAL LABOUR CHARGES		4128.00	3183.00
ADDITIONAL DISCOUNT(5.00%)			159.15
FINAL LABOUR CHARGES			3023.85

TAN CHONG MOTOR SALES PTE. LTD.

ROKIT TIMEA W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGD NO SL1949H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	M/LDG-RR B/MFR LH - SUPPLEMENTARY	85087-HV00A	183.60			OK (A)
2	M/LDG-RR B/MFR RH - SUPPLEMENTARY	85086-HV00A	102.00			OK (A)
3	ANTENNA-SMART KEYLESS	28585-JK60A	53.50			X
4	ANTENNA ASSY-DO	28587-JK60A			64.40	X
5	EMBLEM	90892-4EA0A	87.00			OK
6	EMBLEM-REAR	90890-4EA0A	59.70			OK
7	FINISHER BACK DOOR LOWER	90901-4EA0A	316.50			X
8	STRIKER-TAIL GA	90570-4EA0A	31.70			OK
9	A LOCK LIFT	90502-4EA1B	116.70			OK
10	WEATHER STRIP	90830-4EA0B	158.70			OK
11	DOOR BACK	K0100-HV00A	2936.80			OK
12	A FIN BACK TAILGATE NO PLATE FINISHER	90810-4EU0H	336.00			OK
13	GLASS-TAIL GATE	90300-HV00A	930.00			OK
14	RETAINER-BUMPER RH	79184-4EA0A	23.80			OK
15	RETAINER-BUMPER LH	79185-4EA0A	23.80			OK
16	GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40	OK
17	GROMMET BUMPER \$2.50 EA X 04	63846-3V000	10.00			OK
18	BRACKET-BUMPER RH	85220-4EA0A	35.90			OK
19	BRACKET-BUMPER LH	85221-4EA0A	35.90			OK
20	STAY ASSY-REAR RH	85210-4EAMA	126.00			OK
21	STAY ASSY-REAR LH	85211-4EAMA	126.00			X
22	REINF-BUMPER RH	85030-4EAMA	619.20			OK
23	ENERGY ABSORBER	85090-HV00A	126.40			OK
24	CANGE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00			OK
25	CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20			OK

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGD NO SLE1919H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
26	FINISHER-REAR BUMPER TOP	85071-HV00A	16.80			OK
27	FASCIA RR-BHPR	85022-HV30A	1574.70			OK
28	SPACER LH FLOOR	84979-4EA0A	84.00			X
29	CLIP END PANEL/FINISHER \$1.20 EA X 04	01553-05323	4.80			OK
30	CLIP-FINISHER \$1.20 EA X 04	01554-00181	4.80			OK
31	PLATE-LUGGAGE	84992-4EA0A	63.50			OK
32	PANEL-REAR UPPER	G9110-HV00A	482.60			OK
33	GRONNET FENDER PROTECTOR	01281-00831	1.50			OK
34	CLIP PROTECTOR \$1.20 EA X 05	01553-05131	6.00			OK
35	PROTECTOR-REAR RH FENDER	76748-4EA2A	186.40			X
36	PROTECTOR-REAR LH FENDER	76749-4EA0A	186.40			X
37	CLIP ARC/BUMPER \$1.20 EA X 04 <i>parts</i>	01553-05933	4.80			OK
38	FENDER ARC RH REAR	93828-4EA0A	483.00			X
39	CLIP C/LAMP \$4.00 EA X 02	26398-ED000	9.60			X
40	GRONNET C/LAMP \$1.90 EA X 02	76848-35F00	3.80			X
41	WASHER SEALING C/LAMP \$25.70 EA X 04	76848-83F00	102.80			X
42	LAMP COMB RR,RH TAILGATE	26550-HV55A	215.90			OK
43	LAMP COMB RR,LH TAILGATE	26555-HV55A	215.90			OK
44	LAMP COMB RR,RH	26550-HV00A	323.70			OK
45	LAMP COMB RR,LH	26555-HV00A	323.70			X
46	RUBBER-DGM	G2716-89900	60.20			OK
47	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
48	SUNDRIES - CLIPS	NPN			20.00	OK
49	REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP				60.00	OK

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGH NO SLX1949H

		DAMAGED PARTS & PRICES		
S/PO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
SUB TOTAL		8953.60	0.00	164.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1790.72	0.00	0.00
GRAND TOTAL		7162.88	0.00	164.40
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-5.00%)		358.14	0.00	8.22
OVERALL TOTAL		6960.92		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAE CHONG MOTOR SALES PTE. LTD.

811, SUNKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLK1949M

NETT ITEM	8953.60
LESS 20.00%	-1790.72
NETT AMOUNT	7162.88
ADDITIONAL DISCOUNT(5.00%)	-358.14
FINAL AMOUNT	6804.74

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	164.40
LESS .00%	0.00
SPECIAL NETT AMOUNT	164.40
ADDITIONAL DISCOUNT(5.00%)	-8.22
FINAL AMOUNT	156.18

TOTAL LABOUR CHARGES	3023.85
TOTAL SPARE PARTS CHARGES	6960.92

TOTAL CHARGES	9584.77
ADD T & GST	698.93

GRAND TOTAL	10683.70
-------------	----------

23/04/2018

INS/IC/LAW/0139/2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
Singapore 048581

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SLX1949M

POLCY NO. :

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

Replacement of Damaged Items

- 1 MLDG-RR BMPR RH
- 2 MLDG-RR BMPR LH
- 3 SUPPLY & INSTALL REVERSE SENSOR
- 4
- 5
- 6
- 7


\$102.00 NETT *de*
\$183.60 NETT *de*
\$110.00 *nw*

TOTAL \$ 395.60

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully,

TAN CHONG MOTOR SALES PTE LTD


Lawrence Teo
Insurance Claim Dept

Cc: Surveyor

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 19 June 2018 9:40 AM
To: 'Norsipah'; SUR
Cc: Lawrence Teo
Subject: RE: Finalization: SLX1949M / YP9992Y DOA 27.03.2018

Dear Sipah,

WITHOUT PREJUDICE

Confirmed amount \$9,984.77 before GST @ 7 working days.

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah [mailto:norsipah@tanchong.com]
Sent: Monday, 18 June 2018 2:05 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Lawrence Teo <lawrenceteo@tanchong.com>
Subject: RE: Finalization: SLX1949M / YP9992Y DOA 27.03.2018

Refer attach.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: norsipah@tanchong.com D:+6567038915

Website: www.tanchong.com :: www.nissan.com.sg

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 18 June 2018 12:40 PM
To: Norsipah <norsipah@tanchong.com>; SUR <sur@lkkauto.com>
Cc: Lawrence Teo <lawrenceteo@tanchong.com>
Subject: RE: Finalization: SLX1949M / YP9992Y DOA 27.03.2018

Dear Sipah,

Kindly provides us supplementary and before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah [<mailto:norsipah@tanchong.com>]

Sent: Monday, 18 June 2018 10:27 AM

To: SUR <sur@lkkauto.com>

Subject: FW: Finalization: SLX1949M / YP9992Y DOA 27.03.2018

Hi Veron,

As per req.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: norsipah@tanchong.com D:+6567038915

Website: www.tanchong.com :: www.nissan.com.sg

From: Norsipah

Sent: Tuesday, 5 June 2018 1:54 PM

To: 'Taufikh@lkkauto.com' <Taufikh@lkkauto.com>

Subject: Finalization: SLX1949M / YP9992Y DOA 27.03.2018

Hi Taufikh

For your finalization.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: norsipah@tanchong.com D:+6567038915

Website: www.tanchong.com :: www.nissan.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018		13 Apr 2018 10:38 Edit Adj Rpt	\$99,984.77 Edit Estimates	\$99,984.77 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WATERTECH PLUMBING & CONSTRUCTION PTE LTD , Co. Reg. No.: 200101848M, Tel: +6593699992								
Main Claimant:	CHANG CHEE MENG STANLEY , ID: S7407492H								
Vehicle Reg. No.:	SLX1949M	Date of Loss:	27/03/2018 17:00 - :59 [7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 554016	Policy/Cover Note No.:	A29045895MKC (Comprehensive) Coverage: 16/11/2017 - 15/11/2018						
Vehicle Reg. No. (Insured):	YP9992Y	Policy No. (Claimant):							
		Excess:	\$600.00						
Repairer:	Tan Chong Motor Sales Pte Ltd (HQ) 911 BUKIT TIMAH ROAD, 589623 Bukit Timah - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/05/2018]								
Driver/Customer (Insured):	KANDHASAMY SATHIYARAJ (), NRIC: G2738092T, Tel: +6590030466								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX1949M (554016)

[YP9992Y]

TP

CHANG CHEE MENG STANLEY

Mar 27 2018 5:00PM

[WATERTECH PLUMBING & CONSTRUCTION PTE LTD]

Tan Chong Motor Sales Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On		Thumbnail	Print	
1	13/04/18 10:38	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement From: OD - Reg. No: YP9992Y, Claimant: WATERTECH PLUMBING & CONSTRUCTION PTE LTD	 Load HTML		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/04/18 12:12	Adjuster Immediate Advice	 Load HTML		

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/04/18 12:14	General View	 Load JPG	☒	
2	17/04/18 12:14	General View	 Load JPG	☒	
3	17/04/18 12:14	General View	 Load JPG	☒	
4	17/04/18 12:14	General View	 Load JPG	☒	
5	17/04/18 12:14	General View	 Load JPG	☒	
6	17/04/18 12:14	General View	 Load JPG	☒	
7	17/04/18 12:14	General View	 Load JPG	☒	
8	17/04/18 12:14	General View	 Load JPG	☒	
9	17/04/18 12:14	General View	 Load JPG	☒	
10	17/04/18 12:14	General View	 Load JPG	☒	
11	17/04/18 12:14	General View	 Load JPG	☒	
12	17/04/18 12:14	General View	 Load JPG	☒	
13	17/04/18 12:14	General View	 Load JPG	☒	
14	17/04/18 12:14	General View	 Load JPG	☒	
15	17/04/18 12:14	General View	 Load JPG	☒	
16	17/04/18 12:14	General View	 Load JPG	☒	
17	17/04/18 12:14	General View	 Load JPG	☒	
18	17/04/18 12:14	General View	 Load JPG	☒	
19	17/04/18 12:14	General View	 Load JPG	☒	
20	17/04/18 12:14	General View	 Load JPG	☒	
21	17/04/18 12:14	General View	 Load JPG	☒	
22	17/04/18 12:14	General View	 Load JPG	☒	
23	17/04/18 12:14	General View	 Load JPG	☒	
24	17/04/18 12:14	General View	 Load JPG	☒	
25	17/04/18 12:14	General View	 Load JPG	☒	
26	17/04/18 12:14	General View	 Load JPG	☒	
27	17/04/18 12:14	General View	 Load JPG	☒	
28	17/04/18 12:14	General View	 Load JPG	☒	
29	17/04/18 12:14	General View	 Load JPG	☒	
30	17/04/18 12:14	General View	 Load JPG	☒	
31	17/04/18 12:14	General View	 Load JPG	☒	
32	17/04/18 12:14	General View	 Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	M5IG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	17/04/18 12:14	General View	 Load JPG	☒
34	17/04/18 12:14	General View	 Load JPG	☒
35	17/04/18 12:14	General View	 Load JPG	☒
36	17/04/18 12:14	General View	 Load JPG	☒
37	17/04/18 12:14	General View	 Load JPG	☒
38	17/04/18 12:14	General View	 Load JPG	☒
39	17/04/18 12:14	General View	 Load JPG	☒
40	17/04/18 12:14	General View	 Load JPG	☒
41	17/04/18 12:14	General View	 Load JPG	☒
42	17/04/18 12:14	General View	 Load JPG	☒
43	17/04/18 12:14	General View	 Load JPG	☒
44	17/04/18 12:14	General View	 Load JPG	☒
45	17/04/18 12:14	General View	 Load JPG	☒
46	17/04/18 12:14	General View	 Load JPG	☒
47	17/04/18 12:14	General View	 Load JPG	☒
48	17/04/18 12:14	General View	 Load JPG	☒
49	17/04/18 12:14	General View	 Load JPG	☒
50	17/04/18 12:14	General View	 Load JPG	☒
51	17/04/18 12:14	General View	 Load JPG	☒
52	17/04/18 12:14	General View	 Load JPG	☒
53	17/04/18 12:14	General View	 Load JPG	☒
54	17/04/18 12:14	General View	 Load JPG	☒
55	17/04/18 12:14	General View	 Load JPG	☒
56	17/04/18 12:14	General View	 Load JPG	☒
57	17/04/18 12:14	General View	 Load JPG	☒
58	17/04/18 12:14	General View	 Load JPG	☒
59	17/04/18 12:14	General View	 Load JPG	☒
60	17/04/18 12:14	General View	 Load JPG	☒
61	17/04/18 12:14	General View	 Load JPG	☒
62	17/04/18 12:14	General View	 Load JPG	☒
63	17/04/18 12:14	General View	 Load JPG	☒
64	17/04/18 12:14	General View	 Load JPG	☒
65	17/04/18 12:14	General View	 Load JPG	☒
66	17/04/18 12:14	General View	 Load JPG	☒
67	17/04/18 12:14	General View	 Load JPG	☒
68	17/04/18 12:14	General View	 Load JPG	☒
69	17/04/18 12:14	General View	 Load JPG	☒
70	17/04/18 12:14	General View	 Load JPG	☒
71	17/04/18 12:14	General View	 Load JPG	☒
72	17/04/18 12:14	General View	 Load JPG	☒
73	17/04/18 12:14	General View	 Load JPG	☒
74	17/04/18 12:14	General View	 Load JPG	☒
75	17/04/18 12:14	General View	 Load JPG	☒
76	17/04/18 12:14	General View	 Load JPG	☒
77	17/04/18 12:14	General View	 Load JPG	☒
78	17/04/18 12:14	General View	 Load JPG	☒
79	17/04/18 12:14	General View	 Load JPG	☒
80	17/04/18 12:14	General View	 Load JPG	☒
81	17/04/18 12:14	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	17/04/18 12:14	General View	 Load JPG	☒
83	17/04/18 12:14	General View	 Load JPG	☒
84	17/04/18 12:14	General View	 Load JPG	☒
85	17/04/18 12:14	General View	 Load JPG	☒
86	17/04/18 12:14	General View	 Load JPG	☒
87	17/04/18 12:14	General View	 Load JPG	☒
88	17/04/18 12:14	General View	 Load JPG	☒
89	17/04/18 12:14	General View	 Load JPG	☒
90	17/04/18 12:14	General View	 Load JPG	☒
91	17/04/18 12:14	General View	 Load JPG	☒
92	17/04/18 12:14	General View	 Load JPG	☒
93	17/04/18 12:14	General View	 Load JPG	☒
94	17/04/18 12:14	General View	 Load JPG	☒
95	17/04/18 12:14	General View	 Load JPG	☒
96	17/04/18 12:14	General View	 Load JPG	☒
97	17/04/18 12:14	General View	 Load JPG	☒
98	17/04/18 12:14	General View	 Load JPG	☒
99	17/04/18 12:14	General View	 Load JPG	☒
100	17/04/18 12:14	General View	 Load JPG	☒
101	17/04/18 12:14	General View	 Load JPG	☒
102	17/04/18 12:14	General View	 Load JPG	☒
103	17/04/18 12:14	General View	 Load JPG	☒
104	17/04/18 12:14	General View	 Load JPG	☒
105	17/04/18 12:14	General View	 Load JPG	☒
106	17/04/18 12:14	General View	 Load JPG	☒
107	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
108	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
109	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
110	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
111	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
112	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
113	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
114	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
115	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
116	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
117	19/06/18 09:05	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/04/18 10:37	TPD SLX1949M GIA REPORT.PDF	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/18 10:00	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006841/T1VBE2

Date: 20/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29045895MKC

Claimant Vehicle No: SLX1949M

Insured Vehicle No: YP9992Y

Date of Loss: 27/03/2018

Nature of Claim: TP

Claim No: 554016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX1949M

Make & Model: NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A)

Engine No: MR20519608W

Reg. Date: 20/03/2018 (Man. Year: 2018)

Chassis No: SJNFBAJ11U2217626

Colour: Blue

Odometer: 345 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R19

Rear Tyre Size: 225/45 R19

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,082.24	7,065.42	2,016.82	22.21
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	4,018.00	2,919.35	1,098.65	27.34
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,100.24	9,984.77	3,115.47	23.78
+ GST 7.00/7.00% (S\$)	917.02	698.93	218.09	23.78
Nett Amount (S\$)	14,017.26	10,683.70	3,333.56	23.78

INSPECTION

Date of Assignment: 13/04/2018

Date Inspected: 16/04/2018 Inspected At:

Tan Chong Motor Sales Pte Ltd (HQ)
911 BUKIT TIMAH ROAD
Singapore 589623

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2018)
Parts:	M1-SUV	NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX1949M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ANTENNA-SMART KEYLESS	Not Necessary	53.50 FN	*- FN
2	1		*ANTENNA ASSY-DO	Not Necessary	64.40 FS	*- FS
3	1		*EMBLEM	Necessary	87.00 FN	*87.00 FN
4	1		*EMBLEM-REAR	Necessary	59.70 FN	*59.70 FN
5	1		*FINISHER BACK DOOR LOWER	Not Necessary	316.50 FN	*- FN
6	1		*STRIKER-TAIL GA	Bent	31.70 FN	*31.70 FN
7	1		*A LOCK LIFT	Bent	116.70 FN	*116.70 FN
8	1		*WEATHER STRIP	Twisted	158.70 FN	*158.70 FN
9	1		*DOOR BACK	Bent	2,936.80 FN	*2,936.80 FN
10	1		*A FIN BACK TAILGATE NO PLATE FINISHER	Cut	336.00 FN	*336.00 FN
11	1		*GLASS-TAIL GATE	Necessary	930.00 FN	*930.00 FN
12	1		*RETAINER-BUMPER RH	Necessary	23.80 FN	*23.80 FN
13	1		*RETAINER-BUMPER LH	Necessary	23.80 FN	*23.80 FN
14	2		*GROMMET BUMPER	Necessary	4.40 FS	*4.18 FS
15	4		*GROMMET BUMPER	Necessary	10.00 FN	*10.00 FN
16	1		*BRACKET-BUMPER RH	Necessary	35.90 FN	*35.90 FN
17	1		*BRACKET-BUMPER LH	Necessary	35.90 FN	*35.90 FN
18	1		*STAY ASSY-REAR RH	Deformed	126.00 FN	*126.00 FN
19	1		*STAY ASSY-REAR LH	Not Necessary	126.00 FN	*- FN
20	1		*REINF-BUMPER RR	Bent	619.20 FN	*619.20 FN
21	1		*ENERGY ABSORBER	Deformed	126.40 FN	*126.40 FN
22	2		*CONOE RIVET BUMPER	Necessary	13.00 FN	*13.00 FN
23	3		*CLIP BUMPER	Necessary	22.20 FN	*22.20 FN
24	1		*FINISHER-REAR BUMPER TOW	Deformed	16.80 FN	*16.80 FN
25	1		*FASCIA RR BMPR	Deformed	1,574.70 FN	*1,574.70 FN
26	1		*SPACER LH FLOOR	Not Necessary	84.00 FN	*- FN
27	4		*CLIP END PANEL / FINISHER	Necessary	4.80 FN	*4.80 FN
28	4		*CLIP-FINISHER	Necessary	4.80 FN	*4.80 FN
29	1		*PLATE-LUGGAGE	Deformed	63.50 FN	*63.50 FN
30	1		*PANEL-REAR UPPE	Bent	482.60 FN	*482.60 FN
31	1		*GROMMET FENDER PROTECTOR	Necessary	1.50 FN	*1.50 FN
32	5		*CLIP PROTECTOR	Necessary	6.00 FN	*6.00 FN
33	1		*PROTECTOR-REAR RH FENDER		186.40 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*PROTECTOR-REAR LH FENDER	Not Necessary	186.40 FN	*- FN
35	4		*CLIP ARC/BUMPER	Necessary	4.80 FN	*4.80 FN
36	1		*FENDER ARC RH REAR	Not Necessary	483.00 FN	*- FN
37	2		*CLIP C/LAMP	Not Necessary	9.60 FN	*- FN
38	2		*GROMMET C/LAMP	Not Necessary	3.80 FN	*- FN
39	4		*WASHER SEALING C/LAMP	Not Necessary	102.80 FN	*- FN
40	1		*LAMP COMB RR, RH TAILGATE	Cracked	215.90 FN	*215.90 FN
41	1		*LAMP COMB RR, LH TAILGATE	Cracked	215.90 FN	*215.90 FN
42	1		*LAMP COMB RR, RH	Cracked	323.70 FN	*323.70 FN
43	1		*LAMP COMB RR, LH	Not Necessary	323.70 FN	*- FN
44	1		*RUBBER-DUM	Necessary	60.20 FN	*60.20 FN
45	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*76.00 FS
46	1		*SUNDRIES	Necessary	100.00 FS	*19.00 FS
47	1		*REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP	Bent	60.00 FS	*57.00 FS
48	1		*MLDG-RR BMPR RH	Deformed	102.00 FN	*102.00 FN
49	1		*MLDG-RR BMPR LH	Deformed	183.60 FN	*183.60 FN
50	1		*REVERSE SENSOR	Not Working	110.00 FS	*104.50 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	11,248.10	9,214.28
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	2,165.86	1,790.72
- Add. Disc. on L,N Items 0.00/5.00% (\$\$)	0.00	358.14
Total Parts (\$\$)	9,082.24	7,065.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / INSTALL & TEST REAR REVERSE CAMERA	New	120.00	120.00
2	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	New	360.00	240.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	New	300.00	100.00
4	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	New	150.00	150.00
5	RENEW REAR WINDSCREEN GLASS ASSY	New	240.00	240.00
6	REPAIR BOTH REAR FENDER AND RENEW END PANEL, REAR BUMPER AND TAILGATE	New	1,200.00	875.00
7	S/PAINT REAR PORTION AND BUMPER (2 TONE)	New	1,400.00	1,100.00
8	CHECK LIGHTING	New	48.00	48.00
9	SUPPLY AND RENEW REAR NO. PLATE (SMART PLATE WITH CASING) LONG (NPA)	New	0.00	0.00
10	R/I REAR DVR TO ASSIST REPAIR	New	120.00	120.00
11	TRANSFER TAILGATE MECHANICAL PARTS	New	80.00	80.00
Gross Labour Cost (\$\$)			4,018.00	3,073.00
- 0.00/5.00% Labour Discount (\$\$)			0.00	153.65
Gross Labour after Discount (\$\$)			4,018.00	2,919.35

Report was unsubmitted during this print-out.

< END OF ESTIMATES >