Melimen From (Person): Irene	ay of	CTL	Dat	te/Time: 12042(18	3.104pm
Estimated Cost:	J	Bill to:			10.10
OD (FP)+WS+TP RES / O) To Inspect Vehicle No: tt Workshop m/s	SGN 5692M Sng Ah Tee 17	nutur.	Insured:Tel:	YP 99984 (268 (183	
of	81k 3 Piuneur		#01-18	Doissu con.	
Policy No: DMCVSN30	กรร 1700	Claim No: _	SMIII	2001914 (01-	
Sum Insured:		Excess: _		100000	
Make of Veh:			D.0	810CHO01 - A.C.	
CA / REV / REP. / REV	24 HRS WD (	13-04.2018		LO,D, Endorsement:	
Date/Time: 120H2618 4	40pm Person Contacte	d: Joye		cle (IN)/LOUT	
Date/Time Action/Instru	ction ( / ) Estiny	ate.			
36N 569					
YP 9998	h -x				
17/10/18@ 2.31M	ianArmed with	Sharon V	9 \$ 1950	2, 4 days.	
Red	\$ 3541. 64%)			0	
	177417 6417				

REF: CTL

# ...CLAIM SUBFOLDER...(New Assignment)

Case .	Notified	Est Submitted	Adj Assigned	Adj Rp	t Adj Sut	mitted	Ins Auth'ed	Status	
Main	12 Apr 2018 Sendback Est	12 Apr 2018 11:58 \$\$5,441.00	12 Apr 2018 15:04 Assign					New Assig Cancel Ca	
	Main	Refer	ence		laim Details		Docum	ents	Show All
CLAIM SU	JBFOLDER DETAI	LS		acieminat III	Chief and Marie Lands		INVESTIGATION OF	di manusi di Sala da	
Insured:		NIL, ID:							
Main Claim	nant:	JAHANGE	ER S/O K ABDU	JL HALIM,	ID: S6880374	н			
Vehicle Re	g. No.:	SGN569	2М		Date of Loss:		[136	4/2018 11:00 Months and 1 Reg Date (Man	9 Days From
Claim Type	21	TP / SNN	418D01894C0	2 1			100000	DMCVSN3039331700	
Vehicle Re	g. No. (Insured):	YP9998G		Policy No. (Claimant): D17MTPV01015468		1			
					Excess:		S\$0.		
Repairer:		Sng Ah To Tel: 6268	ee Motor & Pan 6183	el Service I	Pte Ltd (Pionee	er) Blk 3 P	lioneer Road Nor	th, #01-18, 62	28457 Pioneer -
Handling I	nsurer:	China Tai 63898619	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Irene Tay Ht 638986192]			e Tay Hui Ping			
Claimant's	Insurer:	Sompo In	surance Singa	pore Pte. L	td. (HQ) - Tel: 6	5461 6555	ii .		
Adjuster:			Consultants Pt					3/04/2018]	
Adj Asg. R	emarks:	EST \$5821	.87, CASE WITH	SJE.					
ASSOCIA	TED MAIL RECEIV	VED					View	All Comp	ose Case Mail
There are	no mail for this case						- Annie Cons		
8									
ALL ASS	DCIATED TASKS				View All	Search	n Tasks Cr	reate New Task	Complete
Due Dat No results.		ype Task Gro	up Subject	Handle	r Assigned	Ву	Completed On	Created	d On Done?

## Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 12 October 2018 2:31 PM

To:

Sharon Sng; Taufikh (LKKAuto); SUR

Subject:

RE: SGN5692M - FINALISE

Dear Sharon,

WITHOUT PREJUDICE

Confirm Lump Sum \$1,950.00 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com> Sent: Thursday, 23 August 2018 11:12 AM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: SGN5692M - FINALISE

**Best Regards** 

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457 TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <a href="http://www.sngahtee.com">http://www.sngahtee.com</a>



Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID: /ehicle Details	0374H
/ehicle No.:	SGN5692M
ehicle to be Exported:	No
ntended De-registration Date:	25 Apr 2018
ehicle Make:	NISSAN
ehicle Model:	SYLPHY 1.5 4AT
Primary Colour:	Purple
Manufacturing Year:	2006
ingine No.:	HR15043389A
Chassis No.:	JN1BAAG11Z0100904
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,019.00
Original Registration Date:	22 Nov 2006
irst Registration Date:	22 Nov 2006
ransfer Count:	2
Actual ARF Paid: ntended PARF Rebate Details	\$14,731.00
PARF Eligibility:	Forfeited
ARF Eligibility Expiry Date:	-
ARF Rebate Amount: ntended COE Rebate Details	\$0.00
COE Expiry Date:	21 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
QP Paid:	\$25,821.00
COE Rebate Amount:	\$18,459.00
Total Rebate Amount:  Message	\$18,459.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Apr 2018

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

ACCIDENT STATEMENT			
Date Of Report	10/04/2018 16:44		
Date Of Accident	10/04/2018 11:20		
Exact Location Of Accident	CAR PARK OF 194 PANDAN LOOP		
Country/State of Loss	SINGAPORE		

Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGN5692M	
Insured/Policyholder		
Name Of Registered Owner	JAHANGEER S/O K ABDUL HALIM	
NRIC No	S6880374H	
Email Address	JAHANGEER@LJENERGY.COM	
Mobile Phone No	(LOCAL) +65-97868414	
Alternative Phone No	OFFICE-NOPHONE	
Vehicle Particulars		
Manufacturer	NISSAN	

Manufacturer	NISSAN
Model	SYLPHY-1.5 4AT (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken PRIVATE CAR Vehicle Category

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

D17MTPV01015468 Policy Number

Cover Note Number

Driver

Name of Driver JAHANGEER S/O K ABDUL HALIM

NRIC No S6880374H 20/05/1968 Date Of Birth INDOOR Occupation 21/05/1998 Date Of Driving Pass

19 YEARS AND 10 MONTHS Driving Experience

Gender

Mobile Number (LOCAL) +65-97868414

Fax Number

OFFICE-NOPHONE Contact Number

EMail Address JAHANGEER@LJENERGY.COM Address

BLK 683B JURONG WEST CENTRAL 1

#04-104

Postcode

642683

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

CLEMENTI N.P.C

Police Station Address

ROAD: 20 CLEMENTI AVE 5, POSTCODE: 129858, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT D/20180410/7019

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

NO

Was there any audio recorded?

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

Vehicle Make/Model/Colour

YP9998G

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 18

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

I AM AWARED THAT MY IN SURER MAY HAVE A 14 DAY'S TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

### Sketch Plan Pg. 2

KEICH PLAN		
	unknown	
	MUCHOWIT	
SCRIBE CIRCUMSTANCES OF TH	IE ACCIDENT	
2efer to Police	Phene J	
- TO TO TO TO	Thurst	
		Claim own policy
		Claim third party     Claim OD / TP st other works hop
CLARATION		Policy No. DIT MTPV01015 468
é declare the foregoing particulars a	re true in every respect.	Insurer_SOMPO
MILLION .		- By
May .		
dynologe's Signature e & Time:	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel's Signature Name:
e or intie:	Date & Time:	NRIC/FIN No.:





1 of

POLICE REPORT (NP299)

Police Station Of Origin Clementi Police Divisional HQ 20 Clementi Avenue 5 SINGAPORE 129858 Tel No:1800-7740000 Report No. D/20180410/7019

Date/Time Report Made 10/04/2018 18:10	Vide Re	port No.		Station Diary No.
Name Of Informant JAHANGEER S/O K ABDUL HALIM	G030/12/05/20/05/05/		RONG WEST CEN	NTRAL 1 #04-104
ID Type / ID No. NRIC NO / S6880374H	Contact No. Home/Office: Mobile: 97868414			
Nationality SINGAPORE CITIZEN	Email A	ddress geer@yaho	oo.com	
Occupation	Sex	Age	Date of Birth	Race
DEPUTY DIRECTOR	Male	49	20/05/1968	Indian
Institution/School Name	Language English			
Date/Time Of Incident Location Of Incident 10/04/2018 11:20 - 10/04/2018 11:24 Location Of Incident 194 PANDAN LOOP PANTECH BUS		INESS HUB		
	ISINGAF	ORE 1283	53	

#### Brief details.

On Tuesday, 10 April 2018 around 10 a.m. I had parked my car (Registration number SGN 5692M, Nissan Sylphy) at the parking lot below my office at 194 Pandan Loop. After two hours around 12.15 pm, when I come out to drive out for a meeting, I was shocked to see the entire front part of my car including the headlight smashed and mangled and the whole bumper dropped down without seeing any vehicles nearby. I understood from the first sight of my car without seeing any other vehicle, this is a case of hit and run. I immediately with one of my colleagues, Mr Michael approached the parking agent, TOP

Signature Of Officer Recording The Report:	Signature Of Informant: The identity of the person making this		
Not applicable	report has been authenticated by SingPass. No signature is required.		
Signature Of Interpreter: Not applicable	Date/Time: 10/04/2018 18:10		
Officer In-Charge Of Case:	Classification Of Case:		

Authentication Stamp





2 of 2

POLICE REPORT (NP299)

e ... 27 ...

CONTINUATION OF REPORT

Report No. D/20180410/7019

Parking Pte Ltd, upon examining the closed circuit video footage, we managed to track down the vehicle as YP 9998G as the vehicle owned by the company with the name GREAT HARVEST HARDWARE MARINE AND SUPPLIES located at 194 Pandan Loop, #01-14, Singapore 128383. After Identifying the vehicle, which hit my parked car, I along with my colleague approached the company owner Mr Mathew to whom we shown the video evidence. After seeing the video evidence, Mr Mathew readily admitted the mistake and damage caused by his driver, whose particulars are provided in the accident report. Mr Mathew also agreed to claim my car repair cost from his vehicle insurance. After these events, I called upon my insurance agent, who helped to tow down my car to the aurthorized workshop, Sng Ah Tee Motor & Panel services Pte Ltd. Subsequently, I lodged an accident report through Sng Ah Tee.

Victim		Call and a second second	
Person Name	JAHANGEER S/O K ABDUL HALIM		
ID Type	NRIC NO	ID No	S6880374H
Gender	Male	Age	49
Race	Indian	Language	English
Occupation	DEPUTY DIRECTOR	Address Type	
Address	APT BLK 683B JURONG WEST CENTRAL 1 #04-104 hdb SINGAPORE 642683	Mobile No	97868414
Is Informant A Victim?	Yes		

Signature Of Officer Recording The Report:	Signature Of Informant: The identity of the person making this
Not applicable	report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/04/2018 18:10
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

## Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

NIL

Singapore

Claimant Insurer: Sompo Insurance Singapore Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type: Policy No: THIRD PARTY

Ref. No:

Date of Loss: Driveable?

10/04/2018

Vehicle Reg. No.: Party At Fault:

SGN5692M

UNKNOWN

Driver (TP):

JAHANGEER S/O K ABDUL HALIM

Make/Model:

NISSAN SYLPHY, 1.5 4AT (A)

Vehicle Reg. Date:

22/11/2006

Vehicle Colour:

PURPLE

JN1BAAG11Z0100904

Engine No: Odometer: HR15043389A 5 KM Chassis No:

enfor 97495749

Paint Type:

Total Loss?

NO

Est. Duration of Repair

(day)

140

10

REFER TO POLICE REPORT D/20180410/7019

Description of Accident/Loss

Present Location:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS	LKK Auto Consultants hence notify	7	Amount
Parts	the Repairer of the following:		3,611.00
Miscellaneous Items	ems To resurvey before/after spray painting		0.00
Labour	To display damaged part(s) during resurvey     Parts prices are subject to confirmation		1,830.00
Paintwork Labour	Third party survey is on a "Without Prejudice" basis		0.00
Towing	<ul> <li>No illegal modification(s) is allowed</li> </ul>		0.00
	<ul> <li>Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company</li> </ul>	Gross Total (S\$)	5,441.00
	Acknowledged by Repairer	+ GST 7.00% (S\$)	380.87
	Signature: Date:	Nett Amount (S\$)	5,821.87

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

#### REPAIR DETAILS

## Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 12 Apr 2018)

Parts:

143

NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGN5692M)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
4	я.	*FRT NUMBER PLATE	0	0.00	*35.00 FS
2	1	*FRT BUMPER	0.00	0.00	*260.00 F
3	2	*FRT BUMPER SIDE RETAINER	0.00		*30.00 F
4	10	*FRT BUMPER CLIP	0.00		*25.00 F
5	1	*FRT BUMPER LOWER SKIRT	0.00	0.00	1x +220.00 F
6	1	*FRT BUMPER TOWING COVER	0.00	0.00	Rr *15.00 F
7	4	*FRT BUMPER REINFORCEMENT	0.00	0.00	? *135.00 FXN
8		*FRT BUMPER SPONGE	0.00	0.00	
9	1	*FRT FOGLAMP COVER(RH)	0.00		€ - *35.00 F
10	1	*FRT FOGLAMP (RH)	0.00	1000	*230.00 F
11	1	*FRT GRILLE ASSY (CHROME)	0.00	0.00 or	
12		FERT CRILLE EMPLEM	0.00	0.00 4	
	0	*FRT HEADLAMP RH -M - , LH XXXX	0.00	0.00	₹0 *540.00 F
13 14	2	*FRT FENDER (RH)	0.00	0.00	5t-*165.00 F
15	2	*FRT FENDER INNERSHEILD	0.00		120.00 F
16	20	*FRT FENDER INNERSHEILD CLIP	0.00		*50.00 F
17	1	*FRT BONNET	0.00	0.00	*400.00 F
18	1	*FRT BONNET CHROME	0.00	0.00	*68.00 F
19	2	*FRT BONNET HINGE	0.00		X M~90.00 F
20	2	*FRT BONNET RUBBER	0.00	0.00	*50.00 F
21	1	*FRT BONNET LOCK	0.00	0.00	*55.00 F
22	1	*FRT BONNET LOCK CABLE	0.00	0.00	*35.00 F
23	1	*FRT SUPPORT PANEL COMPLETE	0.00	0.00	*480.00 F)
24	1	*FRT SUPPORT BRACE PANEL	0.00	0.00	
25	2	*FRT HORN	0.00	0.00	
26	2	*FRT AIR CON AIR GUIDE	0.00	0.00	x *110.00 F \
27	1	*FRT SUPPORT TOP GARNISH	0.00	0.00	× *75.00 F
28	10	*FRT SUPPORT TOP GARNISH CLIP	0.00	0.00	× *25.00 F
	anchise part. S=SpcNet		0.00		,
	and no part o operior		tal Parts (S\$)		3,611.00
			100		-1

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates of	nla	bour
--------------	-----	------

No	Particulars	Lab.Type	,	Amount
Lab	our Items			-
1	TO CHECK WIRING	New		30.00
2	TO TOP UP AIR CON GAS	New	NV X	100.00
3	TO KNOCK FRT FENDER, WELD, REMOVE & REPLACE ABOVE PARTS	New	400	850.00
4	TO PUTTY & RESPRAY FRT BUMPER, FRT BONNET, FRT FENDER X2, FRT SUPPORT PANEL & AFFECTED AREAS.	New 500	400	850.00
	Gross Labo	our Cost (S\$)	1	,830.00

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## REPAIR DETAILS

# Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 12 Apr 2018)

Parts:

143

NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code:

(Unsubmitted, no print-code for SGN5692M)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

great .				
- 61	imat	OC	nn	Parts
_3	illia	CO	UII	Falls

No	. Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE		0	0.00	mice o
2	1		*FRT BUMPER		0.00	0.00	
3	2		*FRT BUMPER SIDE RETAINER			0.00	260.00 F/
4	10		*FRT BUMPER CLIP		0.00		30.00 F/
5	1		*FRT BUMPER LOWER SKIRT		0.00	0.00	25.00 F/
6	1		*FRT BUMPER TOWING COVER		0.00	0.00	~
7	1		*FRT BUMPER REINFORCEMENT		0.00	0.00	
8	1		*FRT BUMPER SPONGE		0.00	0.00	
9	1		*FRT FOGLAMP COVER(RH)		0.00		75.00 FV
10	1		*FRT FOGLAMP (RH)		0.00	0.00	de - 35.00 FV
11	1		*FRT GRILLE ASSY (CHROME)		0.00	0.00	cm -230.00 FV
12	1		*FRT GRILLE EMBLEM		0.00	0.00	*160.00 FV
13	2		*FRT HEADLAMP RH -M - , LH &		0.00		₩ -28.00 FV
14	1		*FRT FENDER (RH)		0.00		\$790 *540.00 F (4)
15	2		*FRT FENDER INNERSHEILD		0.00	0.00	5t-165.00 F/
16	20		*FRT FENDER INNERSHEILD CLIP		0.00	0.00	↑ 120.00 F/
17	1		*FRT BONNET		0.00	0.00	~ 50.00 F/
18	1		*FRT BONNET CHROME		0.00	0.00	*400.00 FX
19	2		*FRT BONNET HINGE		0.00	0.00	*68.00 F <sub>X</sub>
20	2		FRT BONNET RUBBER		0.00	0.00	*90.00 FX
21	1		*FRT BONNET LOCK		0.00	0.00	*50.00 FX
22	1		FRT BONNET LOCK CABLE		0.00	0.00	*55.00 FX
23	1				0.00	0.00	*35.00 F <sup>X</sup>
24	1		*FRT SUPPORT PANEL COMPLETE		0.00	0.00	₹ *480.00 FX
25	2		*FRT SUPPORT BRACE PANEL *FRT HORN		0.00	0.00	★ *30.00 Fx
26	2				0.00	0.00	* *110.00 FX
27	1		*FRT AIR CON AIR GUIDE		0.00	0.00	x *70.00 FX
28	10		*FRT SUPPORT TOP GARNISH		0.00	0.00	x *75.00 FX
2072		art. S=SpcNett.	*FRT SUPPORT TOP GARNISH CLIP		0.00	0.00	¥ *25.00 F €
		110		Total Parts (S\$)	\$1448.00	ardt	3,611.00

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

F - 41			
Estimat	000	m	Shour
Louinia	COL	<i>J</i> III L	about

No	Particulars	Lab.Type		Amount
Lab	our Items	The Cope of Control		
1	TO CHECK WIRING			-
2	TO TOP UP AIR CON GAS	New		30.00
3	TO KNOCK FRT FENDER, WELD, REMOVE & REPLACE ABOVE PARTS	New	×	100.00
4	TO PUTTY & RESPRAY FRT BUMPER, FRT BONNET, FRT FENDER X2, FRT SUPPORT	New	400	850.00
	PANEL & AFFECTED AREAS.	New	400	850.00
		9-	. (	

Gross Labour Cost (S\$) 930

1,830.00

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

timates on Labour

Particulars

Pur Items

TO TOWING (Puff to GIA / Police Mysit)

New

New

50.00

Gross Labour Cost (S\$)

50.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SGN5692M/19/07/2018 18:39. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18006856/T1QBN2

Date:

15/10/2018

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Claimant Vehicle No:

Date of Loss:

SGN5692M

10/04/2018

Policy No:

DMCVSN3039331700

Insured Vehicle YP9998G

No:

Claim:

Nature of TP Claim No:

SNM18D01894C02

JN1BAAG11Z0100904

HR15043389A

115694 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGN5692M

Make & Model:

NISSAN SYLPHY, 1.5 4AT (A)

22/11/2006 (Man. Year: 2006)

Reg. Date: Colour:

Silver

Engine Capacity: Market Value/New Car

Price.

Sum Insured (S\$):

1498 cc N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

Front Left Side:

195/65R15

Bridgestone 6 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 195/65R15 Bridgestone 6 mm

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,611.00	1,483.00	2,128.00	58.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	980.00	900.00	47.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,491.00	2,463.00	3,028.00	55.14
Approved Total (Overridden) (S\$)		1,950.00	4,040,040,040,040	
(S\$)	5,491.00	1,950.00	3,541.00	64.49
+ GST 7.00/7.00% (S\$)	384.37	136.50	247.87	64.49
Nett Amount (S\$)	5,875.37	2,086.50	3,788.87	64.49

INSPECTION

Date of Assignment:

12/04/2018 Present Location:

Sng Ah Tee Motor & Panel Service Pte

Ltd (Pioneer)

Date Inspected:

13/04/2018 Inspected At:

Sng Ah Tee Motor & Panel Service Pte

Ltd (Pioneer)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair:

4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 15 Oct 2018) Part Source: MRM-SG

NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SGN5692M)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Re	com	ımenc	led	Parts
			-	

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Missing	35.00 FS	*35.00 FS
2	1		*FRT BUMPER	Deformed	260.00 F	*260.00 F
3	2		*FRT BUMPER SIDE RETAINER	Necessary	30.00 F	*30.00 F
4	10		*FRT BUMPER CLIP	Necessary	25.00 F	*25.00 F
5	1		*FRT BUMPER LOWER SKIRT	Not Necessary	220.00 F	*-F
6	1		*FRT BUMPER TOWING COVER	Repair	15.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Not Necessary	135.00 F	*-F
8	1		*FRT BUMPER SPONGE	Cracked	75.00 F	*75.00 F
9	1		*FRT FOGLAMP COVER(RH)	Deformed	35.00 F	*35.00 F
10	1		*FRT FOGLAMP (RH)	Cracked	230.00 F	*230.00 F
11	1		*FRT GRILLE ASSY (CHROME)	Cracked	160.00 F	*160.00 F
12	1		*FRT GRILLE EMBLEM	Cracked	28.00 F	*28.00 F
13	1		*FRT HEADLAMP	O/s Cracked/N/s Not Necessary	540.00 F	*270.00 F
14	1		*FRT FENDER (RH)	Bent	165.00 F	*165.00 F
15	2		*FRT FENDER INNERSHEILD	Torn	120.00 F	*120.00 F
16	20		*FRT FENDER INNERSHEILD CLIP	Necessary	50.00 F	*50.00 F
17	1		*FRT BONNET	Not Necessary	400.00 F	*-F
18	1		*FRT BONNET CHROME	Not Necessary	68.00 F	*-F
19	2		*FRT BONNET HINGE	Not Necessary	90.00 F	*- F
20	2		*FRT BONNET RUBBER	Not Necessary	50.00 F	*- F
21	1		*FRT BONNET LOCK	Not Necessary	55.00 F	*-F
22	1		*FRT BONNET LOCK CABLE	Not Necessary	35.00 F	*- F
23	1		*FRT SUPPORT PANEL COMPLETE	Not Necessary	480.00 F	*- F
24	1		*FRT SUPPORT BRACE PANEL	Not Necessary	30.00 F	*- F
25	2		*FRT HORN	Not Necessary	110.00 F	*- F
26	2		*FRT AIR CON AIR GUIDE	Not Necessary	70.00 F	*-F
27	1		*FRT SUPPORT TOP GARNISH	Not Necessary	75.00 F	*-F
28	10		*FRT SUPPORT TOP GARNISH CLIP	Not Necessary	25.00 F	*-F
F=Fr	anchise	part. S=Spo	:Nett.			

1,483.00 Total Parts (S\$) 3,611.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			2000-00
1	TO CHECK WIRING	New	30.00	30.00
2	TO TOP UP AIR CON GAS	New	100.00	-
3	TO KNOCK FRT FENDER, WELD, REMOVE & REPLACE ABOVE PARTS	New	850.00	400.00
4	TO PUTTY & RESPRAY FRT BUMPER, FRT BONNET, FRT FENDER X2, FRT SUPPORT PANEL & AFFECTED AREAS.	New	850.00	500.00
Sup	plementary #1			
Lab	our Items			
5	TO TOWING	New	50.00	50.00
	Gross Labou	r Cost (S\$)	1,880.00	980.00
	Report was unsubmitted during	ng this print-out.		

< END OF ESTIMATES >