

22/03/2002

ASS. REC. BY:

REF: CS/ASM18001858/RHbez

Special Instruction:

Survivor

Rasul

ASSIGNMENT (Office)

From (Person):

Vale Oh

6804894

of

ASM

Date/Time:

12042018 11:21am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

XE 706L

Insured:

at Workshop m/s

AAK Logistics

Tel:

6677 6227 / 9762 3134

of

4 Penjuru Close

Policy No:

Claim No:

S9MOODSR

Sum Insured:

Excess:

\$ 3000.00

Make of Veh:

D.O.A. 29032018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12042018 9:28am

Person Contacted:

Per Juan

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

'Virtual'

XE-706L - (CQ/AXA16013219/K18392

DOI: 130716

Repair agree \$5400 L/S

17/4-

10:38 am authorise repair by Val

17/4-

1:25pm email repairer via email authorise repair excess \$3000/

Lump Sum \$6500 - (Red: 1907; 22%)

Surveyor: Faran

REF:

5782M

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: XE 706Lat Workshop m/s AAKof 4, Pawan RoadInsured: AKM

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 3000

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 95K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / ☒ REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: XE 706L Yr Regn: 2015 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / ☒ Trailer orMake: MITSUBISHI FUSO FPSI c.c. 11967Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 139041 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: FPSI SBA10143Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R22.5R: 2" x 8" x 10"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TBB tires

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 29/03/14 D.O.I. 13/04/14Survey held at AAKDes. of Damages ☒ Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>16/4</u>	<u>Report via AAK</u>

Date/Time, File Pass to?

☐

Preli. Report

☒

Final Report

1) HS Typist

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format: ODLump Sum / I.B.I.: \$6500

200



# Service Request Details

Claim

S8M00DSR

LKK AUTO CONSULTANTS PTE LTD (OD) ▾

Reference

None

Loss Date

March 29, 2018

Request Date

April 12, 2018

Due Date

April 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

## Actions

Next Step

Agree to perform service

Decline Work

Accept Work

## Vehicle Information

Incident Vehicle Registration #

XE706L

Make

MAZDA MAZDA3

Service Address

...

Primary Contact/Insured

AAK LOGISTICS SERVICES PTE. LTD.  
BLK 153 BUKIT BATOK STREET 11, #03-292, 650153, Singapore  
63380083

Claim Handler

OH Vale  
6568804897  
vale.oh@axa.com.sg

Additional Instructions  
VIRTUAL OD CASE XS - \$3K PLS REVERT ON IA FIRST

Messages   Invoices   History   Documents   Assessment   Metrics   Notes

New Message

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 20 April 2018 9:54 AM  
**To:** 'peijuan\_lee@aakls.com'  
**Cc:** SUR  
**Subject:** FW: XE706L OD AXA  
**Attachments:** Letter of Undertaking.pdf

Dear Pei Juan,

As per conversation earlier, we will confirm at lump sum \$6500/- before GST(7%) and Excess \$3000.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M00DSR

Our Ref: CS/ASM18006858/R1tb

Date: 16/4/2018

The Motor Claims Department  
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO XE 706L**


We thank you for the instruction on 12/04/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/04/2018 @1730PM at the premises of M/s AAK Logistics and have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,407.00</u>
Revised Estimate Amount	: S\$ <u>7,767.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Total	: S\$ <u>7,767.00</u>
Market Value	: S\$ <u>95,000.00</u>
LTA Reimbursement Value	: S\$ <u>36,471.00</u>
Nett Value	: S\$ <u>58,529.00</u>

Description of Damage:

The vehicle sustained damages at the Front portion.



Comments/ Present Status:  
Damages Consistent  
Repair cost economical  
Repair Days: 6

Yours Faithfully,  
Rasul  
Automotive Assessor

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 17 April 2018 1:25 PM  
**To:** peijuan\_lee@aakls.com; auto@aakls.com  
**Cc:** SUR  
**Subject:** RE: XE706L OD AXA  
**Attachments:** Letter of Undertaking.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **XE 706L (Excess \$3000/-). At lump sum \$5400/-.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 17 April 2018 9:46 AM  
**To:** peijuan\_lee@aakls.com; auto@aakls.com  
**Subject:** XE706L OD AXA

Hi Pei Juan,

Meanwhile waiting for authorization from insurance.

Please get insured to sign the undertaking letter and return us first

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

4/17/2018

Claim Portal



TYPE



SENT

4/17/18 10:38 AM

FROM

OH Vale

SUBJECT

Re:RE: Re:XE 706L LUMP SUM AMOUNT

BODY

PLS PROCEED TO AUTH AT LS \$5400/- BEFORE XS, THANK...



TYPE



SENT

4/17/18 9:37 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT

RE: Re:XE 706L LUMP SUM AMOUNT

BODY

Hi, repairer agree on lump sum \$5400/-. Denise



TYPE



SENT

4/16/18 4:49 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT

RE: Re:XE 706L LUMP SUM AMOUNT

BODY

Checking with repairer. denise



TYPE



SENT

4/16/18 4:35 PM

FROM

OH Vale

SUBJECT

Re:XE 706L LUMP SUM AMOUNT

BODY

We are looking at \$5400/- before xs.



TYPE





**Enquire Transfer Fee****Vehicle Details**

Vehicle No. :	XE706L
Vehicle Type :	B36 - Goods (Open) Prime Mover
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	MITSUBISHI
Vehicle Model :	FUSO FP51SDR3VDEA
Chassis No. :	FP51SDA10143
Propellant :	Diesel
Engine No. :	OM457297610
Engine Capacity :	11967 cc
Maximum Power Output :	-
Maximum Laden Weight :	55000 kg
Unladen Weight :	6900 kg
Year Of Manufacture :	2014
Original Registration Date :	16 Jun 2015
Lifespan Expiry Date :	15 Jun 2035
COE Category :	C - Goods Vehicle & Bus
Quota Premium :	\$50,900.00
COE Expiry Date :	15 Jun 2025
Road Tax Expiry Date :	15 Jun 2018
Inspection Due Date :	15 Jun 2018
Intended Transfer Date :	16 Apr 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 15 Jun 2018. You may renew the road tax from 16 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 15 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable (From 16 Jun 2018 to 15 Dec 2018)**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
<b>Total Amount Payable :</b>			<b>25.00</b>

**Amount Payable (From 16 Jun 2018 to 15 Jun 2019)**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
<b>Total Amount Payable :</b>			<b>25.00</b>

**Message**

This vehicle has a road tax Over Payment of \$2,227.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/04/2018 14:39
Date Of Accident	29/03/2018 14:20
Exact Location Of Accident	WESTCOAST HIGHWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE706L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AAK LOGISTICS SERVICES PTE LTD
Co Reg No	201325787M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66776227

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FP51SDR3VDEA-12.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCX/P1932487
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD JUFRI BIN JUMAHAT
NRIC No	S8929870I
Date Of Birth	05/09/1989
Occupation	OUTDOOR
Date Of Driving Pass	01/11/2010
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87492350
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address NO  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. YES  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD2863H  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Sketch Plan #2

### SKETCH PLAN



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On the date 29/03/18 at about 1520 hours I was driving my vehicle A VC706 L along Westcott Highway. The vehicle I XD 286311 (TRC F877 L) in front suddenly jammed. I also jammed brake but I was not able to stop my vehicle A VC706 L in time and hit onto the rear of vehicle B XD 286311 (TRC F877 L). I am claiming my own insurance policy.

The driver of vehicle A VC706 L make the decision regarding the car crashing but they are claiming on their own workshop.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

**Reporting Centre Personnel's Signature**  
Name: \_\_\_\_\_  
NNUC/FIN No.: \_\_\_\_\_

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

5787M

**Vehicle Details**

Vehicle No.:

XE706L

Vehicle to be Exported:

No

Intended De-registration Date:

16 Apr 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

FUSO FP51SDR3VDEA

Primary Colour:

White

Manufacturing Year:

2014

Engine No.:

OM457297610

Chassis No.:

FP51SDA10143

Maximum Power Output:

-

Open Market Value:

\$78,583.00

Original Registration Date:

16 Jun 2015

First Registration Date:

16 Jun 2015

Transfer Count:

0

Actual ARF Paid:

\$3,930.00

**Intended PARF Rebate Details**

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

**Intended COE Rebate Details**

COE Expiry Date:

15 Jun 2025

COE Category:

C - Goods Vehicle &amp; Bus

COE Period(Years):

10

QP Paid:

\$50,900.00

COE Rebate Amount:

\$36,471.00

**Total Rebate Amount:****\$36,471.00**

The information contained herein is correct as at 16 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Please report the details of the accident to speed up the claims process.  
Form must be completed by the Policyholder and/or the Authorised Driver.  
Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to refuse to pay claims.  
The acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.  
This report may be referred to the Police for investigation.

This report is provided by the Singapore GIA Records Management Centre established by the General Insurance Association of Singapore (GIA).  
The report is for the use of the insurance companies and is not to be made available for publication by any other person.  
The insurance companies and the insured person agree to the reporting of this report to the insurance companies to speed up the claims process.

### ACCIDENT STATEMENT

Date of Report: 02/04/2018 14:39  
Date of Accident: 29/03/2018 14:20  
Place/Location of Accident: WEST COAST HIGHWAY  
Country/State of Loss: SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number: XE706L  
Name of Policyholder: [REDACTED]  
Name of Employer: YAK LOGISTICS SERVICES PTE LTD  
Contact No: 201325787M  
Email Address: NOEMAIL  
Mobile Phone No: [REDACTED]  
Alternate Phone No: OFFICE-66776227  
Vehicle Brand/Make: [REDACTED]

Model: MITSUBISHI  
EP51SDR3VDEA-120 D (M)  
Exact Purpose for which vehicle was being used at time of accident: [REDACTED]

Are you driving under your own insurance policy for road to your vehicle? YES

If No, please indicate how to be taken

Vehicle Category: COMMERCIAL VEHICLE

Insurance Company: WA INSURANCE PTE LTD

Name of Insurance Company: COMPREHENSIVE

Type of Coverage: NO

Policy No: V6XP08216

Policy Name: [REDACTED]

Policy No: [REDACTED]

Name: MUHAMMAD IBERGEM UMMAH

Vehicle No: S8929870

Vehicle No: 05094889

Date of Birth: 01/01/2010

Age: 7 YEARS AND MONTHS

Gender: MALE

Address: [REDACTED]

Phone No: [REDACTED]

Mobile No: [REDACTED]

Signature: [REDACTED]

Date: [REDACTED]

Signature: [REDACTED]

Date: [REDACTED]







# AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aakls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

Virtual Insurance Agencies Pte Ltd

192 Waterloo Street, #02-02

Skyline Building, Singapore 187966

Attn: Stanley/Lena

LKK Auto Consultant, hence notify the Repairer of the following:

- To resurvey before spray painting
- To stay damaged until survey resurvey
- Particulars of the damage
- Third party liability on "without Prejudice" basis
- No illegal or fraudulent claims
- Supplementary details to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

UOM

QTY

## Quotation

DATE: 11-Apr-18

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	Signature:	UOM	QTY	UNIT PRICE	AMOUNT (\$)
		Date:				
	Own Damage Repair : XE706L					
1	Front Bumper	Rasul Ap 90010068 6 days P/P 13/04/18 @ 1730 EXCESS: 3000 REVERT Resurvey by paint		1	\$1,227.00	PA ✓ \$1,227.00
2	Front Panel			1	\$1,402.00	PA ✓ \$1,402.00
3	Front Carplate			1	\$38.00	PA ✓ \$38.00
4	Grill Upper			1	\$480.00	CRA ✓ \$480.00
5	Grill Lower			1	\$568.00	CRA ✓ \$568.00
6	Bumper Step		accessories	1	\$230.00	CRA ✓ \$230.00
7	Panel Lock LH			1	\$188.00	BT ✓ \$188.00
8	Panel Lock RH			1	\$188.00	PA ✓ \$188.00
9	Latch LH			1	\$35.00	PA ✓ \$35.00
10	Latch RH			1	\$35.00	PA ✓ \$35.00
11	Bumper side LH			1	\$246.00	PA ✓ \$246.00
12	Bumper side RH			1	\$246.00	PA ✓ \$246.00
13	Coner Panel LH		accessories	1	\$407.00	CRA ✓ \$407.00
14	Coner Panel RH		accessories	1	\$407.00	CRA ✓ \$407.00
15	Headlamp Garnish LH		accessories	1	\$98.00	DE ✓ \$98.00
16	Headlamp Garnish RH		accessories	1	\$98.00	CRA ✓ \$98.00
17	Foglamp Garnish LH		accessories	1	\$98.00	DE ✓ \$98.00
18	Foglamp Garnish RH		accessories	1	\$98.00	DE ✓ \$98.00
19	Water Tank			1	\$518.00	DE ✓ \$518.00
20	Spray Paint			1	\$450.00	✓ \$450.00
21	Logo			1	\$100.00	✓ \$100.00
22	Panel Beat Bumper Bracket & Bumper Top Panel }			1	\$450.00	PA ✓ \$450.00
23	Labour			1	\$800.00	PA ✓ \$800.00
E. & O. E.					SUB-TOTAL	\$8,407.00
SGD: EIGHT THOUSAND NINE HUNDRED NINETY-FIVE AND CENTS FORTY-NINE ONLY.					7% GST	\$588.49
					TOTAL	\$8,995.49

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

Accepted and Confirmed by

AAK LOGISTICS SERVICES PTE LTD

Company Chop & Signature

Authorised Signature

