



Your Ref: MSC/V/18-000166

Date: 02nd May 2018

Our Ref: CS1/MSG18006901/Dqbs2

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay
#24-01 Hong Leong Bldg
Singapore 048581
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
WC 7463C**

INSURED VEHICLE: FU 2037A

ACCIDENT DATE: 10/08/2017

We thank you for your instruction on 13/04/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of WC 7463C from M/s City Adjusters & Investigators Sdn. Bhd.
- b) Singapore Accident Statement of Vehicles FU 2037A.
- c) Colour damaged vehicle photographs of WC 7463C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: WC 7463C
Make & Model	: Nissan – Almera 4
Year of Registration	: 2015
Chassis Number	: PN8BBAN171CA96522

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.