

ASS. REC. BY:

REF: CS/ms(18006907/TtHb

Special Instruction:

Surveyor:

Teechich

ASSIGNMENT (Office)

From (Person):

Jenny Yung

of

mslh

Date/Time: 13042018 4:11pm

Estimated Cost:

Bill to:

OD / TP / MS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ 51008

Insured:

Public Liability

at Workshop m/s

Sin Sheng

Tel:

6863 9595

Policy No:

Claim No:

MSC/m/18-000116

Sum Insured:

Excess:

D.O.A.

09042018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

16042018

H.O.D. Endorsement:

Date/Time:

13042018 5pm

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GZ 51008 - X

Public Liability - X

lump sum \$1450 - (Red: 1211.30 : 45%)

Tan Min

REF:

MSH

ASSIGNMENT

CoE 2021 May.

From:

Date:

16047018

Veh No:

GZ5100S

Yr Regn:

2006 May

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TS / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

GZ 5100S

Make:

Mitsubishi L300

cc 2477

at Workshop n/s:

Sin Sheng

Colour:

Black

A/C: Insured / Std / NI / NA

of

3 Tuas Park Crescent

Sp. Reading:

542/87

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

JMAJNP15V67001/24

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Air / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

185/R14

R:

75

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Prestone

Est. or Market Value:

\$18K.

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GLA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res: Yes or No

D.O.A.

D.O.I.

16/4/18

Lump Sum:

%

3 Val: Yes or No

Survey held at

Sin Sheng

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

frt o/s

Date

Person Contacted:

Vehicle IN / OUT

Susan

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

4/5/18, 3 days, e-mail Susan

RECEIVED 21 MAY 2018

Date/Time: File Pass to?



Prel. Report

21/5 Typist



Final Report

Date/Time: File Return to?

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee

Transportation

150

Photos

Video

7074

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Workshop (\$)

Report Format:

Lump Sum / I.B.I. (\$)

14501

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006907/T1tb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-04-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	GZ 5100S	
Policy No.		Coverage (\$)	0.00	
Claim No.	MSC/M/18-000116	Excess (\$)	0.00	
Assign From	JENNY YONG	Assign Date	13/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/04/2018	Inspection Date	16/04/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Jenny Yong <jenny_yong@sg.msig-asia.com>
Sent: Friday, 13 April, 2018 4:11 PM
To: Catherine Chong (LKK Auto)
Cc: assignments@lkkauto.com
Subject: [New Assignment] - Insured : South Beach Project - forklift collided with vehicle on 9/4/2018 - MSIG : MSC/M/18-000116
Attachments: 13042018160352-0001.pdf

Hi Catherine,

Contractor All Risk Policy

Please get a motor surveyor to inspect third party vehicle GZ5100S on a without prejudice basis.

We understand that the vehicle (van) is at the workshop.

You may contact Susan (workshop) at Tel : 68639595 for the survey.

Attached Accident report and photographs of the van.

Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg   

A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Denise Tay (LKKAUTO)

From: sinsheng engineeringservices <sinsheng1981@gmail.com>
Sent: Monday, 21 May 2018 1:45 PM
To: Denise Tay (LKKAUTO)
Cc: Taufikh (LKKAUTO)
Subject: Re: Accident Involving GZ5100S with Forklift on 09/04/2018

Hi Ms Denise,

We are agreed.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On 21 May 2018 at 13:21, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear Susan,

Parts: 1282

-10%: 1,153.80

Labour: 700

Total 1,853.80

Lump sum at \$1450/-, please check and confirm.

Repair days: 3

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2018 15:06
Date Of Accident	09/04/2018 09:25
Exact Location Of Accident	CARPARK @ SOUTH BEACH AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ5100S
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	L300-2.5 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29004183
Cover Note Number	

Driver

Name of Driver	MOHAMAD FAZLIE BIN SALIM
NRIC No	S8035381B
Date Of Birth	12/11/1980
Occupation	OUTDOOR
Date Of Driving Pass	07/07/2008
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 121 RIVERVALE DRIVE #02-416
 Postcode 540121
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - LESSEE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : NOT APPLICABLE
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON MENTIONED DATE/TIME, I WAS DRIVING ALONG SOUTH BEACH AVENUE CARPARK, INTENDING TO MAKE MY WAY TO THE LOADING BAY AT THE BASEMENT CARPARK. I NOTICED A FORKLIFT (VEHICLE B) ON MY RIGHT AND TRAVELLING AGAINST THE TRAFFIC FLOW. AS I PROCEEDED WITH MY TRAVEL, VEHICLE B SUDDENLY MADE A TURN TOWARDS MY DIRECTION AND ITS FRONT FORK COLLIDED INTO MY VEHICLE'S FRONT RIGHT PORTION, CAUSING DAMAGES. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Make/Model/Colour VEH B
 Details Of Properties FORKLIFT
 Vehicle Category NA/UNKNOWN
 Name of Driver SORKER SUSHANTO
 NRIC/Passport Number G8145269K
 Contact Number 91767421 (KIM YONG JOON)
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please Report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as **truthful and accurate as possible**. The GAA and/or Agent/Insurer is maintaining a database of motor accidents may allow you, with your insurer, to **repudiate policy liability**.
4. The Insurer will proceed with the claims process and/or admission of policy liability on the part of the insured person.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded to the insurers of the GAA Records Management Centre established by the General Insurance Association of Singapore in order to be made available upon application by interested parties.
7. By this agreement, I shall report to the insurers, and hereby consent to the archiving of this report at the centre and the report of the report being made available if required.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided to me or assumed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insured(s) who have insured vehicle(s) involved in this accident (all insured(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insureds"), the insurers, lawyers, law firms, the Motor Vehicle Authority of Singapore and any relevant government agencies/authorities such as the police, for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
 - (ii) investigating the accident in order to file claims;
 - (iii) carrying out an investigation dealing with my instructions or responding to any enquiries by me;
 - (iv) withdrawing my claims (including the handling of correspondence, statements, invoices, reports or notices to me) and/or providing disclosure of certain personal data about me to bring about delivery of the claim as well as on the external record of my accident/claim/accident; and/or
 - (v) complying with applicable law in order to bring, processing, handling and/or dealing with my claims collectively for the Purpose(s);
 - (b) my insurer, my workshop and the GIA may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
 - (c) my Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be used outside of Singapore for one or more of the above Purpose(s);
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information collected under (b) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud (e.g. lawyers, law enforcement and government agencies) as reasonably required for the purposes stated in (b);
 - (ii) in complying with requirements under any regulations, laws or court orders;



Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time

9/25/2023



Reporting Centre Personnel's Signature
Name:
NRCC/H/NC

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

ON MENTIONED DATE/TIME, I WAS DRIVING ALONG SOUTH BEACH AVENUE CARPARK, INTENDING TO MAKE MY WAY TO THE LOADING BAY AT THE BASEMENT CARPARK. I NOTICED A FORKLIFT (VEHICLE B) ON MY RIGHT AND TRAVELLING AGAINST THE TRAFFIC FLOW. AS I PROCEEDED WITH MY TRAVEL, VEHICLE B SUDDENLY MADE A TURN TOWARDS MY DIRECTION AND ITS FRONT FORK COLLIDED INTO MY VEHICLE'S FRONT RIGHT PORTION, CAUSING DAMAGES. NO ONE WAS INJURED.

DECLARATION

I/We declare the foregoing particulars are true and correct.



Witness Officer's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)

Date & Time



Reporting Officer/Personnel's Signature
Name
NRK/21/26/2020

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GZ5100S
Vehicle to be Exported:	No
Intended De-registration Date:	17 Apr 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	L300 HR M
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	4D56LB5632
Chassis No.:	JMAJNP15V6A001124
Maximum Power Output:	-
Open Market Value:	\$12,102.00
Original Registration Date:	11 May 2006
First Registration Date:	11 May 2006
Transfer Count:	0
Actual ARF Paid:	\$606.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 May 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,721.00
COE Rebate Amount:	\$13,918.00
Total Rebate Amount:	\$13,918.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 17 Apr 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Mitsubishi L300

Price Range

Depreciation

> 10 year(s) ol

Vehicle Type

 Search

Home » Used Cars » Direct Owners » Mitsubishi L300 (COE till 06/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

CL LEASING
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE



6769 7117 8720 5000 8720 8000

Mitsubishi L300 (COE till 06/2021)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$19,800**

Depreciation \$6,300 /yr

Reg Date 08-Jun-2006
(3yrs 1mth 21days COE left)

Lifespan 07-Jun-2026

Manufactured 2006

Mileage -

Transmission Manual

Engine Cap 2,477 cc

Curb Weight 1,390 kg

Fuel type Diesel

Features Good Working Condition. White Colour.

Accessories Radio, Aircon, Power Window.

Description Company Spare Vehicle. Selling Due To Underutilized.

COE \$22,326

OMV \$11,886

ARF \$595

Dereg Value \$14,032 as of today (change)

No. of Owners 2

Type of Veh Van

Category COE Car, Direct Owner Sale

Availability Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 07-Apr-2018 | Last Updated on: 12-Apr-2018

Tags: Mitsubishi L300, 2006 Mitsubishi L300, Mitsubishi, L300, Used Mitsubishi

Upfront Payment

» more Financial Info

Transfer Fee \$25

Down Payment \$1,980 (change)

Maximum 90% Loan

1st Instalment \$548

Compare



Preferred Viewing Area

Seller Information

Contact Person(s) Jim

Contact No. 97439445

Enquiry  Contact Se

USEFUL FORMS

» Indemnity form » Sales i

» Receipt » Hand-i

» M01

Instructions on how to complete a consumer deal

Regardless of buying or selling, we'll your paperwork, loans & insurance f

Useful Services



Make sure of this car with STA Evaluation.

Vehicle Evaluati

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002445

Date : 13/04/2018

Vehicle Num. : GZ5100S

Make/Model : MITSUBISHI L300-2006

Chassis/Eng# : JMAJNP15V6A001124/4D56LB5632

Accident Date : 09/04/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS :		
2.	1	FRONT BUMPER		675.00
3.	1	BUMPER SIDE, RH		22.00
4.	1	BUMPER REINFORCEMENT		245.00
5.	1	SIGNAL LAMP		195.00
6.	1	HEADLAMP, RHS		675.00
7.	1	CORNER PANEL, RHS		125.00
8.	1	COMPANY REGISTRATION STICKER		20.00
		Nett Total S\$:		1,957.00
		10.00% Discount S\$:		195.70
				1,761.30
		LABOUR :		
		TO PANEL BEAT/REPAIR RH BODY		450.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		SPRAY PAINTING		450.00
		LOSS OF USE : 4 DAYS @ \$ 120/DAY		
		Labour Total S\$:		900.00

Total S\$: 2,661.30

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Guan 97495749
16/4/18 @ 1540.
Resurvey after repair.
3 days.
Sua @ 11/11/18 @ 11.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006907/T1tbs2		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 23-05-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	GZ 5100S	
Policy No.		Coverage (\$)	0.00	
Claim No.	MSC/M/18-000116	Excess (\$)	0.00	
Assign From	JENNY YONG	Assign Date	13/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI L300	c.c	2477	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JMAJNP15V6A001124	Colour	BLACK	
Odometer	542187	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	AUSTONE	6 mm	
L/H Front Tyre	185 R14	AUSTONE	6 mm	
R/H Rear Tyre	185 R14	AUSTONE	6 mm	
L/H Rear Tyre	185 R14	AUSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2018	Inspection Date	16/04/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 5100S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (N)	DEFORMED	675.00	675.00
1	BUMPER SIDE, RH (N)	CUT	22.00	22.00
1	BUMPER REINFORCEMENT (N)	BENT	245.00	245.00
1	SIGNAL LAMP (N)	CRACKED	195.00	195.00
1	HEADLAMP, RHS (N)	NOT NECESSARY	675.00	-
1	CORNER PANEL, RHS (N)	BENT	125.00	125.00
1	COMPANY REGISTRATION STICKER (N)	NECESSARY	20.00	20.00
	LESS 10% DISCOUNT		-195.70	-128.20
			1,761.30	1,153.80
	<u>LABOUR</u>			
	TO PANEL BEAT / REPAIR RH BODY. TO DISMANTLE/REPLACE ABOVE MENTIONED PARTS.		450.00	350.00
	SPRAY PAINTING.		450.00	350.00
			900.00	700.00
	GRAND TOTAL		2,661.30	1,853.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00

Report Ref No. CS/MSG18006907/T1tbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.