

ASS. REC. BY:

REF:

TP1

CS/TP18006938/Kvbn2

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH12 6284

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A2

Make:

Perant latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

F34329

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1A9L15AUC 278275

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

17/4/18

D.O.I.

13/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14

File pass to Carpark

16/4/18

81 Pp 8 Ppd (Red

17, 688-04,

9514

(No Res)

SH12 6284 - x

16/4

RECEIVED 17 APR 2018

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip: 1

8x15 = 120

Survey Fee:

Transportation:

S - RS, SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

900/-

170 + 120
50
10
80
430



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18006938/Kvb		
NO.2 ANG MO KIO STREET 63 SINGAPORE 569111		Date : 16-04-2018		
		Code : TP378		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	Veh. Inspected		SHF 628M	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		13/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	01/04/2018	Inspection Date	13/04/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHF628M
Vehicle to be Exported:	Yes
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001593
Chassis No.:	VF1ABL15AUC278275
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	27 Jun 2014
First Registration Date:	27 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2022
PARF Rebate Amount:	\$9,373.00

**Intended COE Rebate Details**

COE Expiry Date:	26 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$30,341.00
<b>Total Rebate Amount:</b>	<b>\$39,714.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Apr 2018.

OK

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	02/04/2018 18:34
Date Of Accident	01/04/2018 08:50
Exact Location Of Accident	JURONG EAST MRT TAXI STAND
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SHF628M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

**Vehicle Particulars**

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

**Insurance Company**

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

**Driver**

Name of Driver	NG ENG LEE
NRIC No	S1805023D
Date Of Birth	31/01/1967
Occupation	OUTDOOR
Date Of Driving Pass	23/10/1987
Driving Experience	30 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96223131
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 587 WOODLANDS DRIVE 16  
#07-64  
Postcode 730587  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER  
Vehicle Registration Number of Driver's Own Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1 NAME: UNKNOWN  
GENDER: MALE

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

ON 01.04.2018 AT AROUND 0851HRS, I WAS TRAVELLING STRAIGHT TOWARDS JURONG EAST MRT TAXI STAND. I WAS PICKING UP A PASSENGER. AS I WAS DRIVING OFF, VEHICLE B (SHB1005A) WHICH WAS STATIONARY ON MY RIGHT. HIS PASSENGER OPEN LEFT PASSENGER DOOR AND HIT ONTO MY TAXI RIGHT SIDE FRONT PORTION.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB1005A  
Vehicle Make/Model/Colour SMRT TAXI  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to GIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Calvin  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 628M****AAD1804-025***Not Authorised*  
*11 Sep 8900h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHF 628M**

VF1ABL15AUC278275

RENAULT

LATITUDE

1.4.2018

*Smart***PART****LIST**

1	DOOR PANEL FRT RH	\$	<i>N</i> 2,844.66	}
1	DOOR HINGE UPPER RH	\$	<i>N</i> 261.28	
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55	
1	DOOR CHECK FRT RH	\$	<i>Sn</i> 194.77	
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69	
1	DOOR LOCK FRT RH	\$	<i>N</i> 908.75	
1	DOOR CATCH FRT RH	\$	<i>N</i> 131.23	
1	DOOR HANDLE OUTER FRT RH	\$	<i>Sn</i> 477.76	
1	DOOR HANDLE COVER FRT RH	\$	<i>Sn</i> 13.22	
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sn</i> 133.60	
1	DOOR REGULATOR FRT RH	\$	<i>Sn</i> 505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>Sn</i> 796.46	
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>Sn</i> 120.97	
1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66	
1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82	
1	DOOR HINGE UPPER RH	\$	<i>N</i> 274.50	}
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55	
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06	
1	DOOR LOCK REAR RH	\$	<i>N</i> 908.75	
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i> 1,483.40	}
	<i>By Insurer R11</i>		<i>N</i> 783.83 ✓	
		\$	<b>12,902.88</b>	
		10% \$	<b>1,290.29</b>	
		\$	<b>11,612.59</b>	

**Specical Nett**

1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>nn</i> 80.00 X
1	FRONT DOOR STICKER 'Chassis'	\$	<i>nn</i> 50.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1804-025

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 628M

**TOTAL \$ 130.00****TOTAL PARTS \$ 11,742.59****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,450.00 <i>2001</i>
Putty and spray painting of the affected portion.	\$	2,200.00 <i>2201</i>
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>~</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>~</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>~</i> 170.00 <i>X</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>~</i> 380.00 <i>X</i>

**TOTAL \$ 6,140.00****Over All Total \$ 17,882.59***18,588.04*

**PART BY PART (REPAIR DAY)**

LKK Auto Care Centre  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*7 DAYS  
2 days*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD			Ref : CS/TP18006938/Kvbn2	
NO.2 ANG MO KIO STREET 63SINGAPORE 569111			Date : 18-04-2018	
			Code : TP378	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	Veh. Inspected		SHF 628M	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		13/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC278275	Colour	METALLIC WHITE / RED	
Odometer	734329	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	6 mm	
L/H Rear Tyre	215/60 R16	GITI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/04/2018	Inspection Date	13/04/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 628M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR CHECK BOLT	SERVICEABLE	22.69	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH/RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	FRT FENDER RH	BENT	783.83	783.83
	LESS 10% DISCOUNT		-1,368.66	-78.38
			12,318.04	705.45
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER "CHASSIS" (SN)	NOT NECESSARY	50.00	-
			130.00	-

Report Ref No. CS/TP18006938/Kvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK FRT RH,DOOR CATCH FRT RH,DOOR PANEL REAR RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH AND DOOR LOCK REAR RH.		2,450.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	220.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			6,140.00	450.00
	<b>GRAND TOTAL</b>		<b>18,588.04</b>	<b>1,155.45</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>900.00</b>

Report Ref No. CS/TP18006938/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.