

(08/11/13)

Surveyor: PoonREF: NIS/INC18006947/Rvb

22920

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMB1515at Workshop m/s SMRT

of _____

Insured: SHK 454HPolicy No. 5092649070 140717 - 260718Claims No. MT/0985497-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Survey by 11am

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMB1515K Yr Regn: 2014 / GCTType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MAN NL320P CA22 C.C. 10518Colour MMTI A/C: Insured / Std / NI / NASp. Reading 289487 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA 22224E7002296Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 275/70R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mmD.O.A. 69/07/18D.O.I. 13/04/18Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/5/18 1515K - NA/INC18006947/r3

DA: 090318

SHK 454H - NIS/INC17012705/mibbe2

DA: 270617

18/5/18 Rasul confirmed LS \$2000 (Red 1117.70, 369)

RECEIVED 21 MAY 2018

21/5/2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 21/5 - typistDays Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 2000

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006947/R1vb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 16-04-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGK 454H	Veh. Inspected	SMB 1515K
Policy No.	5092649070	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/04/2018	Inspection Date	13/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0939315-003	SMRT BUSES LTD	SMB 1472A	SKJ 7179P	29/03/2017
2	MT/0995090-001	SMRT BUSES LTD	SMB 342Z	PC 8808D	14/09/2017
3	MT/0980389-002	SMRT BUSES LTD	SMB 5893S	PA 4137T	26/01/2018
4	MT/0939257-002	SMRT BUSES LTD	SMB 1582R	PA 8425K	25/03/2017
5	MT/0987666-002	SMRT BUSES LTD	SMB 1484R	SHB 8685R	27/2/2018
6	MT/0990787-002	SMRT BUSES LTD	SMB 1473Y	SIK 5147B	16/4/2018
7	MT/0985497-002	SMRT BUSES LTD	SMB 1515K	SGK454H	9/3/2018
8	MT/0989067-002	SMRT BUSES LTD	SMB 61J	SIH 4630U	2/4/2018
9	MT/0991323-002	SMRT BUSES LTD	SG 1721J	EN 59Z	20/4/2018

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5092649070	J-STEVE ENTERPRISE	53366533K	GPC	Third Party	SGK454H	SGK454H	14/07/2017	26/07/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 15:36
Date Of Accident	09/03/2018 19:05
Exact Location Of Accident	UPPER BUKIT TIMAH RD BEFORE BS:43021
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1515K
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64823888

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	BUS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D-17087563MFBP
Cover Note Number	

Driver

Name of Driver	TAN KENG TEE
NRIC No	S1255225D
Date Of Birth	18/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	20/10/1979
Driving Experience	38 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address NOADDRESS
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 40

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Bus had reduced speed while approaching to the bus stop (BS: 43021- aft Old Jurong Rd) of Upper Bukit Timah Rd. A Vehicle (Uber – SGK454H) from the opposition direction suddenly make an illegal "U" turn thus collided onto the front right side bumper of my bus. For the alleged accident nobody was injured.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGK454H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver MR CHU
 NRIC/Passport Number
 Contact Number 82286617
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

Bus 03/18/1017

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN




pls refer to PRT report

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SMB1515K
Vehicle Type:	H20 - Public Transport Bus/Coach/Minibus
Vehicle Attachment 1:	Air-Conditioned
Vehicle Scheme:	OmniBus (SMRT - ARF-exempted)
Vehicle Make:	MAN
Vehicle Model:	NL 320F (A22) 11L AUTO ABS TURBO
Chassis No.:	WMAA22ZZ4E7002296
Propellant:	Diesel
Engine No.:	50338342753841
Engine Capacity:	10518 cc
Maximum Power Output:	-
Maximum Laden Weight:	18000 kg
Unladen Weight:	11260 kg
Year Of Manufacture:	2014
Original Registration Date:	27 Oct 2014
Lifespan Expiry Date:	26 Oct 2031
Road Tax Expiry Date:	26 Apr 2018
Inspection Due Date:	26 Oct 2018
Intended Transfer Date:	16 Apr 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 26 Apr 2018. You may renew the road tax from 27 Jan 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 26 Apr 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 27 Apr 2018 to 26 Oct 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	850.00	-	850.00
Total Amount Payable:			875.00

Amount Payable (From 27 Apr 2018 to 26 Apr 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	1,700.00	-	1,700.00
Total Amount Payable:			1,725.00

You may print this page for reference.


OK

Print

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1515K
 Ref. No : BUS/03/18/1017
 Reg. Date : 13/03/2018
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : Tan Keng Tee
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 09/03/2018 07:05:00 PM
 Accident Reported Date / Time : 12/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : IDAC
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SMB1515K - FRONT RIGHT BUMPER CRACKED
 SGK454H (TP) - INSURED WITH NTUC
 Prepared Date : 13/03/2018 09:18:00 AM



Chassis No :

Work Shop :

Mileage :

0

Repair Completed Date / Time :

Summary of Repair Estimates

Adjusted by Surveyor, if applicable

Total Labour Charges	1,060.00	0.00
Total Spray Painting Charges	708.00	0.00
Total Material Charges	952.23	952.23
Other Charges	0.00	0.00
TOTAL	2,720.23	0.00
Lum Sum Total	0.00	0.00
No. of Repair Days	2	2 days - p/p

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

12/04/2018 06:51:32 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 12/04/2018 06:51:32 PM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Quotation Date :

Invoice Amount :

Invoice No :

Invoice Date :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	800
Total Labour	1,060.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	708.00	600
Total Spray Painting & Panel Beating	708.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PIXEL STENCIL RHS FRT	150.00	150
Total Other Costs	150.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
F01001-CW266		6010152	FRONT HEADLAMP PANEL RH	1	974.70	10.00	877.23	Replace	Replace (PA)	No
	COMMO	4005301	SMRT STICKER (S)	1	75.00	0.00	75.00	Replace	Replace (PA)	No
TOTAL MATERIALS										
								952.23	952.23	
TOTAL MATERIALS(Discounted)										
								952.23	952.23	


Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1515K
Ref. No : BUS/03/18/1017
Reg. Date : 27/10/2014
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Tan Keng Tee
Type of Accident : SIDE SWIPE
Date / Time of Accident : 09/03/2018 07:05:00 PM
Accident Reported Date / Time : 12/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095540
Special Instruction to ARC, if any :
SMB1515K - FRONT RIGHT BUMPER CRACKED
SGK454H (TP) - INSURED WITH NTUC
Prepared Date : 13/03/2018 09:18:00 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA22ZZ4E7002296

Mileage

0

Work Shop :

Repair Completed Date / Time :

01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	800.00
Total Spray Painting Charges	: 708.00	600.00
Total Material Charges	: 761.78	761.78
Other Charges	: 150.00	-150.00
TOTAL	: 2,679.78 3117.70	2,011.78
Lum Sum Total	: 2,700.00	2,000.00
No. of Repair Days	: 2.00	2.00
Prepared / Adjusted By	:	RASUL - LKK
Arc / Surveyor Sing Off Date	: 12/04/2018 06:51:32 PM	13/05/2018 05:30:33 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/04/2018 06:51:32 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	800.00
Total Labour	1,060.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	708.00	600.00
Total Spray Painting & Panel Beating	708.00	600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PIXEL STENCIL RHS FRT	150.00	150.00 <i>rec</i>
Lump Sum Adjustment by Surveyor	150.00	-300.00
Total Other Costs	300.00	-150.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
F01001-CW266		6010152	FRONT HEADLAMP PANEL RH	1	974.70	10.00	877.23	Replace	Replace <i>CRA</i> ✓	No
	COMMO N	4005301	SMRT STICKER (S)	1	75.00	0.00	75.00	Replace	Replace <i>AC</i> ✓	No
TOTAL MATERIALS							952.23	952.23		
TOTAL MATERIALS(Discounted)							761.78	761.78		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

952.23
 1550.00

 2502.23
 206
 2001.78
 41-2000

 2days
 5

2967.70.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006947/R1vbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 24-05-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGK 454H	Veh. Inspected	SMB 1515K
Policy No.	5092649070	Coverage (\$)	0.00
Claim No.	MT/0985497-002	Excess (\$)	0.00
Assign From		Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model	MAN NL 320F (A22)	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WMAA22ZZ4E7002296	Colour	MULTI
Odometer	289487	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	8 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/03/2018	Inspection Date	13/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1515K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP PANEL RH	CRACKED	974.70	974.70
	LESS 10% DISCOUNT		-	-97.47
			974.70	877.23
<u>SPECIAL NETT ITEMS</u>				
1	SMRT STICKER (S)(SN)	NECESSARY	75.00	75.00
1	PIXEL STENCIL RHS FRT (SN)	NECESSARY	150.00	150.00
			225.00	225.00
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		1,060.00	800.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		708.00	600.00
			1,768.00	1,400.00
GRAND TOTAL			2,967.70	2,502.23
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,000.00

Report Ref No. NS/INC18006947/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.