

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

120

(560 x 2

days)

Loss of Income (LOI):

S\$

-

(\$ x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.x x

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

3,064.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3,064.50

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

RECEIVED 6 JUN 2018

6/6/18

08/11/13 wel

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SKNF33Jat Workshop m/s Tan Lian

of _____

Insured: SLR1947S

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

CA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3.Val.: Yes or No

CA / REV / REP. / 24 HRS

3775C

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKNF33J Yr Ragn: 2, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: BMW 318 cc 1598Colour: white A/C: Insured / Std / NI / NASp. Reading: 66908 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA3A16010N536883

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Brim / STD A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 14/4/8

Survey held at _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 16/4/8

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have video of fieldL/S \$2,750R (\$2,361.92 / 46%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

ALGAsia Insured's Veh No : SLR6947S

Date of Accident : 14 April 2018



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Ng Inn Khiam (Huang Yinqian)

Date : 18 April 2018

Estimate To Repair SKN833J - B.M.W 316I 1.6 AT D/AB 4DR ABSHD

Chassis No : WBA3A16010NS36583

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	front bumper	\$ 982.80
02	1 pc	front bumper carrier	\$ 440.00
03	1 pc	front bumper emblem badge	\$ 76.00
04	2 ps	front bumper chrome grille @ \$98.50	\$ 197.00
05	1 pc	front bumper tow cover	\$ 24.00
06	1 pc	front bumper centre inner frame	\$ 95.00
07	1 pc	front bumper side inner frame	\$ 110.00
08	2 ps	front bumper side retainer @ \$35.00	\$ 70.00
09	1 pc	front bumper energy foam centre	\$ 60.00
10	1 pc	front bumper energy form side	\$ 45.00
11	2 ps	front bumper carrier stay @ \$45.00	\$ 90.00
12	1 pc	front bumper licence garnish	\$ 90.00
		Less 10 %	\$ 2,279.80 \$ 227.98 \$ 2,051.82
		SPECIAL NETT ITEMS	
13	1 pc	front licence plate	\$ 60.00 \$ 60.00
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 60.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 550.00
03		Putty and spray painting of the affected portion.	\$ 600.00 \$ 1,210.00
		Total	\$ 3,321.82

3296.30
2966.67
3476.67
2781.33

LHK Auto Consultants Pte Ltd notify the Repairer of the following:

- To resurvey before and after spray painting
- To dispute the repair cost during resurvey
- Parts replaced must be subject to confirmation
- Third party liability on "without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

7-3296.3
102
2966.67
3476.67

Not Approved
1/s 2750/2
2018
16/4/18
The photo attached

confirmed
18.04.2018 @ 1300

1307.3

40

20
200
250



Date of Accident : 14 April 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 18 April 2018

Chassis No : WBA3A16010NS36583

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> o/s headlamp <i>Che</i>	\$ 1,989.00
			\$ 1,989.00
		Less 10 %	\$ 198.90
			\$ 1,790.10
		Total	\$ 1,790.10

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3775C

Vehicle Details

Vehicle No.: SKN833J
Vehicle to be Exported: No
Intended De-registration Date: 16 Apr 2018
Vehicle Make: B.M.W.
Vehicle Model: 316i 1.6 AT D/AB 4DR ABS HID
Primary Colour: White
Manufacturing Year: 2013
Engine No.: A907J611N13B16A
Chassis No.: WBA3A16010NS36583
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$35,606.00
Original Registration Date: 27 Feb 2014
First Registration Date: 27 Feb 2014
Transfer Count: 0
Actual ARF Paid: \$31,849.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Feb 2024
PARF Rebate Amount: \$23,886.00

Intended COE Rebate Details

COE Expiry Date: 26 Feb 2024
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$77,501.00
COE Rebate Amount: \$43,380.00
Total Rebate Amount: \$67,266.00

The information contained herein is correct as at 16 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3775C
Vehicle Details	
Vehicle No.:	SKN833J
Vehicle to be Exported:	No
Intended De-registration Date:	16 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	316I 1.6 AT D/AB 4DR ABS HID
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	A907J611N13B16A
Chassis No.:	WBA3A16010NS36583
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$35,606.00
Original Registration Date:	27 Feb 2014
First Registration Date:	27 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$31,849.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2024
PARF Rebate Amount:	\$23,886.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$77,501.00
COE Rebate Amount:	\$43,380.00
Total Rebate Amount:	\$67,266.00

The information contained herein is correct as at 16 Apr 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP014042018

Date 17/05/18

Your Ref SLR6947S

WITHOUT PREJUDICE

Claims Department - Executive in charge _____

ATG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SKN833J / SLR6947S on 14.04.18

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report / _____ copies of photographs _____

☒ Original Tax-invoice number TP0518 / 031

☐ Original rental invoice number _____

☐ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance _____

☒ Vehicle search result

☒ Authorization to act

☐ _____

*Survey under insurance instruction / Independent surveyor / No survey.

LKK

a)	Cost of repair (inclusive GST)	\$ <u>2,941.50</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>2.00</u>
d)	Loss of hire / use / rental / earnings / rental fees	\$ <u>200.00</u>
e)	Scene photographs	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	_____	\$ _____
	Total	\$ <u>3,144.50</u> =====

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlmotor.com.sg / sam@tlmotor.com.sg / johnson.chua@tlmotor.com.sg

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 20 April 2018 3:08 PM
To: 'siewpek@yahoo.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLR 6947S AND SKN 833J ON 14/04/2018
Attachments: TP video - SKN833J.MP4

Our ref: CC6/AIG18006963/Uja3

WONG SIEW PEK MAGDALENE

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SLR 6947S AND SKN 833J ON 14/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ng Ian Khiam ("the third party claimant")
of 26 Hillside Drive #04-04 Singapore 548945 (address),
owner of SKN 833J (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKN 833J that was
damaged pursuant to the accident which occurred on 14/04/18 (date) along
Sentosa Cove Carpark (location)
involving vehicle no/s SLR 69475 ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 16 day of April (month) 20 18 (year)

"The contents of this document apply to vehicle
damages only. All personal injuries and
damages arising therefrom are excluded from
the ambit and application of this document."


Signed by "the third party claimant"


Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,942.50 (Repair Cost), S\$120.00 (Loss of Use) S\$2.00 (Disbursement) for vehicle no. SKN 833J that was damaged pursuant to the accident which occurred on 14/04/2018 (date) along CAR PARK AT SENTOSA (location) involving vehicle no/s SLR 6947S. This is pursuant to the inspection conducted on 16/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NG INN KHIAM (HUANG YINQIAN) ("the third party claimant") of vehicle no. SKN 833J make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKN 833J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 5th (day) of June (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0518/031

(Please quote our reference number TP014042018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Ng Inn Khiam (Huang Yinqian)

Date: 11/05/2018

Vehicle No: SKN 833J
Model: B.M.W. 316I A

Description	Amount
Claim number: MT/0990391 To lump sum repair as recommended by surveyor.	\$2,750.00

Sub Total	\$2,750.00
Add 7% GST	\$192.50
Total	\$2,942.50

Tan Lim Motor Pte Ltd



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE

RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-056512

Date of Request: 16/04/2018

Your Ref No: Online Purchase

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216

Dear Sir/Madam,

Enquiry Date 16/04/2018
Enquiry By Sharon Ow Lee Yong
TP Vehicle No. SLR6947S
Accident Date 14/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLR6947S	AIG Asia Pacific Insurance Pte. Ltd.	24/08/2017-23/08/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE

RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-056512

Date of Request: 16/04/2018

Your Ref No: Online Purchase

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216

Dear Sir/Madam,

Enquiry Date 16/04/2018
Enquiry By Sharon Ow Lee Yong
TP Vehicle No. SLR6947S
Accident Date 14/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2018 Edit Reg		16 Apr 2018 00:00 Edit Adj Rpt	\$2,750.00 Edit Estimates	\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	WONG SIEW PEK MAGDALENE, ID: S7218142E								
Main Claimant:	NG INN KHAM (HUANG YINQIAN), ID: S7513775C								
Vehicle Reg. No.:	SKN833J	Date of Loss:	14/04/2018 00:00 - :59 [49 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1046580626SG	Policy/Cover Note No.:	1700041773						
Vehicle Reg. No. (Insured):	SLR6947S	Policy No. (Claimant):	5088173312-01						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 25/04/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (17/04/2018): No TP GIA Report 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN833J (1046580626SG)
[SLR6947S]
TP
NG INN KHIAM (HUANG YINQIAN)
Apr 14 2018 12:00AM
[WONG SIEW PEK MAGDALENE]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print					
1	17/04/18 16:29		TP video - SKN833J										Load MP4							
Letters/Correspondences															1 per page					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print					
1	(Draft)		Third Party Express Settlement - Payment Breakdown										Edit							
Assessment Reports															1 per page					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print					
1	17/04/18 10:48		Accident Statement From: SC - Reg. No: SLR6947S, Claimant: WONG SIEW PEK MAGDALENE										Load HTM							
Photos/Images															3 per page					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print					
1	16/04/18 21:10		General View										Load JPG							
2	16/04/18 21:10		General View										Load JPG							
3	16/04/18 21:10		General View										Load JPG							
4	16/04/18 21:10		General View										Load JPG							
5	16/04/18 21:10		General View										Load JPG							
6	16/04/18 21:10		General View										Load JPG							
7	16/04/18 21:10		General View										Load JPG							
8	16/04/18 21:10		General View										Load JPG							
9	16/04/18 21:10		General View										Load JPG							
10	16/04/18 21:10		General View										Load JPG							
11	16/04/18 21:10		General View										Load JPG							
12	16/04/18 21:10		General View										Load JPG							
13	16/04/18 21:10		General View										Load JPG							
14	16/04/18 21:10		General View										Load JPG							
15	16/04/18 21:10		General View										Load JPG							
16	16/04/18 21:10		General View										Load JPG							
17	16/04/18 21:10		General View										Load JPG							
18	16/04/18 21:10		General View										Load JPG							
19	16/04/18 21:10		General View										Load JPG							
20	16/04/18 21:10		General View										Load JPG							
21	16/04/18 21:10		General View										Load JPG							
22	16/04/18 21:10		General View										Load JPG							
23	16/04/18 21:10		General View										Load JPG							
24	16/04/18 21:10		General View										Load JPG							
25	16/04/18 21:10		General View										Load JPG							
26	16/04/18 21:10		General View										Load JPG							
27	16/04/18 21:10		General View										Load JPG							

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (5G)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
29	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
30	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
31	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
32	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
33	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
34	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
35	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
36	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
37	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
38	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
39	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
40	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
41	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
42	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
43	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
44	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
45	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
46	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
47	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
48	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
49	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
50	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
51	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
52	16/04/18 21:10	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:27	TP GIA REPORT	Load PDF	
2	06/06/18 10:03	LETTER TO INSURED	Load PDF	
3	12/06/18 10:30	WORKSHOP INVOICE	Load PDF	
4	12/06/18 10:30	AUTHORISATION TO ACT FORM	Load PDF	
5	12/06/18 10:30	Release Voucher	Load PDF	
6	12/06/18 10:30	GIA SEARCH	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR6947S (Insd veh)	Model:	BMW 316I 1.6 AT D/AB 4DR
	SKN833J (TP veh)		ABS HID (A)
Date of Accident:	14/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,469.75
Final Repair Cost	:	\$	2,942.50
Loss of Use	:	\$	120.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,064.50

2.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 3,064.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

12 Jun
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18006963/UJA3Q2

Date: 12/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700041773
Claimant Vehicle No : SKN833J **Insured Vehicle No :** SLR6947S
 Date of Loss: 14/04/2018 Nature of Claim: TP Claim No: 1046580626SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN833J**
 Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A907J611N13B16A
 Reg. Date: 27/02/2014 (Man. Year: 2013) Chassis No: WBA3A16010NS36583
 Colour: White Odometer: 86908 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,901.92	3,006.67	895.25	22.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	470.00	740.00	61.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,111.92	3,476.67	1,635.25	31.99
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	5,111.92	2,750.00	2,361.92	46.20
+ GST 7.00/7.00% (S\$)	357.83	192.50	165.33	46.20
Nett Amount (S\$)	5,469.75	2,942.50	2,527.25	46.20
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,064.50		

INSPECTION

Date of Assignment: 16/04/2018
 Date Inspected: 16/04/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	982.80 FL	*982.80 FL
2	1		*FRONT BUMPER CARRIER	Repair	440.00 FL	*- FL
3	1		*FRONT BUMPER EMBLEM BADGE	Necessary	76.00 FL	*76.00 FL
4	1		*FRONT BUMPER CHROME GRILLE	O/S Cracked	197.00 FL	*98.50 FL
5	1		*FRONT BUMPER TOW COVER	Repair	24.00 FL	*- FL
6	1		*FRONT BUMPER CENTRE INNER FRAME	Not Necessary	95.00 FL	*- FL
7	1		*FRONT BUMPER SIDE INNER FRAME	Not Necessary	110.00 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	70.00 FL	*- FL
9	1		*FRONT BUMPER ENERGY FOAM CENTRE	Torn	60.00 FL	*60.00 FL
10	1		*FRONT BUMPER ENERGY FORM SIDE	Not Necessary	45.00 FL	*- FL
11	2		*FRONT BUMPER CARRIER STAY	Not Necessary	90.00 FL	*- FL
12	1		*FRONT BUMPER LICENCE GARNISH	Deformed	90.00 FL	*90.00 FL
13	1		*FRONT LICENCE PLATE	Bent	60.00 FS	*40.00 FS
14	1		*O/S HEADLAMP	Cracked	1,989.00 FL	*1,989.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,328.80	3,336.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	426.88	329.63
Total Parts (\$\$)	3,901.92	3,006.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	550.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	600.00	250.00
Gross Labour Cost (\$\$)			1,210.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >