## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO: SHA 1285C

DATE 12/4/2018 15:14

MAKE

Qty	Parts Description/ Labour	Type	Unit Price	A	mount
	Rear Bumper / What	J.F.		\$	603.60
	Rear Bumper Clips /			S	22.00
	Rear Bumper Clips 7			1 3	22.00
	SUB TOTAL			\$	625.60
	LESS 20%			\$	125.12
	DISCOUNTED TOTAL			\$	500.48
	Labour Charge				200
	Panel Beating			\$	250.0
	Spray Painting Charge			\$	250.0
	Wiring Charge			\$	50.0
	Towing Fees			\$	60.0
	R/Refix Reverse Sensor			\$	120.0
	TOTAL LABOUR			\$	730.00
	ESTIMATE TOTAL			\$	1,230.48
	Kali (UCK)				
	Kahi Mil				
	13/4/8 1010hs 2 Ports				
	1/ 3/4/0 10/6/25				
	13/4/2				
	11 12				
	2/1/2	Г	LVVA		
	Betore Point y th		LKK Auto Consultants	hence n	otify
	1/0		To resurvey helovalette	wing:	
	11 011 16				
	O. Lose Print y		Parts prices are subject to c	orfirmatio	on
	But	- 1	No illegal months at any	ithout Pn	ejudice" basi
		1	Supplementa	iliwed.	
			is subject to to a approval fro	m Insura	nce Compan
	STATE OF STATE OF STATE OF STATE	A	cknowledged by Repairer		Pall
		8	gnature:		
		D	ate:		
	This is an initial and the form of the control of t		List. The Co. 1		
	This is an initial estimate based on a visual inspection of th	e above ve	micle. The final repair	quanti	un Will

## COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline +65 6383 6280 Facsimile +65 6280 9755

Service Centres

205 Braddell Road Singapore 579701

45 Pandan Road Singapore 809286

75 Sungei Kadut Way Singapore 728791

24 Senoko Loop Singapore 758156





CUSTOME

## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

	C	202111170				
Job Requisition						
1. Date: 12/4/18 Time Received: 0830	3. Vehicle Type:	4. Type of Towing: Normal Tow				
2. New SPARK Kakis	Private Taxi (CTPL/CCPL)	King Dolly				
Name of Customer : MS SiM KIM Khoon	Fleet	Flat Bed				
Contact No. : 93692253	STK (Boon Lay)	Crane-up				
Vehicle No. : 51+ 6 12856	5. Nature of Service:	6. Parts Replaced/Remarks:				
140	Jumpstart	o. Paris rieplacourriemano.				
Make/Model/Colour: 1 40	Recovery					
Email :	Change Tyre / Battery					
7. Location:	8. Vehicle To	ow - In Workshop:				
109 Bishan St 12		ky Exhaust				
9. Preferred Workshop:		heating Steering Faulty				
Braddell Loyang Pandan Brake Faulty Alternator Fault						
Sirriving Suriger Radut						
	Senoko					
Others:	ricks	TI TAN				
10. Odometer Reading :	11. Radio / CD Player	FRONT				
Fuel Level : F 1/4 1/2 3/4 E						
	☐ Not tested					
Job Attended		THE PROPERTY OF THE PROPERTY O				
12. Tow Truck / Recovery Van : VRS QA GA	O _ TZ _ YISHUN _ OTHER					
Name of Driver : Jagan	TOWING					
VI-ICCOIL		PIEAR PLANT				
		#: Cracked X: Dented				
Time Dispatch : / : Scatched O: Mis						
Time of Arrival : 6900		·				
Time Completed : 0930		Signature of Customer				
Cash Invoice Details (if applicable)		THE PART OF THE PA				
13. Cash Invoice No. :						
To. Oddi invoice No.		2				
Customer Acknowledgement		Christian Control of the Control of				
<ul> <li>I have been advised to remove all valuable items in my vehicle, includ cash cards, spectacles, pen, etc.</li> </ul>	ing Global Positioning System (GPS), audio o	compact disk, thumbdrive, carpark coupons,				
b. I understand that any items left behind are at my own risk and SPARI						
c. Surcharge: Towing fee will be levied if the customer decides neither to	o tow nor proceed with the repairs in SPARK	Car Calle™.				
1. /		LIMA -				
12/4/18 090	0					
Date	Sig	gnature of Customer				
14. WORKSHOP						
Name of Attending Staff/Guard Date & Time of	f Arrival	re of Attending Staff/Guard				
Name of Attending Staff/Guard Date & Time of	olgriatui olgriatui	o or Attorioning Stanzauaru				