22/03/2002		PEE COA	1,00,00	1607 /6	don			
SULVEYOR				06987/G		al Instruction:		
-	F			Office)				
From (Person):	Eric Woo	of		LPC	D	ate/Time:	19009018	4-08pm
Estimated Cost				Bill to:				
OD /TD WS	TP RES / OD)	RES/EVA/IN	VIMVIC	S				
	icle No:	CB 684	2B		Insured:	MES	6694X	
at Workshop m	/s	Lian Heng	Painter		Tel:	6453 5	7719	
of		160 Sin Mind	DIM	#06-10				
Policy No:				Claim No:	18/18/	8 / NPUS	150531	
Sum Insured:_				Excess:				
Make of Veh:				-	D	O.A.	81004070	
(Client's Record)			17.1	14.2018 C	after 9-30	um .		
CA / REV /	REP. / REV 24	HRS WP				H.O.D. Endor	semple	
Date/Time: 16	-042018 4-15	om Person C	ontacted: _	Henry	. Vel	icle IN/6	UT	
Date/Time	Action/Instruction							
	CB 1874B-		z minerte					
	27M PEJAX							
	ANTI- DOINTY				,			
	Districted !!	would -	On Lie	12 12 11	1.			
	1/190000	vesurvey	119	10 47 10	<i>K</i>			
14	After p	vesurvey-	13/18 V	y X900				
31/5/18	Submit							

Catherine Chong (LKK Auto)

From:

ERIC WOO JUN KIAT <ericwoo@lonpac.com>

Sent:

Monday, 16 April, 2018 4:08 PM

To:

Serene Tan

Cc:

MT_Claim_SG; assignments@lkkauto.com

Subject:

RE: Our Ref: 18/18/18/VP05/020531 Your Ref: MN/IG/L1/1812343/st Accident

involving SJM6694X & CB6824B along Cypress Ave on 9/4/18

Attachments:

16042018160533.pdf

WITHOUT PREJUDICE SAVE AS TO COST

Dear Serene,

Thank you for your list of surveyors.

We regret we are not agreeable to your panel of surveyor as listed.

We shall be assigning to LKK Auto Consultants Pte Ltd to conduct the survey on your client's vehicle No: CB 6824B.

Dear Catherine / Nivitha,

FYA.

Thank you.

Best Regards, Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Serene Tan [mailto:serene.tan@mneduco.com.sq]

Sent: Monday, 16 April, 2018 3:37 PM

To: ERIC WOO JUN KIAT Cc: MT_Claim_SG

Subject: RE: Our Ref: 18/18/18/VP05/020531 Your Ref: MN/IG/L1/1812343/st Accident involving SJM6694X &

CB6824B along Cypress Ave on 9/4/18

Our Ref: MN.IG.L1.1812343.st

WITHOUT PREJUDICE SAVE AS TO COSTS

NOTICE TO INSURERS <u>OBJECTING</u> TO THE LIST OF MOTOR SURVEYORS PROVIDED WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)

Dear Sir/Mdm,

1. We refer to your email/attachment below.

- 2. We are instructed by our client, KHL TRANSPORTATION CO PRIVATE LIMITED, the claimant and/or Lian Heng Painter Company, the motor workshop for CB 6842B that they are <u>not</u> agreeable to the appointment of the motor surveyors as stated in your said email.
 - In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016), we propose
 to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey
 ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1.	NICKY SEAH	6.	ANDREW HOW
_	(Absolute Appraisal Services)		(Prominent Appraiser Services)
2.	MICHAEL YAP TECK CHYE	7.	NG KONG BENG PATRICK
	(MC-COY Appraiser Pte Ltd)		(Carlink Consultancy)
3.	DIXON YEO	8.	ANANDA KUMAR BISWAS S/O B N BISWAS
	(Treasure Appraisal Services)	72.11	(United Appraisal & Management Pte Ltd)
4.	LOI BOON JUAN	9.	DENNIS YAP TECK WEE
	(PAR Automotive Consultancy)	14.55	(PAL's Appraiser Pte Ltd)
5.	AMAS ONG	10.	ANDY YAP TECK LEE
	(AEON Auto Consultants LLP)		(LCW Appraiser Pte Ltd)

Please let us know within two (2) working days whether you agree to the appointment of any of
the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint
Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)
Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:

11 Sin Ming Road #B2-09 (Unit 2), Thomson V Two Singapore 575629

Tel: 6509-8480 / 6509-8481

Fax: 6509-8482

Email: serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

From: ERIC WOO JUN KIAT [mailto:ericwoo@lonpac.com]

Sent: Monday, April 16, 2018 3:02 PM

To: Igene Lim < igene.lim@mneduco.com.sg>; Serene Tan < serene.tan@mneduco.com.sg>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Our Ref: 18/18/18/VP05/020531 Your Ref: MN/IG/L1/1812343/st Accident involving SJM6694X & CB6824B

along Cypress Ave on 9/4/18

WITHOUT PREJUDICE SAVE AS TO COST

Dear Sir/Madam,

We refer to your fax of 16 April 2018.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards, Eric Woo Claims Executive | Lonpac Insurance Bhd 300 Beach Road, #17-04/07 The Concourse, Singapore 199555 Tel: (65) 6279 9253 | Fax: (65) 6296 3767 M9NH18047531/ 9 & H Motor Pte Ltd - Sin Ming ENTRY DATE & TIME: 10/04/2018 11:14 SUBMITTED BY: Wong Kee Nyuk

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or witholding of material facts may allow insurance companies to repudiete policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the erchiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report

10/04/2018 11:14 09/04/2018 12:25

Date Of Accident

Exact Location Of Accident

ALONG OLD HOLLAND RD

Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number

CB6842B

SINGAPORE

Insured/Policyholder

Name Of Registered Owner

KHL TRANSPORT CO. PRIVATE LIMITED

Co Reg No

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-96221226

Alternative Phone No

OFFICE-96221226

Vehicle Particulars

Manufacturer

TOYOTA

Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle? If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5097352116

Cover Note Number

Driver

Name of Driver

ROSMAN BIN ANWAR

NRIC No

S68074471

Date Of Birth Occupation

17/03/1968

Date Of Driving Pass

OUTDOOR

10/05/1988

Driving Experience

29 YEARS AND 10 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-96221226

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

6

Number of Passengers (Including Driver)

Passenger 1

: PASSENGER NAME: : FEMALE

GENDER:

Passenger 2 NAME: : PASSENGER : FEMALE

GENDER:

: MALE GENDER:

Passenger 4

Passenger 3

NAME:

NAME:

: PASSENGER

: PASSENGER

GENDER:

: MALE

Passenger 5

NAME:

: PASSENGER

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yas, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?

YES NO

Was there any video captured by Car Camera?

Was there any audio recorded?

NO DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJM6694X

Vehicle Make/Model/Colour

Page 2 of 13

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR

93884231



Policyholde. Date & Time

Driver's Signature (if driver is not the policyholder)

- Name: NRIC/FIN NO.

C007C00.4

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful micrepresentation or withholding of material facts may allow insurance companies to repudiate policy Hability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Pelice for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consept that;

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, uso, disclose and/or process my personal data/personal information set out in this [form] and any other personal information. provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s), who have insured volicie(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (by) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the Pursones"
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, low enforcement and government agancies as reasonably required for the purposes stated, or
 - (iii) for complying with requirements under any regulations; laws or court orders.

Policyholder

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel Name:

NRIC/FIN NO.

CARNE SENDERS TO THE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/LPC18006987/Gqbe2 LONPAC INSURANCE BHD 300 BEACH ROAD Date: 04-06-2018 #17-04/07 THE CONCOURSESINGAPORE 199555 Code: LPC2 Policy Particulars :- (THIRD PARTY CLAIM) SJM 6694X CB 6842B Insured Veh. Veh. Inspected Policy No. Coverage (\$) 0.00 18/18/18/VP05/020531 0.00 Claim No. Excess (\$) Assign From **ERIC WOO Assign Date** 16/04/2018 Vehicle Particulars & Condition Make & Model TOYOTA HIACE 0 C.C HIDDEN Engine No. Year of Reg. JTFST22P800012622 Chassis No. SILVER Colour 329165 KM IN ORDER Odometer Steering IN ORDER NII **Brakes** Modification GOOD General **Conditions of Tyres** 3. Size Balance 195 R15 MICHELIN R/H Front Tyre 6 mm 195 R15 MICHELIN L/H Front Tyre 6 mm 195 R15 MICHELIN R/H Rear Tyre 6 mm 195 R15 MICHELIN L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 09/04/2018 **Accident Date** Inspect Date / Time 17/04/2018 (03:30 AM) Survey held at 160 SIN MING DRIVE #06-10 LIAN HENG PAINTER CO. Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/LPC18006987/Gqbe2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A
Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.