

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

: SGQ5467G

Service and Body Repair

Tel: +65 6841 3838

Customer

Registration No

Owner's Name

Ins Policy No.

Date of Accident

Chassis No

Model

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT18001535

Page

1

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

8 SHENTON WAY

: MRHFC5650GT000505

: CIVIC 1.6 VTI YM2016

: GRACE LIM SWEN CHOO (LIN

#27-01 AXA TOWER **SINGAPORE**

Customer No.

Qty

)

Date

; 13. Apr 2018 : WZA006

068811

: AXA INSURANCE S'PORE PTE LTD

Svc Advisor

: PATRICK MOK LIP KAY

Engine No

: R16B21600681

Date | Time

: 13. Apr 2018 4:14:33 PM

Amount

Surveyor Name

Survey Date

Authorisation Date

Unit Price Disc %

0% GST **Amount** Amount incld GST

ltem Description TP DIRECT SETTLEMENT (J/NO: OWNER: GRACE LIM SWEN CHOO OWNER INSURER: LIBERTY INSURANCE ACC DATE: 13/04/2018 SURVEYED BY:

DATE:

| | REF NO: | | | | | | |
|--|---|------------------|--|----------------------------------|---|---|---|
| | TP INSURER: AXA INSURANCE | | | | | | |
| | TP VEH: SLB7776X | | | | | | |
| | | | | | | | |
| BOSUN | SUNDRIES | 1 | 50.00 | | 50.00 | 3.50 | 53.50 |
| BOJSE | SEALANT FOR REAR END PANEL | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BKRP02M | CUT OFF & RENEW RR PANEL. STRAIGHTEN | 1 | 2250.00 | 20 | 1800.00 | 126.00 | 1926.00 |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | 1 | 80.00 | 20 | 64.00 | 4.48 | 68.48 |
| BMI03D | REMOVE & INSTALL REAR COMPARTMENT LININGS | 1 | 225.00 | 20 | 180.00 | 12.60 | 192.60 |
| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 100.00 | 20 | 80.00 | 5.60 | 85.60 |
| BP05R | SPRAY PAINTING ON REPAIRED OR REPLACED AREA (5P) | S. ₁ | 2100.00 | 20 | 1680.00 | 117.60 | 1797.60 |
| | | | s | Sum Labor | 3934.00 | 275.38 | 4,209.38 |
| RS-4P | BUMPER SENSOR 4PCS | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| 66100-TEC-307ZZ | PANEL SETRR. | 1 | 236.00 | 35 | 153.40 | 40.74 | 40444 |
| 71500-TEC-Q00ZZ | | | | 55 | 155.40 | 10.74 | 164.14 |
| | FACE ASSYRR.BUMPER | 1 | 617.20 | 35 | 401.18 | 10.74 28.08 | 429.26 |
| 71502-TEX-Y00 | FACE ASSYRR.BUMPER GARNISHRR.BUMPER LOWER | 1 1 | | | | | |
| 71502-TEX-Y00 71503-TEA-T00 | | 140 | 617.20 | 35 | 401.18 | 28.08 | 429.26 |
| | GARNISHRR.BUMPER LOWER | 1 | 617.20 35.30 | 35 35 | 401.18 22.94 | 28.08 1.61 | 429.26 24.55 |
| 71503-TEA-T00 | GARNISHRR.BUMPER LOWER GARNISHR.RR.BUMPER SIDE | 1 | 617.20 35.30 7.60 | 35 35 35 | 401.18 22.94 4.94 | 28.08 1.61 0.35 | 429.26 24.55 5.29 |
| 71503-TEA-T00 71530-TEA-T00ZZ | GARNISHRR.BUMPER LOWER GARNISHR.RR.BUMPER SIDE BEAM COMPRR.BUMPER | 1 1 | 617.20 35.30 7.60 160.00 | 35 35 35 35 | 401.18 22.94 4.94 104.00 | 28.08 1.61 0.35 7.28 | 429.26 24.55 5.29 111.28 |
| 71503-TEA-T00 71530-TEA-T00ZZ 71593-TEA-T01 | GARNISHRR.BUMPER LOWER GARNISHR.RR.BUMPER SIDE BEAM COMPRR.BUMPER SPACERR.RR.BUMPER SIDE | 1 1 1 | 617.20 35.30 7.60 160.00 11.50 | 35 35 35 35 35 | 401.18 22.94 4.94 104.00 7.47 | 28.08 1.61 0.35 7.28 0.52 | 429.26 24.55 5.29 111.28 7.99 |
| 71503-TEA-T00 71530-TEA-T00ZZ 71593-TEA-T01 71598-TEA-T01 | GARNISHRR.BUMPER LOWER GARNISHR.RR.BUMPER SIDE BEAM COMPRR.BUMPER SPACERR.RR.BUMPER SIDE SPACERL.RR.BUMPER SIDE | 1 1 1 1 | 617.20 35.30 7.60 160.00 11.50 | 35 35 35 35 35 35 | 401.18 22.94 4.94 104.00 7.47 7.47 | 28.08 1.61 0.35 7.28 0.52 0.52 | 429.26 24.55 5.29 111.28 7.99 7.99 |



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

: AXA INSURANCE S'PORE PTE LTD

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT18001535

Page 2

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

8 SHENTON WAY

#27-01 AXA TOWER

Customer No.

: 13. Apr 2018

SINGAPORE 068811

Svc Advisor

: WZA006 : PATRICK MOK LIP KAY

Registration No

: SGQ5467G

Engine No

: R16B21600681

Chassis No

Date | Time

Date

Model

Customer

: MRHFC5650GT000505 : CIVIC 1.6 VTI YM2016

Surveyor Name

: 13. Apr 2018 4:14:33 PM

Owner's Name

: GRACE LIM SWEN CHOO (LIN

Ins Policy No.

Date of Accident

Survey Date

Authorisation Date

0% GST Amount incld GST **Amount** Amount

Survey By Date & Time Excess Status Signature

Total Amount

Sum Item

4,827.36

893.36

337.92

62.54

5,165.28

<u>955.90</u>

Total (inclusive of GST)

Unit Price Disc %

5,165.28

Printed on 14/4/2018 11:18:59 AM

This is a computer generated involce. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| aforesaid. | |
|--|---------------------------------------|
| | ACCIDENT STATEMENT |
| Date Of Report | 14/04/2018 10:27 |
| Date Of Accident | 13/04/2018 11:50 |
| Exact Location Of Accident | CTE NEAR TO BENDEMEER TOWARDS ORCHARD |
| Country/State of Loss | SINGAPORE |
| C C | DETAILS OF OWN VEHICLE |
| Vehicle Registration Number | SGQ5467G |
| Insured/Policyholder | |
| Name Of Registered Owner | GRACE LIM SWEN CHOO |
| NRIC No | S7601632A |
| Email Address | GRACELIMSC@HOTMAIL.COM |
| Mobile Phone No | (LOCAL) +65-91729746 |
| Alternative Phone No | OFFICE-91729746 |
| Vehicle Particulars | |
| Manufacturer | HONDA |
| Model | CIVIC-1.6 I-VTEC (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | SD16V15906/VPC2/R00 |
| Cover Note Number | |
| Driver | |
| Name of Driver | GRACE LIM SWEN CHOO |
| NRIC No | S7601632A |
| Date Of Birth | 22/01/1976 |
| Occupation | INDOOR |
| Date Of Driving Pass | 15/09/2006 |
| Driving Experience | 11 YEARS AND 6 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-91729746 |

OFFICE-91729746

GRACELIMSC@HOTMAIL.COM

Address **BLOCK 473 SEGAR ROAD #04-314**

Postcode 670473 Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER**

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

YES Was any other material or property damaged?

I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLB7776X **VOLKSWAGEN** Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR Vehicle Category

Name of Driver **CHANG HUNG CHUN**

NRIC/Passport Number S2202686J Contact Number 98354467

Address 1A CANTONMENT ROAD #47-07

085101 Postcode

AXA INSURANCE PTE LTD Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 11

Vehicle No 360 5467 G

SKETCH PLAN

Annex D

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (Including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Policyholder's Signature / Date & Time G. 30cm

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

SL8 3G9 77776× 5467G

Please continue to Annex E

| | All the second s |
|--|--|
| Vehicle No SGQ 54676 | Annex E |
| Describe Circumstances of the Accident | |
| On triday (13/4/18), I was travelling along (TE from | Seletar |
| Aerospace View at 80 km/h with want traffic condition | heading |
| towards Orchard. The weather was fair at 34°C and road | was |
| dry. I drove part BIK G + 7 (St George & West Crarden) no | eer to |
| Bademeer Road going towards Orchard Road along CTE is | hen · |
| sudderly a blue sedan car (SLL 1193P) in front of m | le |
| applied the emergency brakes immediately, I responded the | Same |
| and applied emergency brakes and my car came to a ha | Carried III |
| However, the car (SLB 7776 X) behind me could not. | react |
| on time and banged onto the back of my car. I d | id |
| not sustain any injury but the impact had strained my | - 1 |
| I noted the time was 1149 hrs when the accident has | ppered. |
| | 4.1 1.20 1.10 1.11 |
| | |
| | |
| | |
| | |
| Declaration | |
| We declare the foregoing particulars are true in every respect. | |
| M S 26 | |
| H3/37 7 14/4/18 | 7 |
| olicyholder's Signature / Date & Driver's Signature (If driver is not the policyholder) / Date Wilnessed by Reporting Comme 9.30am Personnel | entre |
| | |