



Your Ref: GV/673/11/17

Date: 25<sup>th</sup> April 2018

Our Ref: CS1/LAW18007013/Srbs2

**M/s Gomez & Vasu LLC**  
133 Cecil Street  
#13-01A Keck Seng Tower  
Singapore 069535  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:**  
**SLM 457E**  
**INSURED VEHICLE: SJW 775H**  
**ACCIDENT DATE: 13/05/2017**

We thank you for your instruction on 22/03/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLM 457E from M/s PAL'S Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLM 457E.
- c) Colour damaged vehicle photographs of SLM 457E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLM 457E
Make & Model	: Toyota Vios
Year of Registration	: 2017
Chassis Number	: MHFB29F3102007668
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 13 (Thirteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.