

INS CASE OWNER:

CL

CC 4, Asm 1800 7046

NDA 54

IDAC:

57597

ASSIGNMENT

Signature:

KSC

DOI:

27/11/18

Date / Time:

12/04/2018

Registered in Merimen:

Pre-assign / CCU / FTE

SLN 8203M

58m0043



Insured Vehicle No.:

Claim No.:

Name of Insured:

Muhammed Aslan Bin Kamardin

Policy No.:

GA32658911

Insured Tel No.:

HP:

97102843

Make / Model:

M-BENZ CLK

Excess Sec II :SS

D.O.A.:

31/03/2018

Place of Accident:

Durham Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SGR 8801 A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Optim works



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

11/15

14H

SGR 8801A, X; SLN 8203M, X

or reported to cut lane. To other evidence & write in or before settlement.

29-11-18

FROM THIN TO 30 /

- CL DISF-RED -

- REJECTED -

29-11-18

REVIEWED:

VIDEO SHOWED OIV ENCLOSED LANE

- DO NOT SHARE OI VIDEO TO TP - JIB

25-8-18

- AXA MAINTAINED REJECTION

VIDEO IN SMART CLAIMS.

RECEIVED 03 DEC 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

7 THIN by Email / 616

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: LM TO TP

PRELIMINARY ADVICE Date/Time:

27/11/18

Sent By:

Jm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

5

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 31/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

1350

REF: ASM (AXA)

kua3

ASSIGNMENT

From: Date: 27042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGR 8801A
at Workshop n/s Optima Werkz
of 9A Serangoon North Ave 5

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$24k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: 2/2

Person Contacted:

Vehicle: IN / OUT

Veh No: SGR 8801A Yr Regn: 02 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz C.C. 1339

Colour: M. Black A/C Insured / Std / NI / NA

Sp. Reading: 102877 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMG017507S21202P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 3 mm

Rear

R/Bal: 2 mm

L/Bal: 3 mm

L/Bal: 2 mm

D.O.A: 31/3/18

D.O.I: 27/4/18

Survey held at: ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/4 Rk parts to Catherine

L/S \$1,800

R (\$1,592 80/47%)

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + R\$ 0

) Photos

) Others

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18007046/Kua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 17-04-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 8203M	Veh. Inspected	SGR 8801A	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00CI3	Excess (\$)	0.00	
Assign From		Assign Date	17/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/03/2018	Inspection Date	27/04/2018	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Not Notarised
 6/1/2018 8?
 Murray Abu Pan
 4 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112
 Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011
 Co. Reg. No. 201212455W

Date: 07 April 2018 Third Party Insurer: AXA
 Vehicle No: SGR8801A Third Party Veh No: SLN8203M
 Model: HONDA JAZZ 1.4A Date of Accident: 31/03/2018
 Chassis: JHMGD17507S212029

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT FENDER LH		Bu \$450.80 ✓
1	FRONT FENDER INNER SHIELD LH		D.I. \$98.10 —
10	FRONT FENDER INNER SHIELD CLIP LH	\$3.00	M \$30.00 —
2	FRONT HEADLAMP LH + RH	MS \$524.30	\$1,048.60 ✓
1	FRONT BUMPER		Bu \$530.50 ✓
2	FRONT BUMPER SIDE RETAINER LH + RH	\$20.50	MS \$41.00 ✓
14	FRONT BUMPER CLIP	\$3.00	M \$42.00 —
SUB TOTAL			\$2,241.00
Less 20%			-\$448.20
PARTS TOTAL			\$1,792.80

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION \$600.00 400 ✓
 TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION \$800.00 400 ✓
 TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST \$80.00 20 ✓
 TO TUFF KOTE / ANTI-RUST \$60.00 30 ✓
 TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT \$60.00 ✓

LABOUR TOTAL \$1,600.00

WINSON TOTAL \$3,392.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 7/5/2018

Survey Details:

Date of loss	31-Mar-18
Date of appointment	12-Apr-18
Date of survey	27-Apr-18
Location of survey	Optima Werkz Pte Ltd - Serangoon

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGR 8801A
Make and Model	HONDA JAZZ 1.4M
Date of registration	22-Feb-07
Excess	
Market Value	\$ 24,000.00
Part Rebate	\$ 19,212.00
Nett Loss	\$ 4,788.00

Repair details:

Initial Estimate	\$ 3,392.80
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,156.96
Check items (estimate)	\$ -
Labour	\$ 910.00
Total	\$ 2,066.96
Lump Sum(if applicable)	\$

Number of days for repair	4 days
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

PLEASE INPUT REMARKS FOR MANDATE REQUEST IE. LIABILITY
AND OTHER CRITICAL INFORMATION TO THE CASE.

Mandate:

Liability(TP)		%
Proposed repair cost		\$
Loss of use		\$ no. of days
Loss of rental		\$ no. of days
Loss of income		\$ no. of days
LTA search fees		\$
Others		\$
Proposed Total		#VALUE!



Service Request Details

Claim

S8M00CI3

Reference

None

Loss Date

March 31, 2018

Request Date

April 12, 2018

Due Date

April 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

16/04/2018 @ 10.15am
Biza veh not in
Shannon

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGR8801A

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

MUHAMED AZLAN BIN KAMARUDIN
802C KEAT HONG CLOSE, #13-73, 683802, Singapore

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME

 Accident Statement

TYPE

Reports & Statement

SUB-TYPE

AUTHOR

Merimen

DATE UPLOADED

NAME

 EMAIL.msg

TYPE

Letters and Correspondence

SUB-TYPE

Others

AUTHOR

KADRI Mateen

NAME	 GIA REPORT OF SLN8203M (INSD).PDF
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	KADRI Mateen
DATE UPLOADED	April 12, 2018

NAME	 GIA REPORT OF SGR8801A (TP).PDF
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	KADRI Mateen
DATE UPLOADED	April 12, 2018

Joy Irene (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Thursday, 29 November 2018 9:54 AM
To: Joy Irene (LKKAuto)
Subject: FW: Arrange survey - Accident involving SGR8801A and SLN8203M on 31/03/18 ***
LKK REF: CC4/ASM18007046/ua3 - S8M00CI3

From: LOH Cynthia <cynthia.loh@axa.com.sg>
Sent: Wednesday, 15 August 2018 7:40 PM
To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Subject: RE: Arrange survey - Accident involving SGR8801A and SLN8203M on 31/03/18 *** LKK REF: CC4/ASM18007046/ua3 - S8M00CI3

Dear Thin Thin,

Please check with OI on his claim against TP (NTUC).

Meanwhile, we maintain our rejection.

Thanks & Regards,

Cynthia Loh | Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: cynthia.loh@axa.com.sg
Customer Care No. 1800 8804741



redefining / insurance

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Thin Thin (LKKAuto) [<mailto:thinthin@lkkauto.com>]
Sent: Wednesday, August 15, 2018 5:01 PM
To: LOH Cynthia <cynthia.loh@axa.com.sg>
Subject: RE: Arrange survey - Accident involving SGR8801A and SLN8203M on 31/03/18 *** LKK REF: CC4/ASM18007046/ua3 - S8M00CI3

Dear Cynthia,

We refer to the below matter.

Kindly let us have your further instruction as TP is keep on chasing us for settlement.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Thin Thin (LKKAuto)

Sent: Tuesday, 31 July 2018 5:47 PM

To: 'LOH Cynthia' <cynthia.loh@axa.com.sg>

Subject: FW: Arrange survey - Accident involving SGR8801A and SLN8203M on 31/03/18 *** LKK REF: CC4/ASM18007046/ua3 - S8M00CI3

Importance: High

Your Ref: S8M00CI3

Dear Cynthia,

We refer to the above matter.

Please be inform that we have rejected TP claim as per instruction.

However, TP did not accept our rejection and propose to settle 50/50 under BOLA 9(e). Please see the below email from TP repairer.

In view of the above, kindly let us have your further instruction.

Thanks.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon <sharon@ow.sg>

Sent: Saturday, 7 July 2018 2:43 PM

To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Lily Loi OW <Lily.Lo@ow.sg>; riza@ow.sg

Subject: Re: Arrange survey - Accident involving SGR8801A and SLN8203M on 31/03/18 *** LKK REF: CC4/ASM18007046/ua3

Without Prejudice

Dear Thin Thin,

The accident photos provided by you was taken after the accident. Thus, it can't prove that our client's vehicle encroached into your insured lane when the collision happened.

Both parties giving conflicting versions as to the cause of collision and both parties have no evidence to support their statement. Therefore, we are of the view that liability should be equally shared.

This accident falls under BOLA Scenario 9(e).

Would appeal for you to reconsider of this matter.

Thank you.

Best Regards,

Sharon Ten (Ms)

Claims Executive

Tel: +65 6484-9919 (ext.106)

Fax: +65 6481-1011

OPTIMA WERKZ PTE LTD

Head office: 6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 |

Branch: 9A Serangoon North Ave 5 Singapore 554500 | Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011 |

Branch: 551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 |

www.ow.sg

www.facebook.com/optimawerkz

On 06-Jul-18 6:10 PM, Thin Thin (LKKAuto) wrote:

Without Prejudice,

Dear Sharon,

We refer to the below matter.

Our insured has reiterated that the accident was caused due to the negligence of your client.

Please see the attached accident photos. Based on accident scene photos, it can be seen that your client vehicle encroached into our insured lane and collided with our insured vehicle.

Under such a circumstances, our principal has given the instruction to inform you that we are to reject your client claim and deny the liability, unless you have concrete evidence to prove otherwise.

Yours faithfully,

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon [<mailto:sharon@ow.sg>]

Sent: Wednesday, 27 June 2018 4:49 PM

To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Riza <riza@ow.sg>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Cc: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; winson@ow.sg; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>; lily.loi@ow.sg <lily.loi@ow.sg>

Subject: Re: Arrange survey - Accident involving SGR8801A and SLN8203M on 31/03/18 *** LKK
REF: CC4/ASM18007046/ua3

Without Prejudice

Dear Thin Thin,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18007046/Kja3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 12-12-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 8203M	Veh. Inspected	SGR 8801A	
Policy No.	GA326589/1	Coverage (\$)	0.00	
Claim No.	S8M00CI3	Excess (\$)	0.00	
Assign From		Assign Date	12/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (M)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JHMGD17507S212029	Colour	METALLIC BLACK	
Odometer	102977	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	BRIDGESTONE	3 mm	
L/H Front Tyre	185/55 R15	BRIDGESTONE	3 mm	
R/H Rear Tyre	185/55 R15	BRIDGESTONE	2 mm	
L/H Rear Tyre	185/55 R15	BRIDGESTONE	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/03/2018	Inspection Date	27/04/2018	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 8801A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER LH (CONSISTENT)	BUCKLED	450.80	450.80
1	FRONT FENDER INNER SHIELD LH (CONSISTENT)	DISTORTED	98.10	98.10
10	FRONT FENDER INNER SHIELD CLIP LH @\$3.00 (CONSISTENT)	NECESSARY	30.00	30.00
2	FRONT HEADLAMP LH+RH @\$524.30 (CONSISTENT)	N/S CUT	1,048.60	524.30
1	FRONT BUMPER (CONSISTENT)	BUCKLED	530.50	530.50
2	FRONT BUMPER SIDE RETAINER LH+RH @\$20.50 (CONSISTENT)	N/S DISTORTED	41.00	20.50
14	FRONT BUMPER CLIP @\$3.00 (CONSISTENT)	NECESSARY	42.00	42.00
	LESS 20% DISCOUNT		-448.20	-339.24
			1,792.80	1,356.96
LABOUR				
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.		600.00	400.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.		800.00	400.00
	TO CHECK WIRING ,REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST.		80.00	20.00
	TO TUFF KOTE/ANTI-RUST.		60.00	30.00
	TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT.		60.00	60.00
			1,600.00	910.00
GRAND TOTAL			3,392.80	2,266.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CC4/ASM18007046/Kja3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SGMR00CB	
Reference	CC4/ASM18007046/Ka3a2	
Loss Date	31 March 2018	
Request Date	12 April 2018	
Due Date		
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (ITP)	
Type of Loss	Third Party Vehicle Damage	
Services	Pending verification - Direct Settlement	

Actions

Next Step

Wait for Approve Invoice

Send Invoice

Vehicle Information	
Incident Vehicle Registration #	SGR8801A
Make	TRINO HONDA
Model	JAZZ-1.4 (A)
Service Address	
Primary Contact/Insured	MUHAMMAD AZLAN BIN KAHARUDIN 802C KEAT HONG CLOSE #13-73, 6813802, Singapore
Claim Handler	LOH Cynthia 6568804843 cynthia.loh@laxa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type	Document SubType					
Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED		
Accident Statement	Reports & Statement		Mariam			

