

Jas Tan

CS3, ASM 1800

7047, Ka3.2

39913

ASSIGNMENT

Surveyor:

Kenneth

DOI:

Date / Time:

13.04.18

Registered in Merimen:

Pre-assign / CCU / FTE

XE 3314P

"VIRTUAL"

S8M0007C



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

13-04-18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

XE 3314P

SLW 7472L

GRE 9300



INSRS:

WSP:

Tel:

Liability:

RMKS:

61



INSRS:

WSP:

Tel:

Liability:

RMKS:

WSP: WSP/Imse

Tel:

Liability:

RMKS:



TP

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$100.00

COPY SENT

REF: ASM(CAXA)

Smart claim

ASSIGNMENT

From: Date: 16/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop mis

of

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh.:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$89K

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 30 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SW 7472L Yr Regn: 02 18

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make:

Colour:

Sp Reading:

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 13/4/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

& 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 16/4/18

11.04am

Date / Time Action / Instruction

17/4 File pass to Catherine, Sent mail to 7/loss.
New Car \$96,800.

Date/Time: File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1 \$+R: \$1

2 Photos

3 Copies

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Workshop (\$)

Report Format:

Lump Sum / L.B.I. (\$)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/04/2018 13:24
Date Of Accident	13/04/2018 08:15
Exact Location Of Accident	TPE 6 KM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW7472L
Insured/Policyholder	
Name Of Registered Owner	LAI YIN FEI
NRIC No	S7878304D
Email Address	LAIYINFEI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91838408
Alternative Phone No	HOME-66550772

Vehicle Particulars

Manufacturer	SUBARU
Model	IMPREZA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00448248
Cover Note Number	

Driver

Name of Driver	LAI YIN FEI
NRIC No	S7878304D
Date Of Birth	19/01/1978
Occupation	INDOOR
Date Of Driving Pass	17/09/2001
Driving Experience	16 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91838408
Fax Number	
Contact Number	HOME-66550772
Email Address	LAIYINFEI@GMAIL.COM

Address	1
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	XE3314P (COMMERCIAL VEHICLE)
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


KINDLY REFER TO DOCUMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Heavy traffic at TPE 6km before Pasir Ris Drive 12 exit. Front vehicle (A) GBE9300A slow down and stop. My vehicle (B) also slow down and stop. The back vehicle (C) doesn't stop in time and hit vehicle B and cause chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: DANIEL A JUDE

NRIC/FIN No.: S9001518D

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: DANIEL A JUDE
NRIC/FIN No: 99001518 D

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8304D

Vehicle Details

Vehicle No.: SLW7472L
Vehicle to be Exported: No
Intended De-registration Date: 17 Apr 2018
Vehicle Make: SUBARU
Vehicle Model: IMPREZA 4D 2.0I-S EYESIGHT AWD CVT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: FB20YC16193
Chassis No.: JF1GK7KL5JG008212
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$14,260.00
Original Registration Date: 28 Feb 2018
First Registration Date: 28 Feb 2018
Transfer Count: 0
Actual ARF Paid: \$14,260.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Feb 2028
PARF Rebate Amount: \$10,695.00

Intended COE Rebate Details

COE Expiry Date: 27 Feb 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,322.00
COE Rebate Amount: \$41,738.00
Total Rebate Amount: \$52,433.00

The information contained herein is correct as at 17 Apr 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Foru

3 BEST WAYS TO SELL YOUR CAR!**POST AN AD**

Sell it yourself

SELL BY BIDDING

Get dealers to bid

CO

Get h

Subaru

Min Price ▼

to

No Max ▼

Depreciation ▼

Vehicle Type ▼

Category ▼



Submit

Home » New Cars » Subaru Search Results

Subaru (Authorised Distributor)

Motor Image Enterprises

Hotline : 67038300 / 67038168

05-Apr Pricelist

Select Date

Subaru Search Results (9 vehicles)

Sort by Model (Ascending) ▼

	Car Model	Price	Dealer	Built in
Subaru BRZ 	2.0 (M)	\$132,800	Motor Image Enterprises	Japan
	2.0 (A)	\$133,800 \$12,000 /yr	• 12.8km/l 197bhp 6-speed (M) • 14.1km/l 197bhp 6-speed (A)	
Subaru Forester  360	2.0i-L (A)	\$99,800 \$9,200 /yr	Motor Image Enterprises	Japan
	2.0 XT (A)	\$133,800 \$12,600 /yr	• 15.3km/l 148bhp Lineartronic CVT (A) • 11.8km/l 238bhp Lineartronic CVT (A)	
Subaru XV - The new Subaru XV 2.0i-S EyeSight from \$94,800!		Subaru Forester - Take your adventures further with the Subaru Forester from \$94,800.		
Subaru Impreza 4D 	2.0 (A)	\$96,800	Motor Image Enterprises	Japan
	2.0i-S EyeSight (A) NEW VARIANT	\$96,800 \$9,000 /yr	• 15.2km/l 154bhp Lineartronic CVT (A) • 15.1km/l 154bhp Lineartronic CVT (A)	
Subaru Impreza 5D 	2.0 (A)	\$97,800	Motor Image Enterprises	Japan
	2.0i-S EyeSight (A) NEW VARIANT	\$97,800 \$9,100 /yr	• 15.2km/l 154bhp Lineartronic CVT (A) • 15.1km/l 154bhp Lineartronic CVT (A)	
Subaru Legacy 	2.5i-S EyeSight (A) FACELIFT	\$133,800	Motor Image Enterprises	Japan
			• 12.9km/l 173bhp Lineartronic CVT (A)	
Subaru Levorg 	1.6 GT-S EyeSight (A) FACELIFT	\$136,800	Motor Image Enterprises	Japan
			• 13.5km/l 168bhp Lineartronic CVT (A)	

Subaru Outback

2.5i-S Eyesight (A) **FACELIFT****\$130,800**

Motor Image Enterprises

Japan

• 12.9km/l | 172bhp | Lineartronic CVT (A)

Subaru WRX



2.0 (A)

\$150,800

Motor Image Enterprises

Japan

• 11.6km/l | 264bhp | CVT (A) Lineartronic

2.0 (M)

\$150,800

• 10.9km/l | 264bhp | 6-speed (M)

2.5 STI (M)

\$167,800

• 9.6km/l | 296bhp | 6-speed (M)

\$15,300 /yr ⓘ

Subaru XV

2.0i-S EyeSight (A) **NEW VARIANT****\$99,800**

Motor Image Enterprises

Japan

• 14.2km/l | 153bhp | Lineartronic CVT (A)

\$9,200 /yr ⓘ

Car Model

Price

Dealer

Built in

23 result(s) for **Subaru** models no longer being sold by local distributorsView all [past Subaru cars](#)Subaru XV
(2011-2017)Subaru Impreza 4D
(2012-2016)Subaru Impreza 5D
(2013-2016)Subaru Impreza STI 4D
(2013-2014)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Niss, BMW. Search specially for Singapore Subaru car prices. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car launches, new car promotions, new car reviews, latest car news & car advice. Find New Subaru cars, and the Singapore car prices for this make. Also join our car di for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and real est

Follow [sgCarMart.com](#)
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)



16 April 2018

AXA Insurance Singapore Pte Ltd
88 South Bridge Road

Singapore 058716

Attn: Claims Department

VEHICLE-SLW7472L
CHASSIS: JF1GK7KL5JG008212
ENGINE :FA20YC16193
REG DATE :28 Feb 2018

Based on our assessment, the damage due to frontal and rear crash of the above-mentioned vehicle had resulted in its front and rear body parts, chassis ,engine components , transmission being severely damaged and its safety compromised.

Given that the repair is beyond the economical cost, I seek your assistance and endorsement to declare the above mentioned vehicle a constructive total loss item.



Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Tel :67038109
HP :92992693
FAX :62535535
Email:sayedinah@motorimage.net

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Friday, 13 April, 2018 4:05 PM
To: assignments
Cc: Admin A
Subject: FW: SLW7472L-3RD PARTY CLAIMS-DIRECT ASIA-TP(XE3314P)AXA-SURVEY-16/04/2018-CAR NON DRIVABLE
Attachments: SLW7472L GIA REPORT.PDF
Importance: High

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: Kuan Wei Loong [mailto:weiloong@motorimage.net]
Sent: Friday, 13 April, 2018 2:04 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: Sayedinah Ali <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; SG AXA Insurance SM Claims Service Team <cst@axa.com.sg>
Subject: SLW7472L-3RD PARTY CLAIMS-DIRECT ASIA-TP(XE3314P)AXA-SURVEY-16/04/2018-CAR NON DRIVABLE
Importance: High

Hi Claims Team,

Kindly arrange survey of the above mentioned vehicle. Urgent basis.
(16/04/2018-CAR NON DRIVERBLE)

Best Regards
Kuan Wei Loong
Claims Advisor
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:90903323
Email:weiloong@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

13-04-2018 @ 4:36pm
Sayed vth in
Kenneth
16-04-2018



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0735/2018
DATE : 14-APR-2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : LAI YIN FEI
ADDRESS : APT BLK 683C EDGEDALE PLAINS
#14-681
S(823683)
TELEPHONE NO : 91838408

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00448248
VEHICLE NO : SLW7472L
MODEL CODE : GK7BKBL
MODEL/YEAR : IMPREZA 4D 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YC16193
CHASSIS NO : JF1GK7KL5JG008212
MILEAGE : 1 KM
DATE IN : 14/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 14/04/2018

Print Date : 14/04/2018
Print Time : 17:00:40

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW7472L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION:TPE 6 KM DATE:13/04/2018 TIME:0813HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,PANEL,LH/RH FENDER, HOOD,LH/RH WHEEL HOUSE,LH/RH DOOR	5040.00	4480/-
4	ZZ/003	REPAIR/REPLACE REAR BUMPER,PANEL,BOOTLID,FLOORPAN, LH/RH FENDER,LH/RH DOOR	4480.00	3920/-
5	ZZ/004	RESPRAY FRONT BUMPER,PANEL,LH/RH FENDER,HOOD, LH/RH WHEEL HOUSE,LH/RH DOOR	3780.00	2940/-
6	ZZ/005	RESPRAY REAR BUMPER,PANEL,BOOTLID,FLOOR PAN, LH/RH FENDER,LH/RH DOOR	3360.00	2940/-
7	ZZ/006	DIMENTLE/REFIX UNDERCARRIAGE FRONT LH/RH/CENTER AND REAR LH/RH/CENTER TO FACILITATE REPAIR	1800.00	1680/-
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	✓
9	ZZ/008	REMOVE/REFIX AIRCOND CODENSOR/RADIATOR TO FACILITATE REPAIR	220.00	✓
10	ZZ/009	TO CONDUCT WATER SEEPAGE TEST	100.00	50/-
11	ZZ/011	TRANSFER BOOTLID MECHANISM	150.00	✓
12	ZZ/012	WHEEL ALIGNMENT	200.00	✓
13	ZZ/013	REMOVE/REFIX CARPET,SEAT,REAR BOOT GARNISH,TRIM TO FACILITATE REPAIR	550.00	450/-
14	ZZ/014	REMOVE/REFIX ROOF LINNING	230.00	✓
15	ZZ/015	MECHANICAL REPAIRS-ALTERNATOR,COPRESSOR, STEERING PUMP	200.00	✓
16	ZZ/016	REMOVE/REFIX FRONT AND REAR WIRE HARNESS	600.00	?
17	ZZ/017	FAULT DIAGNOSTIC RESET FIRST ITEM, SUBSEQUENT-\$190	280.00	?
18	ZZ/018	COOLING SYSTEM PRESSURE TEST	100.00	✓
19	ZZ/019	REMOVE/REINSTALL ENGINE TO FACILITATE REPAIR	400.00	?
20	ZZ/020	REMOVE/REINSTALL TRANSMISSION TO FACILITATE REPAIR	400.00	?

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW7472L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
			CHARGES	RECOMMENDATION
21	ZZ/021	REMOVE/INSTALL REAR WINDSCREEN	300.00	250
22	ZZ/022	TO REMOVE/REFIX FUEL TANK	200.00	150
23	ZZ/023	TO CONDUCT FRONT/REAR LIGHTING TEST	100.00	50
24	ZZ/024	TO CONDUCT FRONT/REAR PROTECTANT COATING	1000.00	560
25	ZZ/025	TO CONDUCT FRONT/REAR ANTI-RUST COATING	1160.00	560
26	ZZ/026	TO SUPPLY/INSTALL REVERSE SENSOR-4 EYES	400.00	✓
27	ZZ/027	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	✓
28	ZZ/028	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	100
29	ZZ/029	SUNDRIES	100.00	✓
30	ZZ/10	TRANSFER FRONT LH/RH AND REAR LH/RH DOOR MACHANISM	800.00	X
TOTAL LABOUR CHARGES			26395.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW7472L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1	ALTNTR ASSY	23700AA971	1497.60	?			
2	TENSR AY-V BELT	23769AA080	129.60	✓			
3	V BELT	23780AA070	75.60	✓			
4	CUSHION RUB RH	41022FL000	180.00	?			
5	CUSHION RUB LH	41022FL010	180.00	?			
6	CUSHION RUBBER R	41022FL060	107.60	?			
7	ROD ASSY PRG STPR	PLEASE SEE AE02A9E 41040FE000	64.80	?			
8	GASKET	44011SG000	7.20	?			
9	EXH PIPE ASSY R S20	44200FL040	529.20	?			
10	MUFFLER ASSY RH S2C	44300FL070	496.80	?			
11	TAIL PIPE CUTTER	44370FL000	72.00	X			
12	RADIATOR ASSY	45111FL001	576.00	✓			
13	FAN MAIN	45121FL000	46.50	?			
14	FAN SUB	45121FL010	46.50	?			
15	SHROUD	45122FL000	97.90	✓			
16	MOTOR	45131FG003	272.00	?			
17	MOTOR	45131FL000	258.30	?			
18	TANK RESERVE ASSY	45150FL000	136.80	✓			
19	HOSE RAD IN	45161FL000	32.60	✓			
20	HOSE RAD OUT	45161FL040	28.80	?			
21	RESONATOR COMPL	46043FL010	36.00	✓			
22	CASE-AIR CLNR LWR	46052FL000	45.40	?			
23	CASE-AIR CLNR UPR	46052FL010	45.40	?			
24	FRAME SD UPR CP RH	51021FL0209P	64.80	?			
25	FRAME SD UPR CP LH	51021FL0309P	64.80	?			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW7472L

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	PNL SD OUT QTR RRH	51439FL1409P	R 946.80	X		
27	PNL SD OUT QTR RPSLH	51439FL1509P	R 946.80	X		
28	WHEEL APR F RH	51610FL0209P	144.00	?		
29	FLH WHEEL APRON	51610FL0309P	144.00	?		
30	WHEEL APR F UPR CRH	51610FL1409P	79.20	?		
31	WHEEL APR F UPR CLH	51610FL1509P	79.20	?		
32	BRKT F SUS CP RH	51625FL5419P	B 162.00	✓		
33	BRKT F SUS CP LH	51625FL5509P	B 162.00	✓		
34	WHEEL APR FF C RPLH	51690FL0309P	208.70	?		
35	R FLOOR PANEL 4D	52129FL0319P	R 432.00	?		
36	SKIRT COMPL R 4D	52401FL0309P	B 265.30	✓		
37	RAD PNL COMPL RPR	53029FL0809P	B 376.70	✓		
38	FENDER F RH	57120FL0209P	B 216.00	✓		
39	FENDER F LH	57120FL0309P	B 216.00	✓		
40	HOOD COMPL F	57229FL0109P	B 1072.80	✓		
41	HINGE COMPL F HD RH	57260FL0209P	D 37.90	✓		
42	HINGE COMPL F HD LH	57260FL0309P	D 37.90	✓		
43	LOCK ASSY F HOOD ISR	57310FL030	D 72.70	✓		
44	STRK ASSY F HOOD	57311FL010	D 28.80	✓		
45	TRUNK LID COMPL	57509FL0109P	B 624.00	✓		
46	LOCK AY TRUNK	57530AJ050	In 158.40	✓		
47	STRIKER-TRUNK LID	57531FJ000	B 10.62	✓		
48	WSTR TRUNK	57532FL010	R 57.60	✓		
49	BUMPER PUNCHING F	57702FL300	B 468.00	✓		

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW7472L

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
50 BUMPER FACE R 4D FHI	57704PL240	BA 453.60	✓		
51 ENR ABSORB FOAM STD	57705FL020	60.10	?		
52 BRKT CORNER F FHIRH	57707FL000	Dis 36.00	✓		
53 BRKT CORNER F PHILH	57707FL010	Dis 36.00	✓		
54 BRKT SD F RH	57707FL020	21.60	?		
55 BRKT SD F LH	57707FL030	21.60	?		
56 BRKT SD R 4D FHI RH	57707FL380	30.60	?		
57 BRKT SD R 4D FHI LH	57707FL390	30.60	?		
58 BRKT CORNER R 4D RH	57707FL480	Dis 18.00	✓		
59 BRKT CORNER R 4D LH	57707FL490	Dis 18.00	✓		
60 BEAM COMPL F EU	57711FL0109P	346.00	?		
61 BEAM COMPL R EU	USE FL0409P 57711FL0419P	202.90	?		
62 COVER HOOK F STD	57731FL120	Dis 10.80	✓		
63 COVER HOOK R 4D FHI	57731FL560NN	Dis 9.00	✓		
64 MUD GUARD ASSY F RH	59110FL020	Is 87.60	X		
65 MUD GUARD ASSY F LH	59110FL030	Is 87.60	X		
66 MUDGUARD RRH	59122FL020	64.80	?		
67 MUDGUUARD RLH	59122FL030	64.80	?		
68 PNL COMPL DR F RH	60009FL0409P	920.00	?		
69 PNL COMPL DR F LH	60009FL0509P	920.00	?		
70 PNL COMPL DR R SRH	60409FL0609P	888.00	?		
71 WEATHER STRIP OUT RRH	62280FL120	126.00	?		
72 COVER B PLR AY F RH	63563FL360	25.20	?		
73 COVER B PLR AY F LH	63563FL370	25.20	?		
74 WSHLD GL ASSY	65009FL160	Is 1800.00	✓		

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW7472L

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
75	DAM RUBBER UPR	65045FL000	18.00	—		
76	DAM RUBBER LWR	65045FL010	14.40	—		
77	MOLDING F	65058FL000	108.00	—		
78	WINDOW GL ASSY R EXP	65109FL020	1946.20	?		
79	DAM RUBBER UPR PHI	65145FL000	11.50	?		
80	DAM RUBBER LWR PHI	65145FL010	8.30	?		
81	MOLDING R PHI	65158FL000	38.90	?		
82	COMPRESSOR ASSY	73111FL040	2203.30	?		
83	CONDENSER ASSY VJ	73210FL000	579.30	✓		
84	AIR GUIDE RH	73233FL000	18.00	?		
85	AIR GUIDE LH	73233FL010	18.00	?		
86	HOSE PD	73424FL000	162.00	?		
87	HOSE PS	73425FL000	162.00	?		
88	PIPE	73431FL000	169.20	?		
89	LAMP ASSY HEAD	84002FL100	2520.00	—		
90	LAMP ASSY HEAD	84002FL110	2520.00	—		
91	FOG LAMP ASSY F	84501AJ060	544.00	?		
92	LENS & BODY COMPLRH	84912FL100	378.00	—		
93	LENS & BODY COMPLLH	84912FL110	378.00	—		
94	LENS & BODY COMPLLH	84912FL13A	201.60			
95	LENS & BODY COMPLRH	84912FL140	201.60			
96	SHEET SILICON	86596AL001	18.00	—		
97	MOTOR & PUMP ASSYHL	86611AL100	194.40	?		
98	MOTOR & PUMP ASSYHI	86611FL000	82.80	?		

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

X

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW7472L

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
		NETT	LIST	S/NETT		
99 CAP-WASHER TANK	86615KE000	10.80	?			
100 TANK	86631FL030	68.40	?			
101 HOSE INLET	86655FL150	49.70	?			
102 TAPE DR SASH F F RH	90422FL000	10.80	?			
103 TAPE DR SASH F F LH	90422FL010	10.80	?			
104 TAPE DR SASH F M RH	90422FL020	10.80	?			
105 TAPE DR SASH F M LH	90422FL030	10.80	?			
106 TAPE R DR CTR RH	90422FL140	27.00	?			
107 TAPE R DR RRH	90422FL160	27.00	?			
108 INSULATOR HOOD	90815FL410	64.80	?			
109 GRILLE F BASE FHI	91122FL000	CM 108.00	—			
110 MOLDING WG PLT FHI	91123FL020	CM 108.00	—			
111 MOLDING WG PLT FHI	91123FL030	CM 108.00	—			
112 MOLDING RNG PAINTFHI	91123FL050	' 129.60	?			
113 ORNAMENT F SIX	93013VA090	ME 64.80	✓			
114 LETTER MK R	93079FL020	ME 79.20	—			
115 LETTER MK R IMP	93079FL050	ME 36.00	—			
116 TRIM PNL ASSY TRKR	94511FL100	43.20	?			
117 EYE SIGHT EMBLEM (TCS)	LPH010ES-EMB	43.20	?			
SUB TOTAL		31850.02	0.00	0.00		0.00
LESS DISCOUNT (NETT-20 %)		6370.00	0.00	0.00		0.00
GRAND TOTAL		25480.02	0.00	0.00		0.00
OVERALL TOTAL		25480.02				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLW7472L

TOTAL LABOUR CHARGES	26395.00
TOTAL SPARE PARTS CHARGES	25480.02
GRAND TOTAL	51875.02 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Authorized
May be T/Loss.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM18007047/Ka3s2	
8 SHENTON WAY #24-01		Date: 23-04-2018	
AXA TOWERSINGAPORE 068811			
ATTN: JAS TAN		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XE 3314P	Veh. Inspected	SLW 7472L
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00DZC	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	13/04/2018
2. Vehicle Particulars & Condition			
Make & Model	SUBARU IMPREZA (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JF1GK7KL5JG008212	Colour	METALLIC GREY
Odometer	3092 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/50R17	BRIDGESTONE	9 mm
L/H Front Tyre	205/50R17	BRIDGESTONE	9 mm
R/H Rear Tyre	205/50R17	BRIDGESTONE	9 mm
L/H Rear Tyre	205/50R17	BRIDGESTONE	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.			
5. General Information			
Accident Date	13/04/2018	Inspect Date / Time	16/04/2018 (11:04 AM)
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18007047/Ka3s2

Inspected By



KONG SENG CHEONG

Licensed Appraiser



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAIAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.