

22/03/2018

ASS. REC. BY:

REF:

CS/ASM18007071/Sqbs2

Special Instruction:

Survivor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Richard Any

of

ASM

Date/Time: 17042018 11:53am

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 5042S

Insured:

at Workshop m/s

Toti Ah Swee Spray Painting

Tel:

6366 0286

of

Blk 2 Kranji Loop - #01-02

Policy No:

Claim No:

SSM00ESM

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

14042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

17042018 10:10pm

Person Contacted:

Elaine

Vehicle IN OUT

| Date/Time | Action/Instruction (✓) Estimate           |
|-----------|-------------------------------------------|
|           | SKN 5042S - X                             |
| 18/4-     | Report via merimen                        |
| 07/7/18   | confirmed with Elaine final fig \$9222.49 |
|           | (Red \$3221.11, 26/27)                    |
|           |                                           |
|           |                                           |
|           |                                           |

Excess: \$500 CA

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or


The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn:

c.c. 1979

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA



RECEIVED 11/11/2018

Date/Time: File Pass to?

Date/Time: File Return to?

Date/Time: File Return to?

11/11/2018

Report Format:

Lump Sum / L.B.I. (\$)

Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Week-end (\$)

Survey Fee:

Transportation

S + RS (\$)

Photos

Others

TOTAL

Smart Claim  
9222149

LKK AUTO CONSULTANTS PTE LTD (OD) ▾



## Service Request Details

Claim

S8M00E8M

Reference

None

Loss Date

April 14, 2018

Request Date

April 17, 2018

Due Date

April 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

Next Step

Agree to perform service

### Vehicle Information

Incident Vehicle Registration #

SKN50425

Make

JAGUAR

---

Service Address

---

51 Ubi Avenue 1 #01-25 Paya Ubi, , 408933

---

Primary Contact/Insured

---

ONG HUI PING CHRISTIE  
BLK 272B JURONG WEST STREET 24, #07-96, 642272, Singapore

HOTMAIL@SINGNET.COM.SG

---

Claim Handler

---

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Excess:\$500

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                           |
|----------------------------|-------------------------------------------|
| Date Of Report             | 16/04/2018 16:21                          |
| Date Of Accident           | 14/04/2018 13:50                          |
| Exact Location Of Accident | ALONG JURONG WEST AVE 2 TOWARDS JLN BAHAR |
| Country/State of Loss      | SINGAPORE                                 |

### DETAILS OF OWN VEHICLE

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SKN5042S |
|-----------------------------|----------|

#### Insured/Policyholder

|                          |                                      |
|--------------------------|--------------------------------------|
| Name Of Registered Owner | ONG HUI PING CHRISTIE (WANG HUIPING) |
| NRIC No                  | S7627532G                            |
| Email Address            | NOEMAIL                              |
| Mobile Phone No          | (LOCAL) +65-98452695                 |
| Alternative Phone No     | OTHERS-98452695                      |

#### Vehicle Particulars

|                                                                    |             |
|--------------------------------------------------------------------|-------------|
| Manufacturer                                                       | JAGUAR      |
| Model                                                              | XF 2.0P TSS |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE     |

|                                                                              |     |
|------------------------------------------------------------------------------|-----|
| Are you claiming under your own insurance policy for repair to your vehicle? | YES |
|------------------------------------------------------------------------------|-----|

If No, Please state action to be taken

|                  |             |
|------------------|-------------|
| Vehicle Category | PRIVATE CAR |
|------------------|-------------|

#### Insurance Company

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE         |
| Fleet Policy              | NO                    |
| Policy Number             | GA043072/1            |
| Cover Note Number         |                       |

#### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LOW KWANG MENG PETER  |
| NRIC No              | S7041366C             |
| Date Of Birth        | 18/11/1970            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 05/10/1991            |
| Driving Experience   | 26 YEARS AND 6 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-97951095  |
| Fax Number           |                       |
| Contact Number       |                       |
| EMail Address        | NAUGHTY9795@YAHOO.COM |

|                                                     |                                       |
|-----------------------------------------------------|---------------------------------------|
| Address                                             | BLK 272B JURONG WEST STREET 24 #07-96 |
| Postcode                                            | 642272                                |
| Was driver an employee of the Insured's Company     | NO                                    |
| If No, Relationship of the Driver with the Insured  | SPOUSE                                |
| Vehicle Registration Number of Driver's Own Vehicle | -                                     |
|                                                     | -                                     |
|                                                     | -                                     |
| Insurance Company of Driver's Own Vehicle           | -                                     |
|                                                     | -                                     |
|                                                     | -                                     |

#### General Information of the Accident

|                    |                            |
|--------------------|----------------------------|
| Type Of Accident   | COLLISION - CROSS JUNCTION |
| Weather Conditions | DRIZZLING                  |
| Road Surface       | WET                        |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles involved in the accident                                                 | 2   |
| Was any body injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                          | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

AS PER SKETCH PLAN

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                  |
|-------------------------------------|------------------|
| Vehicle Registration Number         | SLR6465R         |
| Vehicle Make/Model/Colour           | KIA / K3 / BLACK |
| Details Of Properties               |                  |
| Vehicle Category                    | PRIVATE CAR      |
| Name of Driver                      | HUANG CHONG YONG |
| NRIC/Passport Number                | S8167918E        |
| Contact Number                      | 93251618         |
| Address                             |                  |
| Postcode                            |                  |
| Insurance Company Name              |                  |
| Nature Of Damage                    |                  |
| No. Of Passenger (Including Driver) |                  |

## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: Yvonne Toh  
NRIC/FIN No.:

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



VEHICLE A: SKN5042S

VEHICLE B: SLR6465R

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 14/04/2018, AT AROUND 1.50PM, I WAS DRIVING ALONG JURONG WEST AVE 2 TURNING RIGHT TOWARD JALAN BAHAR. WHILE APPROACHING THE T-JUNCTION, THE TRAFFIC LIGHT HAD TURN AMBER AND AFTER I CHECKED THERE WAS NO ONCOMING TRAFFIC ON THE OPPOSITE DIRECTION, I STARTED TO MAKE MY RIGHT TURN. SINCE THE TRAFFIC HAD ALREADY TURN AMBER, THE VEHICLE "B" SLR6465R SHOULD HAD STOP, BUT HE DIDN'T AND BEAT THE TRAFFIC LIGHT. AT THIS MOMENT, I COULDN'T AVOID AND COLLIDED ONTO THE VEHICLE "B" RIGHT FRONT DOOR PORTION. BOTH THE VEHICLE SUSTAIN SERIOUS DAMAGE.

## REMARKS

REPORTING ONLY

OWN DAMAGED CLAIM

THIRD PARTY CLAIM

X

## REMARKS

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD Claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

## DECLARATION

/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name: Yvonne Toh  
NRIC/FIN No.:



## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                    |
|-------------------------------------|--------------------|
| <b>Vehicle Owner Particulars</b>    |                    |
| Owner ID Type:                      | Singapore NRIC     |
| Owner ID:                           | 7532G              |
| <b>Vehicle Details</b>              |                    |
| Vehicle No.:                        | SKN50425           |
| Vehicle to be Exported:             | No                 |
| Intended De-registration Date:      | 18 Apr 2018        |
| Vehicle Make:                       | JAGUAR             |
| Vehicle Model:                      | XF 2.0P TSS        |
| Primary Colour:                     | Red                |
| Manufacturing Year:                 | 2014               |
| Engine No.:                         | 181113183234204PT  |
| Chassis No.:                        | SAJAC05MXEPU25314  |
| Maximum Power Output:               | 177.0 kW (237 bhp) |
| Open Market Value:                  | \$52,396.00        |
| Original Registration Date:         | 23 Jun 2014        |
| First Registration Date:            | 23 Jun 2014        |
| Transfer Count:                     | 0                  |
| Actual ARF Paid:                    | \$66,313.00        |
| <b>Intended PARF Rebate Details</b> |                    |
| PARF Eligibility:                   | Yes                |
| PARF Eligibility Expiry Date:       | 22 Jun 2024        |
| PARF Rebate Amount:                 | \$49,734.00        |
| <b>Intended COE Rebate Details</b>  |                    |
| COE Expiry Date:                    | 22 Jun 2024        |
| COE Category:                       | E - Open Category  |
| COE Period(Years):                  | 10                 |
| QP Paid:                            | \$67,290.00        |
| COE Rebate Amount:                  | \$41,570.00        |
| <b>Total Rebate Amount:</b>         | <b>\$91,304.00</b> |

The information contained herein is correct as at 18 Apr 2018

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ

\$2800 Downpayment Monthly  
From \$738 Onwards, Lowest  
3.68%P.A@GV Cars Financing,  
GV Credit Pte Ltd StarAd

**Lake View Credit Pte Ltd** [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

6 vehicles

jaguar xf 2.0

Advanced Search

| Make             | Model         | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status    |
|------------------|---------------|-------|--------------|----------|---------|---------|----------|-----------|
| Search Selection | jaguar xf 2.0 | Any   | Any          | 2014     | Any     | Any     | Any      | Available |



### Jaguar XF 2.0A Luxury

**\$108,800**

\$13,470 /yr

21-Jan-2014

1,999 cc

87,000 km

Luxury

Available

In House Financing With Low Monthly Of \$792 Available. Different Kind Of Loan Package Available! 1 Owner! Full Service By Wearnes, Last Serviced On Oct 2017. Very Well Maintained. High Trade In. New R...

Speedo Motoring

Posted: 16-Apr-2018 Tags: 2014 Jaguar XF, Jaguar XF, Jaguar, XF, Used Jaguar

PREMIUM AD



### Jaguar XF 2.0A Luxury

**\$116,800**

\$13,930 /yr

30-Apr-2014

1,999 cc

77,000 km

Luxury

Available

Call Us Today To Own This Newly Arrived Beautiful Deep Red Jag XF! Wearnes Agent Unit! 1 Owner Only! Fully Agent Serviced With Receipts! Recent Servicing Done 27 March! Absolutely Worry Free Buy! Eval...

Car Buyers Automotive Pte Ltd

Posted: 14-Apr-2018 Tags: 2014 Jaguar XF, Jaguar XF, Jaguar, XF, Used Jaguar

PREMIUM AD



### Jaguar XF 2.0A Luxury

**\$112,800**

\$13,140 /yr

30-May-2014

1,999 cc

77,000 km

Luxury

Available

Cheapest In Town! Full Agent (Wearnes Automotive) Serviced Record, 1 Careful Owner, Keyless Entry/Go, Reverse Camera, Bluetooth Tel/Audio, Etc. High Paper Value, Accident Free, Good Condition.

Posted: 11-Apr-2018 Tags: 2014 Jaguar XF, Jaguar XF, Jaguar, XF, Used Jaguar



### Jaguar XF 2.0A Luxury

**\$119,888**

\$13,730 /yr

26-Aug-2014

1,999 cc

32,222 km

Luxury

Available

1 Owner, Fully Maintained By Agent, The Only Rose Red Unit In The Market, Very Low Mileage, 100% Accident Free, Immaculate Condition, Loan Up To 90% At 2.98%. View To Believe!

Posted: 14-Apr-2018 Tags: 2014 Jaguar XF, Jaguar XF, Jaguar, XF, Used Jaguar

PREMIUM AD

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but  
Unsure of its Condition?  
Get, STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



### Jaguar XF 2.0A Luxury

**\$123,999**

\$14,000 /yr

31-Oct-2014

1,999 cc

46,000 km

Luxury

Available

Luxurious Silver Exterior And Black Interior! Excellent Condition! High ARF Of \$64,853! Premium Pre Owned 110 Points Check. Please SMS Or Call For Viewing Appointment Or More Enquiries! Flexible Finan...

Premium Automobiles

Posted: 22-Mar-2018 Tags: 2014 Jaguar XF, Jaguar XF, Jaguar, XF, Used Jaguar

PREMIUM AD



### Jaguar XF 2.0A Luxury

**\$118,777**

\$13,140 /yr

28-Nov-2014

1,999 cc

45,000 km

Luxury

Available

Maroon With Beige Interior, 1 Owner, Low Mileage Done. Fully Agent Serviced/Maintained By Wearnes Automotive Since Day 1 With Servicing Just Done On Dec 2017, Pristine Condition, Flawless Exterior And...

Posted: 13-Apr-2018 Tags: 2014 Jaguar XF, Jaguar XF, Jaguar, XF, Used Jaguar

# 卓亚水喷漆公司

## TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

BUSINESS REG. NO: 09935300L

17/04/2018

### AXA INSURANCE SINGAPORE PTE LTD

143 CECIL STREET

#01-01 GB BUILDING

SINGAPORE 069524

ATTN : MOTOR CLAIMS DEPT.

Sebastian.  
17/4/18.

- Part by part  
repair.  
- Photo Before  
Paint

5 days.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### ESTIMATED REPAIR BILL

TYPE OF CLAIM : OWN DAMAGE CLAIM  
NAME : ONE HUI PING CHRISTIE  
VEHICLE NO. : SKN5042S  
MAKE/ MODEL : JAGUAR XF  
POLICY NO/ CN NO. : GA043072/1  
ACCIDENT DATE : 14/04/2018

Excess : \$500  
Authorized:

*[Signature]*  
23/5/18

### MATERIAL COST

|     |                              |             |         |                     |                    |
|-----|------------------------------|-------------|---------|---------------------|--------------------|
| IPC | BONNET                       | ✓ DT        | 2750    | \$                  | 3,650.00           |
| IPC | FRONT GRILLE                 | ✓ CRK       | 1042.60 | \$                  | 1,158.00           |
| IPC | HEAD LAMP RH                 | ✓ CRK       | 2100    | \$                  | 2,590.00           |
| IPC | FRONT BUMPER                 | ✓ Deform.   | 1828.50 | \$                  | 2,221.00           |
| IPC | FRONT BUMPER INNER SHPONG    | ✓ CRK       | 380     | \$                  | 750.00             |
| IPC | FRONT BUMPER CHROME MOULDING | ✓ SCR       |         | \$                  | 250.00             |
| IPC | TOWING COVER                 | ✓ SCR       |         | \$                  | 95.00              |
|     | front bumper sensor RH       | ✓ nme \$190 |         | \$                  | 10,714.00          |
|     |                              |             |         | LESS DISCOUNT 10% : | \$ 1,071.40        |
|     |                              |             |         |                     | <u>\$ 9,642.60</u> |

### LABOUR CHARGE

|                                                                                                                                                                                                                                          |          |     |           |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----|-----------|
| TO USE COMPUTER DIAGNOSTIC & RESET FULL VEHICLE SYSTEM                                                                                                                                                                                   | \$       | 150 | 180.00    |
| TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILIATE REPAIRS , TO REPLACE AND ALIGN THE ABOVE PARTS. | \$       | 700 | 1,200.00  |
| PUTTY AND SPRAY PAINTING ON ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS                                                                                                                                             | \$       | 600 | 1,300.00  |
|                                                                                                                                                                                                                                          | \$       |     | 12,322.60 |
|                                                                                                                                                                                                                                          | GST 7% : | \$  | 862.58    |
|                                                                                                                                                                                                                                          | \$       |     | 13,185.18 |

SINGAPORE DOLLARS : THIRTEEN THOUSAND ONE HUNDRED EIGHTY FIVE AND CENTS EIGHTEEN ONLY.

**NOTE:** THE ESTIMATED PERIOD OF REPAIRS IS EIGHT (8) DAYS

**TOH AH SWEE SPRAY PAINTING CO.**

SALLY ANG (TEL : 63660286)

12493.60

# 卓亚水喷漆公司

## TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: [claims@tohahswee.com.sg](mailto:claims@tohahswee.com.sg)

BUSINESS REG. NO: 09935300L

19/04/2018

### AXA INSURANCE SINGAPORE PTE LTD

143 CECIL STREET

#01-01 GB BUILDING

SINGAPORE 069524

ATTN : MOTOR CLAIMS DEPT.

### ESTIMATED REPAIR BILL - SUPPLEMENTARY ITEMS

TYPE OF CLAIM : OWN DAMAGE CLAIM  
NAME : ONE HUI PING CHRISTIE  
VEHICLE NO. : SKN5042S  
MAKE/ MODEL : JAGUAR XF  
POLICY NO/ CN NO. : GA043072/1  
ACCIDENT DATE : 14/04/2018

### MATERIAL COST

|                            |       |    |        |
|----------------------------|-------|----|--------|
| 1PC FRONT BUMPER SENSOR RH | ✓ DMG | \$ | 190.00 |
| LESS DISCOUNT 10% :        |       | \$ | 19.00  |
|                            |       | \$ | 171.00 |
| GST 7% :                   |       | \$ | 11.97  |
|                            |       | \$ | 182.97 |

SINGAPORE DOLLARS : ONE HUNDRED EIGHTY TWO AND CENTS NINETY SEVEN ONLY.

TOH AH SWEE SPRAY PAINTING CO.  
SALLY ANG (TEL : 63660286)

Sebastian.

19/4/18.

Before Paint Survey

# 卓亚水喷漆公司 TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

BUSINESS REG. NO: 09935300L

*read purpose!*

30/04/2018

## AXA INSURANCE SINGAPORE PTE LTD

143 CECIL STREET

#01-01 GB BUILDING

SINGAPORE 069524

ATTN : MOTOR CLAIMS DEPT.

### FINALISATION

|                   |                         |
|-------------------|-------------------------|
| TYPE OF CLAIM     | : OWN DAMAGE CLAIM      |
| NAME              | : ONE HUI PING CHRISTIE |
| VEHICLE NO.       | : SKN5042S              |
| MAKE/ MODEL       | : JAGUAR XF             |
| POLICY NO/ CN NO. | : GA043072/1            |
| ACCIDENT DATE     | : 14/04/2018            |

### MATERIAL COST

|                                                 |                     |    |           |      |
|-------------------------------------------------|---------------------|----|-----------|------|
| 1PC BONNET                                      | ✓ OT                | \$ | 3,650.00  | 1250 |
| 1PC FRONT GRILLE                                | ✓ CRK               | \$ | 1,158.00  | 620  |
| 1PC HEAD LAMP RH                                | ✓ CRK               | \$ | 2,590.00  | 1850 |
| 1PC FRONT BUMPER                                | ✓ DIF               | \$ | 2,221.00  | 1400 |
| 1PC FRONT BUMPER INNER SHPONG                   | ✓ CRK               | \$ | 750.00    | 250  |
| 1PC FRONT BUMPER CHROME MOULDING                | ✓ CRK               | \$ | 250.00    | 170  |
| 1PC FRONT BUMPER SENSOR RH (SUPPLEMENTARY ITEM) | ✓ DIF               | \$ | 190.00    | 140  |
|                                                 |                     | \$ | 10,809.00 |      |
|                                                 | LESS DISCOUNT 10% : | \$ | 1,080.90  |      |
|                                                 |                     | \$ | 9,728.10  |      |

### LABOUR CHARGE

|                                                                                                                                                                                                                                          |    |        |   |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|--------|---|
| TO USE COMPUTER DIAGNOSTIC & RESET FULL VEHICLE SYSTEM                                                                                                                                                                                   | \$ | 150.00 | ✓ |
| TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHEN, ADJUST. CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILIATE REPAIRS , TO REPLACE AND ALIGN THE ABOVE PARTS. | \$ | 700.00 | ✓ |
| PUTTY AND SPRAY PAINTING ON ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS                                                                                                                                             | \$ | 600.00 | ✓ |

**PART BY PART REPAIR COST : \$ 11,178.10**



TAX CASH SALE

SSP No. 67289

實利基機件(私人)有限公司  
SELEGIE SPAREPARTS PTE LTD

record purposes

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s

cash

SKN 5042

DATE:

18/4/18

| Quantity | DESCRIPTION                  | S    | ots. |
|----------|------------------------------|------|------|
| 1/1      | C22 29968 Front bonnet       | 1750 | N    |
| 1/1      | C22 31443 Head lamp          | 1850 | N    |
| 1/1      | C22 13208 Front bumper       | 1400 | N    |
| 1/1      | C22 13199 Front GRILLE       | 620  | N    |
| 1/1      | 1 C22 16554 bumper Foam      | 280  | N    |
| 1/1      | C22 13205 F/RH side moulding | 170  | N    |
|          |                              |      |      |
|          |                              |      |      |
|          | Plk 2 tangi loop             |      |      |
|          | Unit 01-02                   |      |      |
|          |                              |      |      |
|          | Sub Total                    | 6070 | 00   |
|          | Add GST @ 7%                 | 424  | 90   |

L

Amount Due

6494.90

TAX CASH SALE

SSP No. 67291

實利基機件(私人)有限公司  
SELEGIE SPAREPARTS PTE LTD

Verord proposal

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s

Cal

DATE:

18/4/18

| Quantity     | DESCRIPTION              | \$  | cts. |
|--------------|--------------------------|-----|------|
| 4            | C22 22810 Parking sensor | 140 | 0    |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
|              |                          |     |      |
| Sub Total    |                          | 140 | 00   |
| Add GST @ 7% |                          | 9   | 80   |

Amount Due

A

149 80



卓亞水噴漆公司  
**TOH AH SWEE SPRAY PAINTING CO.**

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.  
TEL: 6366 0115 (WORKSHOP), 6366 0286 (OFFICE) FAX: 6368 5943  
EMAIL: claims@tohahswee.com.sg  
BUSINESS REG. NO: 09935300L  
GST REG. NO: 09-935300-L

02/07/2018

**TAX INVOICE NO.: 18-231**

**AXA INSURANCE SINGAPORE PTE LTD**  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811  
ATTN : MOTOR CLAIMS DEPT.

**FINAL REPAIR BILL**

TYPE OF CLAIM : OWN DAMAGE CLAIM  
CLAIMANT : ONE HUI PING CHRISTINE  
VEHICLE NO. : SKN5042S  
MAKE/ MODEL : **JAGUAR XF**  
POLICY NO. : GA043072/1  
DATE OF ACCIDENT : 14/04/2018

|                                                                     |           |                       |
|---------------------------------------------------------------------|-----------|-----------------------|
| PARTS BY PARTS REPAIR COST AS RECOMMENDED BY<br>YOUR SURVEYOR ----- | SS        | 9,222.49              |
| LESS : EXCESS                                                       | SS        | 500.00                |
|                                                                     |           | <hr/> 8,722.49        |
| ADD : GST 7%                                                        |           | 610.57                |
| <b>TOTAL :</b>                                                      | <b>SS</b> | <hr/> <b>9,333.06</b> |

SINGAPORE DOLLARS : NINE THOUSAND THREE HUNDRED THIRTY THREE AND CENTS  
SIX ONLY

**TOH AH SWEE SPRAY PAINTING CO.**  
Elaine Tham

Claim Ref No. :

**SATISFACTION / DISCHARGE VOUCHER**

TO: **AXA INSURANCE SINGAPORE PTE LTD**  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811  
ATTN: **MOTOR CLAIMS DEPT.**

We / I, hereby declare that the repairs to Our / My Vehicle Registration

No. SKN 5042 S have been completed to Our / My Satisfaction and

We / I agreed that payment of the sum of S\$ 9,333.06

to the Repairer for such repairs shall be in full discharge of Our / My

Claim under Policy No. GA043072/1 in respect of the

damage caused to Our / My said vehicle in the accident which occurred

on 14/04/2018.

We / I authorize insurer to make payment to the workshop (TOH AH

**SWEE SPRAY PAINTING CO.)** appointed by us / me.

Date : 26/4/18

Signature :   
(Insured)

NRIC No. : S76275324

## << Service Request Details

|                                                                                                                |              |                                                                                       |                 |
|----------------------------------------------------------------------------------------------------------------|--------------|---------------------------------------------------------------------------------------|-----------------|
| Claim                                                                                                          | S8M00E8M     | Vehicle Information                                                                   |                 |
| Reference                                                                                                      |              | Incident Vehicle                                                                      | SKN5042S        |
| CS/ASM18007071/Sqboss Date  |              | Registration #                                                                        | Service Address |
| April 14, 2018                                                                                                 | Request Date | Model                                                                                 | JAGUAR 51 Ubi   |
| April 17, 2018                                                                                                 | Due Date     | Avenue 1 #01-25 Paya Ubi, . . , 408933                                                |                 |
| April 17, 2019                                                                                                 | Vendor Name  | Primary Contact/Insured                                                               |                 |
| LKK AUTO CONSULTANTS PTE Loss LTD (OD)                                                                         | Type of      | ONG HUI PING CHRISTIE<br>BLK 272B JURONG WEST STREET<br>24, #07-96, 642272, Singapore |                 |
| Own Damage                                                                                                     | Services     | HOTMAIL@SINGNET.COM.SG                                                                |                 |

### Actions

Next Step

Finish the work

Complete Work

More

| NAME                        | TYPE                       | SUB-TYPE             | AUTHOR                            | DATE<br>UPLOADED |
|-----------------------------|----------------------------|----------------------|-----------------------------------|------------------|
| skn 5042s.pdf               | Forms / Claim Documents    | Estimate / Quotation | LKK AUTO CONSULTANTS PTE LTD (OD) | April 18, 2018   |
| PRELI ADVISED SKN 5042S.pdf | Reports & Statement        | Others               | LKK AUTO CONSULTANTS PTE LTD (OD) | April 18, 2018   |
| EMAIL.msg                   | Letters and Correspondence | Workshop             | KADRI Mateen                      | April 17, 2018   |

SERVICE REQUESTS    MESSAGES    CLAIMS

## << Service Request Details

|                                        |              |
|----------------------------------------|--------------|
| Claim                                  | S8M00E8M     |
| Reference                              |              |
| CS/ASM18007071/Sqboss Date             |              |
| April 14, 2018                         | Request Date |
| April 17, 2018                         | Due Date     |
| April 17, 2019                         | Vendor Name  |
| LKK AUTO CONSULTANTS PTE Loss LTD (OD) | Type of      |
| Own Damage                             | Services     |

Next Step

Finish the work

Complete Work

More

| Vehicle Information             |                      |
|---------------------------------|----------------------|
| Incident Vehicle Registration # | SKN5042S             |
| Service Address                 |                      |
| Model                           | JAGUAR XF 2.0        |
| Ubi, , , 408933                 | Avenue 1 #01-25 Paya |
| Primary Contact/Insured         |                      |

ONG HUI PING CHRISTIE  
 BLK 272B JURONG WEST STREET  
 24, #07-96, 642272, Singapore  
 HOTMAIL@SINGNET.COM.SG



SERVICE REQUESTS

MESSAGES

CLAIMS

◀◀ Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary

General Details

Involving  
1 2014 JAGUAR XF 2.0 (SKN5042S)

Date of Loss  
April 14, 2018

Time of Loss  
13.50

Loss Description  
SKN5042S (INSD) C/W SLR6465R (TP)

Comment

Workshop Details

Total Rebate Amount  
91304

Nett Loss Amount  
\$20,696.00

Assigned Workshop  
LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion \*  
04/24/2018



Days of work completion \*  
7



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKN50425

Registration State

SINGAPORE

Mileage

57765

Purchase Date

mm/dd/yyyy



Registration Date \*

06/23/2014



Age of Vehicle

3

Driver Details

CATEGORY

Manufacturing Year

CATEGORY

Driver Name

POLICY INFORMAT... 2014

FNOL INFORMATI... LOW KWANG MENG PETER

ASSESSMENT INFO... 2014

POST SURVEY INF...



ASSESSMENT INFO...

SAJAC05MXEPU25314

FNOL INFORMATI... 0

CATEGORY

Engine No

POST SURVEY INF...

CATEGORY

Driver License #

POLICY INFORMAT...

181113183234204PT

FNOL INFORMATI...

ASSESSMENT INFO...

181113183234204PT

POST SURVEY INF...

CATEGORY

Engine Capacity

CATEGORY

License Type

POLICY INFORMAT...

1999 cc

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Sum Insured

License Issue Date

POLICY INFORMAT... 0

ASSESSMENT INFO...

0

FNOL INFORMATI...

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

Market Value

CATEGORY

License Expiration Date

POLICY INFORMAT... 0

ASSESSMENT INFO...

112000

FNOL INFORMATI...

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

Address

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

|                            |                          |                   |               |                |               |
|----------------------------|--------------------------|-------------------|---------------|----------------|---------------|
| General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous |
| Summary                    |                          |                   |               |                |               |

Front left side

PIRELLI 6mm

Rear left side

PIRELLI 6mm

Front right side

PIRELLI 6mm

Rear right side

PIRELLI 6mm

SERVICE REQUESTS    MESSAGES    CLAIMS

<<    Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous    Summary    Parts

| Add                               |       | Approve   |          | Deny |                              |             |                        |           |            |              |            |           |                 |           |
|-----------------------------------|-------|-----------|----------|------|------------------------------|-------------|------------------------|-----------|------------|--------------|------------|-----------|-----------------|-----------|
| EDIT                              | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                    | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTH (PAR |
| <div><div></div><div></div></div> | 1     | 1         |          |      | BONNET                       |             |                        | Dented    | 2750       |              | 10         |           | 2475            | Revis     |
| <div><div></div><div></div></div> | 2     | 1         |          |      | FRONT GRILLE                 |             |                        | Cracked   | 1042.6     |              | 10         |           | 938.34          | Revis     |
| <div><div></div><div></div></div> | 3     | 1         |          |      | HEAD LAMP RH                 |             |                        | Cracked   | 2100       |              | 10         |           | 1890            | Revis     |
| <div><div></div><div></div></div> | 4     | 1         |          |      | FRONT BUMPER                 |             |                        | Deformed  | 1828.5     |              | 10         |           | 1645.65         | Revis     |
| <div><div></div><div></div></div> | 5     | 1         |          |      | FRONT BUMPER INNER SPONGE    |             |                        | Cracked   | 380        |              | 10         |           | 342             | Revis     |
| <div><div></div><div></div></div> | 6     | 1         |          |      | FRONT BUMPER CHROME MOULDING |             |                        | Damaged   | 250        |              | 10         |           | 225             | Revis     |
| <div><div></div><div></div></div> | 7     | 1         |          |      | TOWING COVER                 |             |                        | Damaged   | 95         |              | 10         |           | 85.5            | Revis     |
| <div><div></div><div></div></div> | 8     | 1         |          |      | FRONT BUMPER SENSOR RH       |             |                        | Damaged   | 190        |              | 10         |           | 171             | Revis     |

Labour

Add    Approve    Deny

SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR  
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS  
OF  
REPAIR

Reviewing

5



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

|                            |                          |                   |               |                |               |
|----------------------------|--------------------------|-------------------|---------------|----------------|---------------|
| General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous |
| Summary                    | Claim Amount             | \$8,722.49        | Claim Amount  | \$8,722.49     |               |

| CATEGORY | ESTIMATE | REVISED AMOUNT |
|----------|----------|----------------|
|----------|----------|----------------|

Labour \$1,450.00 \$1,450.00

Excess -\$500.00 -\$500.00

Submit for Review