

22/03/2012

ASS. REC. BY:

REF:

CG3 / ICS18007074 / G24052

Special Instruction:

Surveyor

GR

ASSIGNMENT (Office)

From (Person):

Abdul Salim

of

ICS

Date/Time: 16/04/2018 5:39 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SID 85S

Insured:

G8A 5810S

at Workshop m/s

Lee Kuan Sing Motors

Tel:

9666 6354

of

Blk 10 AMK Ind Park A #03-10

Policy No:

Claim No:

DMCV1800025H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

23-04-2018 @ before 12pm

I.O.D. Endorsement:

Date/Time:

17/04/2018 1:21pm

Person Contacted:

Mr. Lee

Vehicle IN / OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|-----------------------------------|
| | SID 85S - X |
| | G8A 5810S - X |
| 24/4/18 | Dismantled |
| | |
| | |
| | |
| | |

PRs

Growth

Xkl

REF: ICS

mermen

ASSIGNMENT

From: Date: 23042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 855

at Workshop m/s

Lee Leung Sing

of

10 Ark Ind Park 2F #03-10

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLD 855 Yr Regn: 29 Apr 2016

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf c.c 1395

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

40714

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WUW 888 AU 86 W042365

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

225/45 ZR 18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23-04-18

Survey held at

w/s

5:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* Repair Estimate : S\$ 4000 - 5000

* 4 days

27/4/18

Submit PRS Report

RECEIVED 30 APR 2018

Date/Time: File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 16 April, 2018 5:39 PM
To: Sow-ye Wong; ECICS Claims; motorsurvey; KIM - SENG SON
Cc: Catherine Chong (LKK Auto (admin-d@lkkauto.com))
Subject: RE: FW: NOTICE OF ACCIDENT - SLD 85S & GBA 5810S ON 08.04.18 @ OPEN CARPARK B/421 HOUGANG AVE 10 @ 09:45 PM Our ref. DMCV1800025H
Attachments: NOTICE OF ACCIDENT (SLD 85S & GBA 5810S ON 08.04.18 Our ref. DMCV1800025H).pdf

Without Prejudice

Dear Sirs,

Thank you for your email.

We are unable to agree to your list of Survey.

We will appoint LKK for the PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Abdul Salam
Claims Division
ECICS Ltd

From: Sow-ye Wong [mailto:wongsylaw@gmail.com]
Sent: Monday, 16 April, 2018 1:54 PM
To: ECICS Claims; motorsurvey; KIM - SENG SON
Subject: Fwd: FW: NOTICE OF ACCIDENT - SLD 85S & GBA 5810S ON 08.04.18 @ OPEN CARPARK B/421 HOUGANG AVE 10 @ 09:45 PM Our ref. DMCV1800025H

Dear Sirs

We thank you for your proposed PRS Surveyors list *below*

We regret to inform you that our Client is unable to agree to your list of nominated Surveyors

Our Client proposes the following list

List of 10 Surveyors

| | Name of Firm | Surveyor | Mobile |
|----|-----------------------------|-----------------|---------------|
| 1. | HJL Auto Appraiser Services | Danny Ho | 9855 0756 |

| | | | |
|-----|------------------------------------|----------------|-----------|
| 2. | CA Appraisal Services | Ang Guea Kiang | 96399762 |
| 3. | Lee Automobile Appraisers Services | Lee Kok Weng | 8188 2833 |
| 4. | Prominent Appraiser Services | Andrew How | 9295 2204 |
| 5. | Prestige Appraiser Services | Francis Ng | 9689 7474 |
| 6. | Sincere Appraisal Services | Dave Chang | 8186 9497 |
| 7. | Prestige Appraiser Services | Louis Ng | 9682 4663 |
| 8. | KTO Automobile Assessors | Kent Ong | 9850 5311 |
| 9. | Aeon Auto Consultants LLP | Amas Ong | 9768 7958 |
| 10. | Precision Appraisal Services | Philip Foo | 9685 2057 |

Please contact our **Mr Kim @ 9668 6354 / 6483 7412**

Appreciate your kind understanding & help

Yours Sincerely

Sow yee

M/s Fong & Fong LLC

cc: Client

From: **ECICS Claims** <claims@ecics.com.sg>

Date: Mon, Apr 16, 2018 at 1:49 PM

Subject: FW: NOTICE OF ACCIDENT - SLD 85S & GBA 5810S ON 08.04.18 @ OPEN CARPARK B/421 HOUGANG AVE 10 @ 09:45 PM Our ref. DMCV1800025H

To: Sow-ye Wong <wongsylaw@gmail.com>, ECICS Claims <claims@ecics.com.sg>, KIM - SENG SON <leeluewsingmotor@live.com>

Without prejudice

Dear Mr. Lee,

Thank you for your email with attachment.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,
Abdul Salam
Claims Division
ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

| | | |
|--------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
|--------------------------|--------------------------|--------------------------|

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Fong & Fong LLC

Advocates & Solicitors

150 South Bridge Road
02 - 09A Fook Hai Building
Singapore 058727

Tel : 9388 1428
Fax : 6532 2367
Email : jflegfin@yahoo.com.sg

Our Ref : FCY / 477 / 18
Your Ref : **GBA 5810S**
AH KEAT LIM KEE HANDCRAFT SHOP - 52970146D
Date : 16 April 2018

M/s ECICI Limited
7 Temasek Blvd
10 - 01 Suntec Tower One
S 038987
Attn: **The Manager - Motor Claims**

Fax: 6338 9267 / Email

M/s Ah Keat Lim Lee Handcraft Shop
87 Geylang Bahru
01 - 2716 Geylang Bahru Industrial Estate
S 339695

Post

Dear Sirs

NOTICE OF ACCIDENT
ACCIDENT INVOLVING SLD 85S & GBA 5810S ON 08.04.18 @ OPEN CARPARK
B/421 HOUGANG AVE 10 @ 09:45 PM

We act for **LIM HONG MUI** owner

Our Client's Car : **SLD 85S**

Your / Your Insured's Lorry : **GBA 5810S**

Date & Time of Accident : **08 APRIL 2018 / 09:45 PM**

Place of Accident : **PARKED AT OPEN CARPARK B/421**

Before our Client proceeds to repair the damaged car, we are requesting a *Pre-Repair Survey*

Kindly let us know within **2 working days** of this Notice whether you or your Insurers would like to conduct a PRS of the car

If we do not receive any reply from you/your Insurers within the stipulated timeline, our Client shall proceed to repair the car without further reference to you & our Client will be compensated for the loss of use of the van for this period of time

Our Client's Appointed Surveyor :

MR LEE KIM WAH

Address :

M/s Lee Luew Sing Motors
10 Ang Mo Kio Industrial Park 2A
03 - 10 AMK Autopoint
S 568047

Tel : 6483 7412 / 6483 0827

Fax : 6483 7416

Mobile : 9668 6354

Copies of our Client's GIA / Police Reports (with 8 Colored Photographs of damage to our Client's car), NRIC, LTA Search, Warrant-To-Act & Letter Of Authority are enclosed for your kind attention

Deeply appreciate your prompt action

Yours Faithfully



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------------------------|
| Date Of Report | 14/04/2018 16:07 |
| Date Of Accident | 08/04/2018 21:45 |
| Exact Location Of Accident | BLK 421 HOUGANG AVE 10(OPEN CARPARK) |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLD85S |
| Insured/Policyholder | |
| Name Of Registered Owner | LIM HONG MUI |
| NRIC No | S1681947F |
| Email Address | INDPEH@GMAIL.COM |
| Mobile Phone No | (LOCAL) +65-90120383 |
| Alternative Phone No | OTHERS-90120383 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | VOLKSWAGEN |
| Model | GOLF |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | A 28735213 AVW |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | PEH OON HUI |
| NRIC No | S2611879D |
| Date Of Birth | 02/08/1963 |
| Occupation | INDOOR |
| Date Of Driving Pass | 01/01/1981 |
| Driving Experience | 37 YEARS AND 3 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-90120383 |
| Fax Number | |
| Contact Number | OTHERS-90120383 |
| EMail Address | INDPEH@GMAIL.COM |

| | |
|---|-----------------|
| Address | 1 SUNRISE CLOSE |
| Postcode | 806598 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | SPOUSE |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|---|
| Type Of Accident | HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 0 |

Details of Police Action

| | |
|---|---|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE |
| Police Station Address | ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: 1800-4849999 - FAX NO: 62181399 |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER ATTACHED

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

Details of Witness 1

| | |
|---------------|----------|
| Name | RAMESH |
| Phone Number | 93380702 |
| Email Address | |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------------|
| Vehicle Registration Number | GBA5810S |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:


- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

SKETCH PLAN

HOUGHAN AVE 10
BLK 421 CARPARK.

A: SLD 85 S
B: GBA 53105



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO POLICE REPORT NO. T/20180409/2193.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:



**SINGAPORE
POLICE FORCE**



T/20180409/2193

1 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20180409/2193

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|-------------------|---------------------------|
| Date/Time Report Made: 09/04/2018 20:53 | Video Report No.: | Station Diary No.: 100 |
|--|-------------------|---------------------------|

Informant's Particulars

| | | | | |
|--|------------|------------------------------|--|----------------------------|
| Name of Informant: PEH OON HUI | | | Address: 1 SUNRISE CLOSE SINGAPORE 808598 | |
| ID Type / ID No.: NRIC NO / S2611879D | | | Contact No.: | Mobile: 90120383 |
| Nationality: MALAYSIAN | | | Email: | |
| Sex: Male | Age: 54 | Date of Birth: 02/08/1963 | Type of Informant: Driver | |
| Race: Chinese | | | Language: English | Institution / School Name: |
| Occupation: DOCTOR | | | Driving Licence Information: Class: 3 | Date of Expiry: |

General Information of the Accident

| | | | | |
|---|------------------------------------|--------------------|--|------------------------------|
| Type of Accident: | Non-Injury Hit and Run | Drink Drive: No | Date/Time of Accident: 08/04/2018 21:45 | Type of Location: CARPARK |
| Location: Along Road 1 HOUGANG AVENUE 10 PUBLIC OPEN CARPARK NEXT TO BLK 421 HOUGANG AVENUE 10 | | | | |
| Weather: Clear | Road Surface: Dry | | Road Speed Limit: | |
| Traffic Flow: One Way | Traffic Control: Not Controlled | | Traffic Volume: No Traffic | |
| Type of Collision: REAR TO FRONT LEFT PASSENGER'S SIDE | | | Anyone conveyed by ambulance: No | |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|--------|------|-------|-------|------------------|-----------------|
| GBA5810S | PICKUP | | | | No Damage | 0 |
| SLD85S | Car | | | | Slightly Damaged | 0 |

Details of Person Involved

| | |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No | Use of Pedestrian Crossing: NA |
| No. of Pedestrians Injured: NIL | |



**SINGAPORE
POLICE FORCE**



T/20180409/2193

2 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C.
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20180409/2193

CONTINUATION OF REPORT

| Driver | | | |
|-----------------------------------|-------------|--|---------------------------------|
| Name | PEH OON HUI | ID No. | S2611879D |
| Related Vehicle | NIL | Contact No. | 90120383 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: 3 Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On the abovementioned date, time and at the abovementioned location, I was informed by the witness (Ramesh, 93380702), that my said car (SLD85S) had been damaged by another vehicle (GBA5810S) when the said vehicle reversed into my car's left side front passenger door. My car was parked at the parking spot since 1910hrs, and was all intact the last I saw it. The mentioned collision occurred when there was nobody in my parked car.



**SINGAPORE
POLICE FORCE**



T/20180409/2193

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

3 of 3




Report No. T/20180409/2193

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

| | |
|--|--|
| Signature Of Officer Recording The Report: F / ALAN KOH ZHENG YONG  | Signature Of Informant:  |
| Signature Of Interpreter: Not applicable | Date/Time: 09/04/2018 20:53 |
| Officer In Charge Of Case: TP / HRT / SI TAN LEE HWANG DAWN Contact No.: 65476215  | Classification Of Case: |
| Authentication Stamp NP168 | |

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|--------------------------------|--------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 1947F |
| Vehicle Details | |
| Vehicle No.: | SLD855 |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 25 Apr 2018 |
| Vehicle Make: | VOLKSWAGEN |
| Vehicle Model: | GOLF 1.4 TSI AT 5G13HZ HID SR |
| Primary Colour: | White |
| Manufacturing Year: | 2015 |
| Engine No.: | CZC405553 |
| Chassis No.: | WVWZZZAUZGW042365 |
| Maximum Power Output: | 92.0 kW (123 bhp) |
| Open Market Value: | \$24,577.00 |
| Original Registration Date: | 29 Apr 2016 |
| First Registration Date: | 29 Apr 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$16,408.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 28 Apr 2026 |
| PARF Rebate Amount: | \$12,306.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 28 Apr 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$47,300.00 |
| COE Rebate Amount: | \$37,879.00 |
| Total Rebate Amount: | \$50,185.00 |

The information contained herein is correct as at 25 Apr 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|--|---------------|--|--|--|------------|---|
| Main | 07 May 2018 10:32 Edit Reg | | 16 Apr 2018 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | -, Co. Reg. No.: -, Email: J@gmail.com | | |
| Main Claimant: | LIM HONG MUI , ID: S1681947F | | |
| Vehicle Reg. No.: | SLD85S | Date of Loss: | 08/04/2018 21:00 - :59 [23 Months and 10 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP | Policy/Cover Note No.: | |
| Vehicle Reg. No. (Insured): | GBA5810S | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Lee Leuw Sing Motor (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-10 AMK AUTOPOINT, 568047 Ang Mo Kio - Tel: | | |
| Handling Insurer: | ECICS Limited (HQ) - Tel: 63374779 /6303 0178 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/04/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SLD85S**
[GBA5810S]
TP
LIM HONG MUI
Apr 8 2018 9:00PM
[-]
Lee Leuw Sing Motor

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser ▼ | |
|---|-----------------|-----------------------------------|------------------------|-------|
| Photos/Images | | | 3 per page ▼ | ✓ |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 2 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 3 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 4 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 5 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 6 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 7 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 8 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 9 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 10 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 11 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 12 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 13 | 25/04/18 13:58 | General View | Load JPG | ✓ |
| 14 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 15 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 16 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 17 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 18 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 19 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 20 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 21 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 22 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 23 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |
| 24 | 25/04/18 13:58 | Dismantled Parts | Load JPG | ✓ |

Documents Checklist

| | | | |
|--|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18007074/GZ4BS2
 Date: 07/05/2018

REFERENCE

Handling Insurer: ECICS Limited Policy No:
 Claimant Vehicle No: SLD85S Insured Vehicle No: GBA5810S
 Date of Loss: 08/04/2018 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD85S
 Make & Model: VOLKSWAGEN GOLF, 1.4 (A)
 Reg. Date: 29/04/2016 (Man. Year: 2015)
 Colour: White
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price
 Engine No: CZC405553
 Chassis No: WVVZZZAUZGW042365
 Odometer: 40714 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR18 Rear Tyre Size: 225/45ZR18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 16/04/2018
 Date Inspected: 23/04/2018 Inspected At: Lee Leuw Sing Motor (HQ)
 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-10 AMK
 AUTOPOINT
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/7/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 07 May 2018) |
| Parts: | 144 | VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLD85S) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >