

ASS. REQ. BY:

REF: CS / FCI 8007077 / Tigbn2

Special Instruction:

Surveyor: Tarifikh

ASSIGNMENT (Office)

From (Person): (WS) Joanne Yong of FCL

Date/Time: 17/04/2018 1248pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGR 9612Y Insured: SHA 2097H

at Workshop m/s MOVA Tel: 6272 3892

of Blk 1008 Bukit Merah Lane 3 #01-04

Policy No: _____ Claim No: D18002872MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11/04/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS DS:

18-04-2018 @ after 11:30am

H.O.D. Endorsement:

Date/Time: 17/04/2018 119pm

Person Contacted: Erny

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGR 9612Y - X
	SHA 2097H - NB/2NC15017726/H/vbn2 DA: 17/01/15
19/4/18 @ 3:29pm	revised to Joanne Yong by email.
11/6/18 @ 4:32pm	confirmed with Kemp LS \$2800, 5 days by email. ched to 1489.15, 35%

Current

Tan

REF: FCL

ASSIGNMENT

CoE 2022 Feb.

From: _____ Date: 18042018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGR 9612Y

at Workshop m/s: Mova

of: B1E 1008 Bukit Merah Lane 3

Insured: #01-04

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SGR 9612Y Yr Regn: 2007 Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Wish CC 1794

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 101977 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZNE100340737

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / SRim / STD A/Rim or _____

Tyre Size: F: 205/55R16

R: _____

after 11:30am

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Bal. or Market Value: 431K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

Front: C R/Bal. 6 mm

Rear: 6 R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____ D.O.I. 18/4/18 @ 2pm

Survey held at: Mova Bym.

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Check burnt

RECEIVED 11 JUN 2018

Date/Time, File Pass to? Preli. Report

1) 11/6/18 Final Report

Date/Time, File Return to? _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:	135
Transportation:	50
) \$ + RS, SI	50
) Photos:	48
) Others:	
TOTAL	283

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format: TP

Lump Sum / I.B.F. (\$) 2800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18007077/T1qb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2097H	Veh. Inspected	SGR 9612Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18002872MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	17/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/04/2018	Inspection Date	18/04/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002872MFSH

Date: 19 April 2018

Our Ref: CS/FC118007077/T1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGR 9612Y

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/04/2018 at the premises of M/s MOVA AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,289.15</u>
Revised Estimate Amount	: S\$ <u>3,128.38</u>
"Check" Items Amount	: S\$ <u>412.20</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 13-04-2018 **Our Ref No.** D18002872MFSH

Accident Date 11-04-2018 **Claim Type.** Third Party

Insured Vehicle SHA2097H **Third Party Vehicle.** SGR9612Y

Survey Location BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08

Contact Person. AVRIL

Contact No. 62723892/ 0 **Fax No.** 62708314

Survey Type DIRECT SETTLEMENT:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop MOVA AUTOMOTIVE PTE LTD **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Notify Insurance Company to Conduct Inspection

Date: 13/4/18
From: Kwan Poh San, Shandy
To: M/S First Capital Insurance Ltd

Dear Sir / Madam

MOTOR ACCIDENT ON 11/4/18 **ALONG** 402 Chao chu kang Ave 3 carpark
INVOLVING SGR 9612 Y & SHA 2097 H

I am registered owner of motor-vehicle registration no SGR 9612 Y which was involved in an accident with motor-vehicle registration no SHA 2097 H insured by you.

As the accident was cause solely by the negligence of your insured's driver, I am holding you full responsible for the damage to my vehicle.

Herewith, I enclose the estimate and GIA report from the repairer, M/s MOVA AUTOMOTIVE PTE LTD at Blk 1008 Bukit Merah Lane 3 #01-04/06/08 Singapore 159722 for your perusal and kindly arrange your surveyor to survey my vehicle at MOVA Automotive Pte Ltd. Any doubt or queries, please contact MOVA Automotive Pte Ltd at Tel: 6272 3892.

Kindly arrange to have my vehicle surveyed by your appointed motor assessor within 48 hours on receipt of my letter at the above mentioned workshop, failing which I will proceed to appoint my own independent motor assessor to inspect my vehicle and authorize the repair without further notice to you.

Please let me hear from you soon.

Date the 13 day of 4 20188

Signed by:



Name :

cc. MOVA Automotive Pte Ltd

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 11 June 2018 4:32 PM
To: 'Keong'; Taufikh (LKKAuto)
Cc: SUR
Subject: RE: SGR9612Y Ready For Finalise

Dear Keong,

Confirm Lump Sum \$2,800.00 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keong [<mailto:keong@moval.com.sg>]
Sent: Friday, 8 June 2018 10:41 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: SGR9612Y Ready For Finalise

Dear Taufikh

Please close this case ,My lady boss chasing ,Thanks.

Best Regards,

Goh Chai Hock (Keong)

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Keong [<mailto:keong@moval.com.sg>]
Sent: Friday, 27 April 2018 1:29 PM
To: 'Taufikh (LKKAuto)'
Subject: SGR9612Y Ready For Finalise

Dear Taufikh

Attach finalise report and photo, Lump sum \$2800.00 and 5 days ,Thanks.

Regards

Keong

Hp 96510098

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 19 April 2018 3:29 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002872MFSH/1
Attachments: CSFCI18007077T1qb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SGR 9612Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 17 April 2018 1:20 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002872MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 17 April, 2018 12:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002872MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

IS YOUR CAR DUE FOR SCRAP OR EXPORT? Use Our **FREE** Service To Get The Best Selling Price!



Toyota Wish Price Range Depreciation > 10 year(s) of Vehicle Type [Advanced Search](#)

Home » Used Cars » Inchcape Pre-Owned » Toyota Wish 1.8A X (COE till 03/2022)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres




DRY
CREW
T-S
MADE
LIKE

Compare

Toyota Wish 1.8A X (COE till 03/2022)

- [Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)



- [Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price	\$35,800	
Depreciation	\$9,110 /yr	
Reg Date	24-Mar-2007 (3yrs 11mths 4days COE left)	
Manufactured	2006	
Mileage	139,525 km (12.6k /yr)	
Transmission	Auto	
Engine Cap	1,794 cc	
Road Tax	\$1,069 /yr	
Power	97.0 kW (130 bhp) View specs of the Toyota Wish (2008-2009)	
Curb Weight	1,300 kg	
Features	Powerful And Reliable 16 Valves VVT-I DOHC Engine, Smooth 4 Speed Steptronic Gearbox, Digital Climate Control Aircon, Airbags, ABS, 7 Seaters.	
Accessories	Sports Rims, Audio Player, Reverse Sensors, Solar Film, Leather Upholstery, Knockdown Rear Seats.	
Description	Well Maintained By Owner. Most Popular Japan Make MPV In The Market. Hassle Free. Brand New Leather Seats. No Repair Needed. Please Call Our Sales Consultant For More Enquiries Now!	
COE	\$25,174	
OMV	\$17,738	
ARF	\$19,512	
Dereg Value	\$19,781 as of today (change)	
No. of Owners	4	
Type of Veh	MPV	
Category	COE Car	
Availability	Available	

- [Add to Shortlist](#) [Add to Compare](#) [Add a Note](#)



Seller Information

Company	Inchcape Pre-Owned * dealer's pricelist * 25 vehs sold 41 vehs available	
Address	2 Pandan Crescent Level 1 Search cars nearby this location	
Location	Inchcape Centre	
Office No	63036303	
Contact Person(s)	Edmund Ng Kelvin Kee	90212360 98719789

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3548B
Vehicle Details	
Vehicle No.:	SGR9612Y
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1ZZ2771082
Chassis No.:	ZNE100340737
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,218.00
Original Registration Date:	27 Feb 2007
First Registration Date:	27 Feb 2007
Transfer Count:	2
Actual ARF Paid:	\$14,759.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,039.00
COE Rebate Amount:	\$20,071.00
Total Rebate Amount:	\$20,071.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Apr 2018

OK

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

12/04/2018

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Page # :- 1
 Veh # :- SGR9612Y
 Veh Model :- TOYOTA WISH
 Estimate# :- CK417348
 Claim # :-
 ACC. Date :- 11/04/18
 Terms :- C.O.D Days
 Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT FENDER RH	1	578.60	578.60 <i>bt</i>
2.	FRONT FENDER COWLING RH	1	273.10	273.10 <i>do</i>
3.	FRONT FENDER COWLING CLIPS	10	5.10	51.00 <i>net</i>
4.	HEADLAMP RH	1	798.40	798.40 <i>cut</i>
5.	HEADLAMP CLIPS	1	5.50	5.50 <i>net</i>
6.	FRONT BUMPER	1	721.30	721.30 <i>dt</i>
7.	FRONT BUMPER FOG LIGHT COVER RH	1	114.70	114.70 <i>de</i>
8.	FRONT BUMPER SIDE BRACKET RH	1	105.60	105.60 <i>de</i>
9.	FRONT BUMPER CLIPS	10	5.10	51.00 <i>net</i>
10.	FRONT BUMPER SPONGE	1	217.30	217.30 <i>cut</i>
11.	FRONT BUMPER REINFORCEMENT	1	398.10	398.10 <i>nn x</i>
12.	WASHER TANK	1	217.60	217.60 <i>? de</i>
13.	SUPPORT PANEL - REPAIR	1		
14.	FRONT INNER PANEL - REPAIR	1		
15.	FRONT DOOR RH - REPAIR	1		
	LIST TOTAL S\$			3,532.20
	25% DISCOUNT S\$			-883.05
				<u>2,649.15</u>
LABOUR :				
	TO REPAIR FRONT INNER PANEL, FRONT SUPPORT PANEL, FRONT DOOR RH, TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS			450 650.00
	TO SRPAY AFFECTED AREAS			600 800.00
	TO CHECK WIRING AND FOCUS HEAD LIGHT			30 50.00
	TO RUST PROOF AFFECTED AREAS			30 40.00
	TO CHECK WHEEL ALIGNMENT			80 100.00
	LABOUR TOTAL S\$			<u>1,640.00</u>

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

12/04/2018

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Page # :- 1 131337

Veh # :- SGR9612Y

Veh Model :- TOYOTA WISH

Estimate# :- CK417348

Claim # :-

ACC. Date :- 11/04/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E



NON-TAX AMOUNT S

AMOUNT S\$ 4,289.15

GST @ 7 % 300.24

AMOUNT DUE S\$ 4,589.39

 Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tarifika 99495749
 18/4/18 @ 2pm
 up
 lumpsum
 Resurvey after repair
 5 days
 see @ lkkauto.com


 23/5/18

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

12/04/2018

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- XA026

Page # :- 1
 Veh # :- SGR9612Y
 Veh Model :- TOYOTA WISH
 Estimate# :- CK417348
 Claim # :-
 ACC. Date :- 11/04/18
 Terms :- C.O.D Days
 Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	FRONT FENDER RH	1	PC	578.60	578.60 ✓
2.	FRONT FENDER COWLING RH	1	PC	273.10	273.10 ✓
3.	FRONT FENDER COWLING CLIPS	10	PC	5.10	51.00 ✓
4.	HEADLAMP RH	1	PC	798.40	798.40 ✓
5.	HEADLAMP CLIPS	1	PC	5.50	5.50 ✓
6.	FRONT BUMPER	1	PC	721.30	721.30 ✓
7.	FRONT BUMPER FOG LIGHT COVER RH	1	PC	114.70	114.70 ✓
8.	FRONT BUMPER SIDE BRACKET RH	1	PC	105.60	105.60 ✓
9.	FRONT BUMPER CLIPS	10	PC	5.10	51.00 ✓
10.	FRONT BUMPER SPONGE	1	PC	217.30	217.30 ✓
11.	FRONT BUMPER REINFORCEMENT	1	PC	398.10	398.10 ✓
12.	WASHER TANK	1	PC	217.60	217.60 ✓
13.	SUPPORT PANEL - REPAIR	1	PC		
14.	FRONT INNER PANEL - REPAIR	1	PC		
15.	FRONT DOOR RH - REPAIR	1	PC		

3134.10
 783.52

 2350.57
 1190.00 - LB

 \$ 3540.57

LIST TOTAL S\$
 25% DISCOUNT S\$

3,532.20
 -883.05

LS \$2800/-

2,649.15

LABOUR :

TO REPAIR FRONT INNER PANEL, FRONT SUPPORT PANEL, FRONT DOOR RH, TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS

5 days

TO SRPAY AFFECTED AREAS

TO CHECK WIRING AND FOCUS HEAD LIGHT

TO RUST PROOF AFFECTED AREAS

TO CHECK WHEEL ALIGNMENT

LABOUR TOTAL S\$

450 650.00
 600 800.00
 30 50.00
 30 40.00
 80 100.00

1190 / 1,640.00

Main Office:
 Move Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

12/04/2018

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- XA026

Page # :- 1 131337

Veh # :- SGR9612Y

Veh Model :- TOYOTA WISH

Estimate# :- CK417348

Claim # :-

ACC. Date :- 11/04/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E



NON-TAX AMOUNT S	
AMOUNT S\$	4,289.15
GST @ 7 %	300.24
AMOUNT DUE S\$	4,589.39

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tarifika 99495748
 12/4/18 2pm
 up
 Lumpsom
 Rekening after repair.
 5days
 9400@lumpsum.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007077/T1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2097H	Veh. Inspected	SGR 9612Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18002872MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	17/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ZNE100340737	Colour	SILVER
Odometer	101977	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	6 mm
L/H Front Tyre	205/55 R16	DUNLOP	6 mm
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/04/2018	Inspection Date	18/04/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 9612Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH	BENT	578.60	578.60
1	FRONT FENDER COWLING RH	DEFORMED	273.10	273.10
10	FRONT FENDER COWLING CLIPS @\$5.10	NECESSARY	51.00	51.00
1	HEADLAMP RH	CUT	798.40	798.40
1	HEADLAMP CLIPS	NECESSARY	5.50	5.50
1	FRONT BUMPER	DEFORMED	721.30	721.30
1	FRONT BUMPER FOG LIGHT COVER RH	DEFORMED	114.70	114.70
1	FRONT BUMPER SIDE BRACKET RH	DEFORMED	105.60	105.60
10	FRONT BUMPER CLIPS @\$5.10	NECESSARY	51.00	51.00
1	FRONT BUMPER SPONGE	CRACKED	217.30	217.30
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	398.10	-
1	WASHER TANK	DEFORMED	217.60	217.60
1	SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT INNER PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-883.05	-783.53
			2,649.15	2,350.57
LABOUR				
	TO REPAIR FRONT INNER PANEL, FRONT SUPPORT PANEL, FRONT DOOR RH. TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS.		650.00	450.00
	TO SPRAY AFFECTED AREAS.		800.00	600.00
	TO CHECK WIRING AND FOCUS HEAD LIGHT.		50.00	30.00
	TO RUST PROOF AFFECTED AREAS.		40.00	30.00
	TO CHECK WHEEL ALIGNMENT.		100.00	80.00
			1,640.00	1,190.00
GRAND TOTAL			4,289.15	3,540.57

Report Ref No. CS/FCI18007077/T1qbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00
---	--	--	----------

Report Ref No. CS/FCI18007077/T1qbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.